

INS. CASE NO. OWNER: **GO Sashe**

CC4/ASM19015401/T1ga3

LKK: IDAC: **134548**

Surveyor: **TAUFIKH**

ASSIGNMENT  
DOI: **04/09/2019**

Date/Time: **30/08/2019**

Registered in Merimen: \_\_\_\_\_

Pre-assign / CCU / FTE

 Insured Vehicle No. : **SKU 8468R** Claim No. : **S9M01YQC**  
 Name of Insured : **PEH KENG HWEE** Policy No. : **VPA/P2253087**  
 Insured Tel No. : \_\_\_\_\_ HP: **+65-81639661** Make / Model : **TOYOTA PRIUS PLUS-1.8 (A)**  
**Excess Sec II : S5** D.O.A : **28/08/2019 09:45** Place of Accident : **JUNCTION OF MOHAMAD SULTAN ROAD / MARTIN ROAD**  
 Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_  
 If NO, Driver Name / Age : \_\_\_\_\_ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

**SKT 4002H**



INSRS: **VANTAGE**  
WSP: **AUTOMOTIVE**  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time	SKT 4002H - X	SKU 8468R - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	<b>7 CPL 17/9/19.</b>
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
			After call ltr to OI:	<input checked="" type="checkbox"/>
			Authorisation To Act:	<input checked="" type="checkbox"/>
			Release Voucher:	<input type="checkbox"/>
			Final Repair Bill:	<input checked="" type="checkbox"/>
			Car Rental Invoice:	<input checked="" type="checkbox"/>
			Towing Invoice	<input checked="" type="checkbox"/>
			LTA / GIA :	<input checked="" type="checkbox"/>
			Medical Bill:	<input checked="" type="checkbox"/>
			PIR:	<input checked="" type="checkbox"/>
			Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
			LOD	<input checked="" type="checkbox"/>
			Payment Breakdown Form:	<input type="checkbox"/>
			Post-Repair Photos:	<input type="checkbox"/>
			Others:	<input type="checkbox"/>

**17/9 - Email LOI liability clear send TP.**  
**29/11 - TO seek mandate.**  
**4/12 - pending mandate approval. ✓**  
**5/12 - send to 4441-54 as Rev TP LOD, file pass in send by.**

**PRELIMINARY ADVICE** Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

**FINALIZATION** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: **TAUFIKH**

Repair Cost: **PIP S\$ 5034.10** (3 days) Reduction: **2524.30 % 50** Email  Call

**FINAL SETTLEMENT** Date/Time: **5/12/19** Confirm with: **LEATHERINE** Email  Call

Final Liability: **% 100** (Agreed / Assessed) BOLA S/N No. : **9C** If NO or B 28, Ass. Lia : \_\_\_\_\_

Repair Cost: **(WGS) S\$ 4214.24**

Loss of Rental (LOR): **S\$ 224.76** (3 days) x **\$74.90**

Loss of Use (LOU): **S\$ -** (5 x days)

Loss of Income (LOI): **S\$ -** (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search **S\$ 2.00**

Medical: **S\$ -**

Disbursement: **S\$ -** (e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle  
 2) Report Format: **TP**  
 3) Survey fee: **#3501-**

**Total: S\$ 4441.54 Global Sum S\$:**

**FINAL PAYMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: **S\$ 4441.54** Name 1: **AUTO FRANCE**

Payee 2: (Strike if N.A.) **S\$ -** Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) **S\$ -** Name 3: \_\_\_\_\_

**COPY SENT**  
**21/12/19**

✓ **GIA**



# AUTOFRANCE

(A Division of Vantage Automotive Limited)  
 Business Registration No. S2907220C GST Registration No. M2-0000551-1  
 305 Alexandra Road  
 159942, Singapore  
 Tel : 6376 2288  
 Fax : 6477 7373



GST Registration No. M2-0000551-1

## E S T I M A T E

Estimate No. : BP 4323 Page No. : 1 of 2  
 Date Estimated : 29/08/2019  
 Prepared By : Andy Ooi Lee Keong

**- ESTIMATE REPAIR FOR -**

Lee Dong Chan  
 355 BUKIT TIMAH ROAD  
 #08-04  
 Singapore 259724

**- ACCOUNT - 77**

Axa Insurance Pte Ltd  
 No. 8 Shenton Way  
 #24-01 Axa Tower  
 Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT4002H	VF38E5GZTFL011178	04/06/2015	508SW1.6 Allure	10

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM AGAINST AXA INSURANCE-SKU8468R DOA. 28/08/2019	0.00
SUNDRIES <i>Nu</i>	<i>50.</i> 150.00
LABOUR TO REMOVE, REPLACE, REPAIR AND REALIGN REAR BUMPER TAILGATE PANEL AND ALL AFFECTED AREAS <i>500</i>	<i>1000</i> 1,500.00
LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREAS <i>500.</i>	<i>1000</i> 1,500.00
TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE (NETT)	<i>560.</i> 600.00
TO REMOVE AND REINSTALL REAR BUMPER SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	✓ 120.00
<b>Total Labour 1:</b>	<b>3,870.00</b>

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1611343680	TAILGATE	1	2,886.00	10.00	<i>FX</i> 2,597.40
1611916580	REAR BUMPER	1	956.00	10.00	<i>de</i> 860.40
1611901380	BRACKET SET	1	130.00	10.00	<i>net</i> 117.00
745387	REFLECTOR RH	1	61.00	10.00	<i>net</i> 54.90
742162	BUMPER BRACKET	1	80.00	10.00	<i>net</i> 72.00
7422W6	BUMPER ABSORBER	1	152.00	10.00	<i>net</i> 136.80
1608321780	SENSOR-OBSTACLE DETECTION FRT/REAR	4	99.00	10.00	<i>net</i> 356.40
1608472280	SENSOR-OBSTACLE DETECTION FRT/REAR	2	180.00	10.00	<i>net</i> 324.00
7422W9	BUMPER BRACKET	1	502.00	10.00	<i>net</i> 451.80
8666CX	BADGE	1	32.00	10.00	<i>net</i> 28.80
9809004580	BADGE 508 SW	1	55.00	10.00	<i>net</i> 49.50
00007810AH	RR BADGE LION	1	46.00	10.00	<i>net</i> 41.40
<b>Total Parts :</b>					<b>5,090.40</b>

*#8960.40*

# AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

## E S T I M A T E

Estimate No. : BP 4323  
Date Estimated : 29/08/2019  
Prepared By : Andy Ooi Lee Keong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT4002H	VF38E5GZTFL011178	04/06/2015	508SW1.6 Allure	10

Taufik 97445149  
WP  
4/9/19 @ 1145  
Resurvey before paint  
30 days  
sure/kharto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To supply damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp	Date	Labour 1	:	3,870.00
		Parts	:	5,090.40
		Labour 2	:	0.00
		Excess	:	0.00
		Total GST @ 7%	:	627.23
		Grand Total	:	9,587.63

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

# AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

## E S T I M A T E

Estimate No. : **BP 4323**  
 Date Estimated : **29/08/2019**  
 Prepared By : **Andy Ooi Lee Keong**

Page No. : 1 of 2

**- ESTIMATE REPAIR FOR -**

Lee Dong Chan  
 355 BUKIT TIMAH ROAD  
 #08-04

Singapore 259724

**- ACCOUNT - 77**

Axa Insurance Pte Ltd  
 No. 8 Shenton Way  
 #24-01 Axa Tower  
 Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT4002H	VF38E5GZTFL011178	04/06/2015	508SW1.6 Allure	10

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM AGAINST AXA INSURANCE-SKU8468R DOA. 28/08/2019	0.00
SUNDRIES	50. 150.00
LABOUR TO REMOVE, REPLACE, REPAIR AND REALIGN REAR BUMPER TAILGATE PANEL AND ALL AFFECTED AREAS <sup>500</sup>	1000 1,500.00
LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREAS <sup>500</sup>	1000 1,500.00
TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE (NETT)	<del>500</del> 600.00
TO REMOVE AND REINSTALL REAR BUMPER SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	✓ 120.00

Total Labour 1: **3,870.00**

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1611343680	TAILGATE	1	2,886.00	10.00	Rp 2,597.40
1611916580	REAR BUMPER	1	956.00	10.00	de 860.40
1611901380	BRACKET SET	1	130.00	10.00	net 117.00
745387	REFLECTOR RH	1	61.00	10.00	? 54.90
742162	BUMPER BRACKET	1	80.00	10.00	net 72.00
7422W6	BUMPER ABSORBER	1	152.00	10.00	? 136.80
1608321780	SENSOR-OBSTACLE DETECTION FRT/REAR	4	99.00	10.00	? 356.40
1608472280	SENSOR-OBSTACLE DETECTION FRT/REAR	2	180.00	10.00	? 324.00
7422W9	BUMPER BRACKET	1	502.00	10.00	? 451.80
8666CX	BADGE	1	32.00	10.00	net 28.80
9809004580	BADGE 508 SW	1	55.00	10.00	net 49.50
00007810AH	RR BADGE LION	1	46.00	10.00	net 41.40

Total Parts : **5,090.40**

305 Aljunied Road  
 Vantage Automotive Centre  
 Singapore 139943  
 Service Booking: 6477 7377  
 Parts: 6477 7420  
 Vantage 24-Hour Assist: 6473 8888  
 Fax: 6477 7300



**PEUGEOT**

**FINALIZATION REPORT**  
**SERVICE TAX INVOICE**  
 RE-PRINT

REPAIR ORDER NO. <b>bp 115165</b>	Date IN <b>01/10/2019</b>	Invoice Number	Page No. <b>1 of 1</b>
	Payment Term <b>30 Days From Invoice</b>	Invoice Date	
	Customer Service Advisor <b>Simon Koh Eng Aun</b>	Invoice By <b>Simon Koh Eng Aun</b>	

CUSTOMER INFORMATION	INVOICE TO <b>77</b>
<b>Lee Dong Chan</b> 355 BUKIT TIMAH ROAD #08-04  Singapore 255734	<b>Axa Insurance Pte Ltd</b> No. 8 Shenton Way #24-01 Axa Tower Singapore 068811

REGISTRATION No. <b>SKT4002H</b>	CHASSIS No. <b>VF38E5GZTFL011178</b>	STOCK No. <b>208526</b>	REGISTRATION DATE <b>04/06/2015</b>	MODEL <b>508SW1.6 Allure</b>	MILEAGE <b>75071</b>
-------------------------------------	---	----------------------------	--	---------------------------------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM AGAINST AXA INSURANCE-SKUB468R DOA. 28/08/2019	0	0.00	0.00
	SUNDRIES	1	0.00	50.00
	LABOUR TO REMOVE, REPLACE, REPAIR AND REALIGN REAR BUMPER TAILGATE PANEL AND ALL AFFECTED AREAS	1	0.00	1,000.00
	LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREAS	1	0.00	1,000.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE (NETT)	2	0.00	600.00
	TO REMOVE AND REINSTALL REAR BUMPER SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	1	0.00	120.00
<b>Sub-Total :</b>				<b>2,770.00</b>

CODE	DESCRIPTION	UNITS	DISC %	NETT
0000742162	BUMPER BRACKET RH	1	10.00	72.00
00007810AH	RR BADGE LION	1	10.00	41.40
00008666CX	PEUGEOT EMBLEM	1	10.00	28.80
1611901380	BRACKET SET	1	10.00	117.00
1611916580	REAR BUMPER	1	10.00	860.40
9809004580	BADGE 508 SW	1	10.00	49.50
<b>Sub-Total :</b>				<b>1,169.10</b>

Attending CSO : Simon Koh  
 Should you require further explanation, please reach me at

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	3,939.10
Labour Charges	2,770.00	Less Insurance Excess	S\$	0.00
Parts Charges	1,169.10	GST @ 7%	S\$	275.74
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	4,214.84
		Less Deposit/Voucher	S\$	0.00

Computer generated invoice. No signature is required.	Amount Payable	S\$	4,214.84
---	----------------	-----	----------

All amounts are in Singapore Dollars.  
 Work was carried out subject to the Company's Terms and Conditions of Service.  
 No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
 For credit purchases, interest @1% per month will be debited on overdue amounts.

## Acknowledgement

Accident Involving SKT4002H and SKU8468R on 28/08/2019.

I, Lee Dong Chan the owner of Vehicle Registration Number SKT4002H, have been advised by Customer Service Adviser and understand the content of my motor claim as specify herein:

- Type of claim:  Claiming own-policy only.  
 Claiming own-policy and uninsured losses.  
 Direct settlement with 3<sup>rd</sup>-Party Insurer [Any reversion to own-policy claim shall be submitted to my insurer within 14 days from date of accident as required by my Policy].
- Vantage Automotive Limited being an appointed Approved Reporting Centre is bound by GIA not to induce, instigate, encourage or procure any owner or driver of any motor vehicle to engage the services of any solicitors to make any third party claims.
- The estimated repair costs shall be subjected to insurer surveyors' finalisation on completion of job and after considering additional parts and/or labours discovered in the course of repair.
- A compulsory policy excess NIL, stated in the Motor Policy taken up by you, is applicable for own-damage claim.
- Loss of Use and Cost of Rental shall be computed in accordance to the number of days as recommended by the surveyor and the Benchmark Rates published in State Courts Practice Directions for Non-injury Motor Accident (NIMA) Claims.
- I am fully aware that Vantage Automotive Limited is assisting me in my claim against the third-party insurer. I shall release Vantage Automotive Limited against any liability, loss claim or proceedings which may arise out of or in the course of or by reasons of execution of the services.
- In the event that my insurer or third party insurer is not prepared to settle the claim due to breach of policy or other reasons, I shall pay Vantage Automotive Limited the full repair bill.
- A towing charge of \$120.00, administration fee of \$300.00 and storage fee \$50.00 per day is chargeable to me if my vehicle is not repaired by Vantage Automotive Limited.
- The average time span to settle a claim is 6 months or longer for complex cases. Any correspondence or status enquiry of the mentioned claim shall be directed to the under-mentioned personnel:

Name: Ms Caroline Tan  
Tel.: 6319 0174  
email: pml-pbsp@simedarby.com.sg

10. Special Instructions:

COR: \$4214.84

LOR: \$224.70

Signed by:

Lee Dong Chan

Name: Lee Dong Chan  
NRIC No.: S7389285F  
Date: 28 AUG 2019

GIA  
SEARCH: \$2.00  
FEE

**LETTER OF AUTHORIZATION- MOTOR INSURANCE 3<sup>RD</sup> PARTY CLAIMS**

I, Lee Dong Chan the Owner of the vehicle number: SKT 4002 H.  
hereby do authorize Vantage Automotive Ltd to proceed with the repairs of my vehicle as  
per 3<sup>rd</sup> party insurer and the surveyor's recommendation which I file against the 3<sup>rd</sup> party  
insurer and shall pay the amount of car rental (if any including GST) to Vantage  
Automotive Ltd upon collection of my vehicle and duly complete and sign the discharge  
voucher.

I further aware that Vantage Automotive is assisting me in the claim against the third-  
party insurer. I shall release Vantage Automotive Limited against the liability.

Regardless of all circumstances or reasons causing the delay or unsuccessful claim(s), I  
agreed that Vantage Automotive will not be held responsible or liable in any event if the  
claim is either partially successful and or unsuccessful.

Dated the                      days of 28 AUG 2019 201

Lee Dong Chan

Owner name /signature

**Simon Koh**

Customer Service Advisor  
Accident & Bodyshop

Witness (name / signature)

S7389285F

NRIC No.

S8288606J

NRIC No.

**AutoFrance**A division of Vantage Automotive Limited  
BUSINESS REGN. NO. 52907220C

305 Alexandra Road

Singapore 159942

Tel (65) 6376 2288

Fax (65) 6477 7373

**Sales**

Tel (65) 6376 2288

Fax (65) 6477 7373

**Service/Parts**

Tel (65) 6477 7377/420

Fax (65) 6477 7398

**24-hr Roadside Assistance**

Tel (65) 6473 8588

[www.peugeot.com.sg](http://www.peugeot.com.sg)

## SATISFACTION CUM DISCHARGE VOUCHER

Date: 04 OCT 2019To: AXA Insurance Pte Ltd.

### MOTOR VEHICLE CLAIM

Vehicle Owner's Name: Lee Dong ChanVehicle Registration No.: SKT 4002 HMake / Model: Peugeot 508 SW 1.6 Allure

Motor Policy Number: \_\_\_\_\_

Date of Accident: 28/8/2019Owner's Excess: NIL

Repairs Cost: \_\_\_\_\_

I/We certify that the repairs to my/our vehicle number SKT 4002 H have been completed by AutoFrance, a division of Vantage Automotive Limited, of 305 Alexandra Road, Singapore 159942, to my/our entire satisfaction. Payment of the repair charges that are claimable under the Policy will be deemed and settled by me/us.

*Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.*

Owner/Insured Signature: Lee Dong ChanDate: 04 OCT 2019Job No.: BP115165

13401/g

## ◀ Service Request Details

Claim

S9M01YQC

Reference

None ✎

Loss Date

August 28, 2019

Report Date

Aug 30, 2019 9:09:00 AM

Request Date

August 30, 2019

Due Date

September 6, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Simon

T: 10.300.M

V: Out

E: ✓

### Actions

Next Step

Agree to perform service

Decline Work	Accept Work
--------------	-------------

### Vehicle Information

Incident Vehicle Registration #

SKT4002H

MODEL

508 ALLURE-1.6 (A)

### Service Address

---

...

### Primary Contact/Insured

---

PEH KENG HWEE (BAI JINGHUI)

BLK 76A REDHILL ROAD, #09-08, 151076, Singapore

alvin\_su@a-sourcecomp.com

### Claim Handler

---

GO Sashe

sashe.goms@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

## Catherine Chong (LKK Auto)

---

**From:** Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>  
**Sent:** Friday, 30 August, 2019 8:44 AM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** Melody Teoh Man Lin; Andy Ooi Lee Keong; Liu Chun Cheong; Katherine Chong  
**Subject:** [EXTERNAL] Third Party Claim: SKT4002H & SKU8468R / DOA: 28/8/2019 at Saiboo St / Martin Rd / Mohamed Sultan Rd junction  
**Attachments:** ESTIMATE-SKT4002H.pdf; GIA Report.PDF; TP Insurer.pdf  
**Importance:** High  
**Categories:** Mateen

Dear Officer In-Charge,

Our client's vehicle had involved in an accident with your insured vehicle on the above stated date and location. Kindly refer to the attached documents for your necessary arrangement.  
If there is any enquiries, please do not hesitate to contact me @ +65-6477 7413 / +65-9690 4556.

Thank you.

*Best Regards,*

*Simon Koh Eng Aun*

*Customer Service Advisor (Bodyshop)*

*Vantage Automotive Limited*

*305 Alexandra Road*

*#02-01 Vantage Automotive Limited*

*Singapore 159942*

*Regent Motors Limited (FORD)*

*AutoFrance ( PEUGEOT )*

**Mobile:** +65-9690 4556

**DID:** +65-6477 7413

**Email:** [simon.koh.engaun@simedarby.com.sg](mailto:simon.koh.engaun@simedarby.com.sg)

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 4/12/2019

### Survey Details:

Date of loss	28-Aug-19
Date of appointment	30-Aug-19
Date of survey	4-Sep-19
Location of survey	VANTAGE AUTOMOTIVE LTD

### Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SKT4002H
Make and Model	PEUGEOT 508 SW ALLURE 1.6
Date of registration	4-Jun-15
Parf Rebate	
Market Value	\$ 72,000.00
Parf Rebate	\$ 60,614.00
Nett Loss	\$ 11,386.00

### Repair details:

Initial Estimate	\$ 8,960.40
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 1,169.10
Check items (estimate)	\$ -
Labour	\$ 2,770.00
<b>Total</b>	<b>\$ 3,939.10</b>
Lump Sum(if applicable)	\$ -

Number of days for repair	<b>3</b>
---------------------------	----------



**Remarks:**

--

**Mandate:**

Liability(TP)		100%	
Proposed repair cost	\$	4,214.84	W/GST
Loss of use	\$	-	
Loss of rental	\$	224.70	3days x \$74.90
Loss of income	\$	-	
LTA search fees	\$	2.00	
Others	\$	-	
<b>Proposed Total</b>	<b>\$</b>	<b>4,441.54</b>	

 **<MANDATE IA> - S9M01YOC {ACCIDENT INVOLVING  
SKU 8468R & SKT 4002H ON 28/08/2019}**

Type

 Question

Message

LIABILITY: 100% BOLA 9c - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$4441.54 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CPL

[Reply](#)

# AUTOFRANCE

(A Division of Vantage Automotive Limited)  
Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road  
Vantage Automotive Centre  
Singapore 159942  
Service Booking: 6477 7377  
Parts: 6477 7420  
Vantage 24-Hour Assist: 6473 8588  
Fax: 6477 7300



PEUGEOT

## SERVICE TAX INVOICE

REPAIR ORDER NO. <b>bp 115165</b>	Date IN <b>01/10/2019</b>	Invoice Number <b>5399400 / WSH</b>	Page No. <b>1 of 1</b>
	Payment Terms <b>30 Days From Invoice</b>	Invoice Date <b>26/11/2019</b>	
	Customer Service Advisor <b>Simon Koh Eng Aun</b>	Invoice By <b>Katherine Chang Fui Poh</b>	

CUSTOMER INFORMATION	INVOICE TO <b>77</b>
<b>Lee Dong Chan</b> 355 BUKIT TIMAH ROAD #08-04 Singapore 259724	<b>Axa Insurance Pte Ltd</b> No. 8 Shenton Way #24-01 Axa Tower Singapore 068811

REGISTRATION No. <b>SKT4002H</b>	CHASSIS No. <b>VF38E5GZTFL011178</b>	STOCK No. <b>208526</b>	REGISTRATION DATE <b>04/06/2015</b>	MODEL <b>50BSW1.6 Allure</b>	MILEAGE <b>75071</b>
-------------------------------------	---	----------------------------	--	---------------------------------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM AGAINST AXA INSURANCE SKUB468R DOA.28/08/2019	0	0.00	0.00
	SUNDRIES	1	0.00	50.00
	LABOUR TO REMOVE, REPLACE, REPAIR AND REALIGN REAR BUMPER TAILGATE PANEL AND ALL AFFECTED AREAS	1	0.00	1,000.00
	LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREAS	1	0.00	1,000.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE (NETT)	2	0.00	600.00
	TO REMOVE AND REINSTALL REAR BUMPER SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	1	0.00	120.00
<b>Sub-Total :</b>				<b>2,770.00</b>

CODE	DESCRIPTION	UNITS	DISC %	NETT
0000742162	BUMPER BRACKET RH	1	10.00	72.00
00007810AH	RR BADGE LION	1	10.00	41.40
00008666CX	PEUGEOT EMBLEM	1	10.00	28.80
1611901380	BRACKET SET	1	10.00	117.00
1611916580	REAR BUMPER	1	10.00	860.40
9809004580	BADGE 50B SW	1	10.00	49.50
<b>Sub-Total :</b>				<b>1,169.10</b>

Attending CSO : Simon Koh  
Should you require further explanation, please reach me at

Service Packages	<b>0.00</b>	Total Labour/Parts/Service Package Charges	<b>S\$ 3,939.10</b>
Labour Charges	<b>2,770.00</b>	Less Insurance Excess	<b>S\$ 0.00</b>
Parts Charges	<b>1,169.10</b>	GST @ 7%	<b>S\$ 275.74</b>
Lubricant/Misc	<b>0.00</b>	Invoice Total Amounts	<b>S\$ 4,214.84</b>
		Less Deposit/Voucher	<b>S\$ 0.00</b>

Computer generated invoice. No signature is required.	<b>Amount Payable</b>	<b>S\$ 4,214.84</b>
---	-----------------------	---------------------

All amounts are in Singapore Dollars.  
Work was carried out subject to the Company's Terms and Conditions of Service.  
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
For credit purchases, interest @1% per month will be debited on overdue amounts.





# Re:<MANDATE IA> - S9M01YQC {ACCIDENT INVOLVING SKU 8468R & SKT 4002H ON 28/08/2019}

Type

📍 Question

Message

PLS PROCEED AS PROPOSED

Reply

AXA Insurance Pte. Ltd.  
No. 8 Shenton Way  
#24-01 Axa Tower  
Singapore 068811  
Attention: Motor Claims

Lkk

“Without Prejudice”

Your Ref :  
Our Ref :  
Date : 27 November 2019  
Subject : **ACCIDENT INVOLVING VEHICLES SKT4002H & SKU8468R ON 28.08.2019**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:

Cost of repair	: S\$	4,214.84
Car Rental	: S\$	224.70
GIA search fee	: S\$	2.00
Total	: S\$	4,441.54

A copy each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair Bill & GIA search slip
3. Copy of Car Rental Bill & Car Rental Agreement & Certificate of Insurance.
4. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

For any correspondence, please contact Ms Katherine Chong at 6477 7364 or email to [katherine.chong@simedarby.com.sg](mailto:katherine.chong@simedarby.com.sg).

Yours sincerely



Katherine Chong  
Senior Assistant (Body & Paint)

**AUTOFRANCE**

(Business Registration Number: 52907220C)

Peugeot Showroom & Service Centre:  
305 Alexandra Road, Singapore 159942  
6376 2288 (Sales) | 6477 7377 (Servicing) | 6473 8588 (24-Hour Assist)  
E: [autofrancesg@simedarby.com.sg](mailto:autofrancesg@simedarby.com.sg)  
www.peugeot.com.sg



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19015401/T1ga3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:SASHE

Date : 17-12-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 8468R	Veh. Inspected	SKT 4002H
Policy No.	VPA/P2253087	Coverage (\$)	0.00
Claim No.	S9M01YQC	Excess (\$)	0.00
Assign From		Assign Date	30/08/2019

## 2. Vehicle Particulars & Condition

Make & Model	PEUGEOT 508	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF38E5GZTFL011178	Colour	BLACK
Odometer	73849	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	6 mm
L/H Front Tyre	215/55 R17	MICHELIN	6 mm
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	28/08/2019	Inspection Date	04/09/2019
Survey held at	305 ALEXANDRA ROAD #02-01		
Repairer	AUTOFRANCE		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 4002H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	50.00
1	TAILGATE (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	2,597.40	-
1	REAR BUMPER (SN) (CONSISTENT)	DEFORMED	860.40	860.40
1	SET BRACKET (SN) (CONSISTENT)	NECESSARY	117.00	117.00
1	REFLECTOR RH (SN) (CONSISTENT)	NOT NECESSARY	54.90	-
1	BUMPER BRACKET (SN) (CONSISTENT)	NECESSARY	72.00	72.00
1	BUMPER ABSORBER (SN) (CONSISTENT)	NOT NECESSARY	136.80	-
4	SENSOR -OBSTACLE DETECTION FRT/REAR (SN) (CONSISTENT)	NOT NECESSARY	356.40	-
2	SENSOR -OBSTACLE DETECTION FRT/REAR (SN) (CONSISTENT)	NOT NECESSARY	324.00	-
1	BUMPER BRACKET (SN) (CONSISTENT)	NOT NECESSARY	451.80	-
1	BADGE (SN) (CONSISTENT)	NECESSARY	28.80	28.80
1	BADGE 508 SW (SN) (CONSISTENT)	NECESSARY	49.50	49.50
1	RR BADGE LION (SN) (CONSISTENT)	NECESSARY	41.40	41.40
			<b>5,240.40</b>	<b>1,219.10</b>
<b>LABOUR</b>				
	LABOUR TO REMOVE ,REPLACE ,REPAIR AND REALIGN REAR BUMPER TAILGATE PANEL AND ALL AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF TAILGATE.		1,500.00	1,000.00
	LABOUR TO PUTTY AND RESPRAY REAR BUMPER ,TAILGATE PANEL AND ALL AFFECTED AREAS.		1,500.00	1,000.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE .		600.00	600.00
	TO REMOVE AND REINSTALL REAR BUMPER SENSORS ,CONDUCT DISTANCE SETTINGS.		120.00	120.00
			-	-
			-	-
			-	-
			<b>3,720.00</b>	<b>2,720.00</b>
<b>GRAND TOTAL</b>			<b>8,960.40</b>	<b>3,939.10</b>

Report Ref No. CC4/ASM19015401/T1ga3q2



RECOMMENDED COST OF REPAIRS			3,939.10
-----------------------------	--	--	----------

Report Ref No. CC4/ASM19015401/T1ga3q2

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automotive Assessor

HO LEONG CHUAN  
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## Service Request Details

Claim	5FM01YQC
Reference	CCA/ASM19015401/71g3q2
Loss Date	28 August 2019
Report Date	30 Aug 2019 9:09:00 AM
Request Date	27 September 2019
Due Date	

Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

**Actions**

Next Step: Wait for Approve Invoice

[Add Invoice](#)

Vehicle Information	
Incident Vehicle Registration #	SKT4003H
Make	TPVD PEUGEOT
Model	508 ALLURE-1.6 (A)
Service Address	

...

Primary Contact/Insured	
PEH KENG HWEE (BAI JINGHUI)	
BLK 76A REDHILL ROAD, #09-08, 151076, Singapore	
ahin_su@sourcecomp.com	

Claim Handler	
CHAN KUN CHUAN	
68805444	
klanchuan.chan@axa.com.sg	

### Additional Instructions

Messages [Invoices](#) [History](#) [Documents](#) [Assessment](#) [Metrics](#) [Notes](#)

Document Type  Document Subtype

[Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKXInvoice1 (P).pdf	Invoice		LKX AUTO CONSULTANTS PTE LTD (TP)	20 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LKInspection (7).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LKKAAdjustment1a (7).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
PARF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
MANDATE IA DD 04122019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LJK AUTO CONSULTANTS PTE LTD (TP)	9 September 2019
 TP - IA.pdf	Form / Claim Documents	Assessment	LJK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PRG).msg	Letters and Correspondence	Workshop	KADRI MATEEN	30 August 2019
 GIA REPORT OF SKUB445R (INSO).PDF	Reports & Statement	GIA Report	KADRI MATEEN	30 August 2019
 GIA REPORT OF SKT4002H (TP).pdf	Reports & Statement	GIA Report	KADRI MATEEN	30 August 2019