

Sketch Plan




SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


   21/3/19

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
IRIC/RN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/9/2018 around 2130hrs. I was travelling along sungei gedong ramp. I was behind vehicle B queuing to entry. The front vehicle B slide a little backwards and touch my front car plate no. There is no damage to my car but only few dots to the car bumper caused by my vehicle plate no.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
[If driver is not the policyholder]
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:



AIG Asia Pacific Insurance Pte. Ltd.

Singapore
Tel :
Fax :
www.AIG.com.sg
CLAIMS DEPARTMENT
Co. Reg. No. 201009404M

Claim No: 5848659252SG Date of Survey: 25/04/2018
Repairer: APEX MOTORING

REFERENCE

Insured: LCRF PTE. LTD. Policy No: 999994796
Claimant: ASIA EXPRESS CAR RENTAL
PTE LTD
Date of Loss: 22/04/2018 Nature of Claim: TP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SLH9481B
Make & Model: TOYOTA COROLLA ALTIS, 1.6 Reg. Date: 24/11/2016
CLASSIC CVT (A)
Engine No: 1ZRY343142 Chassis No: MR053REH104561381

CONDITION OF TYRES

Front Tyre Size:	205/55 R 16	Rear Tyre Size:	205/55 R 16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable):	Yes	Engine Modification:	No		
Handbrake (Serviceable):	Yes	Steering (Serviceable):	Yes	Pre-accident Condition:	Average

TOTAL OFFER

Offer Authorized By:

Offer Initiated By:

Approved Gross Total:

- Offer Made Directly to Claimant, Info below NOT given to repairer -

KUMAR, UTHAYA on 10 Jul 2018 10:11

KUMAR, UTHAYA on 10 Jul 2018 10:10

S\$0.00

(No Betterment/Depreciation, Excess)

COST OF CLAIMS

	Repairer's	Our Offer	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 2.0 days

Authorised Repair : Yes

Inspection conducted by : Kumar, Uthaya (AIG Claims Dept)

Signature : -

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	REPAIR	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	REPLACE	0.00 F	*- F
3	1		*REVERSE SENSOR	REUSED	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

AIG Asia Pacific Insurance Pte. Ltd./SLH9481B/10/07/2018 10:11

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

AIG Asia Pacific Insurance Pte. Ltd./SLH9481B/10/07/2018 10:11
--

< END OF REPORT >



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no. 53058468m

Our Reference KAAS/TA/4985/9481/TP/04 18

Invoice No 4985

Date 02 May 2018

PHOTOCOPY

To: Asia Express Car Rental Pte Ltd
c/o 25 Kaki Bukit Road 4
#01-55, Synergy @ Kaki Bukit
Singapore 417800

INVOICE	
PARTICULARS	AMOUNT
Vehicle No SLH 9481B	
Make/Model Toyota Corolla Altis Classic 1.6 CVT	
<input checked="" type="checkbox"/> Inspection of Vehicle)
<input checked="" type="checkbox"/> Appraisal Report)
<input checked="" type="checkbox"/> 58 Colored Photographs)
<input checked="" type="checkbox"/> Transport charges)
<input checked="" type="checkbox"/> Re-inspection fee)
<input type="checkbox"/> Disbursements)
<input type="checkbox"/> Others (Specify))
	SGD 538.00
Total	SGD 538.00

Dollars: Five Hundred and Thirty-Eight Only

(Cheque should be crossed and make payable to "Kelvin Automotive Appraising Services")



Kelvin Automotive Appraising Services

25 Kaki Bukit Road 4 #01-55 S417800


S/no AX-4985

S/no	Description	Amount
1	Parts and labour for repair of Toyota Altis SLH9481B (Lump Sum)	\$4,300
Total:		\$4,300

Vehicle No

SLH9481B


Date

02 May
2018
Apex Motoring

VEHICLE HIRING AGREEMENT

6747 4649 : EMERGENCY BREAKDOWN SERVICE (24 HOURS)

Vehicle No: <i>STE1237</i>	Vehicle Out Date: <i>26/11</i>
Make & Model: <i>Toyota Altis</i>	Vehicle In Date: <i>26/04/18</i>
THIRD PARTY INSURANCE NON WAIVER EXCESS:	Total Charges: <i>\$225</i>
HIRER'S PARTICULARS	
Name (as in I/C): <i>Sim Chuan Boon</i>	Name (as in I/C):
NRIC / Passport No: <i>S1641224F</i>	NRIC / Passport No:
Date of Birth:	Date of Birth:
Address:	Address:
Employment Details:	Employment Details:
Driving License Passed Date:	Driving License Passed Date:
Tel: HP H O	Tel: HP H O



PETROL LEVEL (OUT)

LOW | 1/8 | 1/4 | 3/8 | 1/2 | 5/8 | 3/4 | 18 | FULL

MILEAGE OUT: *24113*

D : DENT | C : CRACK | S : SCRATCH | G : GAP | P : PAINT OFF

IMPORTANT

- Only persons above 21 & below 65 years of age and signing this agreement may drive the vehicle.
- Vehicle is strictly for use in Singapore only and may not be driven out of Singapore without the prior written consent of Asia Express Car Rental Pte Ltd.
- All vehicles are fitted with anti theft device which will response to the RF at the Singapore customs. Hirer will be fully liable for all cost and charges incurred in event that the immobiliser is being activated at the Singapore customs. There will be no refund of unused rental and the hirer shall bear the cost of the following charges i) S\$300.00 for towing from Singapore Customs ii) S\$200.00 for resetting of immobiliser.
- Use of vehicle for illegal purposes (e.g. In connection with theft, drug pedaling or trafficking, smuggling) is strictly prohibited.
- In case of accident, the hirer shall report to the rental office immediately. If there are bodily injuries, a police report must be made within 24 hours.
- Punctured tyres, empty petrol tank, flat battery due to negligence, loss of vehicle's key or locked key inside the vehicle, by itself does not constitute to a breakdown and that in the event, the Owner's 24 hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at S\$50 per trip (from 8AM to 10.59PM) and S\$80 per trip (from 11PM to 7.59AM). Punctured and damaged tyres that cannot be reused will be charged accordingly from S\$90-S\$250 per tyre.
- Emergency Breakdown and Towing Service is only available up to 400km from the Malaysia Custom, excluding Genting Highlands.
- All vehicles are supplied with petrol and should be returned with petrol level likewise. There will be no refund for excess petrol.
- The hirer shall be liable for late return charges at rate shown per hour per day. Latest returning time is 6pm.
- Windscreen and windows damages are not covered under insurance (Range from S\$300-S\$1500).
- No Smoking, Durians and Transportation of Pets are allowed. Hirer is responsible for a penalty of S\$300.


I have read and agree to the terms and conditions on both sides of this agreement. All information I have provided Asia Express Car Rental Pte Ltd in connection with this agreement is true.

[Signature]
18/11/18

VEHICLE HIRING AGREEMENT

6747 4649 : EMERGENCY BREAKDOWN SERVICE (24 HOURS)

Vehicle No: <u>S5F 3105 L</u>	Vehicle Out Date: <u>26/04/2018</u> <u>1613</u>
Make & Model: <u>TOYOTA ACES</u>	Vehicle In Date: <u>30/04/2018</u>
THIRD PARTY INSURANCE NON WAIVER EXCESS:	Total Charges: <u>\$300</u>
HIRER'S PARTICULARS	ADDITIONAL DRIVER'S PARTICULARS
Name (as in I/C):	Name (as in I/C):
NRIC / Passport No:	NRIC / Passport No:
Date of Birth:	Date of Birth:
Address:	Address:
Employment Details:	Employment Details:
Driving License Passed Date:	Driving License Passed Date:
Tel: HP H O	Tel: HP H O



PETROL LEVEL (OUT)

LOW | 1/8 | 1/4 | 3/8 | 5/8 | 3/4 | 7/8 | FULL


MILEAGE OUT: 298133

D : DENT | C : CRACK | S : SCRATCH | G : GAP | P : PAINT OFF

IMPORTANT

- Only persons above 21 & below 65 years of age and signing this agreement may drive the vehicle.
- Vehicle is strictly for use in Singapore only and may not be driven out of Singapore without the prior written consent of Asia Express Car Rental Pte Ltd.
- All vehicles are fitted with anti theft device which will response to the RF at the Singapore customs. Hirer will be fully liable for all cost and charges incurred in event that the immobiliser is being activated at the Singapore customs. There will be no refund of unused rental and the hirer shall bear the cost of the following charges i) S\$300.00 for towing from Singapore Customs ii) S\$200.00 for resetting of immobiliser.
- Use of vehicle for illegal purposes (e.g. In connection with theft, drug pedaling or trafficking, smuggling) is strictly prohibited.
- In case of accident, the hirer shall report to the rental office immediately. If there are bodily injuries, a police report must be made within 24 hours.
- Punctured tyres, empty petrol tank, flat battery due to negligence, loss of vehicle's key or locked key inside the vehicle, by itself does not constitute to a breakdown and that in the event, the Owner's 24 hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at S\$50 per trip (from 8AM to 10.59PM) and S\$80 per trip (from 11PM to 7.59AM). Punctured and damaged tyres that cannot be reused will be charged accordingly from S\$90-S\$250 per tyre.
- Emergency Breakdown and Towing Service is only available up to 400km from the Malaysia Custom, excluding Genting Highlands.
- All vehicles are supplied with petrol and should be returned with petrol level likewise. There will be no refund for excess petrol.
- The hirer shall be liable for late return charges at rate shown per hour per day. Latest returning time is 6pm.
- Windscreen and windows damages are not covered under insurance (Range from S\$300-S\$1500).
- No Smoking, Durians and Transportation of Pets are allowed. Hirer is responsible for a penalty of S\$300.

I have read and agree to the terms and conditions on both sides of this agreement. All information I have provided Asia Express Car Rental Pte Ltd in connection with this agreement is true.



6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Insured	-
Policy No.	-
Sum Insured	-
Excess	-
Our Reference	KAAS/TA/4985/9481/TP/04 18
Date	02 May 2018

To: Asia Express Car Rental Pte Ltd
c/o 25 Kaki Bukit Road 4
#01-55, Synergy @ Kaki Bukit
Singapore 417800

VEHICLE APPRAISAL REPORT

Name of Workshop	Apex Motoring
Place of inspection	25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit, Singapore 417800
Date of Assignment	24 April 2018
Date of Accident	22 April 2018
Date of Inspection	24 April 2018

PARTICULARS OF INSPECTED VEHICLE

Registration No	SLH 9481B	Engine No	Hidden From View
Make/Model	Toyota Corolla Altis Classic 1.6 CVT	Chassis Frame No	MR053REH104561381
Year of Manufacture/Reg	2016	Colour	Silver
Class/Type	Saloon	Odometer Reading	113,131 KM

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition	Good	Undercarriage (Front)	Serviceable
Paintwork	Good	Undercarriage (Rear)	Serviceable
Footbrakes	Serviceable	Market Value	-
Steering	Serviceable	Scrap Value (PARF/OMV)	-

CONDITION OF TYRES ON VEHICLE


	<u>Make/Size</u>	<u>Thread Balance</u>
Front Left	CAPTURAR 205 / 55 ZR16	7mm
Rear Left	DUNLOP 205 / 55 R16	7mm
Front Right	CAPTURAR 205 / 55 ZR16	7mm
Rear Right	DUNLOP 205 / 55 R16	7mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
LIST ITEMS:-					
1	1 pc	Rear bumper	Deformed	\$ 564.10	\$ 564.10
2	1 pc	Rear bumper reinforcement	Buckled	\$ 397.20	\$ 397.20
3	2 pcs	Rear bumper side retainer @S\$47.00	Necessary	\$ 94.00	\$ 94.00
4	2 pcs	Rear bumper side support @S\$24.50	Necessary	\$ 49.00	\$ 49.00
5	1 set	Rear bumper fasteners	Necessary	\$ 35.00	\$ 35.00
6	1 pc	Bootlid	Damaged	\$ 606.75	Repair
7	1 pc	Bootlid logo emblem	Necessary	\$ 65.10	\$ 65.10
8	1 pc	Bootlid "corolla" emblem	Necessary	\$ 60.20	\$ 60.20
9	1 pc	Bootlid "altis" emblem	Necessary	\$ 54.00	\$ 54.00
10	1 pc	Bootlid weatherstrip <i>Not Replaced</i>	Deformed	\$ 231.10	\$ 231.10
11	2 pcs	Taillamp assy @S\$495.35	Cracked	\$ 990.70	\$ 990.70
12	1 pc	Rear end panel (complete) <i>Repair</i>	Buckled	\$ 519.10	\$ 519.10
13	1 pc	Rear end panel top garnish	Deformed	\$ 239.20	\$ 239.20
14	1 pc	Spare tyre panel	Buckled	\$ 499.40	Repair
				\$ 4,404.85	\$ 3,298.70
Less 25%					\$ 824.68
				\$ 4,404.85	\$ 2,474.03
SPECIAL NETT ITEMS:-					
15	1 set	Reverse sensor	Not Working	\$ 300.00	\$ 250.00 <i>200</i>
16	1 tube	Rear end panel sealant <i>Not Replaced</i>	Necessary	\$ 60.00	\$ 40.00 <i>+</i>
				\$ 360.00	\$ 290.00 <i>200</i>
Sub - Total				\$ 4,764.85	\$ 2,764.03



6 tampines st 73, #01-03, singapore 528825
tel 6746 2118 fax 6746 1148
reg no: 53058468m

Our Reference
Vehicle Number

KAAS/TA/4985/9481/TP/04 18
SLH 9481B

APPRAISEMENT SCHEDULE


S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 4,764.85	\$ 2,764.03
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,040.00	\$ 960.00 600
2		To check wiring and rewire		\$ 60.00	\$ 50.00 30
3		To remove and reinstall bootlid components		\$ 80.00	\$ 60.00 30
4		To remove and reinstall rear boot upholstery		\$ 120.00	\$ 100.00 40
5		To remove and reinstall reverse sensor		\$ 140.00	\$ 100.00 50
6		To anti-rust	1400	\$ 140.00	\$ 120.00 50
7		To putty and spray-paint of affected areas		\$ 960.00	\$ 880.00 600
				\$ 2,540.00	\$ 2,270.00
				total: 3511.37 y/s: 2.8k 04 days	
		Sub - Total		\$ 7,304.85	\$ 5,034.03

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered

Squarely to the Rear

portion of the vehicle



The general area of damages is at the **Rear portion**
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Apex Motoring** is \$ 7,304.85
We have adjusted the cost to \$ 5,034.03 and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 4,300.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **5** working days.

58 photographs were taken at the time of static inspection

This report is strictly done in a **Without Prejudice Basis**

We are reverting the matter to you a decision

We enclose herewith our Invoice No. **4985** for our services rendered and
we thank you for engaging our services

Kelvin Automotive Appraising Services



KELVIN TEO
Licensed Automotive Appraiser
Nitec in Automotive Technology
Dip MS
MSAAA

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG19015448/Atd3s2

78 SHENTON WAY #08-16

CHARTIS BUILDING

SINGAPORE 079120

Date : 18-09-2019



ATTN: MARICEL OLEA

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SLG 5945L	Veh. Inspected	SLH 9481B
Policy No.	999994796	Coverage (\$)	0.00
Claim No.	5848659252SG003	Excess (\$)	0.00
Assign From	MARICEL OLEA	Assign Date	30/08/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104561381	Colour	SILVER
Odometer	216673	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	6 mm
L/H Rear Tyre	205/55 R16	KUMHO	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--

5. General Information

Accident Date	22/04/2018	Inspection Date	04/09/2019
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 9481B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	REPLACED	564.10	564.10
1	REAR BUMPER REINFORCEMENT	REPLACED	397.20	397.20
2	REAR BUMPER SIDE RETAINER @ \$47.00	REPLACED	94.00	94.00
2	REAR BUMPER SIDE SUPPORT @ \$24.50	REPLACED	49.00	49.00
1	SET REAR BUMPER FASTENERS	REPLACED	35.00	35.00
1	BOOTLID	REPAIRED SEE LABOUR	606.75	-
1	BOOTLID LOGO EMBLEM	REPLACED	65.10	65.10
1	BOOTLID "COROLLA" EMBLEM	REPLACED	60.20	60.20
1	BOOTLID "ALTIS" EMBLEM	REPLACED	54.00	54.00
1	BOOTLID WEATHERSTRIP	NOT CHANGED	231.10	-
2	TALLAMP ASSY @ \$495.35	REPLACED	990.70	990.70
1	REAR END PANEL	REPAIRED SEE LABOUR	519.10	-
1	REAR END PANEL TOP GARNISH	REPLACED	239.20	239.20
1	SPARE TYRE PANEL	REPAIRED SEE LABOUR	499.40	-
	LESS 25% DISCOUNT		-	-637.13
			4,404.85	1,911.37
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	REPLACED	300.00	200.00
1	TUBE REAR END PANEL SEALANT (SN)	NOT CHANGED	60.00	-
			360.00	200.00
LABOUR				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS, INCLUSIVE OF THE REPAIR OF BOOTLID, REAR END PANEL AND SPARE TYRE PANEL.		1,040.00	600.00
	TO CHECK WIRING AND REWIRE.		60.00	30.00
	TO REMOVE AND REINSTALL BOOTLID COMPONENTS.		80.00	30.00
	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY.		120.00	40.00
	TO REMOVE AND REINSTALL REVERSE SENSOR.		140.00	50.00

Report Ref No. CS/AIG19015448/Atd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO ANTI-RUST.		140.00	50.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		960.00	600.00
			2,540.00	1,400.00
GRAND TOTAL			7,304.85	3,511.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS/AIG19015448/Atd3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.