

22/03/2002

ASS. REC. BY:

REF: CS/SPF19015452/FVF302

Special Instruction:

Supervisor: Ram

ASSIGNMENT (Office)

From (Person): Hafizul Furhan Rahmat of SPF Date/Time: 2.9.19 10.289.4

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SG 50982 Insured: GBC 967X

at Workshop m/s Comfortdelgro Engineering Tel: 969 0177
of 205 Braddehill Road Bld D

Policy No: Claim No: AEMD/105/009/2019/088

Sum Insured: Excess:

Make of Veh: D.O.A. 23/8/19
(Client's Record)

CA / REV / REP. / REV 24 HRS "mp" H.O.D. Endorsement:

Date/Time: 2.9.19 11.02a.m Person Contacted: chan Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 967X : X
	SG 50982 : X
	upper range - \$1300 - \$1500
6/9/19	final fig \$ 1340

Do Not Finalise

(08/11/11)

ASS. REC. BY:

Ram

REF

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SG5098Z

at Workshop m/s: comfortdelgro Engineering

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days Res.: Yes or No

Lump Sum: _____

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SG5098Z Yr Regn: JUN / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer or _____

Make: VOVO B9TL-9.40 C.C. 9364

Colour: green A/C: Insured / Std / NI / NA

Sp. Reading 223929 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV354P9286A177931

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70 R22.5

R: 275/70 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or continental

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm LAST Rear

L/Bal. 7 mm

L/Bal. 7 mm RIB: 7

D.O.A. 23/8/2009

D.O.I. 2/9/19

Survey hold at comfortdelgro

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 09 SEP 2019

Date/Time, File Pass to?

Preli. Report

Days Of Repair: 3

1)

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 6/9 - typist

Add Fee: : Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

270

Transportation:

3 + RS, ...

Photos

Others

TOTAL

270

Report Format :

TP

Lump Sum / I.B.I: (\$

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Monday, 2 September 2019 10:28 AM
To: assignments; Admin-D (LKKAuto)
Cc: Frankie THAY (SPF); Rosalyn TAN (SPF)
Subject: Pre-repair survey on SG 5098Z (vs GBC 967X)

Message Classification: Unclassified

Our ref: AEMD/105/009/2019/088

Hi,

Kindly conduct pre-repair survey on SG5098Z at

COMFORTDELGRO ENGINEERING PTE LTD
205 Braddell Road Singapore 579701
BLK D - BUS ACCIDENT REPAIR

Contact: Chan Foo Heng
HP: 9690 1177

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4860 | FAX: (65) 6478 4850



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Sam Tan Kiam Meng <samtan@cdge.com.sg>
Sent: Monday, 2 September 2019 10:10 AM
To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Denis Teo Chin Chye <denisteo@sparkcarcare.com>; Chan Foo Heng <chanfh@cdge.com.sg>; Patrick Chung Chan Kim <patrickchung@cdge.com.sg>
Subject: Re: SPF Accident Claims Section(GAS Bus - SG 5098Z Third Part Claim against GBC 967X)

Hi Hafizul,

Please refer to attach SAS report and check liability for the mentioned accident case.

Kindly arrange surveyor to inspect the bus on Tuesday morning. (03/09/2019)

GAS Bus - SG 5098Z Third Part Claim against GBC 967X

P-I-C: Chan Foo Heng

HP: 9690 1177

Address:

COMFORTDELGRO ENGINEERING PTE LTD

205 Braddell Road Singapore 579701

BLK D - BUS ACCIDENT REPAIR

Warmest Regards

Sam Tan | ComfortDelGro Engineering Pte Ltd | BAR 📞

☎(65)6383 7369 | 📠(65)6286 0309 | ✉samtan@cdge.com.sg

Address: 205 Braddell Road, Singapore 579701

🌱 Please consider the environment before printing this e-mail

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>

Sent: Friday, 30 August 2019 9:59 AM

To: Sam Tan Kiam Meng <samtan@cdge.com.sg>

Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>

Subject: SPF Accident Claims Section

Dear Sam,

Kindly submit to us your accident claims.

We will arrange for our surveyor to liaise with you.

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4860 | FAX: (65) 6478 4850



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein

shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

- ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/08/2019 11:59
Date Of Accident	23/08/2019 09:15
Exact Location Of Accident	P'GGOL FIELD X P'GGOL EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5098Z
Insured/Policyholder	
Name Of Registered Owner	GO AHEAD SINGAPORE PTE LTD
Co Reg No	201541900C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63847169

Vehicle Particulars

Manufacturer	VOLVO
Model	B9TL-9.4 D AUTO TURBO ABS (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-18091603MFBP
Cover Note Number	

Driver

Name of Driver	LOW HEE AUN
NRIC No	S1282092E
Date Of Birth	06/05/1957
Occupation	OUTDOOR
Date Of Driving Pass	19/12/1980
Driving Experience	38 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81119613
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	235 S'GOON AVE 3 #05-08
Postcode	550235
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	9

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY BUS WAS ON THE EXTREME LEFT LANE OF A 3-LANE RD ALONG PUNGGOL FIELD WHERE IT'S MEAN FOR GOING STRAIGHT & TURNING RIGHT WHILE THE REMAINING 2 LANES IS JUST PURELY MEAN FOR TURNING RIGHT. WHILST TURNING RIGHT TOWARDS B/S 65529 - AFT PUNGGOL FIELD ALONG PUNGGOL EAST WHEN A BLUE NISSAN POLICE VAN THAT WAS ON THE MIDDLE LANE HEAD STRAIGHT INSTEAD OF TURNING RIGHT. AS A RESULT, THE FRONT LEFT MIRROR & CORNER BUMPER OF THE NISSAN VAN GRAZED AGAINST THE REAR RIGHT PANEL OF MY BUS

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	DIFFERENT FORMAT
Was there any audio recorded?	NO

Details of Witness 1


Name	DHARWAN
Phone Number	92789383
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC967X
Vehicle Make/Model/Colour	BLUE NISSAN URVAN MICROBUS 3.0 4DR 5MT ABS AIRBAG

Details Of Properties	FRONT LEFT MIRROR & CORNER BUMPER
Vehicle Category	GOVERNMENT
Name of Driver	TAN LYE SENG
NRIC/Passport Number	
Contact Number	88181894
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan



POLICE REPORT 1



**SINGAPORE
POLICE FORCE**



T/20190823/2121

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No. T/20190823/2121

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/08/2019 15:19		Vide Report No.: F/20190323/0063		Station Diary No.: 108	
Informant's Particulars					
Name of Informant: LOW HEE AUN			Address: APT BLK 235 SERANGOON AVENUE 3 #05-08 SINGAPORE 550235		
ID Type / ID No.: NRIC NO / S1282092E			Contact No.: Home/Office:		Mobile: 81119613
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 06/05/1957	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Bus driver			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/08/2019 09:15	Type of Location: JUNCTION
Location: Along Road 1 PUNGGOL EAST JUNCTION PUNGGOL EAST TOWARDS PUNGGOL FIELD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC967X	Van				Slightly Damaged	5
SG5098Z	Bus/Coach/Mi nibus				Slightly Damaged	30

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT 2



**SINGAPORE
POLICE FORCE**



T/20190823/2121

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20190823/2121

CONTINUATION OF REPORT

Driver			
Name	TAN LYE SENG	ID No.	S8019619I
Related Vehicle	GBC967X (Van)	Contact No.	88181894
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LOW HEE AUN	ID No.	S1282092E
Related Vehicle	SG5098Z (Bus/Coach/Minibus)	Contact No.	81119613
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I am currently working as a Bus Captain for GoAhead Bus. On 23/08/2019, I was tasked to drive Bus Service No: 62.

On 23/08/2019 at about 0918hrs, I was driving along Punggol East Road. As I approached the junction of Punggol East and Punggol Field, I was on the extreme left lane of a 3 right turning lanes as I wanted to make a right turn.

As soon as I was going to make a right turn, one police van, GBC967X was on the middle lane drove straight instead. Due to my bus turning right and the van moving forward, it hit onto the side of my bus.

At that point of time, there was no one injured and it was attended by police.

Due to the accident, the side of my bus was damage and dented. As for the police van, there was some minor damage to its left headlight.



**SINGAPORE
POLICE FORCE**



T/20190823/2121

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3


Report No. T/20190823/2121

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan


IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 3 PHUA JIA JUN, MARK 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 23/08/2019 15:19
Officer In Charge Of Case: TP / GIT / SI ONG CHEE HIEN Contact No.: 65476437	Classification Of Case:

Authentication Stamp
NP168


POLICE REPORT 4

Accident Photo




Accident Photo



Accident Photo



Accident Photo





ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : Third Party - GAS

Vehicle No. : SG 5098Z

Make & Model : VOLVO B9TL

Year of Manufacture : 2016

Chassis No. : YV3S4P928GA177931

Ins Company : NA

Engine No. : 195177

Excess : NA

Policy No. : NA

Date of Accident : 23/8/2019

Time of Accident : 09:15

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : Chan Foo Heng

Signature : _____

Parts (a) Cost / List Price Items	\$	-
Less 10%	\$	-
Total of Cost / List	\$	-
(b) Nett Price Items	\$	-
Less		
Total of Nett Item		
(c) Special Nett Items	\$	-
Total Parts Cost (Appendix A)	\$	-
Labour (Appendix B)	\$	1,650.00 \$1340
Total Repair Cost	\$	1,650.00 \$1340

Contact No
Operations
 63837369 – Chan Foo Heng / Sam Tan
chanfh@cdge.com.sg
samtan@cdge.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : PARASURAM

Company : LKK

Survey conducted on : 2/9/19 at 1500hrs

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 3 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: 2/9/19

Spark Car Care

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No. : SG 5098Z Case Owner : Chan Foo Heng
 Make & Model : VOLVO B9TL Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	Repair o/s no. 5 rear wheelarch panel	\$360.00	\$280
2	Repair o/s no. 6 rear wheelarch panel	\$360.00	\$280
3	Replace exterior advertisement sticker	\$480.00	\$400
4	Respray all accident body panel	\$450.00	\$380
<p><i>Handwritten notes:</i></p> <p>RAM (LKK) 88622778 Para@ram@lkk.com 2/9/19 3 days Part by Part</p>			
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 6 September 2019 5:40 PM
To: chanfh@cdge.com.sg; SUR; samtan@cdge.com.sg
Subject: SG 5098Z-DOA: 23/8/2019
Attachments: MARKING.pdf

Dear Foo Heng/Sam,

WITHOUT PREJUDICE

For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19015452/Fvf3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 23-09-2019	
ATTN : HAFIZUL FARHAN RAHMAT		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 967X	Veh. Inspected	SG 5098Z
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/088	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	02/09/2019
2. Vehicle Particulars & Condition			
Make & Model	VOLVO B9TL 9.4L	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	YV3S4P928GA177931	Colour	GREEN
Odometer	223929	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
R/H Rear Tyre	275/70 R22.5	CONTINENTAL	7 mm
L/H Rear Tyre	275/70 R22.5	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/08/2019	Inspection Date	02/09/2019
Survey held at	205 BRADDELL ROAD BLK D		
Repairer	COMFORTDELGRO ENGINEERING PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5098Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REPAIR O/S NO.5 REAR WHEELARCH PANEL.		360.00	280.00
	REPAIR O/S NO.6 REAR WHEELARCH PANEL.		360.00	280.00
	REPLACE ECTERIOR ADVERTISEMENT STICKER.		480.00	400.00
	RESPRAY ALL ACCIDENT BODY PANEL.		450.00	380.00
			1,650.00	1,340.00
	GRAND TOTAL		1,650.00	1,340.00
RECOMMENDED COST OF REPAIRS				1,340.00

Report Ref No. CS/SPF19015452/Fvf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,300-\$1,500

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.