

7282801

ASS. REC. BY:

REF:

CS/1CC190154SH/RISf302

Special Instruction:

Assigner: Rasy

ASSIGNMENT (Office)

From (Person): Crystabelle Tan

of

FCIS

Date/Time: 29/8/2019.

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 5615 X

Insured: 86V 7625C

at Workshop m/s Hitachi Capital

Tel:

of 8 Fourth Lok Yang Rd

Policy No:

Claim No: DMPC1900230H/02/CT

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/8/2019.

(Client's Record)

CA / REV / REP. / REV 24 HRS

4/9/2019 2pm.

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN OUT

Date/Time

Action/Instruction Informate ()

SHA 5615 X - X

86V 7625C - X.

ASS. REC. BY:

REF:

ICS

910B

WE XP 124: 2023/FEB

ASSIGNMENT

From:

Date:

4/9/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 5615X.

at Workshop m/s Hitachi Capital Vonn.

of 8 Fourth Lokyang Rd

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

4/9/2019 3pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLA 5615X

Yr Regn: 2008 / FEB

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA FIT 1.3 GA

C.C 1339

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

134206

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

6E61021285

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

B3 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

26/08/19

D.O.I.

04/09/19

Survey held at

HITACHI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

03/10/19

Confirmed AS \$ 1,200/- @ 3 days with Rasul.
(\$ 1,622.00 Red - 58%)

RECEIVED 03 OCT 2019

Date/Time, File Pass to?

03/10/19

1)

Type

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S+RS, SI

Photos

Others

TOTAL

250

11

261

Report Format:

Lump Sum / L.B.R. (\$ 1,200/- 4/5)

Nivitha (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 30 August 2019 5:41 PM
To: assignments
Subject: Fw: SLA5615X / SGV7625C DOA: 26/8/2019 TP SURVEY & LIABILITY - Our Ref : DMPC1900230H/02/CT
Attachments: SLA5615X.PDF

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Sent: Friday, 30 August 2019 5:34 PM
To: SUR <sur@lkkauto.com>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>; HengCheong, Poon <poonhengcheong@hcspl.com.sg>
Subject: FW: SLA5615X / SGV7625C DOA: 26/8/2019 TP SURVEY & LIABILITY - Our Ref : DMPC1900230H/02/CT

Dear LKK,

Kindly assist to arrange survey on 4 September 2019, next Wednesday, 2pm.

Please revert for confirmation.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Thursday, August 29, 2019 5:33 PM
To: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>

HengCheong, Poon <poonhengcheong@hcspl.com.sg>

Subject: RE: SLA5615X / SGV7625C DOA: 26/8/2019 TP SURVEY & LIABILITY - Our Ref : DMPC1900230H/02/CT

WITHOUT PREJUDICE

Dear Vonn

Our Insured liability is down.

Aside to LKK

Please arrange PRI.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Vonn, LM Siow [<mailto:vonnlm.siow@hcspl.com.sg>]

Sent: Thursday, 29 August, 2019 4:44 PM

To: ECICS Claims

Cc: Jamilah, Binte MohdKassim; JiongHow, Ng; HengCheong, Poon

Subject: SLA5615X / SGV7625C DOA: 26/8/2019 TP SURVEY & LIABILITY

Dear sirs,

We refer to the subject above and the attachment is for your reference.

Vehicle is NOT IN workshop, please advise who should we liaise for the survey arrangement.

Kindly advise on the liability.

Thanks & Regards

Vonn Siow

Motor Claims Advisor

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

DID: 6833 6274 Mobile: 96435107

e: vonnlm.siow@hcspl.com.sg

w: www.hitachi-capital.com.sg

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

RE: SLA5615X DOA: 26/8/2019 FINALIZATION

Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>

Thu 3/10/2019 10:54 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Hi Rasul,

We accept the COR at LS, \$1200 before GST, 3 days.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, October 3, 2019 10:25 AM
To: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: RE: SLA5615X DOA: 26/8/2019 FINALIZATION

Hi Vonn,

Finalised amount round up is \$ 1200 / 3 days lump sum


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Vonn, LM Siow [<mailto:vonnlm.siow@hcspl.com.sg>]
Sent: Wednesday, 2 October, 2019 5:16 PM
To: Rasul (LKKAuto); CS A Team; SUR
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng
Subject: SLA5615X DOA: 26/8/2019 FINALIZATION

Dear Rasul,

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	918B
Vehicle Details	
Vehicle No.:	SLA5615X
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	L13A4024186
Chassis No.:	GE61021255
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$11,975.00
Original Registration Date:	02 Feb 2008
First Registration Date:	02 Feb 2008
Transfer Count:	2
Actual ARF Paid:	\$13,173.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Feb 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,061.00
COE Rebate Amount:	\$14,347.00
Total Rebate Amount:	\$14,347.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Sep 2019

OK

27,000
14,347
12,653

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2019 14:17
Date Of Accident	26/08/2019 08:45
Exact Location Of Accident	BLK 359 CLEMENTI AVE 2 CARPARK C5 LOT 392
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA5615X
Insured/Policyholder	
Name Of Registered Owner	WATANABE DAISUKE
NRIC No	S7168918B
Email Address	SGJPWJ@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96251038
Alternative Phone No	OTHERS-88915435

Vehicle Particulars

Manufacturer	HONDA
Model	FIT-1.3 G (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA012787
Cover Note Number	

Driver

Name of Driver	WATANABE DAISUKE
NRIC No	S7168918B
Date Of Birth	02/07/1971
Occupation	INDOOR
Date Of Driving Pass	22/07/2008
Driving Experience	11 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96251038
Fax Number	
Contact Number	OTHERS-88915435
Email Address	SGJPWJ@GMAIL.COM

Address	BLK 356 CLEMENTI AVE 2 #05-279
Postcode	120356
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	SJC2389G
	-
	-
Insurance Company of Driver's Own Vehicle	LIBERTY INSURANCE PTE LTD
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	IN CARPARK
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV7625C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR KAL
NRIC/Passport Number	
Contact Number	98257989
Address	
Postcode	
Insurance Company Name	ECICS LIMITED
Nature Of Damage	
No. Of Passenger (Including Driver)	

* Any false reporting may be referred to the Police for investigation.

4) The report will be reviewed by the members of the Governance Management Unit – established by the General Assembly. A signature of a signatory (that is, an employee) and the copies of the report will form a file to be made available upon application by interested parties.

3. Consent under the Personal Data Protection Act (PDPA)

© 2001 Blackwell Science Ltd *Journal of Internal Medicine* 250: 101–107



Sketch Plan Pg. 2

SKETCH PLAN Blk 359 Clementi Ave 2 Carpark C5

392 S.A. 301/1X	393	394	Shelter	handicapped lot
-----------------------	-----	-----	---------	--------------------

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was a taxi driver working in Singapore when I was driving to a client's office on 20th Aug 2019, the person who I was driving to told me that he has an elderly person on my car, Honda Fit S.A. 9013X. I took 2 photos of the damage when I arrived in carpark C5 in 359 Clementi Ave 2 at 11:45 AM.

DECLARATION

I hereby declare that the information provided is true and correct.

[Signature]



Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 29/08/2019

ECICS
ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 26/08/2019 @ 08:45
VRN : SLA5615X
MODEL : HONDA FIT 1.3G
TP VRN : SGV7625C

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER <i>de -</i>	1	\$ 532.00	\$ 532.00	
2 FRONT BUMPER CLIP <i>re -</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER SIDE RETAINER RH <i>re -</i>	1	\$ 26.00	\$ 26.00	
4 HEADLAMP RH <i>scd -</i>	1	\$ 627.00	\$ 627.00	
			\$ 1,240.00	
Discount -20%			\$ 248.00	
			\$ 992.00	
5 FRONT FENDER RH	Repair			
6 FRONT FENDER LH	Repair			
	PARTS TOTAL		\$ 992.00	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	\$ 750.00	250
Putty, Blend And Spray Paint on Front Bumper, Front Fender RH & LH.	\$ 1,000.00	250
Check Wiring, Re-align Headlamps & Taillamps, Ensure Proper Functioning	\$ 80.00	30

LABOURS TOTAL \$ 1,830.00

Grand Total : \$ 2,822.00
Add 7% GST : \$ 197.54
Nett Total : \$ 3,019.54

No. of repair days: 4

CUSTOMER SIGNATURE

Signature
9/9/19
Hp 90010068
3 days
4/3
04/09/19 @ 1600
Repy after repair



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

P= 992-W

L= 530-W

1,522-W

-20% LS

T= 1,217-60

VEHICLE ESTIMATE dated 29/08/2019

ECICS

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 26/08/2019 @ 08:45

VRN : SLA5615X

MODEL : HONDA FIT 1.3G

TP VRN : SGV7625C

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
PARTS REPLACEMENT				
1. Body Repair				
1 FRONT BUMPER <i>de</i>	1	\$ 532.00	\$ 532.00	
2 FRONT BUMPER CLIP <i>me</i>	10	\$ 5.50	\$ 55.00	
3 FRONT BUMPER SIDE RETAINER RH <i>me</i>	1	\$ 26.00	\$ 26.00	
4 HEADLAMP RH <i>me</i>	1	\$ 627.00	\$ 627.00	
			\$ 1,240.00	
			\$ 248.00	
			\$ 992.00	✓
5 FRONT FENDER RH	Repair			
6 FRONT FENDER LH	Repair			
	PARTS TOTAL		\$ 992.00	

Discount -20%

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	\$ 750.00	250
Putty, Blend And Spray Paint on Front Bumper, Front Fender RH & LH.	\$ 1,000.00	250
Check Wiring, Re-align Headlamps & Taillamps, Ensure Proper Functioning	\$ 80.00	30
		530
LABOURS TOTAL	\$ 1,830.00	

Grand Total : \$ 2,822.00
Add 7% GST : \$ 197.54
Nett Total : \$ 3,019.54

No. of repair days: 4

Paul
Hp 90010068

3 days

4/3

04/09/19 @ 1600

Ready after repair



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19015454/R1SF3N2

Date: 09/10/2019

REFERENCE

Handling Insurer: ECICS Limited Policy No:
 Claimant Vehicle No: SLA5615X Insured Vehicle No: SGV7625C
 Date of Loss: 26/08/2019 Nature of Claim: TP Claim No: DMPC1900230H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA5615X Engine No: L13A4024186
 Make & Model: HONDA FIT, 1.3 G (A) Chassis No: GE61021255
 Reg. Date: 02/02/2008 (Man. Year: 2007) Odometer: 134206 km
 Colour: Red
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R15 Rear Tyre Size: 195/50R15
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	992.00	992.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	530.00	1,300.00	71.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,822.00	1,522.00	1,300.00	46.07
Approved Total (Overridden) (\$\$)		1,200.00		
(\$\$)	2,822.00	1,200.00	1,622.00	57.48
+ GST 7.00/7.00% (\$\$)	197.54	84.00	113.54	57.48
Nett Amount (\$\$)	3,019.54	1,284.00	1,735.54	57.48

INSPECTION

Date of Assignment: 29/08/2019
 Date Inspected: 04/09/2019 Inspected At: Hitachi Capital Asia Pacific Pte. Ltd (HQ)
 No 8 Fourth Lok Yang Road
 Singapore 629705
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2019)
Parts: 144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA5615X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	532.00 FL	*532.00 FL
2	10		*FRONT BUMPER CLIP	Necessary	55.00 FL	*55.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	26.00 FL	*26.00 FL
4	1		*HEADLAMP RH	Scratched	627.00 FL	*627.00 FL
5	1		*FRONT FENDER RH (NPA)	Repair	0.00 FS	*- FS
6	1		*FRONT FENDER LH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,240.00	1,240.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	248.00	248.00
Total Parts (\$\$)	992.00	992.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF FRONT AFFECTED AREA	New	750.00	250.00
2	PUTTY,BLEND AND SPRAY PAINT ON FRONT BUMPER,FRONT FENDER RH & LH	New	1,000.00	250.00
3	CHECK WIRING,RE-ALIGN HEADLAMPS & TAILLAMPS,ENSURE PROPER FUNCTIONING	New	80.00	30.00
Gross Labour Cost (S\$)			1,830.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >