

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1991947/AMK

Date: 02 Sep 2019

Policy No: 5050685487-08

Veh Reg No: SJG783T

Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO

WS Ref: TP/AIG/AMK

Chassis No: MR053ZEE106109604

Claim Type: Third Party

Engine No: 3ZZ4768924

Accident Date: 30/08/2019

Reg. Date: 20/06/2008

TP Veh Reg No: SKF6437Y

Estimate Repair Cost to Vehicle No :SJG783T

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	534.60	1 PC	534.60	✓
2 REAR BUMPER SPONGE	155.70	1 PC	155.70	✓
3 REAR BUMPER RH SIDE REFLECTOR	42.70	1 PC	42.70	✓
4 REAR BUMPER SIDE RETAINER	58.60	2 PC	117.20	✓
5 REAR BUMPER CORNAL RETAINER	37.80	2 PC	75.60	✓
6 REAR BUMPER CLIP	3.89	5 PC	19.45	✓
7 REAR BOOT	911.60	1 PC	911.60	✓
8 REAR BOOT INNER LOCK	126.80	1 PC	126.80	✓
9 REAR BOOT INNER RUBBER	194.70	1 PC	194.70	50/100
10 REAR BOOT INSULATOR	291.60	1 PC	291.60	✓
11 REAR BOOT CLIP	3.21	9 PC	28.89	✓
12 REAR BOOT REFLECTOR	195.70	2 PC	391.40	✓
13 REAR BOOT HINGE	72.40	2 PC	144.80	?
14 REAR BOOT LOGO	55.80	1 PC	55.80	✓
15 REAR BOOT EMBLEM '1.6'	32.13	1 PC	32.13	✓
16 REAR BOOT EMBLEM 'COROLLA'	51.17	1 PC	51.17	✓
17 REAR BOOT EMBLEM 'ALTIS'	50.22	1 PC	50.22	✓
18 REAR BOOT NUMBER PLATE GARNISH	213.21	1 PC	213.21	✓
19 REAR END PANEL	580.60	1 PC	580.60	✓
20 REAR END PANEL INNER TOP GARNISH	227.20	1 PC	227.20	✓
21 REAR END PANEL INNER TOP GARNISH CLIP	3.21	2 PC	6.42	✓
22 TAILLAMP	424.10	2 PC	848.20	✓
23 TAILLAMP INNER GASKET	29.80	2 PC	59.60	✓
24 TAILLAMP LOWER RETAINER	32.10	2 PC	64.20	✓
25 RH TAILLAMP PANEL	103.40	1 PC	103.40	✓
26 REAR RH FENDER	927.45	1 PC	927.45	✓
27 REAR RH FENDER INNER TRIM	388.90	1 PC	388.90	✓
28 REAR RH FENDER AIR SCROP GRILLE	155.40	1 PC	155.40	✓
29 REAR WINDSCREEN GLASS MOULDING	109.78	1 PC	109.78	✓
30 REAR SPARE TYRE PANEL TOP BOARD	369.20	1 PC	369.20	✓
			7,277.92	
Less 25%			1,819.48	5,458.44
Special Net				
31 REVERSE SENSOR	200.00	1 SET	200.00	✓
32 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
33 REAR NUMBER PLATE	35.00	1 PC	35.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 30/08/2019
TP Veh Reg No: SKF6437Y

Estimate No: ES1991947/AMK
Date: 02 Sep 2019
Policy No: 5050685487-08
Veh Reg No: SJG783T
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053ZEE106109604
Engine No: 3ZZ4768924
Reg. Date: 20/06/2008

Estimate Repair Cost to Vehicle No :SJG783T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
34 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>Mu</i> 40.00 ✓	315.00
			315.00	315.00
Labour				
35 TOWING	50.00	1 LA	50.00 ✓	
36 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00 ✓	
37 REMOVE & REFIX REAR BUMPER,REAR BOOTLID & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR END PANEL,RH TAILLAMP PANEL,REAR RH FENDER;KNOCKING & REPAIR REAR LH FENDER,REAR SPARE TYRE PANEL,CHASSIS FRAMES & REALIGN REAR RH DOOR THE SAME	1,500.00	1 LA	1,500.00 <i>1300</i>	
38 PUTTY & RESPRAY REAR BUMPER,REAR BOOT,BOTH FENDERS,RH TAILLAMP PANEL,REAR END PANEL,REAR SPARE TYRE PANEL,REAR RH DOOR,CHASSIS FRAMES & ALL AFFECTED AREAS	1,400.00	1 LA	1,400.00 <i>1200</i>	
39 REMOVE & REFIX REAR SEAT,CARPETS TO FACILITATE REPAIR	100.00	1 LA	100.00 ✓	
40 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00 <i>?</i>	
41 RUSTPROOFING	120.00	1 LA	120.00 <i>900</i>	
			3,520.00	3,520.00
Total				S\$ 9,293.44
Add GST @ 7%				650.54
Total Amount Payable				S\$ 9,943.98

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

DORLYN LI

AUTHORISED SIGNATURE



24 Hours Towing Services

Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 36616

CASH SALE / JOB ORDER

Date: 30/8/19

Cheng Hee

Messrs: _____
车牌 Vehicle No. S5G783
车型 Model No. 7-AH15
时间 (日/夜) 联络号码 92272551
Time (day/night): _____ Contact No: _____
由 Location: 37 Upper Cross St
到 To: Antipoint 01-04
银额 其他 Others: _____
Cash \$ 50/- Tow Truck
经手人 Driver Name: dy
Authorised By: _____

☐ Jump Start/Changing of battery
☐ Tyre Replacement
☒ Accident/Breakdown
☐ Multi/Basement
☐ With Load/Cargo Box
☐ King Dolly
☐ Transport Charge
☐ Low Body Kit
☐ Door Opening Service
☐ Crane Up/Winch Out
☐ Collect Doc/Key
☐ Repo
☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

E. & O. E.