

ke

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1991947/AMK

Date: 02 Sep 2019

Policy No: 5050685487-08

Veh Reg No: SJG783T

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053ZEE106109604

Engine No: 3ZZ4768924

Reg. Date: 20/06/2008

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 30/08/2019

TP Veh Reg No: SKF6437Y

Not Authorised

11 Days @ 88506

Recovery After Pain

11 days

Estimate Repair Cost to Vehicle No :SJG783T

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	534.60	1 PC	<i>Bt</i> 534.60	—
2 REAR BUMPER SPONGE	155.70	1 PC	<i>cm</i> 155.70	—
3 REAR BUMPER RH SIDE REFLECTOR	42.70	1 PC	<i>scr</i> 42.70	—
4 REAR BUMPER SIDE RETAINER	58.60	2 PC	<i>dis</i> 117.20	—
5 REAR BUMPER CORNAL RETAINER	37.80	2 PC	<i>cm</i> 75.60	—
6 REAR BUMPER CLIP	3.89	5 PC	<i>re</i> 19.45	—
7 REAR BOOT	911.60	1 PC	<i>Bt</i> 911.60	—
8 REAR BOOT INNER LOCK	126.80	1 PC	<i>re</i> 126.80	—
9 REAR BOOT INNER RUBBER	194.70	1 PC	<i>dis</i> 194.70	X
10 REAR BOOT INSULATOR	291.60	1 PC	<i>cm</i> 291.60	—
11 REAR BOOT CLIP	3.21	9 PC	<i>re</i> 28.89	—
12 REAR BOOT REFLECTOR	<i>cm/dis</i> 195.70	2 PC	391.40	—
13 REAR BOOT HINGE	72.40	2 PC	<i>R</i> 144.80	X
14 REAR BOOT LOGO	55.80	1 PC	<i>re</i> 55.80	—
15 REAR BOOT EMBLEM '1.6'	32.13	1 PC	<i>re</i> 32.13	—
16 REAR BOOT EMBLEM 'COROLLA'	51.17	1 PC	<i>re</i> 51.17	—
17 REAR BOOT EMBLEM 'ALTIS'	50.22	1 PC	<i>re</i> 50.22	—
18 REAR BOOT NUMBER PLATE GARNISH	213.21	1 PC	<i>way</i> 213.21	—
19 REAR END PANEL	580.60	1 PC	<i>Bt</i> 580.60	—
20 REAR END PANEL INNER TOP GARNISH	227.20	1 PC	<i>dis</i> 227.20	—
21 REAR END PANEL INNER TOP GARNISH CLIP	3.21	2 PC	<i>re</i> 6.42	—
22 TAILLAMP	<i>dis cm</i> 424.10	2 PC	848.20	—
23 TAILLAMP INNER GASKET	29.80	2 PC	<i>re</i> 59.60	—
24 TAILLAMP LOWER RETAINER	32.10	2 PC	<i>cm</i> 64.20	—
25 RH TAILLAMP PANEL	103.40	1 PC	<i>Bt</i> 103.40	—
26 REAR RH FENDER	927.45	1 PC	<i>Bt</i> 927.45	—
27 REAR RH FENDER INNER TRIM	388.90	1 PC	<i>Reform</i> 388.90	—
28 REAR RH FENDER AIR SCROP GRILLE	155.40	1 PC	<i>dis</i> 155.40	—
29 REAR WINDSCREEN GLASS MOULDING	109.78	1 PC	<i>re</i> 109.78	—
30 REAR SPARE TYRE PANEL TOP BOARD	369.20	1 PC	<i>cm</i> 369.20	—
			7,277.92	
Less 25%			1,819.48	5,458.44
Special Net				
31 REVERSE SENSOR	200.00	1 SET	<i>Re</i> 200.00	—
32 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>re</i> 40.00	—
33 REAR NUMBER PLATE	35.00	1 PC	<i>Bt</i> 35.00	—

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 30/08/2019
TP Veh Reg No: SKF6437Y

Estimate No: ES1991947/AMK
Date: 02 Sep 2019
Policy No: 5050685487-08
Veh Reg No: SJG783T
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chassis No: MR053ZEE106109604
Engine No: 3ZZ4768924
Reg. Date: 20/06/2008

Estimate Repair Cost to Vehicle No :SJG783T

Description	U/Price	Quantity	List Price	Amount
34 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<u>SS</u> 40.00	<u>SS</u> 40.00
Labour			315.00	315.00
35 TOWING	50.00	1 LA	50.00	✓
36 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
37 REMOVE & REFIX REAR BUMPER, REAR BOOTLID & ATTACHMENTS, TAIL LAMP, TO CUT, WELD & RENEW REAR END PANEL, RH TAIL LAMP PANEL, REAR RH FENDER, KNOCKING & REPAIR REAR LH FENDER, REAR SPARE TYRE PANEL, CHASSIS FRAMES & REALIGN REAR RH DOOR THE SAME	1,500.00	1 LA	1,500.00	1300
38 PUTTY & RESPRAY REAR BUMPER, REAR BOOT, BOTH FENDERS, RH TAIL LAMP PANEL, REAR END PANEL, REAR SPARE TYRE PANEL, REAR RH DOOR, CHASSIS FRAMES & ALL AFFECTED AREAS	1,400.00	1 LA	1,400.00	1200
39 REMOVE & REFIX REAR SEAT, CARPETS TO FACILITATE REPAIR	100.00	1 LA	100.00	✓
40 TO MOUNT ON CAR-O-LINER, JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
41 RUSTPROOFING	120.00	1 LA	120.00	90
			3,520.00	3,520.00
			Total	SS 9,293.44
			Add GST @ 7%	650.54
			Total Amount Payable	SS 9,943.98

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

8608.82
45 # 6850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: