

ASS. REC. BY:

REF: CS | SMD 19015469 | Kv f3

Special Instruction: n2

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Grau Tio of SMO Date/Time: 2.9.19 1.55pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMM 7468R Insured: PBJ 4521K

at Workshop m/s Wei Lee Motor Tel: 64569830

of Block 9 Sin mng Industri Estate #01-32

Policy No: Dlgm mc 01007260 Claim No: (MTD) 1904104

Sum Insured: Excess:

Make of Veh: D.O.A. 26/8/2019 (Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 2.9.2019 1.55pm Person Contacted: Karim Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMM 7468R -x
	PBJ 4521K - CC4 / ASN 11015293 / Gbt D.O.A - 26/8/2019
12/9/19	Send preli revised via merimen

ASS. REC. BY:

REF: SMO/

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s wei tee
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal or Market Value: \$ 21k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMM 7488R Yr Regn: 01, 10
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Wagon
 Make: Honda Odyssey c.c. 2354
 Colour: M. Black A/C: Insured / Std / NI / NA
 Sp. Reading: 11112P T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHM RB 3850.9 2201525
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD / RIM or
 Tyre Size: F: 215/55R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal: 5 mm Rear R/Bal: 6 mm
 L/Bal: 5 mm L/Bal: 6 mm
 D.O.A. 26/8/18 D.O.I. 4/9/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
O/S 1st body
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>

9/9 @ 259pm 6/1 Day @ 1700 confirmed with Karen (Recd 1322.64, 447)

RECEIVED 10 SEP 2019

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 2
 Resurvey No. of Trip: _____

1) _____
 Date/Time, File Return to?
 2) 9/9 - typist
 Report Format: menimen
 Lump Sum / I.B.I.: (\$) 1700 =

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Survey Fee	
Transportation	<u>250</u>
S - R.S. St	<u>11</u>
Prints	
Others	
TOTAL	<u>261</u>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Thelma Choo	Date:	05 Sep 2019
Preliminary Advice			

Insured Vehicle No	: FBJ4521K	Accident Date	: 26/08/2019
TP Vehicle No	: SMM7468R	Assignment Date	: 02/09/2019
Make	: HONDA ODYSSEY	Est. Duration of Repair	: 2
Date of Inspection	: 4/9/2019		
Inspection At	: WEI LEE MOTOR WORKS		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	3,022.64
Revised Amount	:SS	2,121.12
Check Items (Estimated)	:SS	0.00
Total	:SS	2,121.12
Lump Sum Repair	:SS	
Total Loss Consideration		
New for Old Value	:SS	
Pre-Accident Value	:SS	
COE / PARF Rebate	:SS	
Salvage Value	:SS	
Margin for Repair	:SS	

Remarks

- The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments :The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Aug 2019		02 Sep 2019 13:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	TAN HUI MING ZAC, ID: S9638987F		
Main Claimant:	KH LEASING PTE. LTD., Co. Reg. No.: 201611813C		
Vehicle Reg. No.:	SMM7468R	Date of Loss:	26/08/2019 19:00 - :59
Claim Type:	TP / CMTD1904104	Policy/Cover Note No.:	D18MTMC01007260 (Comprehensive)
Vehicle Reg. No. (Insured):	FBJ4521K	Policy No. (Claimant):	
		Excess:	
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/09/2019]		
Adj Asg. Remarks:	WS: 6456 9830 KAREN		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 2 September, 2019 1:55 PM
To: karen Seah; Choo, Thelma; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1904104/THE - LKK/ FB4521K & SMM7468R ACC ON 26.08.19

Without Prejudice

Our Reference: CMTD1904104/THE
Your Reference: SMM7468R

Hi Karen,

As spoken and agreed, we will appoint **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for **SMM7468R** on a without Prejudice Basis and any admission of liability basis.

Please submit your report via Merimen upon completion of survey.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom

disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Teo, Grace
Sent: Monday, September 02, 2019 10:42 AM
To: 'karen Seah'; Choo, Thelma
Cc: Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1904104/THE - LIA(SUV)/ FBJ4521K & SMM7468R ACC ON 26.08.19

Without Prejudice

Our Reference: CMTD1904104/THE
Your Reference: SMM7468R

Hi Karen,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Thelma Choo** is the handler of this case who can be contacted at 63224 681.

As spoken, kindly advise when your client will be leaving the vehicle at your premises for the survey.

Aside to Thelma,

Please refer to the liability request from **Wei Lee Motor Works**.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: karen Seah [mailto:weileemotorworks@gmail.com]

Sent: Saturday, August 31, 2019 11:48 AM

To: Claims - Motor Survey

Subject: TP survey for vehicle no:SMM7468R

Your insured vehicle no: FBJ4521K

Accident involving vehicle no: SMM7468R/FBJ4521K/SHC5170Z

DOA: 26/08/2019 AT Yishun Ave 1

Dear officer incharge

I refer to the above case,attached with the accident report.Please arrange to survey the vehicle.

Thank you.

--

Best Regards,

Karen Seah

Wei Lee Motor Works

Block 9 Sin Ming Industrial Estate

#01-32 Singapore 575644

Tel: 6456 9830

Fax: 6458 0128

Company registration: 269436/00J

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	813C
Vehicle Details	
Vehicle No.:	SMM7468R
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT SR
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	K24Z21301532
Chassis No.:	JHMRB38509C201525
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$33,532.00
Original Registration Date:	18 Jan 2010
First Registration Date:	18 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$33,532.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jan 2020
PARF Rebate Amount:	\$16,766.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,190.00
COE Rebate Amount:	\$701.00
Total Rebate Amount:	\$17,467.00

The information contained herein is correct as at 05 Sep 2019.

OK

威利摩哆

WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

*wed 2/9/19am
11 AM - 12 AM LKK
Thei machod
CMTD 1904/104/THE
Kenneth
969/0663*

*Not authorized
L1 Sy @ 1700
Penny After Paint
2 days*

31,AUG 2019

Sompo Insurance (S) Pte Ltd
50 Raffles Place
#05-01/06
Singapore Lane Tower
S 048623

Attn: Motor claim dept=3rd party claim
Claiming against your insured vehicle no: FBJ4521K
Accident involving vehicle no: SMM7468R/FBJ4521K/SHC5170Z
DOA: 26/08/2019 AT Yishun Ave 1

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SMM7468R

To supply--

Description	Qty	Amount
Front door	1 <i>Not/way</i>	1,122.10 ✓
Side mirror	1 <i>Not</i>	516.80 ✓
Rh side skirt	1 <i>Not</i>	426.90 X
Parts		2,065.80
Parts less 20%		413.16
		1,652.64

To remove/transfer doorboard,door glass and all attachments to new door.	120.00	<i>601</i>
To remove damaged parts and attachments		
Repair/reshape dented areas.		
Replace/align above parts into position	750.00	<i>3001</i>
To spray paint.	500.00	<i>4501</i>

	3,022.64	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015469/KVF3N2

Date: 12/09/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTMC01007260
Claimant Vehicle No :	SMM7468R	Insured Vehicle No :	FBJ4521K
Date of Loss:	26/08/2019	Nature of Claim:	TP
		Claim No:	CMTD1904104

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM7468R	Engine No:	K24Z21301532
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRB38509C201525
Reg. Date:	18/01/2010 (Man. Year: 2009)	Odometer:	111129 km
Colour:	Metallic Black		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	1,652.64	1,311.12	341.52	20.67	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,370.00	810.00	560.00	40.88	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	3,022.64	2,121.12	901.52	29.83	
Approved Total (Overridden) (S\$)		1,700.00			
	(S\$)	3,022.64	1,700.00	1,322.64	43.76
+ GST 7.00/7.00% (S\$)	211.58	119.00	92.58	43.76	
Nett Amount (S\$)	3,234.22	1,819.00	1,415.22	43.76	

INSPECTION

Date of Assignment: 02/09/2019

Date Inspected: 04/09/2019 Inspected At:

Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL
ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2019)
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMM7468R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT DOOR	Dented/Warped	1,122.10 FL	*1,122.10 FL	
2	1		*SIDE MIRROR	Dented	516.80 FL	*516.80 FL	
3	1		*RH SIDE SKIRT	Repair	426.90 FL	*- FL	
					Sub Total (S\$)	2,065.80	1,638.90
					- List Item Discount on L Items 20.00/20.00% (S\$)	413.16	327.78
					Total Parts (S\$)	1,652.64	1,311.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE/TRANSFER DOORBOARD,DOOR GLASS AND ALL ATTACHMENTS TO NEW DOOR	New	120.00	60.00
2	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DENTED AREAS.REPLACE/ALIGN ABOVE PARTS INTO POSITION	New	750.00	300.00
3	TO SPRAY PAINT	New	500.00	450.00
Gross Labour Cost (S\$)			1,370.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >