



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department
Contact : 62238122 Fax No. : 62244174

hklc [Redacted]

Estimate : ES707471

Date : 29/08/2019
Vehicle Num. : SMM 3550L
Make/Model : BMW 316
Chassis/Eng# :
Accident Date : 29/08/2019
Claim No. :
Reference :
Policy No. :

Not Allocated
hklc
h/s 67350
2/9/19
Whispered Allocated
7dy.

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	REAR BUMPER	1233.25	1,233.25
2.	2PCS	REAR BUMPER SIDE RETAINER	75.75	151.50
3.	12PCS	REAR BUMPER CLIP	8.00	96.00
4.	1PC	REAR BUMPER REINFORCEMENT	687.95	687.95
5.	1PC	REAR BUMPER SPONGE	129.00	129.00
6.	4PCS	REVERSE SENSOR	265 x 2 = 530	1,147.40
7.	1PC	BOOT LID LOGO	78.50	78.50
8.	1PC	BOOT LID WEATHERSTRIP	225.45	225.45
9.	1PC	BOOT LID M3 EMBLEM	95.00	95.00
10.	1PC	FRONT BUMPER	1315.45	1,315.45
11.	2PCS	FRONT BUMPER SIDE RETAINER	35.10	70.20
12.	12PCS	FRONT BUMPER CLIP	8.00	96.00
13.	1PC	FRONT BUMPER REINFORCEMENT	615.50	615.50
14.	1PC	FRONT BUMPER SPONGE	95.00	95.00
15.	2PCS	RADIATOR GRILLE	185.00 x 2 = 370	454.30
16.	1PC	N/S HEADLAMP	2205.43	2,205.43
17.	2PCS	HEADLAMP LOWER BRACKET	131.50	263.00
18.	1PC	FRONT BUMPER LOGO	81.50	81.50
19.	1PC	FRONT NUMBER PLATE BASE	79.90	79.90
20.	2PCS	HEADLAMP TOP BRACKET	15.20	30.40
21.	20PCS	REAR FENDER INNER TRIM CLIP	8.00	160.00
22.	1PC	BOOT LID LOCK	368.30	368.30

List TotalS\$: 10,760.50
10.00% Discount S\$: 1,076.05
Total 9,684.45

but support panel centre garnish Torn 266.00

CONTINUE / ...


7920.43
102
7128.38

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department
Contact : 62238122 Fax No. : 62244174

Estimate : ES707471

Date : 29/08/2019
Vehicle Num. : SMM 3550L
Make/Model : BMW 316
Chassis/Eng# :
Accident Date : 29/08/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1PC	SPECIAL NETT ITEMS : FRONT NUMBER PLATE	Scn	45.00 40
2.	1PC	COOLANT	11	25.00 X
3.	1SET	GRILLE STICKER	11	150.00 -
Special Nett Total S\$:				220.00

LABOUR :				
TO CHECK LIGHT SYSTEM AND WIRING			30	50.00
TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS			80	150.00
TO RE-INITIALISE PDC/SONAR			180	300.00
INSTALL REVERSE SENSOR IN NEW BUMPER			11x	80.00
TO VACCUM, REOIL AND REGAS AIR CON			11x	100.00
DROP EXHAUST AND REPAIR			80	250.00
LABOUR/PANEL BEATING			700	1,100.00
SPRAY PAINTING			800	1,200.00
Labour Total S\$:				3,230.00

E. & O.E. Total S\$: 13,134.45

for FALCON AIR AUTO SERVICES PTE LTD
TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2060
9188-18
735v

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg