

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP :10443**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/1039/2019/NS  
**Date** : 30-Aug-19

**Vehicle NOT IN workshop. Please arrange for survey**

### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms Low Juek Tiang  
**Address** : 24 Gardenia Road  
Singapore 578828  
**Telephone** : HP +65 98189168  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 2100427029-04  
**Vehicle No** : **SBB 9899 E**  
**Model Code** : Audi A3 Sedan 1.4 TFSI  
**Model / Year** : Aug-15  
**Engine No** : CZC 267076  
**Chassis No** : WAUZZZ8V8G1004767  
**Mileage** :  
**Date In** :  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 29-Aug-19  
**Place of Accident** : Thomson Rd - Whitley Rd Junction

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SBB 9899 E

<u>S/N Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1 To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2 To dismantle and renew front bumper, bonnet and both headlights. To repair both front fenders. To inspect front lock carrier for further damages. Re-organise rear crash managements. Reinstall all parts removed.	\$ <del>3,150.00</del> 500	
3 To respray front bumper, bonnet and both front fenders.	\$ <del>3,600.00</del> 1100	
4 To carry out diagnostic checks.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>	<b>: \$ <u>7,302.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SBB 9899 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>deband</i>	\$ 1,830.00	✓
2	FROONT BUMPER FIXING PARTS <i>seen</i>	\$ 170.00	+
3	FRONT BUMPER COVER TRIM - LH / RH <i>seen</i>	2 \$ 296.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>seen</i>	2 \$ 148.00	+
5	FRONT BUMPER PULL STRAP - LOWER <i>seen</i>	4 \$ 187.00	+
6	FRONT BUMPER GUIDE SECTION - LH / RH <i>seen</i>	2 \$ 70.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>RH cut</i>	2 \$ 198.00	99.
8	RADIATOR GRILLE <i>could</i>	\$ 637.00	✓
9	RADIATOR GRILLE COVER ?	\$ 89.00	?
10	FRONT BUMPER SIDE REINFORCEMENT ?	\$ 660.00	?
11	FRONT BUMPER FOAM FILLER PIECE ?	\$ 125.00	?
12	FRONT BUMPER COVER ?	\$ 51.00	?
13	SIGNAL HORN RETAINER - LH LOW TONE <i>seen</i>	\$ 182.00	+
14	SIGNAL HORN RETAINER - RH HIGH TONE	\$ 182.00	+
15	CAUTION SIGN <i>seen</i>	NEC \$ 13.00	✓
16	AIRCON STICKER	NEC \$ 7.00	✓
17	BONNET <i>Rep</i>	\$ 2,898.00	+
18	BONNET ATTACHMENT PARTS <i>?</i>	\$ 149.00	+
19	BONNET CATCH HOOK <i>seen</i>	\$ 81.00	+
20	BONNET STRIKER - LH / RH <i>seen</i>	2 \$ 200.00	+
<b>SUB TOTAL SPARE PARTS</b>		<b>\$ 8,173.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SBB 9899 E

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET EDGE PROTECTION - FRONT <i>new</i>	\$	25.00 <i>X</i>
22	BONNET CATCH HOOK <i>new</i>	\$	58.00 <i>X</i>
23	BONNET LID LOCK <i>new</i>	2 \$	367.00 <i>X</i>
24	BONNET BOWDEN CABLE <i>new</i>	\$	53.00 <i>X</i>
25	BONNET LID LOCK CABLE <i>new</i>	\$	67.00 <i>X</i>
26	GAS DISCHARGE LAMP HEADLIGHT - LH / RH <i>RH ?</i>	2 \$	3,650.00 <i>?</i>
27	HEADLIGHT LIFT CYLINDER - LH / RH <i>new</i>	2 \$	362.00 <i>X</i>
28	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2 \$	44.00 <i>X</i>
29	RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>	\$	11.00 <i>X</i>
30	FRONT NO. PLATE <i>Dented</i>	S/N \$	40.00 <i>✓</i>
31	SUNDRIES <i>?</i>	\$	300.00 <i>?</i>
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 13,150.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 7,302.00</b>
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 20,452.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lim  
Surveyed Date : 02/09/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 04 Days.

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant