

ASS. REC. BY:

REF: CS / SMO 19015478 / EY 130

Special Instruction:

SURVEYOR

STAFF

ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMO

Date/Time: 2.9.19 15.18p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 4434U

Insured: FBP 9213K

at Workshop m/s SMRT

Tel: 68662671

of 60 Woodland Industrial Park E9

Policy No: D19MTM01005431

Claim No: CMTD190434

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30.4.2019

CA : REV. / REP. / REV 24 HRS

"up"

H.O.D. Enforcement:

Date/Time: 2.9.19 3.28p.m

Person Contacted: Shari

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 4434U - C3/ AIG 120125L Y 21421 P1 D.O.A - 01/14/2012
	FBP 9213K - X

photo ok

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 4434U Yr Regn: 96/3/14
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota PinaS c.c. 1798
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 64825 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: J70KN36U205739346
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/50R15
 R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or NEUTON

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 30/8/19 D.O.I. 2/9/19
 Survey held at SMRT

Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>4/9</u>	<u>Sent Preli. Revise by Merimen</u>
<u>30/9/19</u>	<u>Finalize Coll. - \$5750.5 (Ph Seen)</u>
	<u>(Red = \$12,450-54, 68%)</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 1/10/19 Typist

Report Formas:

Temp. Sum / L.B.I. = \$5750/=

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Wash and ...

Survey Fee:

Transportation:

S + RS \$

Photos

Other

Total

<u>150</u>
<u>11</u>
<u>461</u>

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 04 Sep 2019

Preliminary Advice

Insured Vehicle No	: FBP9213K	Accident Date	: 30/08/2019
TP Vehicle No	: SHC4434U	Assignment Date	: 02/09/2019
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 5.00
Date of Inspection	: 02/09/2019		
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (HQ) NO. 61 WOODLANDS INDUSTRIAL PARK E9, #04-04 PREMIUM BUILDING SINGAPORE 757047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages N/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,200.54
Revised Amount	:S\$	6,777.45
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,777.45

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a "without prejudice" basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Sep 2019		02 Sep 2019 15:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUHAMMAD SHAH DANIAL BIN ROSLI, ID: 59813950H		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHC4434U	Date of Loss:	30/08/2019 16:00 - :59
Claim Type:	TP / CMTD1904134	Policy/Cover Note No.:	D19MTMC01005431 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBP9213K	Policy No. (Claimant):	
		Excess:	
Repaier:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/09/2019]		
Adj Asg. Remarks:	WS: SHANTI 68662671/2 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 2 September, 2019 3:15 PM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis); 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; Choo, Thelma
Cc: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis); Koo Yew Chung (Auto Svcs/ARC/ARC); Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis); Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis); angbangkien@smrt.com.sg; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1904134/THE - LKK/ FBP9213K(nr) & SHC4434U ACC On 30.08.19

Without Prejudice

Our Reference: CMTD1904134/THE
Your Reference: SHC4434U

Hi Shanti,

We acknowledged receipt of your claim documents.

*Please be informed that **Ms. Thelma Choo** is the handler of this case who can be contacted at 63224 681.*

Please be informed, we have appointed **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for **SHC4434U** on a without Prejudice and any admission of liability basis.

Please submit your report via Merimen upon completion of survey.

Aside to Thelma,

For your update.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) [<mailto:BThaiyalN@smrt.com.sg>]

Sent: Monday, September 02, 2019 8:24 AM

To: 'motorsurvey@sompo.com.sg'

Cc: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis); Koo Yew Chung (Auto Svcs/ARC/ARC); Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis); Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis); Keith Ang Bang Kien (Auto Svcs/ARC/ARC/Taxis)

Subject: RE: SHC4434U - Sompo Insurance

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHC4434U** within 48 hours according to GIA guide line, involving your insured **FBP9213K**

Vehicle in Woodlands Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available abroad.

ACCIDENT STATEMENT

Date Of Report: 31/08/2019 11:45
 Date Of Accident: 30/08/2019 16:00
 Exact Location Of Accident: MARINA BOULEVARD AND BAYFRONT AVENUE
 Country/State of Loss: SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SHC4434U
Insured/Policyholder
 Name Of Registered Owner: SMRT TAXIS PTE LTD
 Co Reg No: 198905369K
 Email Address: NOEMAIL
 Mobile Phone No: (LOCAL) +65-80000000
 Alternative Phone No: OFFICE-80000000

Vehicle Particulars

Manufacturer: TOYOTA
 Model: PRIUS TAXI-1.8 (A)
 Exact Purpose for which vehicle was being used at time of accident: HIRE AND REWARD

Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken: THIRD PARTY
 Vehicle Category: TAXI

Insurance Company

Name of Insurance Company: MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage: THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy: YES
 Policy Number: D-19093197MFSH
 Cover Note Number:

Driver

Name of Driver: TAY KOK LENG
 NRIC No: S7611374F
 Date Of Birth: 15/12/1976
 Occupation: OUTDOOR
 Date Of Driving Pass: 14/01/2011
 Driving Experience: 8 YEARS AND 7 MONTHS
 Gender: MALE
 Mobile Number: (LOCAL) +65-80000000
 Fax Number:
 Contact Number:
 EMail Address: NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TAMPINES N.P.C
 Police Station Address ROAD, TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident


REFER TO POLICE REPORT - T/20190830/2181

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBP9213K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver UNKNOWN
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. The first part of the document is a title page. It contains the title of the document, the author's name, and the date of the document. The title is "The History of the United States of America". The author is "John Adams". The date is "1776".

2. The second part of the document is a preface. It contains the author's introduction to the document. The author states that the document is a history of the United States of America, and that it is written for the purpose of informing the public of the events that have shaped the nation.

3. The third part of the document is the main body of the text. It contains the author's account of the events that led to the founding of the United States. The author begins with the early history of the colonies, and then moves on to the American Revolution. He describes the battles, the political struggles, and the eventual independence of the United States.

4. The fourth part of the document is a conclusion. The author summarizes the events of the American Revolution, and offers his thoughts on the future of the United States. He concludes that the United States is a young nation, and that it has the potential to become a great power.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

Driver's Signature: _____
 (If driver is not the policyholder)
 Date & Time: _____

Reporting Centre Personnel's Signature:
Name: _____
Title: _____

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBP9213K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode



**SINGAPORE
POLICE FORCE**



T/20190830/2181

1 of 3

Police Station Of Origin:
Tampines N.P.C
8 Tampines Avenue 4 SINGAPORE 529682
Tel No 1800-5871999

Report No: T/20190830/2181

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/08/2019 19:43	Video Report No.: A/70190830/0122	Station Diary No.: 120
--	--------------------------------------	---------------------------

Informant's Particulars

Name of Informant: TAY KOK LENG		Address: 19 TAMPINES AVENUE 8 #11-30 SINGAPORE 529603	
ID Type / ID No: NRIC NO / S7641374H		Contact No: Home/Office: Mobile: 85333883	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 42	Date of Birth: 15/12/1976	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/08/2019 16:00	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 MARINA BOULEVARD BAYFRONT AVENUE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBP9213K	Motorcycle				Slightly Damaged	0
SHC4434U	TAXI				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999



T/20190830/2181

2 of 3

Report No: T/20190830/2181

CONTINUATION OF REPORT

Driver			
Name	TAY KOK LENG	ID No.	S7641374F
Related Vehicle	SHC4434U (TAXI)	Contact No.	85333883
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 30/08/2019 at about 1600hrs, I was driving my SMRT taxi bearing SHC4434U along second lane of Marina Boulevard. As I approached the X-junction between Marina Boulevard and Bayfront Ave, I was turning left as the traffic light was in my favour. All of a sudden, there was a motorcycle that had collided into my taxi's front left side. The motorcycle was from the extreme left lane which is only for turning left. I then stopped and made a check. The rider was conscious and able to stand up. Ambulance and traffic police came. Traffic police took my taxi's in car camera memory card and told me to lodge a traffic accident report vide A/20190830/0122 with IO in charge IO Shahrul. Ambulance conveyed the rider to hospital.

As such, I am lodging this traffic accident report.



SINGAPORE
POLICE FORCE



T/20190830/2181

3 of 3

Report No. T/20190830/2181

Police Station Of Origin:
Tampines N.P.C.
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 MUHAMMAD ANIYAL BIN
BAHARUDDIN

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

30/08/2019 19:43

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SIAH NIZAM BIN SAMARRI

Contact No.: 65421504

Classification Of Case:

Authentication Stamp

NP158



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHC4434U
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR5893733
Chassis No.:	JTDKN36U205739346
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	26 Mar 2014
First Registration Date:	26 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2022
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$18,811.00
Total Rebate Amount:	\$24,668.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Sep 2019

OK

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757706
FAX Number : 63685582
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 02/09/2019

User ID : kimmingchin

Section A - Accident Details


Registration Number	SHC4434U
Case Reference Number	TAX/08/19/2136
Registration Date	26/3/2014
Company Type	SMRT Taxi Pte Ltd
Make	TOYOTA
Model	PROUS
Name of Driver	TAY KOK LENG
Type of Accident	Side Swipe
Accident Date and Time	30/8/2019 4:00 PM
Accident Reported Date and Time	31/8/2019 11:23 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	30/8/2019 5:05 PM
Replacement Vehicle issued?	No
Job Card Number	24103148
Special Instruction to ARC, if any	TOWED \$40 /TP
Prepared Date and Time	1/9/2019 8:51 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$2,412.00	\$1,000.00
Total Spare Part Cost	\$8,246.89	\$4,390.65
Total Other Cost	\$1,101.00	\$216.00
TOTAL COST	\$12,773.89	\$6,106.65
Lump Sum Total	\$12,800.00	\$6,100.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Fleet Supervisor Team	STEVE CHEN
ARC / Surveyor Sign Off Date	01/09/2019 9:38 AM	02/09/2019 5:00 PM
Signature		
Remarks	L/S Repair, TAKE AFTER SPRAY	

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Toyota Prous

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/09/2019

User ID : klmingschin

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$500.00
Total Labour	\$1,014.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO REPSRAY APRON PANEL LH	\$180.00	\$0.00
TO REPSRAY FRONT FENDER LH	\$378.00	\$200.00
TO REPSRAY RIM	\$180.00	\$0.00
REPSRAY MIRROR COVER LH	\$180.00	\$50.00
TO REPSRAY SILL MEMBER PANEL LH	\$180.00	\$0.00
TO REPSRAY ROCKER PANEL MOULDING	\$180.00	\$150.00
TO REPSRAY FRONT DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,412.00	\$1,000.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$56.00 / ARC
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 / ARC
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$20.00 / ARC
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	\$120.00	\$20.00 / ARC
TO TRANSFER DOOR MECHANISM	\$120.00	\$20.00 / ARC
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00 / ARC
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00 / ARC
Total Other Costs	\$1,101.00	\$216.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace / ARC
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X NN
		53867-47030	SEAL, FRONT FENDER TO COWL, SIDE LH	1.00	\$15.20	25.00	\$11.40	Replace	Replace / ARC
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given X NN
		53852-47020	FENDER LINER PAD, FR WHEEL LH	1.00	\$48.30	25.00	\$36.23	Replace	Replace / CUT
		48520-80294	SHOCK ABSORBER FRT/LH	0.00	\$394.20	0.00	\$0.00	Replace	Check X NN
		43550-47011	WHEEL HUB FRT	0.00	\$349.70	0.00	\$0.00	Replace	Check X NN
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace / ARC
		66720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given X NN
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair X R
		52116-47040	BUMPER SUPPORT FLH	1.00	\$75.40	25.00	\$57.30	Replace	Replace / BR
	Body	53301-47060	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Repair X R
	BODY LH	53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given X NN

\$157.00

\$117.75
\$60.00

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 6365582
Estimator Telephone Number : 6862623
Accident Reporting Number : 6862672

Date Generated : 02/09/2019

User ID : kimmingchin

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81170-47500	HEAD LAMP LH	1.00	\$945.20	25.00	\$708.90	Replace	Replace
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
	GLASS LH	62120-47021	QUARTER GLASS FRT/LH	1.00	\$234.90	25.00	\$176.18	Replace	Replace
	UNDERCARRIAGE	53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given
		53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace
	BODY LH	53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Not Given
		42611-47140	WHEEL DISC	1.00	\$1,484.20	25.00	\$1,113.15	Replace	Replace
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
	BODY LH	61404-47030	SILL MEMBER OUTER LH	0.00	\$519.90	0.00	\$0.00	Replace	Not Given
	UNDERCARRIAGE	48609-47040	SHOCK ABSORBER MOUNTING FRT_RH/LH	0.00	\$193.80	0.00	\$0.00	Replace	Not Given
	UNDERCARRIAGE	48609-47040	SHOCK ABSORBER MOUNTING FRT_RH/LH	0.00	\$193.80	0.00	\$0.00	Replace	Not Given
	UNDERCARRIAGE	48825-47020	STABILIZER BAR LINK FRT/RH/LH	0.00	\$195.00	0.00	\$0.00	Replace	Not Given
	UNDERCARRIAGE	43202-47030	STEERING KNUCKLE LH FRT	0.00	\$580.80	0.00	\$0.00	Replace	Not Given
	UNDERCARRIAGE	45047-48165	TIE ROD END LH	0.00	\$159.30	0.00	\$0.00	Replace	Not Given
	UNDERCARRIAGE	48068-47050	LOWER ARM FRT/LH	0.00	\$625.90	0.00	\$0.00	Replace	Not Given
		75852-47900	MOULDING BODY, LH	1.00	\$673.80	25.00	\$505.20	Replace	Replace
	BODY LH	67064-47980	DOOR RRLH	0.00	\$694.40	0.00	\$0.00	Replace	Not Given
	BODY LH	88745-12120	HINGE LOWER LHF DOOR	0.00	\$95.10	0.00	\$0.00	Replace	Not Given
	Body	88610-47021	CHECK ASSY, FR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Not Given
	VM	75729-47021	DOOR BELT FRT/LH	0.00	\$69.20	0.00	\$0.00	Replace	Not Given
	BODY LH	87945-47310	MIRROR ASSY, LH	1.00	\$1,224.90	25.00	\$918.68	Replace	Replace
	BODY LH	87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	25.00	\$80.55	Replace	Replace
		67002-47070	DOOR FRT/LH	1.00	\$894.40	25.00	\$670.80	Replace	Replace
Total					\$13,659.05		\$4,390.65		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

6511-60 \$4883-70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

19200-54

Section A - Accident Details

Registration Number	SHC4434U
Case Reference Number	TAX08/19/2138
Registration Date	26/3/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAY KOK LENG
Type of Accident	Side Swipe
Accident Date and Time	30/8/2019 4:00 PM
Accident Reported Date and Time	31/8/2019 11:23 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	30/8/2019 5:05 PM
Replacement Vehicle issued?	No
Job Card Number	24103148
Special Instruction to ARC, if any	TOWED \$40 /TP
Prepared Date and Time	1/9/2019 8:51 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



SMRT

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$500.00
Total Spray Cost	\$2,412.00	\$1,000.00
Total Spare Part Cost	\$8,248.89	\$4,049.18
Total Other Cost	\$1,101.00	\$216.00
TOTAL COST	\$12,775.89	\$5,765.18
Lump Sum Total	\$12,800.00	\$5,760.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / Somp
ARC / Surveyor Sign Off Date	02/09/2019 5:05 PM	02/09/2019 5:00 PM
Signature		
Remarks		L/S repair, TAKE AFTER SPRAY.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0233	Invoice Number	
Quotation Date	16.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$500.00
Total Labour	\$1,014.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
RESPRAY MIRROR COVER LH	\$180.00	\$50.00
TO RESPRAY SILL MEMBER PANEL LH	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,412.00	\$1,000.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$56.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$20.00
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	\$120.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$20.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00
Total Other Costs	\$1,101.00	\$216.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-15310	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
			SEALANT WSCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
		53857-47030	SEAL FRONT FENDER TO COWL SIDE LH	1.00	\$15.20	25.00	\$11.40	Replace	Replace ✓
		53826-47050	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 30 Woodlands Industrial Park St, Singapore 757135
 FAX Number: 67693392
 Estimate Telephone Number: 68652623
 Accident Reporting Number: 48662672

Date Generated: 27/03/19
 User ID: PabRuan

	53652-47025	FENDER LINER PAD, FR WHEEL LH	1.00	\$49.30	25.00	\$36.98	Replace	Replace	✓
	48520-80294	SHOCK ABSORBER FRT/LH	0.00	\$394.20	0.00	\$0.00	Replace	Check	X
	43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Check	X
		STICKER DECAL SMRT (DOOR)	1.00	\$80.00	0.00	\$80.00	Replace	Replace	✓
	68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given	X
	52115-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	✓
	52115-47040	BUMPER SUPPORT FLH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	✓
Body	53301-47060	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Repair	✓
BODY LH	53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X
	81170-47500	HEAD LAMP LH	1.00	\$945.20	25.00	\$708.90	Replace	Replace	✓
	53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	✓
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
GLASS LH	62120-47021	QUARTER GLASS FRT/LH	1.00	\$234.90	25.00	\$178.18	Replace	Replace	✓
UNDERCARRIAGE	53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$48.10	0.00	\$0.00	Replace	Not Given	X
	53870-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	✓
BODY LH	53702-47050	FENDER APRON SUB FRT/LH	0.00	\$537.80	0.00	\$0.00	Replace	Not Given	X
	42511-47140	WHEEL DISC	1.00	\$1,484.20	25.00	\$1,113.15	Replace	Replace	✓
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
BODY LH	61404-47030	SILL MEMBER OUTER LH	0.00	\$519.80	0.00	\$0.00	Replace	Not Given	X
UNDERCARRIAGE	48609-47040	SHOCK ABSORBER MOUNTNG FRT, RH/LH	0.00	\$193.80	0.00	\$0.00	Replace	Not Given	X
UNDERCARRIAGE	48609-47040	SHOCK ABSORBER MOUNTNG FRT, RH/LH	0.00	\$193.80	0.00	\$0.00	Replace	Not Given	✓
UNDERCARRIAGE	48820-47020	STABILIZER BAR LINK FRT/RH/LH	0.00	\$195.00	0.00	\$0.00	Replace	Not Given	X
UNDERCARRIAGE	43202-47030	STEERING KNUCKLE LH FRT	0.00	\$580.80	0.00	\$0.00	Replace	Not Given	X
UNDERCARRIAGE	45047-49185	TIE ROD END LH	0.00	\$159.30	0.00	\$0.00	Replace	Not Given	X
UNDERCARRIAGE	48089-47050	LOWER ARM FRT/LH	0.00	\$825.90	0.00	\$0.00	Replace	Not Given	✓
	75852-47990	MOULDING BODY, LH	1.00	\$573.60	25.00	\$505.20	Replace	Replace	✓
BODY LH	67004-47080	DOOR RRLH	0.00	\$894.40	0.00	\$0.00	Replace	Not Given	X
BODY LH	68740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X
Body	68610-47021	CHECK ASSY, FR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X
VM	75720-47021	DOOR BELT FRT/LH	0.00	\$69.20	0.00	\$0.00	Replace	Not Given	X
BODY LH	87940-47310	MIRROR ASSY LH	1.00	\$1,224.90	25.00	\$918.68	Replace	Replace	✓
BODY LH	87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	25.00	\$80.55	Replace	Replace	✓
	67002-47070	DOOR FRT/LH	1.00	\$894.40	25.00	\$670.80	Replace	Replace	✓
Total				\$13,659.05		\$5,061.48			

5061.48
 - 208

4049.18

+ 500.00

+ 1216.00

5765.18

4545.50

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Sep 2019		02 Sep 2019 15:18 Edit Adj Rpt	S\$5,750.00 Edit Estimates	S\$5,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MUHAMMAD SHAH DANIAL BIN ROSLI , ID: S9813950H								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4434U	Date of Loss:	30/08/2019 16:00 - :59 [65 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904134	Policy/Cover Note No.:	D19MTMC01005431 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	FBP9213K	Policy No. (Claimant):							
		Excess:							
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 11/09/2019]								
Adj Asg. Remarks:	WS: SHANTI 68662671/2 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC4434U (CMTD1904134)
 [FBP9213K]
 TP
 SMRT TAXIS PTE LTD
 Aug 30 2019 4:00PM
 [MUHAMMAD SHAH DANIAL BIN ROSLI]
 Smrt Automotive Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/09/19 17:31	Adjuster Immediate Advice		 Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/09/19 17:51	General View		 Load JPG	☒
2	30/09/19 17:51	General View		 Load JPG	☒
3	30/09/19 17:51	General View		 Load JPG	☒
4	30/09/19 17:51	General View		 Load JPG	☒
5	30/09/19 17:51	General View		 Load JPG	☒
6	30/09/19 17:51	General View		 Load JPG	☒
7	30/09/19 17:51	General View		 Load JPG	☒
8	30/09/19 17:51	General View		 Load JPG	☒
9	30/09/19 17:51	General View		 Load JPG	☒
10	30/09/19 17:51	General View		 Load JPG	☒
11	30/09/19 17:51	General View		 Load JPG	☒
12	30/09/19 17:51	General View		 Load JPG	☒
13	30/09/19 17:51	General View		 Load JPG	☒
14	30/09/19 17:51	General View		 Load JPG	☒
15	30/09/19 17:51	General View		 Load JPG	☒
16	30/09/19 17:51	General View		 Load JPG	☒
17	30/09/19 17:51	General View		 Load JPG	☒
18	30/09/19 17:51	General View		 Load JPG	☒
19	30/09/19 17:51	General View		 Load JPG	☒
20	30/09/19 17:51	General View		 Load JPG	☒
21	30/09/19 17:51	General View		 Load JPG	☒
22	30/09/19 17:51	General View		 Load JPG	☒
23	30/09/19 17:51	General View		 Load JPG	☒
24	30/09/19 17:51	General View		 Load JPG	☒
25	30/09/19 17:51	General View		 Load JPG	☒
26	30/09/19 17:51	General View		 Load JPG	☒
27	30/09/19 17:51	General View		 Load JPG	☒
28	30/09/19 17:51	General View		 Load JPG	☒
29	30/09/19 17:51	General View		 Load JPG	☒
30	30/09/19 17:51	General View		 Load JPG	☒
31	30/09/19 17:51	General View		 Load JPG	☒
32	30/09/19 17:51	General View		 Load JPG	☒
33	30/09/19 17:51	General View		 Load JPG	☒
34	30/09/19 17:51	General View		 Load JPG	☒
35	30/09/19 17:51	General View		 Load JPG	☒
36	30/09/19 17:51	General View		 Load JPG	☒
37	30/09/19 17:51	General View		 Load JPG	☒
38	30/09/19 17:51	General View		 Load JPG	☒
39	30/09/19 17:51	General View		 Load JPG	☒
40	30/09/19 17:51	General View		 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	30/09/19 17:51	General View		Load JPG ☒
42	30/09/19 17:51	General View		Load JPG ☒
43	30/09/19 17:51	General View		Load JPG ☒
44	30/09/19 17:51	General View		Load JPG ☒
45	30/09/19 17:51	General View		Load JPG ☒
46	30/09/19 17:51	General View		Load JPG ☒
47	30/09/19 17:51	General View		Load JPG ☒
48	30/09/19 17:51	General View		Load JPG ☒
49	30/09/19 17:51	General View		Load JPG ☒
50	30/09/19 17:51	General View		Load JPG ☒
51	30/09/19 17:51	General View		Load JPG ☒
52	30/09/19 17:51	General View		Load JPG ☒
53	30/09/19 17:51	General View		Load JPG ☒
54	30/09/19 17:51	General View		Load JPG ☒
55	30/09/19 17:51	General View		Load JPG ☒
56	30/09/19 17:51	General View		Load JPG ☒
57	30/09/19 17:51	General View		Load JPG ☒
58	30/09/19 17:51	Odometer Reading		Load JPG ☒
59	30/09/19 17:51	Chassis Number		Load JPG ☒
60	30/09/19 17:51	Chassis Number		Load JPG ☒
61	30/09/19 17:51	General View		Load JPG ☒
62	30/09/19 17:51	General View		Load JPG ☒
63	30/09/19 17:51	General View		Load JPG ☒
64	30/09/19 17:51	General View		Load JPG ☒
65	30/09/19 17:51	After Repair Photo		Load JPG ☒
66	30/09/19 17:51	After Repair Photo		Load JPG ☒
67	30/09/19 17:51	After Repair Photo		Load JPG ☒
68	30/09/19 17:51	After Repair Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	02/09/19 15:05	TP - SAS		Load PDF
2	02/09/19 15:16	TP - ACK+ASSIGN LKK		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015478/EYF3E2

Date: 14/10/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTMC01005431
Claimant Vehicle No :	SHC4434U	Insured Vehicle No :	FBP9213K
Date of Loss:	30/08/2019	Nature of Claim:	TP
		Claim No:	CMTD1904134

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4434U	Engine No:	2ZR5893733
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U205739346
Reg. Date:	26/03/2014 (Man. Year: 2014)	Odometer:	647525 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Neuton 5 mm	Rear Left Side:	Neuton 5 mm
Front Right Side:	Neuton 5 mm	Rear Right Side:	Neuton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,673.54	5,061.48	8,612.06	62.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,527.00	1,716.00	2,811.00	62.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,200.54	6,777.48	11,423.06	62.76
Approved Total (Overridden) (S\$)		5,750.00		
Nett Amount (S\$)	18,200.54	5,750.00	12,450.54	68.41

INSPECTION

Date of Assignment:	02/09/2019	
Date Inspected:	02/09/2019 Inspected At:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building Singapore 757047
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2019)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4434U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER CLIPS (DISC 25%) (10PCS)	Necessary	16.10 F	*12.08 F
2	1	*SEAL, FRONT FENDER TO COWL SIDE LH (DISC 25%)	Necessary	15.20 F	*11.40 F
3	1	*FENDER LINER PAD, FR WHEEL. LH (DISC 25%)	Cut	49.30 F	*36.98 F
4	1	*BUMPER SUPPORT F/LH (DISC 25%)	Broken	76.40 F	*57.30 F
5	1	*HEAD LAMP LH (DISC 25%)	Cut	945.20 F	*708.90 F
6	1	*FENDER FRT / LH (DISC 25%)	Dented	723.40 F	*542.55 F
7	1	*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
8	1	*QUARTER GLASS FRT / LH (DISC 25%)	Cut	234.90 F	*176.18 F
9	1	*FENDER LINER FRT / LH (DISC 25%)	Torn	171.70 F	*128.78 F
10	1	*WHEEL DISC (DISC 25%)	Cut	1,484.20 F	*1,113.15 F
11	1	*MOULDING BODY, LH (DISC 25%)	Broken	673.60 F	*505.20 F
12	1	*MIRROR ASSY, LH (DISC 25%)	Broken	1,224.90 F	*918.68 F
13	1	*COVER, OUTER MIRROR, LH (DISC 25%)	Broken	107.40 F	*80.55 F
14	1	*DOOR FRT / LH (DISC 25%)	Dented	894.40 F	*670.80 F
15	1	*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
16	1	*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
17	1	*PROTECTOR, FRONT FENDER SIDE PANEL LH	Not Necessary	114.50 F	*- F
18	1	*SHOCK ABSORBER FRT / LH	Not Necessary	394.20 F	*- F
19	1	*WHEEL HUB FRT	Not Necessary	549.70 F	*- F
20	1	*HINGE UPPER LHF, DOOR	Not Necessary	80.50 F	*- F
21	1	*HOOD HINGE LH	Not Necessary	55.90 F	*- F
22	1	*FENDER PROTECTOR FRT / LH UPPER	Not Necessary	46.10 F	*- F
23	1	*FENDER APRON SUB FRT / LH	Not Necessary	637.80 F	*- F
24	1	*TYRE	Not Necessary	126.74 F	*- F
25	1	*SILL MEMBER OUTER LH	Not Necessary	519.80 F	*- F
26	2	*SHOCK ABSORBER MOUNTING FRT, RH / LH	Not Necessary	193.80 F	*- F
27	2	*SHOCK ABSORBER MOUNTING FRT, RH / LH	Not Necessary	193.80 F	*- F
28	2	*STABILIZER BAR LINK FRT / RH / LH	Not Necessary	195.00 F	*- F
29	1	*STEERING KNUCKLE LH FRT	Not Necessary	580.80 F	*- F
30	1	*TIE ROD END LH	Not Necessary	159.30 F	*- F
31	1	*LOWER ARM FRT / LH	Not Necessary	625.90 F	*- F
32	1	*DOOR RR / LH	Not Necessary	894.40 F	*- F
33	1	*HINGE LOWER LHF, DOOR	Not Necessary	90.10 F	*- F
34	1	*CHECK ASSY, FR DOOR	Not Necessary	150.30 F	*- F
35	1	*DOOR BELT FRT / LH	Not Necessary	69.20 F	*- F
36	1	*BUMPER FRT	Repair	482.00 F	*- F
37	1	*HOOD PANEL	Repair	748.10 F	*- F
Total Parts (\$\$)					13,673.54 5,061.48

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,014.00	500.00
2	SPRAY PAINT	New	2,412.00	1,000.00
3	TOWING CHARGE	New	56.00	56.00
4	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM	New	125.00	0.00
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING	New	120.00	60.00
6	TO REMOVE AND REFIX UNDERCARRIAGE	New	200.00	0.00
7	TO REMOVE AND REFIX WING MIRROR	New	120.00	20.00
8	TO REMOVE & REFIX FRONT LHS / RHS QUATER GLASS	New	120.00	20.00
9	TO TRANSFER DOOR MECHANISM	New	120.00	20.00
10	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	20.00
11	TO REMOVE AND REFIT TYRE	New	120.00	20.00
Gross Labour Cost (S\$)			4,527.00	1,716.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >