

ASS. REC. BY:

REF: CS/FCI 19015479 / ~~4~~rf3

Special Instruction:

Supervisor: Kenneth

ASSIGNMENT (Office)

(CWS)

From (Person): Srine of FCI Date/Time: 2.9.19 2.32p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 9479J Insured: SHD 35894

at Workshop m/s Chow Gwan Motor Tel: 64841626

of Blk 10 Hmt Industrial Park 2A Ave 5 #01-15

Policy No: _____ Claim No: D19005646 MPSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30.8.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{mp''} H.O.D. Endorsement: _____

Date/Time: 2.9.19 2.32p.m Person Contacted: Alan Yon Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SMA 9479J - X
	SHD 35894 - CC3/TMI 1501/750/klvhs2 Rep - 26/06/2018
3/9/19	Email preli revised to FCI
8/10	88274.96 email & confirm (Red 1740.53, 1790)

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Chen Green

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 578k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 1. B. / % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMA 9479J Yr Regn: 06, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Vord c.c. 1496

Colour: N. Black A/C: Insured / Std / NI / NA

Sp. Reading: 23278 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RUI . 1301607

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 0 mm

Rear R/Bal. 0 mm

L/Bal. 0 mm

D.O.A. 30/8/19

D.O.I. 2/9/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1	File pass to <u>[Signature]</u> 24/10/2019

RECEIVED 25 OCT 2019

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to? 2) 25/10 - typist

Days Of Repair: 10

Resurvey No. of Trip: 1

- Add Fee: : Site Insp (\$)
- : Interview (\$)
- : Tech Invs (\$)
- : Weekend (\$)

Survey Fee:	170
Transportation:	50
S + RS, SI	50
Fuel	42
Others	
TOTAL	312

Report Format: CWS
Lump Sum / I.B.I: (\$ 874.96)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005646MFSH

Our ref: CS/FCI19015479/Kvf3

Date : 3/9/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 9479J


We thank for your instruction on 2/9/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/9/2019 at the premises of M/s CHEW GOON MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$10,015.48
Revised Estimate Amount	: S\$8,237.24
"Check" Items Amount	: S\$354.88
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	30-08-2019	Our Ref No. D19005646MFSH
Accident Date	30-08-2019	Claim Type. Third Party
Insured Vehicle	SHD3589H	Third Party Vehicle. SMA9479J
Survey Location	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-15,16,17 & #03-05AMK AUTOPOINT	
Contact Person.	KELLY	
Contact No.	64841626/ 0	Fax No. 64840465
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHEW GOON MOTOR	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 3 September 2019 11:31 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19005646MFSH/1-SMA 9479J
Attachments: SMA 9479J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMA 9479J
Date of survey: 2/9/2019
Number of days (estimated) : 10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 2 September 2019 2:38 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005646MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Monday, 2 September, 2019 2:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005646MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 640J

Vehicle Details

Vehicle No.: SMA9479J
Vehicle to be Exported: No
Intended Deregistration Date: 30 Aug 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Black
Manufacturing Year: 2018
Engine No.: L15B5551611
Chassis No.: RU11301607
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$21,863.00
Original Registration Date: 25 Jun 2018
First Registration Date: 25 Jun 2018
Transfer Count: 0
Actual ARF Paid: \$12,609.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Jun 2028
PARF Rebate Amount: \$9,456.00

Intended COE Rebate Details

COE Expiry Date: 24 Jun 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$36,426.00
COE Rebate Amount: \$32,125.00
Total Rebate Amount: \$41,581.00

The information contained herein is correct as at 30 Aug 2019

OK



redefining / insurance

AXA Insurance Pte Ltd
1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
(65) 6880 4740
customer.care@axa.com.sg
www.axa.com.sg

Certificate of Insurance

account number
03288

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189)- Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 -Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	NATASHA SAWHNEY	Certificate number	GA368588 / 1
Cover	Comprehensive	Chassis number	RU11301607
Plan name	Flexi	Engine number	L1585551611
NCD applicable	10%		
Vehicle registration number	SMA9479J		
Period of Insurance	from 25/06/2019 to 24/06/2020 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
- (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 600.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: First Capital Insurance Limited

Accident Date : 30.08.2019

Not Notified
Resony - By pain
10 days
8274.96

Third Party
 Policy No: _____

Date: 02.09.2019

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Vezel" Reg. No. SMA9479J Claiming Against Your Insured Veh. No. SHD3589H			
1pc	Tailgate <i>1100.90</i>		<i>Bt</i> 1,160.00 ✓
1pc	Tailgate Glass Moulding Top <i>121.80</i>	90.00	<i>na</i> 195.00 —
2pcs	Tailgate Glass Moulding Sides		<i>na</i> 180.00 —
1pc	Tailgate Glass Moulding Lower		<i>na</i> 175.00 —
1pc	Tailgate Emblem		<i>na</i> 26.00 X
1pc	Tailgate Badge Vezel		<i>na</i> 34.50 ✓
2pcs	Tailgate Lamps <i>olssux nlsom</i>	253.00	<i>na</i> 506.00 ✓
2pcs	Tailgate Lamp Gaskets	35.00	<i>na</i> 70.00 X
1pc	Tailgate Lock		<i>na</i> 160.00 —
1pc	Tailgate Lock Catch		<i>na</i> 25.70 X
1pc	Tailgate Weatherstrip		<i>cm</i> 145.00 —
1pc	Tailgate Trim Board		<i>ngom</i> 245.00 —
12pcs	Tailgate Trim Board Clips	3.80	<i>na</i> 45.60 —
1pc	Tailgate Stopper LH		<i>na</i> 12.50 —
1pc	Tailgate Inner Handle Pocket		<i>na</i> 45.00 —
1pc	Rear Bumper <i>853.00</i>	3.80	<i>Bt</i> 892.00 —
10pcs	Rear Rumper Clips	29.30	<i>na</i> 38.00 —
2pcs	Rear Rumper Brackets		<i>R</i> 58.60 X
1pc	Rear Rumper Reflector LH		<i>cm</i> 155.70 —
1pc	Rear Rumper Inner Boot Sensor		<i>ngom</i> 245.00 —
1pc	Rear Rumper Inner Boot Sensor Buzzer		<i>cm</i> 110.00 —
1pc	Rear Bumper Side Cover LH		<i>na</i> 90.00 —
1pc	End Panel <i>side</i>		<i>R</i> 549.00 —
1pc	End Panel Ganish		<i>na</i> 102.00 —
1pc	Rear Styrofoam Storage Box		<i>cm</i> 450.00 —
1pc	Spare Tyre Panel		<i>Bt/na</i> 897.00 —
1pc	Spare Tyre Panel Insulation		<i>na</i> 142.00 <i>dash</i>
1pc	Spare Tyre Top Board <i>285.45</i>		<i>na</i> 452.00 —
1pc	Spare Tyre Panel Lower Cover		<i>na</i> 185.00 —
1pc	Rear Fender Trim Board LH		<i>cm</i> 309.00 ✓
	Less 20%		7,700.60
			1,540.12
			6,160.48
	Rear Rumper Reverse Sensor		<i>na</i> 280.00 SN <i>2001n</i>
	Rear Windscreen Sealant		<i>na</i> 50.00 SN <i>401n</i>
	Rear Windscreen Fastener		<i>na</i> 50.00 SN <i>301n</i>
	Rear View Cam Bracket Adhesive Tape		<i>na</i> 15.00 SN ✓
		CIF	6,555.48

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Accident Date : 30.08.2019

Policy No: Third Party

Date: 02.09.2019

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Vezel" Reg. No. SMA9479J Claiming Against Your Insured Veh. No. SHD3589H		
		B/F	6,555.48
	To Dismantle / Transfer Tailgate Fittings / Ancillary Accessories		150.00 <i>60c</i>
	To Dismantle / Transfer Tailgate Glass.		160.00 <i>120c</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims etc		80.00 ✓
	To Supply Rear Body Panel Sealant		100.00 <i>60c</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		150.00 <i>90c</i>
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module etc		120.00 <i>70c</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Front Panel etc. Cnt, Weld End Panel, Spare Tyre Panel, and Parts Replacement		1,600.00 <i>1200c</i>
	To Respray Affected Areas		1,100.00 <i>800c</i>
			<u>10,015.48</u>

LJK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementry claim(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19015479/Kvf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3589H	Veh. Inspected	SMA 9479J
Policy No.		Coverage (\$)	0.00
Claim No.	D19005646MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	02/09/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	RU11301607	Colour	METALLIC BLACK
Odometer	23278	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	8 mm
L/H Front Tyre	215/60 R16	DUNLOP	8 mm
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/08/2019	Inspection Date	02/09/2019
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 9479J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BENT	1,160.00	1,100.90
1	TAILGATE GLASS MOULDING TOP	NECESSARY	195.00	121.80
2	TAILGATE GLASS MOULDING SIDES @\$90.00	NECESSARY	180.00	180.00
1	TAILGATE GLASS MOULDING LOWER	NECESSARY	175.00	175.00
1	TAILGATE EMBLEM	NOT NECESSARY	26.00	-
1	TAILGATE BADGE VEZEL	NECESSARY	34.50	34.50
2	TAILGATE LAMPS @\$253.00	N/S CRACKED / O/S SERVICEABLE	506.00	253.00
2	TAILGATE LAMP GASKETS @\$35.00	NOT NECESSARY	70.00	-
1	TAILGATE LOCK	DENTED	160.00	160.00
1	TAILGATE LOCK CATCH	TO REPAIR SEE LABOUR	25.70	-
1	TAILGATE WEATHERSTRIP	CUT	145.00	145.00
1	TAILGATE TRIM BOARD	MTG CRACKED	245.00	245.00
12	TAILGATE TRIM BOARD CLIPS @\$3.80	NECESSARY	45.60	45.60
1	TAILGATE STOPPER LH	MISSING	12.50	12.50
1	TAILGATE INNER HANDLE POCKET	DENTED	45.00	45.00
1	REAR BUMPER	BENT	892.00	853.00
10	REAR BUMPER CLIPS @\$3.80	NECESSARY	38.00	38.00
2	REAR BUMPER BRACKETS @\$29.30	TO REPAIR SEE LABOUR	58.60	-
1	REAR BUMPER REFLECTOR LH	CRACKED	155.70	155.70
1	REAR BUMPER INNER BOOT SENSOR	MTG BROKEN	245.00	245.00
1	REAR BUMPER INNER BOOT SENSOR BUZZER	CRACKED	110.00	110.00
1	REAR BUMPER SIDE COVER LH	DISTORTED	90.00	90.00
1	END PANEL	BENT	549.00	549.00
1	END PANEL GARNISH	DENTED	102.00	102.00
1	REAR STYROFOAM STORAGE BOX	CRACKED	450.00	450.00
1	SPARE TYRE PANEL	BENT / BUCKLED	897.00	897.00
1	SPARE TYRE TOP BOARD	DENTED	452.00	285.45
1	SPARE TYRE PANEL LOWER COVER	DENTED	185.00	185.00
1	REAR FENDER TRIM BOARD LH	CRACKED	309.00	309.00

Report Ref No. CS/FCI19015479/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,511.72	-1,357.49
			6,046.88	5,429.96
1	SPARE TYRE PANEL INSULATION (SN)	NECESSARY	142.00	80.00
	LESS 20% DISCOUNT		-28.40	-
			113.60	80.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED	280.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN FASTENER (SN)	NECESSARY	50.00	30.00
1	REAR VIEW CAM BRACKET ADHESIVE TAPE (SN)	NECESSARY	15.00	15.00
			395.00	285.00
	LABOUR			
	TO DISMANTLE/TRANSFER TAILGATE FITTINGS/ANCILLARY ACCESSORIES.		150.00	60.00
	TO DISMANTLE/TRANSFER TAILGATE GLASS.		160.00	120.00
	TO DISMANTLE/REFIT TRUNK COMPARTMENT BOARDS & TRIMS ETC.		80.00	80.00
	TO SUPPLY REAR BODY PANEL SEALANT.		100.00	60.00
	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL.		150.00	90.00
	TO CONDUCT REAR ELECTRICAL CHECK,REPLACE REVERSE SENSORS,MODULE ETC.		120.00	70.00
	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR CHASSIS MEMBER,INNER PANEL,FRONT PANEL ETC.CNT,WELD END PANEL,SPARE TYRE PANEL AND PARTS REPLACEMENT.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK CATCH AND REAR BUMPER BRACKETS.		1,600.00	1,200.00
	TO RESPRAY AFFECTED AREAS.		1,100.00	800.00
	-		-	-
	-		-	-
	-		-	-
			3,460.00	2,480.00
	GRAND TOTAL		10,015.48	8,274.96



RECOMMENDED COST OF REPAIRS			8,274.96
-----------------------------	--	--	-----------------

Report Ref No. CS/FCI19015479/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.