

ASS. REC. BY:

REF: CS/MSG19015485/Uxf3n2

Special Instruction:

Survivor: Marcus

ASSIGNMENT (Office)

From (Person): Koh Ming Shao

of MSIG

Date/Time: 2.9.19 16.44p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SML 6538J

Insured:

SLP 3679X

at Workshop m/s Think One Autocare

Tel:

9793 8472

of NO 18 Dafa Ave 2

Policy No: 29114756 MFP

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29.8.2019

CA / REV / REP. / REV 24 HRS

"up"

3.9.2019

H.O.D. Endorsement:

Date/Time: 2.9.2019 4.51p.m

Person Contacted:

Michael

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SML 6538J - X
	SLP 3679 - X
4/9/19	Send preli revised by merimen

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MS14/
ASSIGNMENTFrom: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

17A36479

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SML 6538Y

Yr Regn:

5, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA1

Make:

Honda vezel

c.c

1496

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

11296

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU 11313955

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

29/8/19

D.O.I.

3/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s L.L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/9/19 1/5 @ 2950 contact with m. chief (Red 5411-35, 659)

RECEIVED 06 SEP 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

6/9- typist

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS, \$

) Photos

) Others

)

TOTAL

Report Format :

Merimen

Lump Sum / I.B.I. (\$

2950/2

150

11

161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Koh Ming Shao	Date: 04 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLP3679X	Accident Date	: 29/08/2019
TP Vehicle No	: SML6538J	Assignment Date	: 02/09/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 3.00
Date of Inspection	: 03/09/2019		
Inspection At	: THINK ONE AUTOCARE PTE LTD (HQ) NO. 18 DEFU AVENUE 2 SINGAPORE 539522		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,272.70
Revised Amount	:S\$	2,543.60
Check Items (Estimated)	:S\$	1,764.00
Total	:S\$	4,307.60
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		02 Sep 2019 16:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G																							
Main Claimant:	AAKASH TRANZ , Co. Reg. No.: 53021142D																							
Vehicle Reg. No.:	SML6538J	Date of Loss:	29/08/2019 10:00 - :59 [3 Months From LTA Reg Date (Man Yr)]																					
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020																					
Vehicle Reg. No. (Insured):	SLP3679X	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2, 539522 Ubi - Tel: 68443300																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Koh Ming Shao - 6594 2546]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/09/2019]																							
Driver/Custodian (Insured):	SOH BAK HIANG (58 / Male) , NRIC: S1492511B Email:																							
Adj Asg. Remarks:	on WP. OI:Grab. Liab: unclear. Agree on SJE. Assign: LKk Auto Consultants Pte Ltd. Contact: Michael @ 9793 8472.																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 142D

Vehicle Details

Vehicle No.: SML6538J

Vehicle to be Exported: No

Intended Deregistration Date: 03 Sep 2019

Vehicle Make: HONDA

Vehicle Model: VEZEL 1.5X CVT

Primary Colour: Silver

Manufacturing Year: 2018

Engine No.: L15B5563966

Chassis No.: RU11313955

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$22,570.00

Original Registration Date: 29 May 2019

First Registration Date: 29 May 2019

Transfer Count: 0

Actual ARF Paid: \$13,598.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 May 2029

PARF Rebate Amount: \$10,198.00

Intended COE Rebate Details

COE Expiry Date: 28 May 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$27,000.00

COE Rebate Amount: \$26,281.00

Total Rebate Amount: \$36,479.00

The information contained herein is correct as at 03 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIa Records Management Centre established by the General Insurance Association of Singapore (GIa) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2019 17:11
Date Of Accident	29/08/2019 10:25
Exact Location Of Accident	ALONG CHURCH STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML6538J
Insured/Policyholder	
Name Of Registered Owner	AAKASH TRANZ
Co Reg No	53021142D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97273824
Alternative Phone No	OFFICE-97273824

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 1.5X CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	510996097
Cover Note Number	

Driver

Name of Driver	RAJENDRAN SUBAIYAH THEVAR
NRIC No	S2678514F
Date Of Birth	14/03/1960
Occupation	OUTDOOR
Date Of Driving Pass	17/09/2007
Driving Experience	11 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97273824
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 445 YISHUN AVENUE 11
#03-50
Postcode 760445

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : NIL
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP3679X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

100' 0" 100' 0" 100' 0"

100' 0" 100' 0" 100' 0"

100' 0" 100' 0" 100' 0"



100' 0" 100' 0" 100' 0"



Police Station Of Origin:
Yishun North N.P.C.
31 Yishun Central SINGAPORE 718827
Tel No: 1800-8526695



T20180329268

2 of 2

Report No. T20180329268

CONTINUATION OF REPORT

Brief Details.

1. On 29 August 2018 between 10.25am to 10.35 am, I was driving private hire vehicle registration No: SML6538J along Church Street inside my vehicle was passenger (male about 30+ years old) seated at the left passenger seat. After I cleared the traffic light junction located at Church / Collyer Quay & Cecil Street I turned at the bend area located at Collyer Quay and suddenly the vehicle driver (male 40 + years old) of registration No: SLP3679X driving on the right lane entered my lane.
2. I applied jammed brake and the left side of this vehicle registration No: SLP3679X, slid & sweep onto the right side of my vehicle. The impact caused me to jerk forward and I sustained pain at the right neck area. My passenger was not injured. The driver of the vehicle registration No: SLP3679X was not injured and I am not. If his passenger seated inside his vehicle, is injured or not. The driver alighted and left me to drive to the side of the road to discuss the matter. However when I drove to the side of the road, the said driver had driven off.
3. No Police or ambulance was called in and no government was damage. will be visiting a doctor after lodging this report. My passenger is not injured and did not complain of any pain.

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

SML6538J HONDA VEZEL

DATE 29/8/2019

No	Qty	DESCRIPTION	AMOUNT S\$
1	1	FRONT BUMPER	1,150.00
2	1	FRONT FENDER RH o/s	752.00
3	1	FRONT FENDER GARNISH RH o/s	422.00
4	1	FRONT HEADLAMP RH o/s	2,205.00
5	1	FRONT DOOR HANDLE OUTER RH o/s	198.00
6	1	FRONT DOOR RH o/s	1,258.00
7	1	FRONT DOOR OUTER HANDLE RH o/s	198.00
8	1	FRONT WHEEL RIM o/s	420.00
			\$ 6,603.00
front bumper fog lamp garnish o/s 98.50 grazed.			LESS 10% 20%
			\$ 660.30
			\$ 5,942.70

No	Qty	DESCRIPTION	SPECIAL NETT	AMOUNT S\$
1	5	FRONT FENDER GARNISH CLIP	6.00	\$ 30.00

LABOUR & MISCELLANEOUS:

1	To remove damaged parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refix and align into position refix all necessary components/attachments	300	1,000.00
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	600	1,000.00
3	To conduct front headlamp alignment	20	30.00
4	To transfer door components with all necessary attachments	11X	150.00
5	To apply anti rust solution on affected areas	11X	120.00
			\$ 2,300.00

Think One Auto Consultants hence notify the resurvey of the following:

- To resurvey (with or without spray painting)
- To disassemble (part(s)) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No third party mediation is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015485/UVF3N2

Date: 09/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SML6538J	Insured Vehicle No :	SLP3679X
Date of Loss:	29/08/2019	Nature of Claim:	TP
		Claim No:	604426

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML6538J	Engine No:	L15B5563966
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11313955
Reg. Date:	29/05/2019 (Man. Year: 2018)	Odometer:	11296 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,061.35	2,780.96	3,280.39	54.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	920.00	1,380.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,361.35	3,700.96	4,660.39	55.74
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	8,361.35	2,950.00	5,411.35	64.72
+ GST 7.00/7.00% (S\$)	585.29	206.50	378.79	64.72
Nett Amount (S\$)	8,946.64	3,156.50	5,790.14	64.72

INSPECTION

Date of Assignment:	02/09/2019	
Date Inspected:	03/09/2019	Inspected At: Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2 Singapore 539522
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML6538J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	1,150.00 FL	*765.50 FL
2	1		*FRONT FENDER O/S	Repair	752.00 FL	*- FL
3	1		*FRONT FENDER GARNISH O/S	Grazed	422.00 FL	*288.50 FL
4	1		*FRONT HEADLAMP O/S	Cracked	2,205.00 FL	*1,866.20 FL
5	1		*FRONT DOOR HANDLE OUTER O/S (SCRATCHED)	Not Consistent With The Impact	198.00 FL	*- FL
6	1		*FRONT DOOR O/S	Repair	1,258.00 FL	*- FL
7	1		*FRONT DOOR OUTER HANDLE O/S	Repeated	198.00 FL	*- FL
8	1		*FRONT WHEEL RIM O/S	Defaced	420.00 FL	*420.00 FL
9	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Grazed	98.50 FL	*98.50 FL
10	5		*FRONT FENDER GARNISH CLIP	Necessary	30.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	6,731.50	3,468.70
- List Item Discount on L Items 10.00/20.00% (\$\$)	670.15	687.74
Total Parts (\$\$)	6,061.35	2,780.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIX AND ALIGN INTO POSITION REFIX ALL NECESSARY COMPONENTS/ATTACHMENTS	New	1,000.00	300.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	600.00
3	TO CONDUCT FRONT HEADLAMP ALIGNMENT	New	30.00	20.00
4	TO TRANSFER DOOR COMPONENTS WITH ALL NECESSARY ATTACHMENTS	New	150.00	0.00
5	TO APPLY ANTI RUST SOLUTION ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (S\$)			2,300.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >