

INS. CASE OWNER:

Norsiah

CC6/AIG19015499/ R1 da3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

PASAR

DOI:

28/9/2019

Date / Time: 2/9/19

Registered in Merimen: 2/9/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SGK 7678H

Claim No. : 8956196322SG

Name of Insured : PAN ZHUOXIONG

Policy No. : 2100469482

Insured Tel No. : HP: +65-91875821

Make / Model : CITROEN C4 CACTUS-1.2 PURETECH

Excess Sec II : S\$

D.O.A. : 31/8/2019

Place of Accident : CHOA CHU KANG RD (NEAR TECK WHYE LANE)

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT (YES / NO) ; TP GIA REPORT: (YES / NO)

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

GM 3328J

INSRS:
WSP: WOON MENG
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	GM 3328J - CC4/AXA17003955/T1fb3q2; DOA:22/2/17	Non-Reporting ltr (1st):	
	SGK 7678H - CC4/AIG18002639/T1db3; DOA:31/1/18	Non-Reporting ltr (2nd):	
	- CS/AIG17014213/Krbn2; DOA: 21/7/17	Non-Reporting ltr (Final):	
	- CS/CTI17014415/T1vbe2; DOA:21/7/17	Notification ltr (if non-pickup):	
	- CC4/AXA15006740/Rya3n2; DOA:16/4/15	Call OE:	
13/12/19	FILE AMB TO HANA TO LONE	After call ltr to OE:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OE:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice	☐
		LTA / GIA :	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	S\$ (days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: 9/12/19		Confirm with Woon Meng	
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. 27	Email ☒	Call ☐
Repair Cost: (w/hjt)	S\$ 2728.50	If NO or B 28, Ass. Lia :	
Loss of Rental (LOR):	S\$ - (days)	COPY SENT 16/12/19	
Loss of Use (LOU):	S\$ 400.00 (\$ 80 x 5 days)		
Loss of Income (LOI):	S\$ - (\$ x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]			
GIA/LTA Search	S\$ 2.00		
Medical:	S\$ -	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	S\$ - (e.g. Tow/ Independent)	2) Report Format: TP	
Legal Cost	S\$ -	3) Survey fee: \$320	
Total:	S\$ 3130.50	Global Sum S\$:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	S\$ 3130.50	Name 1:	Woon Meng Motor Pte Ltd
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

Date: _____ Person Contacted: _____ Vehicle: IN / OUT _____

349/21

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel: 63268523
 (Email Address : woonmeng@singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

To : AIG Asia Pacific Insurance Pte Ltd
 Motor Claims Dept

Dear Sirs :

RE : ESTIMATE COST FOR OPEL COMBO - GM3328J
ACCIDENT INVOLVING GM3328J & SGK7678H ON 31/08/2019

TP CLAIM

Date : 27 Sep 19

Fax : 64193727

ITEMS

DESCRIPTION

QTY

PRICE

- 1 Rear bumper *de*
- 2 Rear bumper bracket (plastic) @\$68ea *1. ne*
- 3 Rear bumper bracket (Metal) @\$68ea *1. ne*
- 4 Rear tailgate o/s *repair*
- 5 Combo 1.7 *ne*
- 6 CDTI *ne*
- 7 Rear tailgate lock o/s *X SVC*
- 8 Rear tailgate n/s *repair*
- 9 Rear end panel *repair*
- 10 Opel *ne*

Less 10%

1pc	\$	858.00
2pcs	\$	136.00
2pcs	\$	136.00
1pc	\$	99.00 X
1pc	\$	99.00
1pc	\$	99.00
1pc	\$	198.00 X
1pc	\$	1,095.00 X
1pc	\$	357.00 X
1pc	\$	65.00
	\$	3,142.00
	\$	(314.20)
	\$	2,827.80

- 11 70km. *ne*
- 12 Spax *ne*
- 13 Rear windscreen sealant. *X n*
- 14 Rear number plate *6*
- 15 Rear sensor. *o/s*

Sum Carried Forward

1pc	\$	10 15.00
1pc	\$	10 15.00
2pcs	\$	40.00 X
1pc	\$	35.00
1set	\$	220.00
	\$	3,152.80

1393
 102
 1253.70

275

LKK Auto Consultants henceforth the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature: _____
Date: _____

Sum Carried Forward

\$ 3,152.80

Labour Charge & Misc

To remove, repair, replace & install damaged parts.

) \$ 800.00 ⁵⁰⁰
)
~~450~~

To R & R sensor wiring.

\$ ~~80.00~~ 60

To R & R wiring.

\$ 60.00 Xnn

To R & R rear windscreen glass o/s.

\$ 80.00 Xnn

To R & R rear windscreen glass n/s.

\$ 80.00 Xnn

1160

To putty & spray painting.

P - 1253.70

\$ ~~800.00~~ 600

Total

S/N - 275.00

\$ 5,052.80

L - 1160.00

Supp. P - 508.50

All prices quoted are subjected to 7% GST.

T - 3197.20

20%

2557.76

L/S - 2,550

Rasul

Hp 90010068

4 days

L/S

4 days

27/05/19 @ 1500

Resurvey after repair

LKK Auto Consultants henceforth the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature: _____
Date: _____

email to Rasul on 27/9/19

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng@singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 27 Sep 19

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR OPEL COMBO - GM3328J (SUPPLEMENTARY) ACCIDENT INVOLVING GM3328J & SGK7678H ON 31/08/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper sponge @\$105ea	2pcs	\$ 210.00 <i>OK</i>
2	Rear bumper reinforcement.	1pc	\$ 355.00 <i>st</i>
			\$ 565.00
	Less 10%		\$ (56.50)
			<u>\$ 508.50</u>

Total

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 27 Sep 19

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR OPEL COMBO - GM3328J

ACCIDENT INVOLVING GM3328J & SGK7678H ON 31/08/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper <i>de</i>	1pc	\$ 858.00
2	Rear bumper bracket (plastic) @\$68ea ¹	2pcs	\$ 136.00
3	Rear bumper bracket (Metal) @\$68ea ¹	2pcs	\$ 136.00
4	Rear tailgate o/s <i>repair</i>	1pc	\$ 99.00
5	Combo 1.7 <i>per</i>	1pc	\$ 99.00
6	CDTI <i>per</i>	1pc	\$ 99.00
7	Rear tailgate lock o/s X	1pc	\$ 198.00
8	Rear tailgate n/s <i>repair</i>	1pc	\$ 1,095.00
9	Rear end panel <i>repair</i>	1pc	\$ 357.00
10	Opel <i>per</i>	1pc	\$ 65.00
			\$ 3,142.00
	Less 10%		\$ (314.20)
			\$ 2,827.80
11	70km. <i>per</i>	1pc	\$ 10 15.00
12	5pax <i>per</i>	1pc	\$ 10 15.00
13	Rear windscreen sealant, X	2pcs	\$ 40.00
14	Rear number plate <i>lt</i>	1pc	\$ 35.00
15	Rear sensor. <i>per</i>	1set	\$ 220.00
	Sum Carried Forward		\$ 3,152.80

Sum Carried Forward

\$ 3,152.80

Labour Charge & Misc

To remove, repair, replace & install damaged parts.

} \$ ~~800.00~~ ⁵⁰⁰ ~~400~~
}

To R & R sensor wiring.

\$ ~~80.00~~ 60

To R & R wiring.

\$ 60.00 X

To R & R rear windscreen glass o/s.

\$ 80.00 X

To R & R rear windscreen glass n/s.

\$ 80.00 X

To putty & spray painting.

\$ ~~800.00~~ 600

Total

\$ 5,052.80

All prices quoted are subjected to 7% GST.



Rasul

Hp 90010068

4 days

L/S

27/05/19 @ 1500

Recovery after repair

View Received Message

This mail is associated with :

***GM3328J (8956196322SG)
[SGK7678H]**

TP
SENKEE LOGISTICS PTE LTD
Aug 31 2019 2:20PM
[PAN ZHUOXIONG]
Woon Meng Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/11/2019 14:54 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3230.50) - GM3328J - Claim Handler: MdNoor, Norsiah

Approved:3230.50:* Please offer LOU between \$80 - \$100/day

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Sep 2019 Edit Reg		27 Sep 2019 00:00 Edit Adj Rpt	\$52,550.00 Edit Estimates	\$52,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	PAN ZHUOXIONG, ID: S8178738G								
Main Claimant:	SENKEE LOGISTICS PTE LTD, Co. Reg. No.: 197000800H								
Vehicle Reg. No.:	GM3328J	Date of Loss:	31/08/2019 14:00 - :59 [177 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8956196322SG	Policy/Cover Note No.:	2100469482 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGK7678H	Policy No. (Claimant):	P1559728						
	Excess:								
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (20/11/2019): Alert - Adj Mandate Approved (\$3230.50) - GM3328J - Claim Handler: MdNoor, Nors...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GM3328J (8956196322SG)
[SGK7678H]
TP
SENKEE LOGISTICS PTE LTD
Aug 31 2019 2:20PM
[PAN ZHUOXIONG]
Woon Meng Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

Thumbnail

Print

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

1

(Draft)

Third Party Express Settlement – Payment Breakdown

1

Edit

Assessment Reports

1 per page

Thumbnail

Print

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

1

15/11/19 08:47

Adjuster Immediate Advice

1

Load HTML

Photos/Images

3 per page

Thumbnail

Print

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

1

14/11/19 17:51

Chassis Number

1

Load JPG

2

14/11/19 17:51

General View

1

Load JPG

3

14/11/19 17:51

General View

1

Load JPG

4

14/11/19 17:51

General View

1

Load JPG

5

14/11/19 17:51

General View

1

Load JPG

6

14/11/19 17:51

General View

1

Load JPG

7

14/11/19 17:51

General View

1

Load JPG

8

14/11/19 17:51

General View

1

Load JPG

9

14/11/19 17:51

General View

1

Load JPG

10

14/11/19 17:51

General View

1

Load JPG

11

14/11/19 17:51

General View

1

Load JPG

12

14/11/19 17:51

General View

1

Load JPG

13

14/11/19 17:51

General View

1

Load JPG

14

14/11/19 17:51

General View

1

Load JPG

15

14/11/19 17:51

General View

1

Load JPG

16

14/11/19 17:51

General View

1

Load JPG

17

14/11/19 17:51

General View

1

Load JPG

18

14/11/19 17:51

General View

1

Load JPG

19

14/11/19 17:51

General View

1

Load JPG

20

14/11/19 17:51

General View

1

Load JPG

21

14/11/19 17:51

General View

1

Load JPG

22

14/11/19 17:51

General View

1

Load JPG

23

14/11/19 17:51

General View

1

Load JPG

24

14/11/19 17:51

General View

1

Load JPG

25

14/11/19 17:51

General View

1

Load JPG

26

14/11/19 17:51

General View

1

Load JPG

27

14/11/19 17:51

General View

1

Load JPG

28

14/11/19 17:51

General View

1

Load JPG

29

14/11/19 17:51

General View

1

Load JPG

30

14/11/19 17:51

General View

1

Load JPG

31

14/11/19 17:51

General View

1

Load JPG

32

14/11/19 17:51

General View

1

Load JPG

33

14/11/19 17:51

General View

1

Load JPG

34

14/11/19 17:51

General View

1

Load JPG

35

14/11/19 17:51

General View

1

Load JPG

36

14/11/19 17:51

General View

1

Load JPG

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	14/11/19 17:51	General View	1	Load JPG	☒
38	14/11/19 17:51	General View	1	Load JPG	☒
39	14/11/19 17:51	General View	1	Load JPG	☒
40	14/11/19 17:51	General View	1	Load JPG	☒
41	14/11/19 17:51	General View	1	Load JPG	☒
42	14/11/19 17:51	General View	1	Load JPG	☒
43	14/11/19 17:51	General View	1	Load JPG	☒
44	14/11/19 17:51	General View	1	Load JPG	☒
45	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
46	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
47	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
48	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
49	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
50	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
51	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
52	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
53	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
54	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
55	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
56	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
57	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
58	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
59	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
60	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
61	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
62	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
63	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
64	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
65	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
66	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
67	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
68	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
69	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
70	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
71	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
72	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
73	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
74	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
75	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
76	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
77	14/11/19 17:51	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/09/19 18:59	TP GIA REPORT	1	Load PDF	
2	02/10/19 10:27	TP ESTIMATE - MARKED	1	Load PDF	
3	14/11/19 17:52	TP_ESTIMATE-MARKED-FINAL	1	Load PDF	
4	15/11/19 08:37	GIA SEARCH FEE	1	Load PDF	
5	15/11/19 08:37	LOD	1	Load PDF	
6	31/12/19 10:11	WORKSHOP INVOICE	1	Load PDF	
7	31/12/19 10:11	AUTHORISATION TO ACT FORM	1	Load PDF	
8	31/12/19 10:11	Release Voucher	1	Load PDF	
9	31/12/19 10:11	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/09/19 12:00	OI GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGK7678H (Insd veh)	Model:	OPEL COMBO 1.7 D AZ (M)
	GM3328J (TP veh)		
Date of Accident:	31/08/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	5,950.59
Final Repair Cost	:	\$	2,728.50
Loss of Use	:	\$	400.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,130.50

5.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____100_____(%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Woon Meng Motor Pte Ltd	:	\$ 3,130.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

31 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19015499/R1DA3Q2

Date: 31/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100469482
 Claimant Vehicle No : GM3328J Insured Vehicle No : SGK7678H
 Date of Loss: 31/08/2019 Nature of Claim: TP Claim No: 8956196322SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GM3328J
 Make & Model: OPEL COMBO, 1.7 D AZ (M) Engine No: Z17DTH01092799
 Reg. Date: 29/11/2004 (Man. Year: 2004) Chassis No: W0L0XCF2553004485
 Colour: White Odometer: 0 km
 Engine Capacity: 1686 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm
 Front Right Side: Roadstone 6 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,661.30	2,037.20	1,624.10	44.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,160.00	740.00	38.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,561.30	3,197.20	2,364.10	42.51
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	5,561.30	2,550.00	3,011.30	54.15
+ GST 7.00/7.00% (S\$)	389.29	178.50	210.79	54.15
Nett Amount (S\$)	5,950.59	2,728.50	3,222.09	54.15
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,130.50		

INSPECTION

Date of Assignment: 27/09/2019

Date Inspected: 27/09/2019 Inspected At:

Woon Meng Motor Pte Ltd (Bukit Batok)
 50 Bukit Batok Street 23., #01-06
 Midview Building
 Singapore 659578

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	858.00 FL	*858.00 FL
2	2		*REAR BUMPER BRACKET (PLASTIC)	Necessary	136.00 FL	*136.00 FL
3	2		*REAR BUMPER BRACKET (METAL)	Necessary	136.00 FL	*136.00 FL
4	1		*REAR TAILGATE O/S	Repair	99.00 FL	*- FL
5	1		*COMBO 1.7	Necessary	99.00 FL	*99.00 FL
6	1		*CDTI	Necessary	99.00 FL	*99.00 FL
7	1		*REAR TAILGATE LOCK O/S	Serviceable	198.00 FL	*- FL
8	1		*REAR TAILGATE N/S	Repair	1,095.00 FL	*- FL
9	1		*REAR END PANEL	Repair	357.00 FL	*- FL
10	1		*OPEL	Necessary	65.00 FL	*65.00 FL
11	1		*70KM	Necessary	15.00 FS	*10.00 FS
12	1		*5PAX	Necessary	15.00 FS	*10.00 FS
13	2		*REAR WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS
14	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
15	1		*SET REAR SENSOR	Distorted	220.00 FS	*220.00 FS
16	2		*REAR BUMPER SPONGE	Cracked	210.00 FL	*210.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	355.00 FL	*355.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	4,032.00	2,233.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	370.70	195.80
Total Parts (\$\$)	3,661.30	2,037.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR ,REPLACE & INSTALL DAMAGED PARTS	New	800.00	500.00
2	TO R&R SENSOR WIRING	New	80.00	60.00
3	TO R&R WIRING	New	60.00	0.00
4	TO R&R REAR WINDSCREEN GLASS O/S	New	80.00	0.00
5	TO R&R REAR WINDSCREEN GLASS N/S	New	80.00	0.00
6	TO PUTTY & SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (S\$)			1,900.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >