

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Adress : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

To : AIG Asia Pacific Insurance Pte Ltd
 Motor Claims Dept

Dear Sirs :

TP CLAIM

Date : 27 Sep 19

Fax : 64193727

RE : ESTIMATE COST FOR OPEL COMBO - GM3328J
ACCIDENT INVOLVING GM3328J & SGK7678H ON 31/08/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper <i>de</i>	1pc	\$ 858.00
2	Rear bumper bracket (plastic) @\$68ea ¹	2pcs	\$ 136.00
3	Rear bumper bracket (Metal) @\$68ea ¹	2pcs	\$ 136.00
4	Rear tailgate o/s <i>repair</i>	1pc	\$ 99.00
5	Combo 1.7 <i>na</i>	1pc	\$ 99.00
6	CDTI <i>na</i>	1pc	\$ 99.00
7	Rear tailgate lock o/s X	1pc	\$ 198.00
8	Rear tailgate n/s <i>repair</i>	1pc	\$ 1,095.00
9	Rear end panel <i>repair</i>	1pc	\$ 357.00
10	Opel <i>na</i>	1pc	\$ 65.00
			\$ 3,142.00
	Less 10%		\$ (314.20)
			\$ 2,827.80
11	70km. <i>na</i>	1pc	\$ 10 15.00
12	5pax <i>na</i>	1pc	\$ 10 15.00
13	Rear windscreen sealant. X	2pcs	\$ 40.00
14	Rear number plate <i>na</i>	1pc	\$ 35.00
15	Rear sensor. <i>na</i>	1set	\$ 220.00
	Sum Carried Forward		\$ 3,152.80

Sum Carried Forward

\$ 3,152.80

Labour Charge & Misc

To remove, repair, replace & install damaged parts.

} \$ 800.00 ⁵⁰⁰~~450~~
}

To R & R sensor wiring.

\$ ~~80.00~~ 60

To R & R wiring.

\$ 60.00 X

To R & R rear windscreen glass o/s.

\$ 80.00 X

To R & R rear windscreen glass n/s.

\$ 80.00 X

To putty & spray painting.

\$ ~~800.00~~ 600

Total

\$ 5,052.80

All prices quoted are subjected to 7% GST.

LKK Approved hence notify the Repairer the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
4 days
L/S
27/09/19 @ 1500
Resurvey after repair