

Brunner

Steve

REF: NITUC NS/INC M015524/ESF3

ASSIGNMENT

From:

Date:

2.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 4555 D

at Workshop m/s SMRT

of 60 woodland Industrial Park

Insured:

Policy No.

Claims No. MT/1062211-001


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHC 4555 D

Yr Regn:

16/7/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c 1798

Colour

M/M

A/C: Insured / Std / NI / NA

Sp. Reading

514/22

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTOKN36455747165

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Falken

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

30/8/19

D.O.I.

2/9/19

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHC 4555 D - CC3/ CAI 15002382/ K1 W9 312

DCA-04/01/2015

08/19/2134

SHC 6105 G - CC3/ TI 17019323/ K16392

DCA-04/01/2017

SHC 6105 G

9/9/19

Finalize \$299, 1 days (Ph Sun)

C \$399.32 Rd - 67%

RECEIVED 13 SEP 2019

9/9/2019

Date/Time, File Pass to?

13/09/19

1)

Typ. 24

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

1

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$) 200/- L/S

TP Claims against NTUC Income: Follow-Through Survey

Date: 12/09/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1062211-001	SMRT TAXIS PTE LTD	SHC 4555D	SHC 6105G	30/08/2019	14:15	\$ 599.32	\$ 200.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 31/08/2019 09:51
Date Of Accident 30/08/2019 14:15
Exact Location Of Accident VICTORIA STREET TOWARDS BRAS BASAH ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC4555D
Insured/Policyholder
Name Of Registered Owner SMRT TAXIS PTE LTD
Co Reg No 198905369K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-800000000

Vehicle Particulars

Manufacturer TOYOTA
Model PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident HIRE AND REWARD

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number D-19093197MFSH
Cover Note Number

Driver

Name of Driver CHUA SAY CHEONG
NRIC No S6836582A
Date Of Birth 24/09/1968
Occupation INDOOR
Date Of Driving Pass 08/04/1986
Driving Experience 33 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-80000000
Fax Number
Contact Number
Email Address NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name SEMBAWANG NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-5549999 - FAX NO: 68522499
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20190831/2048

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC6105G
 Vehicle Make/Model/Colour
 Details Of Properties SILVERCAB
 Vehicle Category TAXI
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

A = SHC 4555D (SMET TAXI)

B = SHC 6105 (SILVER COLOR TAXI)

12885
VICTORIA

Happened
on 30/08/19
@ 1415 hrs

BRAS BASAH ROAD

CHUA SİY $\Omega(50N)h$

31/08/19 @ 0859 hrs



DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 369K

Vehicle Details

Vehicle No.: SHC4555D

Vehicle to be Exported: No

Intended Deregistration Date: 02 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon

Manufacturing Year: 2014

Engine No.: 2ZR6099033

Chassis No.: JTDKN36U505747165

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$32,920.00

Original Registration Date: 16 Jul 2014

First Registration Date: 16 Jul 2014

Transfer Count: 0

Actual ARF Paid: \$8,088.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Jul 2022

PARF Rebate Amount: \$5,661.00

Intended COE Rebate Details

COE Expiry Date: 15 Jul 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$53,269.00

COE Rebate Amount: \$19,098.00

Total Rebate Amount: \$24,759.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Sep 2019

OK



Case Details

Case Reference Number : TAXI08/19/2134
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4555D

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8330-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 30/08/2019 06:15 AM
 Vehicle Age(In Months) : 61

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main	VE	6505466	MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	X / M1
Standard	Main	BODY RH	6505598	COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	1	80.55	Replace	/ M13
Total Spare Part Cost									139.32	Surveyor Total				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
Final Spare Part Cost									111.46	Final Sur Total				
										80.55				
										20				
										64.44				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	RESPRAY MIRROR COVER RH	180.00	80	
Total:			180.00	80.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	80	/ M1
2	Main	TO REPLACE SUNDRY PARTS	100.00	10	/ M1
3	Main	TO WASH AND VACUUM	60.00	0	
Total:			280.00	90.00	

632.79*

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	111.46	64.44
Total Labour Cost	0.00	0.00
Total Spray Painting	180.00	80.00
Other	280.00	90.00
Overall Total	571.46	234.44
Lump Sum Repair Option	☒	☒
Lump Sum Total	550.00	250.00
Surveyor Approved Amount		250.00
No of Repair Days*	2	1
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		
Survey Date	02/09/2019	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHC4555D
Case Reference Number	TAX/08/19/2134
Registration Date	16/7/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHUA SAY CHEONG
Type of Accident	Side Swipe
Accident Date and Time	30/8/2019 2:15 PM
Accident Reported Date and Time	31/8/2019 9:29 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103142
Special Instruction to ARC, if any	TP /RIGHT WING MIRROR
Prepared Date and Time	1/9/2019 7:30 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Right Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$180.00	\$80.00
Total Spare Part Cost	\$139.32	\$80.55
Total Other Cost	\$280.00	\$39.45
TOTAL COST	\$599.32	\$200.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	02/09/2019 3:21 PM	02/09/2019 12:11 PM
Signature		
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0053	Invoice Number	
Quotation Date	04.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
Total Labour		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
RESpray MIRROR COVER RH	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$180.00	\$80.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$80.00
TO REPLACE SUNDRY PARTS	\$100.00	\$10.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$50.55)
Total Other Costs	\$280.00	\$39.45

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
	VE	81730-52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given
	BODY RH	879157-4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	25.00	\$80.55	Replace	Replace
Total					\$172.70		\$80.55		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

80.55
+ 170.00

250.55

200

200.44

L/S \$200/-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19015524/Esf3s2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 17-09-2019	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 6105G	Veh. Inspected	SHC 4555D	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1062211-001	Excess (\$)	0.00	
Assign From		Assign Date	02/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U505747165	Colour	MAROON	
Odometer	514122	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	FALKEN	5 mm	
L/H Front Tyre	195/50 R15	FALKEN	5 mm	
R/H Rear Tyre	195/50 R15	FALKEN	5 mm	
L/H Rear Tyre	195/50 R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/08/2019	Inspection Date	02/09/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4555D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, OUTER (DISC 25%)	MISSING	107.40	80.55
1	MIRROR LAMP RH	NOT NECESSARY	65.30	-
			172.70	80.55
LABOUR				
	SPRAY PAINT.		180.00	80.00
	TO REMOVE AND REFIX WING MIRROR.		120.00	80.00
	TO REPLACE SUNDRY PARTS.		100.00	10.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			460.00	170.00
GRAND TOTAL			632.70	250.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				200.00

Report Ref No. NS/INC19015524/Esf3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.