

REG BY: SteveREF: NTUC NS/INC 19015526/ESF392

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. MT/1060932-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 5775J

Yr Regn:

14/12/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Proace

c.c.

1798

Colour:

Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

190225

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J70 KB3F4903576733

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

2/9/19

D.O.I.

3/9/19

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR7 / N/S FR7

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 5775J - NA [09012957] / SD.O.A - 29/02/200809/19/2008SVV 6551C - XSVV 6551C16/9/19 Finalize Confir \$1144.10, 3 repair days(\$ 7,630.08 Red - 87%)17/9/2019

RECEIVED 18 SEP 2019

Date/Time, File Pass to?

18/09/19

: Prel. Report



: Final Report

1) Type of

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Form:

Lump Sum / P/P:

1,144.10 P/P

TP Claims against NTUC Income: Follow-Through Survey

Date : 17/09/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1060932-002	SMRT TAXIS PTE LTD	SHB 5775J	SIV 6551C	02/09/2019	10:55	\$ 8,774.18	\$ 1,144.10

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2019 09:17
Date Of Accident	02/09/2019 10:55
Exact Location Of Accident	OUTRAM ROAD TOWARDS CBD BEFORE CTE ENTRANCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5775J
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	PANG KIN HUNG
NRIC No	S7172622C
Date Of Birth	04/12/1971
Occupation	OUTDOOR
Date Of Driving Pass	20/03/1991
Driving Experience	28 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WEI HEN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING IN THE EXTREME LEFT LANE ALONG OUTRAM ROAD TOWARDS CBD BEFORE CTE ENTRANCE WITH ONE PASSENGER (MALE CHINESE) ON BOARD. SUDDENLY A VEHICLE SJV6551C WHICH WAS TRAVELLING ON MY RIGHT CUT TOWARDS MY LANE ABRUPLY AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI. AFTER WHICH THE IMPACT PUSHED MY TAXI TOWARDS THE KERB AND THE LEFT PORTION OF MY TAXI HIT ONTO THE KERB.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV6551C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	FLORA TAN HAR LAN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

B - STV6551C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.



Driver's Signature _____
(If driver is not the policyholder)
Date & Time: 2/2/14

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 369K

Vehicle Details

Vehicle No.: SHB5775J

Vehicle to be Exported: No

Intended Deregistration Date: 03 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: PRIUS HYBRID 1.8 CVT

Primary Colour: Maroon

Manufacturing Year: 2017

Engine No.: 2ZR8261157

Chassis No.: JTDKB3FU903576733

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$29,007.00

Original Registration Date: 14 Dec 2017

First Registration Date: 14 Dec 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Dec 2025

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 13 Dec 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$34,159.00

COE Rebate Amount: \$26,801.00

Total Rebate Amount: \$30,551.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Sep 2019

OK

Case Details

Case Reference Number :

TAX/09/19/2008

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5775J

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-8350-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 02/09/2019 02:56 AM

Vehicle Age(In Months) : 21

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			END SET, TIE ROD, LH	1	155.90	155.90	25.00	116.93	Replace	0	0	Not Give	X NN
One Time Key In	Main			JOINT ASSY, LWR BALL, RH & LH	1	200.10	200.10	25.00	150.07	Replace	0	0	Not Give	X NN
One Time Key In	Main			LOWER ARM SUB-ASSY, FRONT LH	1	631.60	631.60	25.00	473.70	Replace	0	0	Not Give	X NN
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	1	554.20	554.20	25.00	415.65	Replace	0	0	Check	X NN
One Time Key In	Main			SHAFT ASSY, FRONT DRIVE, LH	1	1,175.10	1,175.10	25.00	881.32	Replace	0	0	Not Give	X NN
One Time Key In	Main			LINK ASSY, FRONT STABILIZER, RH & LH	1	196.70	196.70	25.00	147.52	Replace	0	0	Not Give	X NN
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair	Front LH XR
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	front LH / TN
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0	Repair	X R
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace	/ BR

Total Spare Part Cost 5,962.18

Lump Sum Discount (%) 0.00

Final Spare Part Cost 5,962.18

Surveyor Total 923.92

Lump Sum Dis (%) 0

Final Sur Total 923.92

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace	X 99 R
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	/ noc
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair	Front RH X R
Total Spare Part Cost									5,962.18	Surveyor Total 923.92				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									5,962.18	Final Sur Total 923.92				

274.10

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	676.00	250	
Total:			676.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY RIM	360.00	100	Spray 2 rim
3	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
Total:			1,116.00	500.00	


Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
2	Main	TO REMOVE AND REFIX UNDERCARRIAGE	200.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	40	for 2 rim
Total:			1,020.00	170.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO REMOVE AND REFIT TYRE	120.00	20	✓ 11
6	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓ 11
7	Main	TO REPLACE SUNDRY PARTS	100.00	10	✓ 11
8	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,020.00	170.00	

10719.34

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,962.18	923.92
Total Labour Cost	676.00	250.00
Total Spray Painting	1,116.00	500.00
Other	1,020.00	170.00
Overall Total	8,774.18	1,843.92
Lump Sum Repair Option		
Lump Sum Total	0.00	1,843.92
Surveyor Approved Amount		1,843.92
No of Repair Days*	5	3
Remarks	*	P/P repair, finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		
Survey Date	03/09/2019	

Save Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

Section A - Accident Details

Registration Number	SHB5775J
Case Reference Number	TAX/09/19/2008
Registration Date	14/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	PANG KIN HUNG
Type of Accident	Side Swipe
Accident Date and Time	2/9/2019 10:56 AM
Accident Reported Date and Time	2/9/2019 4:18 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24103176
Special Instruction to ARC, if any	TP/ LEFT PORTION / RIGHT PORTION
Prepared Date and Time	3/9/2019 7:06 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$250.00
Total Spray Cost	\$1,116.00	\$500.00
Total Spare Part Cost	\$5,962.18	\$224.10
Total Other Cost	\$1,020.00	\$170.00
TOTAL COST	\$8,774.18	\$1,144.10 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	03/09/2019 7:18 AM	03/09/2019 2:23 PM
Signature		
Remarks	P/P repair, finalize sent to stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0088	Invoice Number	
Quotation Date	08.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$676.00	\$250.00
Total Labour	\$676.00	\$250.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY RIM	\$360.00	\$100.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,116.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$40.00
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$10.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,020.00	\$170.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		45047491 95	END SET, TIE ROD, LH	0.00	\$155.90	0.00	\$0.00	Replace	Not Given X
		43330191 15	JOINT ASSY, LWR BALL, RH & LH	0.00	\$200.10	0.00	\$0.00	Replace	Not Given X
		48069470 60	LOWER ARM SUB-ASSY, FRONT LH	0.00	\$831.60	0.00	\$0.00	Replace	Not Given X
		43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Check X
		43420470 40	SHAFT ASSY, FRONT DRIVE LH	0.00	\$1,175.10	0.00	\$0.00	Replace	Not Given X
		48820470 40	LINK ASSY, FRONT STABILIZER, RH & LH	0.00	\$196.70	0.00	\$0.00	Replace	Not Given X
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair K
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace ✓
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair R
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace ✓
		53801470 80	FENDER SUB-ASSY, FR RH	1.00	\$933.10	25.00	\$0.00	Replace	Repair R

		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair
Total					\$7,907.34		\$224.10		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r}
 224.10 \\
 + 250.00 \\
 + 670.00 \\
 \hline
 1144.10
 \end{array}$$



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19015526/Esf3s2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 23-09-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 6551C	Veh. Inspected	SHB 5775J	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1060932-002	Excess (\$)	0.00	
Assign From		Assign Date	03/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU903576733	Colour	MAROON	
Odometer	190225	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/50 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/50 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/50 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/09/2019	Inspection Date	03/09/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5775J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUPPORT, FR BUMPER RH (DISC 25%)	BROKEN	76.90	57.68
1	EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	TYRE (SN)	TORN	126.74	126.74
1	END SET, TIE ROD, LH	NOT NECESSARY	155.90	-
1	JOINT ASSY, LWR BALL, RH & LH	NOT NECESSARY	200.10	-
1	LOWER ARM SUB-ASSY, FRONT LH	NOT NECESSARY	631.60	-
1	HUB & BEARING ASSY, RH & LH	NOT NECESSARY	554.20	-
1	SHAFT ASSY, FRONT DRIVE, LH	NOT NECESSARY	1,175.10	-
1	LINK ASSY FRONT STABILIZER, RH & LH	NOT NECESSARY	196.70	-
1	LINER, FR FENDER, RH	NOT NECESSARY	198.40	-
1	WHEEL, DISC FRONT	TO REPAIR SEE LABOUR	1,555.10	-
1	COVER, FR BUMPER	TO REPAIR SEE LABOUR	495.50	-
1	FENDER SUB-ASSY, FR, RH	TO REPAIR SEE LABOUR	933.10	-
1	WHEEL, DISC FRONT	TO REPAIR SEE LABOUR	1,555.10	-
			7,907.34	224.10
LABOUR				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF WHEEL, DISC FRONT; COVER, FR BUMPER; FENDER SUB-ASSY, FR, RH AND WHEEL, DISC FRONT. SPRAY PAINT.			676.00	250.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			1,116.00	500.00
TO REMOVE AND REFIX UNDERCARRIAGE.			100.00	20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING.			200.00	-
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)			120.00	60.00
TO REMOVE AND REFIT TYRE.			240.00	40.00
TO CHECK WIRING AND SYSTEM FUNCTION.			120.00	20.00
TO REPLACE SUNDRY PARTS.			80.00	20.00
			100.00	10.00

Report Ref No. NS/INC19015526/Esf3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,812.00	920.00
GRAND TOTAL			10,719.34	1,144.10
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,144.10

Report Ref No. NS/INC19015526/Esf3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.