

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10606

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1041/2019/NS
Date : 2-Sep-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Scott Graham
Address : 115A Dunbar Walk
Singapore 459424
Telephone : HP +65 91707640
Type of Claim : Own Damage Claims
Policy No. : 2100387642-04
Vehicle No : **SKP 6895 E**
Model Code : Audi Q3 1.4 TFSI S TRO
Model / Year : 30/9/2014
Engine No : CHP 172623
Chassis No : WAUZZZ8U2ER118740
Mileage : 79443
Date In : 29-Aug-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Aug-19
Place of Accident : Along Changi Road

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKP 6895 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and transfer both rhs front and rear door's multi-lock system and power window devices.	S/N \$ 560.00 ✓	
3	To dismantle and renew front bumper assy, rhs front and rear doors. Re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00 1500 1000.	
4	To respray front bumper, rhs front fender, rhs front and rear doors, door handle, and rhs wing mirror cover.	\$ 4,300.00 2350 1650	
5	To renew rhs front rim and tyre. Carry out wheel alignment.	S/N \$ 280.00 ✓	
6	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 8,892.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKP 6895 E**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,749.00	Sx
2	FRONT BUMPER LOWER SPOILER	TBC	X nh
3	WHEEL ARCH TRIMS	TBC	cut — 373.60
4	FRONT DOOR - RH	\$ 2,412.00	bt — 1929.60
5	OUTER DOOR SEAL - RH	\$ 151.00	nei — 121.20
6	PROTECTIVE FILM	\$ 24.00	X photo
7	FRONT DOOR ATTACHMENT PARTS	\$ 97.00	X nh
8	FRONT DOOR CATCH	\$ 109.00	X nh
9	BONDING AGENT	\$ 45.00	nei — 35.92
10	FRONT DOOR MOUNTING BAR	\$ 110.00	X
11	EXTERIOR DOOR HANDLE	\$ 137.00	X
12	DOOR HANDLE CAP - PASSENGER DOOR	\$ 27.00	X
13	OUTER WINDOW APERTURE SEAL - RH	\$ 152.00	X
14	WINDOW REGULATOR WITHOUT MOTOR - RH	\$ 250.00	X
15	REAR DOOR - RH	\$ 2,412.00	bt — 1929.60
16	OUTER DOOR SEAL - RH	\$ 157.00	nei — 125.60
17	DOOR SEAL BRACKET - RH REAR	\$ 17.00	X photo
18	REAR DOOR CATCH	\$ 109.00	X
19	DOOR SEAL BRACKET - RH REAR	\$ 17.00	X
20	WINDOW APERTURE SEAL - RH OUTER	\$ 185.00	X
21	DOOR COVER	TBC	X
22	ALUMINIUM RIM	TBC	X
23	GOOD YEAR EAGLE F1	TBC	photo — 80% 450
24	SUNDRIES	\$ 600.00	76.32 nei —
TOTAL SPARE PARTS		\$ 8,760.00	
TOTAL LABOUR CHARGES		\$ 8,892.00	
GRAND TOTAL		\$ 17,652.00	21,892.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpik 9729544
Not Authorise.
Ex: to be advise
2/9/19 @ 445
Resumy before paint
29 days
sure the auto car.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1041/2019/NS
Date 3-Sep-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SKP 6895 E
Model No Audi Q3 1.4 TFSI S TRO

Quantity	Description	Unit Price	Amount
Parts			
1	Headlight RHS	\$ 1,885.00 <i>X^{un}</i>	
2	Water deflector RHS	\$ 61.00 <i>X^{un}</i>	
3	Data plate for tyre pressure	\$ 38.00	\$ 30.08 <i>nl</i>
4	Door cover RHS front	\$ 233.00 <i>X^{un}</i>	
		\$ 2,217.00	\$ 30.08
Labours			
1	To respray bonnet.	\$ 1,200.00	\$ 550.00 <i>/</i>
Labour total		\$ 1,200.00	\$ 550.00
Parts total		\$ 2,217.00	\$ 30.08
GRAND TOTAL		\$ 3,417.00	\$ 580.08

For Premium Automobiles Pte Ltd

Authorised Signature