

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE



2 SEP 2019

Estimate No. : b1 52566
Date Estimated : 31/08/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chuen Lian Shiong
75 Almond Crescent

Singapore 677829

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFQ9938A	V458564	10/09/2015	218i AT	0

DESCRIPTION

Replacing rear bumper panel and attachments, bootlid,
rework tail panel

Spray rear bumper, bootlid and tail panel ?

To remove and install boot compartment carpet and garnish
to facilitate repairs.

To replace rear windscreen glass.

To conduct water leak tests.

To supply and install rear windscreen solar film.

To check electrical wiring systems and lightings at the
rear section for proper function.

To carry out body cavity preservation.
(Per panel).

Sundries

Total Labour 1: 8,115.00

DESCRIPTION

TRUNK LID
REAR BUMPER PANEL PRIMED (PDC)
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
LETTERING 218 I
GROMMET
PLAQUE 74MM
BUMP STOP
REAR WINDOW ESG

QTY	PRIC
1	1,204.35
1	1,045.45
1	61.35
1	61.35
1	458.10
1	64.10
2	0.80
2	71.25
10	3.70
1	654.35

VALUE
1,204.35
1,045.45
61.35
61.35
458.10
64.10
1.60
142.50
37.00
654.35

1700w New wind panel
2550 Repair boot panel

1660 2,819.00

230 271.00

487 574.00

63 75.00

451 531.00

150 177.00

100 118.00

? 150.00

bt
ale
?
?
?
ale
ale
?
?

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 52566**
Date Estimated : **31/08/2019**
Prepared By : **Joseph Yaguel**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFQ9938A	V458564	10/09/2015	218i AT	0

DESCRIPTION	QTY	PRIC	VALUE
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85

Total Parts : **4,067.45**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 18/9/1901145 Claim No. _____

Date&Time 18/9/1901145 Excess S\$ _____

Surveyor's Name Tan Kah Sign [Signature]

Surveyor's Tel 9747779 Authorised Yes / No _____

Authorised Date 18/9/19 Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tan.kah@lkk.com.sg

No. of Working Days Recommend 6 days



Labour 1	:	8,115.00
Parts	:	4,067.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	852.77
Grand Total	:	13,035.22

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **