

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

2 SEP 2019

Estimate No. : b1 52566
Date Estimated : 31/08/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Chuen Lian Shiong
75 Almond Crescent

Singapore 677829

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFQ9938A	V458564	10/09/2015	218i AT	0

DESCRIPTION

Replacing rear bumper panel and attachments, bootlid,
rework tail panel

Spray rear bumper, bootlid and tail panel

To remove and install boot compartment carpet and garnish
to facilitate repairs.

To replace rear windscreen glass.

To conduct water leak tests.

To supply and install rear windscreen solar film.

To check electrical wiring systems and lightings at the
rear section for proper function.

To carry out body cavity preservation.
(Per panel).

Sundries

VALUE

3,400.00

2,819.00

271.00

574.00

75.00

531.00

177.00

118.00

150.00

Total Labour 1: 8,115.00

DESCRIPTION

QTY

PRIC

VALUE

TRUNK LID

1

1,204.35

1,204.35

REAR BUMPER PANEL PRIMED (PDC)

1

1,045.45

1,045.45

RR BUMPER LH SIDE GUIDE

1

61.35

61.35

RR BUMPER RH SIDE GUIDE

1

61.35

61.35

REAR BUMPER CARRIER

1

458.10

458.10

LETTERING 218 I

1

64.10

64.10

GROMMET

2

0.80

1.60

PLAQUE 74MM

12

71.25

142.50

BUMP STOP

10

3.70

37.00

REAR WINDOW ESG

1

654.35

654.35

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 52566
Date Estimated : 31/08/2019
Prepared By : Joseph Yaguel

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFQ9938A	V458564	10/09/2015	218i AT	0

DESCRIPTION

DECOUPING RING PDC TORQUE CONVERTER
(DG) CLEANER R1 (100ML)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) GLASS PRIMER 30ML (VP206)

QTY	PRIC	VALUE
4	5.05	20.20
1	26.15	26.15
2	131.55	263.10
1	27.85	27.85

Total Parts : 4,067.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 18/9/1901145 Claim No. _____

Date & Time 18/9/19 11:45 Excess S\$ _____

Surveyor's Name Tan Kah Sign [Signature]

Surveyor's Tel 97497429 Authorised Yes / No _____

Authorised Date 18/9/19 Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tan.kah@lkk.com.sg

Approved Working Days Recommend 6 days



Labour 1	:	8,115.00
Parts	:	4,067.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	852.77
Grand Total	:	13,035.22

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52566**
Date Estimated : **31/08/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Chuen Lian Shiong
75 Almond Crescent

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 677829

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFQ9938A	WBA2A32040V4585	10/09/2015	218i AT	0
DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT	
To replace rear boot lid, rear bumper and attachments etc including to make good tail end panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	2,550.00 ✓	0	2,550.00	
To respray rear bumper, rear boot lid and tail end panel.	2,292.00	0	2,292.00	
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00 ✓	0	230.00	
To remove and install rear windscreen glass in order to carry out repair job	574.00 ✓	0	574.00	
To conduct water leak tests.	75.00 ✓	0	75.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00 ✓	0	150.00	
To carry out body cavity preservation.	100.00 ✓	0	100.00	
Sundries	150.00 ✓	0	150.00	
# To replace SMART opener control unit and sensor wire for SMART bottom opener including to check for function.	451.00 rec ✓	0	451.00	

Handwritten: 6532

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#	2.70	3	0	8.10
# BLIND RIVET NUT M6	1,204.35	1	0	1,204.35 ?
TRUNK LID	1,045.45	1	0	1,045.45 ?
REAR BUMPER PANEL PRIMED (PDC)	1.00	2	0	2.00
# EXPANDING NUT	45.30	1	0	45.30
# SUPPORT	61.35	1	0	61.35
RR BUMPER LH INNER SIDE GUIDE	61.35	1	0	61.35
RR BUMPER RH INNER SIDE GUIDE	64.10	1	0	64.10 ?
LETTERING 218 I	0.80	2	0	1.60 ?
GROMMET	71.25	1	0	71.25 ?
PLAQUE 74MM				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

# REAR BUMPER HEAT INSULATOR	60.60	1	0	60.60
# PLUG BLACK D=5MM	0.95	4	0	3.80
# PLUG BLACK D=5MM	0.95	3	0	2.85
# SENSOR WIRE FOR SMART OPENER BOTTOM	41.50	1	0	41.50
# CONTROL UNIT SMART OPENER	494.60	1	0	494.60
DECOUPING RING PDC TORQUE CONVERTER	5.05	4	0	20.20 ?
# ULTRASONIC SENSOR GLACIERSILBER(WA8	368.80	2	0	737.60
(DG) CLEANER R1 (100ML)	26.15	1	0	26.15 ?
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2	0	263.10 ?
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1	0	27.85 ?
#				
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	6,572.00
Total Parts :	4,243.10
Total Labour & Parts :	10,815.10 ✓
GST @7%:	757.06
Grand Total :	11,572.16

FAX TO	IND. PARTY	DATE	
FAX NO	Tanfikh	13/10/19	6
FAX TO	2K1K		
FAX NO			
TO			
NO			
CONFIRMED			
DATE			
PLT			

LOSS OF USE = \$60 X 8 DAYS.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52566**
Date Estimated : **31/08/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Chuen Lian Shiong
75 Almond Crescent

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 677829

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFQ9938A	WBA2A32040V4585	10/09/2015	218i AT	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
# To replace SMART opener control unit and sensor wire for SMART bottom opener including to check for function.	451.00	0	451.00 <i>rec</i>

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#	2.70	3	0	8.10 <i>rec</i>
# BLIND RIVET NUT M6	1.00	2	0	2.00 <i>rec</i>
# EXPANDING NUT	45.30	1	0	45.30 <i>rec</i>
# SUPPORT	60.60	1	0	60.60 <i>bb</i>
# REAR BUMPER HEAT INSULATOR	0.95	4	0	3.80 <i>rec</i>
# PLUG BLACK D=5MM	0.95	3	0	2.85 <i>rec</i>
# PLUG BLACK D=5MM	41.50	1	0	41.50 <i>ad's</i>
# SENSOR WIRE FOR SMART OPENER BOTTOM	494.60	1	0	494.60 <i>over</i>
# CONTROL UNIT SMART OPENER	368.80	2	0	737.60 <i>rw</i>
# ULTRASONIC SENSOR GLACIERSILBER(WA8				

SUPPLEMENTARY ITEMS

Total Labour :	451.00
Total Parts :	1,396.35
Total Labour & Parts :	1,847.35

