

INSURANCE OWNER:

CC3 /AIG1901 5546, 72 kb39

LKK:

IDAC:

Surveyor:

Taufik

DOI:

ASSIGNMENT

17/11/19

Date / Time:

3/11/19

Registered in Merit:

2/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 45135

Name of Insured:

CHENG GHEE HOE TIMOTHY

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

31/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

0055464834

Policy No.:

1800070531

Make / Model:

MITSUBISHI

Place of Accident:

LP NEAR TO TOL VI BK 963

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLK 76092



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/11/19
Chandra11/12/19
Chandra

SLK 76092 - 2

SLX 45135 - 1

one pass to type mandate.

File pass to SLK 76092 to close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

20/11/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject-Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

RIP SS 12,464.20 (6 days) Reduction: 20 %

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

SS 100 (Agreed / Assessed) BOLA S/N No. : 23

Repair Cost:

CW(657) SS 13,356.89

Loss of Rental (LOR):

SS 684.80 (8 days) X \$80

Loss of Use (LOU):

SS - (5 - x - days)

Loss of Income (LOI):

SS - (5 - x - days)

LOR only

LOU only

LOR + LOI

LOR + LO

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 14,044.89 Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 13,360.09

Name 1:

PERFORMANCE MOTORS LTD

Payee 2: (Strike if N.A.)

SS 684.80

Name 2:

BCL RENT A CAR PTE LTD

Payee 3: (Strike if N.A.)

SS -

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

B320

BMW Dealer

Performance Motors Limited

A BMW Group Motors Company
 CO. Reg. No. 197401155M GST Reg. No. M2/002081-X
 Toll-free Number: (1800-2211287)

101, Alexandra Road
 Singapore 119941
 Fax: 67477770

289, Kembangan Road
 Singapore 438180
 Fax: 67447777

111, Alexandra Road
 Singapore 119941
 Fax: 67798001
 (AfterSales/Insurance)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

16/9/2019
 any 9 rep

Estimate No. : b1 52569	Page No. : 1 of 5
Date Estimated : 02/09/2019	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Dylan Ng Foo Eng (Huang Furong) 2 Toh Yi Drive #08-163 Singapore 590002	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	HU32256	25/01/2017	3181A/4Dr	0

DESCRIPTION	VALUE
Replace front bonnet, left front side fender, front bumper and remove attachment etc include knock on accident dent	✓ 12580 3,825.00
Spray painting front bonnet, left front fender and front bumper	✓ 12898 3,221.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights	✓ 1150 177.00
To carry out body cavity preservation (Per panel)	✓ 1200 236.00
To replace left headlight	✓ 1408 481.00
Sundries	✓ 150 150.00
Total Labour 1: 8,090.00	

DESCRIPTION	QTY	PRICE	VALUE
BONNET	1	1,274.80	1,274.80
FRT LH SIDE PANEL	1	702.65	702.65
FRT LH 2 SIDE PANEL BRACKET	1	34.95	34.95
FRT LH TOP SUPPORT SIDE PANEL	1	20.00	20.00
FRT RH TOP SUPPORT SIDE PANEL	1	20.00	20.00
FRT LH BOTTOM MOUNTING SIDE PANEL	1	20.00	20.00
FRT RH BOTTOM MOUNTING SIDE PANEL	1	20.00	20.00
LH FOG LAMP SUPPORT	1	41.85	41.85
FRT BUMPER PANEL PRIMED (SPORT LINE	1	1,037.05	1,037.05
FRT LH GRILLE (SPORT)	1	128.60	128.60
LH HEADLIGHT LED TECHNOLOGY	1	3,068.40	3,068.40
Total Parts 1:			8,368.30

Email 26/10
 car 12,484.20, 6dys

Performance Motors Limited

a Lion Derby Motors Company

Co. Reg. No. 19740133M GST Reg. No. M2-0020081-X
Toll-Free Number 11866-22332891

302, Alexandra Road
Lion Derby Performance Centre
Singapore 119941
Fax: 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 421220
Fax: 63443172

315, Alexandra Road
Lion Derby Business Centre
Singapore 119944
Fax: 64794821 (AfterSales)
64756626 (MOTORS)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52569
Date Estimated : 02/09/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK76092	NU32256	25/01/2017	318iA/4Dr	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time: 17/9/19 6:42pm Excess \$5

Surveyor's Name: Tan Jia Hui

Surveyor's Tel: 97495714

Authorised: Yes / No

Authorised Date: 17/9/19

RESURVEY PARTS PHOTO BY SURVEYOR: Yes / No

Surveyor's Email: tanjiahui@lkk.com.sg

Working Days Requirement: 5-6 days

Labour 1	8,090.00
Parts	6,388.30
Labour 2	0.00
Excess	0.00
Total GST @ 7%	1,012.08
Grand Total	

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401550W, GST Reg. No. M2-0020081-A



Final Report

Estimate No. : b1 52569
Date Estimated : 02/09/2019
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -
Dylan Ng Foo Eng (Huang Furong)
2 Toh Yi Drive
#08-163

Singapore 590002

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	WBA8E36050NU32256	25/01/2017	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper, bonnet, front left fender and attachments including remove attachments to facilitate the repairs and knock out dented area caused by the accident.	2,550.00		2,550.00
To respray bonnet, front left fender and front bumper.	2,898.00		2,898.00
To check electrical wiring systems at the front section for proper function.	150.00		150.00
To carry out body cavity preservation. (2x) (Per panel).	200.00		200.00
To replace left LED technology headlight.	408.00		408.00
Sundries.	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BONNET	1,274.80	1.00		1,274.80
FRT LH SIDE PANEL	702.65	1.00		702.65
FRT LH 2 SIDE PANEL BRACKET	34.95	1.00		34.95
FRT BUMPER PANEL PRIMED (SPORT LINE	1,037.05	1.00		1,037.05
# LH HEADLIGHT BRACKET	10.35	1.00		10.35
LH HEADLIGHT LED TECHNOLOGY	3,068.40	1.00		3,068.40

SUPPLEMENTARY ITEMS

Total Labour :	6,356.00
Total Parts :	6,128.20
Total Labour & Parts :	12,484.20
Deduction for Excess :	0.00
Total Repair Costs less Excess:	12,484.20
GST @7%:	873.89
Grand Total :	13,358.09

Performance Motors Limited

A member of the Sincere Group
Co. Reg. No. 197401559K GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52569**
Date Estimated : **02/09/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Dylan Ng Foo Eng (Huang Furong)
2 Toh Yi Drive
#08-163

Singapore 590002

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	WBA8E36050NU32256	25/01/2017	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# LH HEADLIGHT BRACKET	10.35	1.00		10.35 <i>de</i>
------------------------	-------	------	--	-----------------

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	10.35
Total Labour & Parts :	10.35

www.slk.com

Performance Motors Limited

A Sime Darby Motors Company
Co Reg. No. 197451599K GST Reg. No. M2-0020081-X
Toll-Free Number: (1800-2254264)

101, Alexandra Road
Sime Darby Performance Centre
Singapore 119947
Fax: 64747772

185, Kangkong Alamy Road
East Coast Centre
Singapore 418180
Fax: 63447075

119, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Fax: 64796021 (AfterSales)
64796424 (Motors)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

16/9/2019
any 9 rps

Estimate No. : b1 52569
Date Estimated : 02/09/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Dylan Ng Foo Eng (Huang Furong)
2 Toh Yi Drive
#08-163

Singapore 590002

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	NU32256	25/01/2017	318iA/4Dr	0

DESCRIPTION

Replace front bonnet, left front side fender, front bumper and remove attachment etc include knock on accident dent

2550 3,825.00

Spray painting front bonnet, left front fender and front bumper

2698 3,221.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To carry out body cavity preservation (Per panel).

200 236.00

To replace left headlight.

408 481.00

Sundries.

7 150.00

Total Labour 11: 8,090.00

DESCRIPTION

BONNET
FRT LH SIDE PANEL
FRT LH 2 SIDE PANEL BRACKET
FRT LH TOP SUPPORT SIDE PANEL
FRT RH TOP SUPPORT SIDE PANEL
FRT LH BOTTOM MOUNTING SIDE PANEL
FRT RH BOTTOM MOUNTING SIDE PANEL
LH FOG LAMP SUPPORT
FRT BUMPER PANEL PRIMED (SPORT LINE)
FRT LH GRILLE (SPORT)
LH HEADLIGHT LED TECHNOLOGY

QTY	PRIC
1	1,274.80
1	702.65
1	34.95
1	20.00
1	20.00
1	20.00
1	20.00
1	20.00
1	41.85
1	1,037.05
1	128.60
1	3,068.40

VALUE
1,274.80
702.65
34.95
20.00
20.00
20.00
20.00
20.00
41.85
1,037.05
128.60
3,068.40

Total Parts : 6,368.30

Performance Motors Limited

A Star Carby Motors Company

Co. Reg. No. 3770135W GST Reg. No. M2-0020081-X

Toll-Free Number: 1800-2282287

101, Alexandra Road
Star Carby Performance Centre
Singapore 119943
Fax: 64747770

240, Kembangan Road
Star Carby Centre
Singapore 119943
Fax: 64747770

101, Alexandra Road
Star Carby Performance Centre
Singapore 119943
Fax: 64747770 (ATTENTION: (WUENHUA))



GST REG. NO : M2 - 0020081 - X
ESTIMATE

Estimate No. : b1 52569
Date Estimated : 02/09/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	NU32256	25/01/2017	3181A/4Dr	0

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured Losses / Direct Settlement

Sign No. _____ Case No. _____

Date & Time: 17/9/19 8:42pm Excess \$4

Surveyor's Name: Tan Jia Hui Sig: [Signature]

Surveyor's Tel: 97495764 Authorized: Yes / No

Authorized Date: 17/9/19

RESURVEY PARTS PHOTO BY SURVEYOR: Yes / No P.M. Yes / No

Surveyor's E-mail: tan.jia.hui@lkk.com.sg

No. of Working Days Recommended: 5-6 days

Labour 1	8,090.00
Parts	6,368.30
Labour 2	0.00
Excess	0.00
Total GST @ 7%	1,012.08
Grand Total	

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 11 December 2019 10:22 AM
To: PBSP
Cc: Admin A
Subject: RE: REQ FOR DIRECT SETTLEMENT - SLK7609Z & SLX4513X - AIG ON 31.08.19 ****LKK
REF:CC3/AIG19015546/kb3

Tracking:	Recipient	Delivery
	PBSP	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 11/12/2019 10:22 AM
	shupeil@lkkauto.com	Delivered: 11/12/2019 10:22 AM
	olivialau@lkkauto.com	Delivered: 11/12/2019 10:22 AM

Without Prejudice

Dear Sir/Madam,

We refer to the above matter and your e-mail below.

We confirm settlement as per your LOD on this matter.

We will do the necessary accordingly.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khanchna (LKK Auto)
Sent: Monday, 9 September 2019 12:00 PM
To: PBSP <pml-pbsp@simedarby.com.sg>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: REQ FOR DIRECT SETTLEMENT - SLK7609Z & SLX4513X - AIG ON 31.08.19 ****LKK
REF:CC3/AIG19015546/kb3

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Monday, 9 September 2019 11:54 AM

To: Shu Pei (LKKAuto) <shupe@lkkauto.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: Re: REQ FOR DIRECT SETTLEMENT - SLK7609Z & SLX4513X - AIG ON 31.08.19 ****LKK
REF:CC3/AIG19015546/kb3

Dear Sirs

Please advise if your insured had reported the accident?

Kindly reply on liability.

Thank you.

Regards,

Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 3 September 2019 2:43 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: 甯瑤 © <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: FW: REQ FOR DIRECT SETTLEMENT - SLK7609Z & SLX4513X - AIG ON 31.08.19 ****LKK
REF:CC3/AIG19015546/kb3

Dear Sir /Madam,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Khanchna at DID: 6841 2360.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 2 September 2019 7:50 PM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: REQ FOR DIRECT SETTLEMENT - SLK7609Z & SLX4513X - AIG ON 31.08.19

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Print Received Message

This mail is associated with :

***SLK7609Z (0055799287SG)
[SLX4513S]**

TP

DYLAN NG FOO ENG (HUANG FURONG)

Aug 31 2019 10:00PM

[CHENG GHEE HOCK, TIMOTHY (ZHENG ZHIFU, TIMOTHY)]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 09/12/2019 16:09 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14044.89) - SLK7609Z - Claim Handler: Lee, Ming-Yao

Approved:14044.89:Plase proceed to settle at best

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2019 Edit Reg		17 Sep 2019 00:00 Edit Adj Rpt	S\$12,484.20 Edit Estimates	S\$12,484.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	CHENG GHEE HOCK, TIMOTHY (ZHENG ZHIFU, TIMOTHY), ID: S7147806H	
Main Claimant:	DYLAN NG FOO ENG (HUANG FURONG), ID: S7521013B	
Vehicle Reg. No.:	SLK7609Z	Date of Loss: 31/08/2019 22:00 - :59 [31 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0055799287SG	Policy/Cover Note No.: 1800030531 (Comprehensive)
Vehicle Reg. No. (Insured):	SLX4513S	Policy No. (Claimant): 5106940920
		Excess:
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com	
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 12/09/2019]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
• AIG_SG_EXPRESS (09/12/2019): Alert - Adj Mandate Approved (S\$14044.89) - SLK7609Z - Claim Handler: Lee, Ming-...		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK7609Z (0055799287SG)

[SLX4513S]

TP

DYLAN NG FOO ENG (HUANG FURONG)

Aug 31 2019 10:00PM

[CHENG GHEE HOCK, TIMOTHY (ZHENG ZHIFU, TIMOTHY)]

Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video										1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	04/09/19 11:59	Video - Accident							Load MP4		
Letters/Correspondences										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	03/12/19 14:37	General View							Load JPG		
2	03/12/19 14:37	General View							Load JPG		
3	03/12/19 14:37	General View							Load JPG		
4	03/12/19 14:37	General View							Load JPG		
5	03/12/19 14:37	General View							Load JPG		
6	03/12/19 14:37	General View							Load JPG		
7	03/12/19 14:37	General View							Load JPG		
8	03/12/19 14:37	General View							Load JPG		
9	03/12/19 14:37	General View							Load JPG		
10	03/12/19 14:37	General View							Load JPG		
11	03/12/19 14:37	General View							Load JPG		
12	03/12/19 14:37	General View							Load JPG		
13	03/12/19 14:37	General View							Load JPG		
14	03/12/19 14:37	General View							Load JPG		
15	03/12/19 14:37	General View							Load JPG		
16	03/12/19 14:37	General View							Load JPG		
17	03/12/19 14:37	General View							Load JPG		
18	03/12/19 14:37	General View							Load JPG		
19	03/12/19 14:37	General View							Load JPG		
20	03/12/19 14:37	General View							Load JPG		
21	03/12/19 14:37	General View							Load JPG		
22	03/12/19 14:37	General View							Load JPG		
23	03/12/19 14:37	General View							Load JPG		
24	03/12/19 14:37	General View							Load JPG		
25	03/12/19 14:37	General View							Load JPG		
26	03/12/19 14:37	General View							Load JPG		
27	03/12/19 14:37	General View							Load JPG		
28	03/12/19 14:38	Reinspection Photo							Load JPG		
29	03/12/19 14:38	Reinspection Photo							Load JPG		
30	03/12/19 14:38	Reinspection Photo							Load JPG		
31	03/12/19 14:38	Reinspection Photo							Load JPG		
Documentation										1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	03/09/19 14:10	TP EST & GIA REPORT.							Load PDF		
2	18/09/19 17:11	TP ESTIMATE- MARKED							Load PDF		
3	08/10/19 09:31	RENTAL RECEIPT							Load PDF		

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
4	20/11/19 15:45	LETTER TO OI		Load PDF	
5	29/11/19 17:05	GIA SEARCH		Load PDF	
6	29/11/19 17:05	LOD		Load PDF	
7	12/12/19 09:36	WORKSHOP INVOICE		Load PDF	
8	12/12/19 09:36	AUTHORISATION TO ACT FORM		Load PDF	
9	12/12/19 09:36	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	04/09/19 11:59	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX4513S (Insd veh)	Model:	BMW 318i 1.5 (A)
	SLK7609Z (TP veh)		
Date of Accident:	31/08/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	15,481.46
Final Repair Cost	:	\$	13,358.09
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	684.80 8 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	14,044.89

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
 23
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 13,360.09
2)	BKW Rent-A-Car Pte Ltd	:	\$ 684.80
3)		:	\$

JOANNE LEE KHANG MIN

12 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
 Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19015546/T1KB3Q2

Date: 12/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800030531
Claimant SLK7609Z **Insured Vehicle No :** SLX4513S
Vehicle No : SLK7609Z
Date of Loss: 31/08/2019 **Nature of Claim:** TP **Claim No:** 0055799287SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK7609Z
Make & Model: BMW 318i, 1.5 (A) **Engine No:** F0131472B38B15A
Reg. Date: 25/01/2017 (Man. Year: 2016) **Chassis No:** WBA8E36050NU32256
Colour: Grey **Odometer:** 45972 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 225/50R17 **Rear Tyre Size:** 225/50R17
Front Left Side: Bridgestone 6 mm **Rear Left Side:** Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm **Rear Right Side:** Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,528.65	6,278.20	250.45	3.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,940.00	6,206.00	1,734.00	21.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,468.65	12,484.20	1,984.45	13.72
+ GST 7.00/7.00% (S\$)	1,012.81	873.89	138.92	13.72
Nett Amount (S\$)	15,481.46	13,358.09	2,123.37	13.72
+ Car Rental (8.0 x S\$80.00/day + 7.00% GST) (S\$)		684.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		14,044.89		

INSPECTION

Date of Assignment: 17/09/2019
Date Inspected: 17/09/2019 **Inspected At:** Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941
Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BONNET	Bent	1,274.80 FS	*1,274.80 FS
3	1		*FRT LH SIDE PANEL	Bent	702.65 FS	*702.65 FS
4	1		*FRT LH 2 SIDE PANEL BRACKET	Bent	34.95 FS	*34.95 FS
5	1		*FRT LH TOP SUPPORT SIDE PANEL	Not Necessary	20.00 FS	*- FS
6	1		*FRT RH TOP SUPPORT SIDE PANEL	Not Necessary	20.00 FS	*- FS
7	1		*FRT LH BOTTOM MOUNTING SIDE PANEL	Not Necessary	20.00 FS	*- FS
8	1		*FRT RH BOTTOM MOUNTING SIDE PANEL	Not Necessary	20.00 FS	*- FS
9	1		*LH FOG LAMP SUPPORT	Not Necessary	41.85 FS	*- FS
10	1		*FRT BUMPER PANEL PRIMED (SPORT LINE)	Deformed	1,037.05 FS	*1,037.05 FS
11	1		*FRT LH GRILLE (SPORT)	Not Necessary	128.60 FS	*- FS
12	1		*LH HEADLIGHT LED TECHNOLOGY	Cracked	3,068.40 FS	*3,068.40 FS
13	1		*LH HEADLIGHT BRACKET	Deformed	10.35 FS	*10.35 FS
Total Parts (\$\$)					6,528.65	6,278.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE FRONT BONNET ,LEFT FRONT SIDE FENDER ,FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDING KNOCK ON ACCIDENT DENT	New	3,825.00	2,550.00
2	SPRAY PAINTING FRONT BONNET ,LEFT FRONT FENDER AND FRONT BUMPER	New	3,221.00	2,898.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	236.00	200.00
5	TO REPLACE LEFT HEADLIGHT	New	481.00	408.00
Gross Labour Cost (S\$)			7,940.00	6,206.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >