

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E16/9/2018
any & rep
P
8 SEP 2019

Estimate No. : b1 52569
Date Estimated : 02/09/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Dylan Ng Foo Eng (Huang Furong)
2 Toh Yi Drive
#08-163

Singapore 590002

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	NU32256	25/01/2017	318iA/4Dr	0

DESCRIPTIONVALUE

Replace front bonnet, left front side fender, front bumper and
remove attachment etc include knock on accident dent

2550 3,825.00

Spray painting front bonnet, left front fender and front
bumper

2898 3,221.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

To carry out body cavity preservation.
(Per panel).

200 236.00

To replace left headlight.

408 481.00

Sundries.

? 150.00

Total Labour 1: 8,090.00

DESCRIPTIONQTYPRICVALUE

BONNET

1 1,274.80

b7 1,274.80

FRT LH SIDE PANEL

1 702.65

b6 702.65

FRT LH 2 SIDE PANEL BRACKET

1 34.95

? 34.95

FRT LH TOP SUPPORT SIDE PANEL

1 20.00

? 20.00

FRT RH TOP SUPPORT SIDE PANEL

1 20.00

? 20.00

FRT LH BOTTOM MOUNTING SIDE PANEL

1 20.00

? 20.00

FRT RH BOTTOM MOUNTING SIDE PANEL

1 20.00

? 20.00

LH FOG LAMP SUPPORT

1 41.85

? 41.85

FRT BUMPER PANEL PRIMED (SPORT LINE)

1 1,037.05

del 1,037.05

FRT LH GRILLE (SPORT)

1 128.60

? 128.60

LH HEADLIGHT LED TECHNOLOGY

1 3,068.40

CVR 3,068.40

Total Parts : 6,368.30

Sime Darby Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401359W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52569
Date Estimated : 02/09/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	NU32256	25/01/2017	318iA/4Dr	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 17/9/19 Claim No. 17/9/19

Date & Time 17/9/19 2.42pm Excess S\$ 0

Surveyor's Name Tan Jie Sign Tan Jie

Surveyor's Tel 9749574 Authorised Yes / No

Authorised Date 17/9/19 Time 2.42pm

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No Yes / No

Surveyor's E-mail tan.jie@lkk.com.sg

No. of Working Days Recommend 5-6 days

Labour 1	:	8,090.00
Parts	:	6,368.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,012.08

Grand Total