

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

2019

Estimate No. : b1 52569	Page No. : 1 of 5
Date Estimated : 02/09/2019	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Dylan Ng Foo Eng (Huang Furong) 2 Toh Yi Drive #08-163 Singapore 590002	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	NU32256	25/01/2017	318iA/4Dr	0

DESCRIPTION

Replace front bonnet, left front side fender, front bumper and
remove attachment etc include knock on accident dent

12550 3,825.00

Spray painting front bonnet, left front fender and front
bumper

12898 3,221.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

1150 177.00

To carry out body cavity preservation.
(Per panel).

1200 236.00

To replace left headlight.

1408 481.00

Sundries.

150.00

Total Labour 1: 8,090.00

DESCRIPTION

BONNET
FRT LH SIDE PANEL
FRT LH 2 SIDE PANEL BRACKET
FRT LH TOP SUPPORT SIDE PANEL
FRT RH TOP SUPPORT SIDE PANEL
FRT LH BOTTOM MOUNTING SIDE PANEL
FRT RH BOTTOM MOUNTING SIDE PANEL
LH FOG LAMP SUPPORT
FRT BUMPER PANEL PRIMED (SPORT LINE
FRT LH GRILLE (SPORT)
LH HEADLIGHT LED TECHNOLOGY

QTY	PRIC
1	1,274.80
1	702.65
1	34.95
1	20.00
1	20.00
1	20.00
1	20.00
1	20.00
1	41.85
1	1,037.05
1	128.60
1	3,068.40

VALUE
1,274.80
702.65
34.95
20.00
20.00
20.00
20.00
20.00
41.85
1,037.05
128.60
3,068.40

Total Parts : 6,368.30

Email 21/10

CoR \$12,484.20, 6dys.

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52569
Date Estimated : 02/09/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	NU32256	25/01/2017	318iA/4Dr	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 12/9/19 14:20 Excess S\$ _____

Surveyor's Name Tanjir Sign _____

Surveyor's Tel 97405744 Authorised Yes / No _____

Authorised Date 12/9/19

RESURVEY PARTS PHOTO BY SURVEYOR Yes No PML Yes / No

Surveyor's E-mail tanjir@lkk.com.sg

Working Days Recommend 5-6 days

Labour 1	:	8,090.00
Parts	:	6,368.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,012.08
Grand Total	:	

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52569**
Date Estimated : **02/09/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Dylan Ng Foo Eng (Huang Furong)
2 Toh Yi Drive
#08-163

Singapore 590002

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	WBA8E36050NU32256	25/01/2017	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper, bonnet, front left fender and attachments including remove attachments to facilitate the repairs and knock out dented area caused by the accident.	2,550.00		2,550.00
To respray bonnet, front left fender and front bumper.	2,898.00		2,898.00
To check electrical wiring systems at the front section for proper function.	150.00		150.00
To carry out body cavity preservation. (2x) (Per panel).	200.00		200.00
To replace left LED technology headlight.	408.00		408.00
Sundries.	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BONNET	1,274.80	1.00		1,274.80
FRT LH SIDE PANEL	702.65	1.00		702.65
FRT LH 2 SIDE PANEL BRACKET	34.95	1.00		34.95
FRT BUMPER PANEL PRIMED (SPORT LINE	1,037.05	1.00		1,037.05
# LH HEADLIGHT BRACKET	10.35	1.00		10.35
LH HEADLIGHT LED TECHNOLOGY	3,068.40	1.00		3,068.40

SUPPLEMENTARY ITEMS

Total Labour :	6,356.00
Total Parts :	6,128.20
Total Labour & Parts :	12,484.20 *
Deduction for Excess :	0.00
Total Repair Costs less Excess:	12,484.20
GST @7%:	873.89
Grand Total :	13,358.09

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52569**
Date Estimated : **02/09/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Dylan Ng Foo Eng (Huang Furong)
2 Toh Yi Drive
#08-163

Singapore 590002

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK7609Z	WBA8E36050NU32256	25/01/2017	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# LH HEADLIGHT BRACKET	10.35	1.00		10.35 <i>de ✓</i>
------------------------	-------	------	--	-------------------

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	10.35
Total Labour & Parts :	10.35