

INS. CASE OWNER:

SUNDARI

CC4/III19015547/Uga3

LKK:

IDAC:

Surveyor:

MARCUS

DOI: 03/09/2019

Date / Time: 03/09/2019

Registered in Merimen: 03/09/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SHD 4063B

Claim No. : _____

Name of Insured : COMFORT TRANSPORTATION PTE LTD

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : HYUNDAI IONIQ HYBRID

Excess Sec II : S\$ _____ D.O.A : 28/08/2019 21:05

Place of Accident : ROBINSON RD TOWARDS COLLYER QUAY

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : LONG YAW NAN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : +65-81829563 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SBC 8222J

INSRS:
WSP: Tick Hai Motor &
Tel: Welding Services
Liability :
RMKS:INSRS:
WSP:
Tel:
Liability :
RMKS:INSRS:
WSP:
Tel:
Liability :
RMKS:INSRS:
WSP:
Tel:
Liability :
RMKS:

| Date/Time | | STAGE | DATE / PIC |
|-----------|--|-----------------------------------|----------------|
| | SHD 4063B - CC4/AXA13001570/H1hf3y; DOA: 21.1.13 | Non-Reporting ltr (1st): | |
| | SBC 8222J - NA/INC10014346/r; DOA: 20/7/10 | Non-Reporting ltr (2nd): | |
| 27/9 | - Pending liability approval (approved) | Non-Reporting ltr (Final): | |
| 7/10 | - Submit WP report (file plus Admin to close) | Notification ltr (if non-pickup): | |
| | | Call OI: | |
| | | After call ltr to OI: | |
| | | Documentation Check List: | Handler Typist |
| | | Notification ltr (if non-pickup) | |
| | | After call ltr to OI: | |
| | | Authorisation To Act: | |
| | | Release Voucher: | |
| | | Final Repair Bill: | |
| | | Car Rental Invoice: | |
| | | Towing Invoice: | |
| | | LTA / GIA : | |
| | | Medical Bill: | |
| | | PIR: | |
| | | Mandate/Reject Instruction: | |
| | | LOD | |
| | | Payment Breakdown Form: | |
| | | Post-Repair Photos: | |
| | | Others: | |

| | | | |
|---|---|--|--|
| PRELIMINARY ADVICE Date/Time: _____ Sent By: _____ | | Confirm by: <u>MARCUS</u> | |
| Repair Cost: <u>115</u> S\$ <u>79501-</u> (5 days) Reduction: <u>\$10873.04</u> S\$ | | Email <input type="checkbox"/> Call <input type="checkbox"/> | |
| FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ | | Email <input type="checkbox"/> Call <input type="checkbox"/> | |
| Final Liability: | % <u>100</u> (Agreed / Assessed) BOLA S/N No. : <u>27</u> | If NO or B 28, Ass. Lia : | |
| Repair Cost: | S\$ _____ | | |
| Loss of Rental (LOR): | S\$ _____ (_____ days) | | |
| Loss of Use (LOU): | S\$ _____ (\$ x _____ days) | | |
| Loss of Income (LOI): | S\$ _____ (\$ x _____ days) | | |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one] | | | |
| GIA/LTA Search: | S\$ _____ | | |
| Medical: | S\$ _____ | 1) Claim status: Normal/Reject/Private Settle | |
| Disbursement: | S\$ _____ (e.g. Tow/ Independent) | 2) Report Format: <u>WP</u> | |
| Legal Cost: | S\$ _____ | 3) Survey fee: <u>84501-</u> | |
| Total: | S\$ _____ Global Sum S\$: | | |
| FINAL PAYMENT Date/Time: _____ Confirm with: _____ | | Email <input type="checkbox"/> Call <input type="checkbox"/> | |
| Payee 1: | S\$ _____ Name 1: _____ | | |
| Payee 2: (Strike if N.A.) | S\$ _____ Name 2: _____ | | |
| Payee 3: (Strike if N.A.) | S\$ _____ Name 3: _____ | | |

larger case

Not Authorized
Hak
1/5 7780
3/9/19
The...
S...
1

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

Vehicle Number: SBC8222J
Vehicle Model : Merc. E200CGI
Chassis : WDD2120482A221074

| S/N. | Item Description | Amount (\$) |
|------------|--|--------------|
| 1 | Rear Boot Lid 2102.32 Bmt/Suc | \$ 2,327.25 |
| 2 | Rear Boot Rubber Twl | \$ 138.03 |
| 3 | Rear Boot Lock (Top) 822 | \$ 221.49 |
| 4 | Rear Boot Lock (Bottom) 11 | \$ 361.13 |
| 5 | Rear Boot Trimboard 111 | \$ 825.40 |
| 6 | Rear Boot Taillamp x 2 pcs 11 | \$ 914.85 |
| 7 | Rear Boot Hinge x 2 pcs 11 | \$ 240.75 |
| 8 | Rear Boot Switch 11 | \$ 160.50 |
| 9 | "E200" Emblem nu | \$ 90.25 |
| 10 | "CGI" Emblem nu | \$ 84.20 |
| 11 | C&C Emblem nu | \$ 48.00 |
| 12 | Mercedes Centre Logo nu | \$ 51.70 |
| 13 | Number Plate Top Chrome Garnish nu | \$ 99.51 |
| 14 | Taillamp x 2 pcs Cne | \$ 1,187.70 |
| 15 | Taillamp Lower Bracket x 2 pcs Cne | \$ 118.77 |
| 16 | Rear Bumper 265 | \$ 1,203.75 |
| 17 | Rear Bumper Side Retainer x 2 pcs 11 | \$ 64.20 |
| 18 | Rear Bumper Centre Bracket Cne | \$ 256.85 |
| 19 | Rear Bumper Lower Bracket x 3 pcs 11-10x25 Cne | \$ 52.97 |
| 20 | Rear Bumper Lower Diffuser 246.32 Dis | \$ 393.23 |
| 21 | Rear Bumper Side Chrome x 2 pcs nu | \$ 224.70 |
| 22 | Rear Bumper Centre Chrome nu | \$ 141.24 |
| 23 | Rear Bumper Reinforcement 321 | \$ 601.88 |
| 24 | Reverse Sensor Wire 11 | \$ 128.40 |
| 25 | Rear Exhaust 12 | \$ 1,540.80 |
| 26 | Rear Exhaust Cover 11 | \$ 36.92 |
| 27 | End Panel m/suf | \$ 979.05 |
| 28 | End Panel Top Garnish twl | \$ 104.33 |
| 29 | Rear Fender Inner Trimboard (LH) 11 | \$ 184.20 |
| 30 | Headrest x 2 pcs 681 n/s Aohd/cne | \$ 1,540.80 |
| Total : | | \$ 14,322.82 |
| Less 10% : | | \$ 1,432.28 |
| Amount : | | \$ 12,890.54 |

22.40

10C

| S/N | Special Nett Item | Amount (\$) |
|----------|---|-------------|
| 1 | Reverse Sensor x 4 pcs <i>215K23 430 IN) Shogoh</i> | \$ 802.50 |
| 2 | End Panel Sealant <i>all</i> | \$ 50.00 |
| | | |
| | | |
| Amount : | | \$ 852.50 |

2pcs. 430 10%
✓ S.N

| Labour | Amount (\$) |
|--|--------------|
| To computer diagnostic and resetting | \$ 380.00 |
| To check rear electrical wiring system | \$ 180.00 |
| To remove & reinstall components from old boot to new boot | \$ 200.00 |
| To remove interior trim & garnishes to facilitate repair | \$ 220.00 |
| To remove, and reinstall reverse sensors | \$ 120.00 |
| To remove & reinstall exhaust | \$ 280.00 |
| To spray anti-rusting coating on affected areas | \$ 150.00 |
| Labour to remove, cut, change & panel beating | \$ 1,850.00 |
| To putty and respray affected areas | \$ 1,500.00 |
| | |
| | |
| Labour Total : | \$ 4,880.00 |
| Total (Parts & Labour) | \$ 18,623.04 |

2
30
60
80
50
60
60
600
900

LKK Auto Consultants hence notify

the Regener of the following

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

• Repairs to be carried out using original

P-8811
102
7528.90
98195
7812

Cecilia

ARIDAS & ASSOCIATES

ACRA REG. NO : 53131060D

NOTARY PUBLIC

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

NO. 75 BUKIT TIMAH ROAD, #03-13, BOON SIEW BUILDING, SINGAPORE 229833

TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713

E-mail : aridasv@singnet.com.sg

VYTINGAM ARIDAS

LLB (Hons) Lond. M.A.

Barrister, (Lincoln's Inn)

Service of Court Documents
By Fax
Is Not Acceptable

Our Ref : AA.21582.19.159

Your Ref : Please advise

2 SEPTEMBER 2019

**INDIA INTERNATIONAL INS PTE LTD**

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLES SBC 8222J AND SHD 4063B
ALONG ROBINSON ROAD/CECIL ST JUNCTION ON 28 AUGUST 2019 AT
21:10.**

We are instructed by **TAN BOON GUAN@CHEN WEN PAN** to notify you of a road traffic accident on 02/05/19 at 14:30 involving our client's vehicle registration number **SBC 8222J** and vehicle registration number **SHD 4063B** driven by your insured at the material time.

Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Our client's motor vehicle **SBC 8222J**.

Please contact **Ms Connie** at office number: **6842 9089**. Vehicle can be inspected at:

**M/s Tick Hai Motor & Welding Services,
Block 1 Kaki Bukit Avenue 6,
#01-54 Auto @ Kaki Bukit, Singapore 417883.**

Yours faithfully,

ARIDAS & ASSOCIATES

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



AVIVA

Mercedes-Benz e200

Price Range

Depreciation

2010

Vehicle Type



Home » Used Cars » Next Drive » Mercedes-Benz E-Class E200 CGI

Mercedes-Benz E-Class E200 CGI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$48,800

Depreciation ⓘ

\$19,390 /yr

View models with similar depre

Reg Date

20-Oct-2010

(1yr 1mth 15days COE left)

Mileage

56,000 km (6.3k /yr)

Manufactured ⓘ

2010

Road Tax ⓘ

\$974 /yr

Transmission

Auto

Dereg Value ⓘ

\$34,627 as of today (change)

OMV ⓘ

\$53,923

COE ⓘ

\$44,129

ARF ⓘ

\$53,923

Engine Cap

1,796 cc

Power

135.0 kW (181 bhp)

Curb Weight ⓘ

1,615 kg

No. of Owners ⓘ

3

Type of Vehicle

Luxury Sedan

Features

View specs of the Mercedes-Benz E-Class Saloon (2009-2013)

Description

Super Low Mileage! Definitely The Best Choice For COE Renewal. Superb Original Interior Condition For It's Age. No Typical Peeling Buttons Issues. View To Believe!

Category

PARF Car, Low Mileage Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



- Free

ket value of your existing car for free. Get started



Price Chart



Click on the point to view

Shortlist

Com

Report Error

M

Seller Information

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 682B

Vehicle Details

Vehicle No.: SBC8222J

Vehicle to be Exported: No

Intended Deregistration Date: 03 Sep 2019

Vehicle Make: MERCEDES BENZ

Vehicle Model: E 200CGI

Primary Colour: Silver

Manufacturing Year: 2010

Engine No.: 27186030065575

Chassis No.: WDD2120482A221074

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$53,923.00

Original Registration Date: 16 Aug 2010

First Registration Date: 16 Aug 2010

Transfer Count: 0

Actual ARF Paid: \$53,923.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Aug 2020

PARF Rebate Amount: \$26,961.00

Intended COE Rebate Details

COE Expiry Date: 15 Aug 2020

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$39,000.00

COE Rebate Amount: \$3,283.00

Total Rebate Amount: \$30,244.00

The information contained herein is correct as at 03 Sep 2019

OK

18/09/19.
Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 3 September, 2019 9:01 AM
To: Aridas & Associates; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SBC8222J (Accident involving SBC8222J and SHD4063B on 28.08.2019)
Attachments: shd4063b_20190902142616.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SBC8222J and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

P. Connie

T. 9.30am

V. 1h

E. ✓

From: Aridas & Associates [mailto:aridasv@singnet.com.sg]
Sent: 02 September, 2019 4:43 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SBC8222J (Accident involving SBC8222J and SHD4063B on 28.08.2019)

Dear Sir,

Our client has chosen LKK. Please liaise with Connie directly at telephone number: 68429089.

Regards,
Marina
ARIDAS & ASSOCIATES

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: Monday, September 02, 2019 2:32 PM
To: 'aridasv@singnet.com.sg'
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SBC8222J (Accident involving SBC8222J and SHD4063B on 28.08.2019)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

ARIDAS & ASSOCIATES

ACRA REG. NO : 53131060D
NOTARY PUBLIC
ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

NO. 75 BUKIT TIMAH ROAD, #03-13, BOON SIEW BUILDING, SINGAPORE 229833
TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713
E-mail : aridasv@singnet.com.sg

VYTINGAM ARIDAS
LLB (Hons) Lond. M.A.
Barrister, (Lincoln's Inn)

Service of Court Documents
By Fax
Is Not Acceptable

Our Ref : AA.21582.19.159
Your Ref : Please advise

2 SEPTEMBER 2019

INDIA INTERNATIONAL INS PTE LTD



Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLES SBC 8222J AND SHD 4063B
ALONG ROBINSON ROAD/CECIL ST JUNCTION ON 28 AUGUST 2019 AT
21:10.**

We are instructed by **TAN BOON GUAN@CHEN WEN PAN** to notify you of a road traffic accident on 02/05/19 at 14:30 involving our client's vehicle registration number **SBC 8222J** and vehicle registration number **SHD 4063B** driven by your insured at the material time.

Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Our client's motor vehicle **SBC 8222J**.

Please contact **Ms Connie** at office number: **6842 9089**. Vehicle can be inspected at:

**M/s Tick Hai Motor & Welding Services,
Block 1 Kaki Bukit Avenue 6,
#01-54 Auto @ Kaki Bukit, Singapore 417883.**

Yours faithfully,
ARIDAS & ASSOCIATES

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 7 October 2019 4:33 PM
To: Stanley Lai; Mei Kwan (LKKAuto)
Cc: Mekavathanan Sarangapani; Sundari Nagarajan - III
Subject: RE: MCTT19080744 *** LKK REF: CC4/III19015547/Uga3

Dear Stanley,

Thus we shall proceed to submit WP report to your end and close off the matter as survey has been done.

Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Stanley Lai [mailto:stanley.lai@iii.com.sg]
Sent: Monday, 7 October 2019 2:07 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Mekavathanan Sarangapani <mekavathanan@iii.com.sg>; Sundari Nagarajan - III <sundari@iii.com.sg>
Subject: RE: MCTT19080744 *** LKK REF: CC4/III19015547/Uga3

Dear Mei Kwan & Cecilia,

Apologies, cancel the paper survey assignment please.

We had earlier on 3rd September 2019 appointed you as the SJE for this case.

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 3 September, 2019 9:01 AM
To: Aridas & Associates <aridas@aridas.com.sg>; 'sur@lkkauto.com' <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Sundari Nagarajan - III <sundari@iii.com.sg>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. 58C8222J (Accident involving 58C8222J and SHD40638 on 28.08.2019)

Dear Sir / Madam,

Please conduct a survey on TP vehicle 58C8222J and let us have your report urgently.

This claim will be handled by Ms Sundari.

Kindly upload this survey request email to member.

Thank You.

Best Regards,
Gabriel Wee


INDIA
INTERNATIONAL
INSURANCE
SINGAPORE
64 Cecil Street, #05-10B Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Aridas & Associates <aridas@aridas.com.sg>
Sent: 02 September, 2019 4:43 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. 58C8222J (Accident involving 58C8222J and SHD40638 on 28.08.2019)

Dear Sir,

Our client has chosen LKK. Please liaise with Connie directly at telephone number: 68429089.

Regards,
Marina
ARIDAS & ASSOCIATES

As such, kindly let us have your survey report urgently.

Thanks.

Warmest regards,

Stanley Lai

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company


INDIA
INTERNATIONAL
INSURANCE
SINGAPORE
Serving the region since 1987

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Sent: Monday, 7 October, 2019 1:35 PM

To: Mekavathanan Sarangapani <mekavathanan@iii.com.sg>; Stanley Lai <stanley.lai@iii.com.sg>; Sundari Nagarajan - III <sundari@iii.com.sg>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|---------------|--|--|--|------------|---|
| Main | 03 Sep 2019 Edit Reg | | 03 Sep 2019 00:00 Edit Adj Rpt | S\$7,750.00 Edit Estimates | S\$7,750.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R | | | | | | | | |
| Main Claimant: | TAN BOON GUAN @ CHEN WEN PAN, ID: S0476682B | | | | | | | | |
| Vehicle Reg. No.: | SBC8222J | Date of Loss: | 28/08/2019 21:00 - :59 [108 Months and 12 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / MCT19080744 | Policy/Cover Note No.: | MCOM0015 | | | | | | |
| Vehicle Reg. No. (Insured): | SHD4063B | Policy No. (Claimant): | GA053720 | | | | | | |
| | Excess: | | | | | | | | |
| Repairer: | Tick Hai Motor & Welding Services - Kaki Bukit (HQ) BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 6747 4676, 68429089 | | | | | | | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagara... - 6347 6071] | | | | | | | | |
| Claimant's Insurer: | AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/09/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| • III_SG (30/09/2019): Alert - Adj Mandate Approved (S\$0.00) - SBC8222J - Claim Handler: Sundari Nagara... | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SBC8222J (MCT19080744)
[SHD4063B]

TP















































TAN BOON GUAN @ CHEN WEN PAN

Aug 28 2019 9:00PM

[COMFORT TRANSPORTATION PTE LTD]

Tick Hai Motor & Welding Services - Kaki Bukit

| Upload Documents | | Upload Photos | Compose New Letter | View View in Browser | |
|----------------------------------|-----------------|-----------------------------------|------------------------------------|---|-------------------------------------|
| Photos/Images | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 21 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 22 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 23 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 24 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 25 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 26 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 27 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 28 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 29 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 30 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 31 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 32 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 33 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 34 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 36 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 38 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |
| 43 | 16/10/19 08:42 | General View | | Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 44 | 16/10/19 08:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 16/10/19 08:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 16/10/19 08:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 16/10/19 08:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 16/10/19 08:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 16/10/19 08:42 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 84 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 16/10/19 08:43 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 91 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 92 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 93 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 94 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 95 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 96 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 97 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 98 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 99 | 16/10/19 08:43 | General View | Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|------------|--|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 100 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 101 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 102 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 103 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 104 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 105 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 106 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 107 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 108 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 109 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 110 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 111 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 112 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 113 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 114 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 115 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 116 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 117 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 118 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 119 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| 120 | 16/10/19 08:43 | General View | | Load JPG <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 03/09/19 14:14 | EMAIL FROM III DD 03.09.2019 | | Load PDF <input type="checkbox"/> |
| 2 | 03/09/19 14:14 | NOTIFICATION FROM LAWYER + TP GIA REPORT | | Load PDF <input type="checkbox"/> |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 04/09/19 08:51 | Singapore Accident Statement | | Load PDF <input type="checkbox"/> |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19015547/UGA3Q2

Date: 16/10/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SBC8222J Insured Vehicle No: SHD4063B
 Vehicle No: SBC8222J
 Date of Loss: 28/08/2019 Nature of Claim: TP Claim No: MCT19080744

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBC8222J
 Make & Model: MERCEDES-BENZ E200, 1.8 CGI (A) Engine No: 27186030065575
 Reg. Date: 16/08/2010 (Man. Year: 2010) Chassis No: WDD2120482A221074
 Colour: Silver Odometer: 89635 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R17 Rear Tyre Size: 245/45Z R17
 Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
 Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 13,743.06 | 7,979.90 | 5,763.16 | 41.94 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,880.00 | 1,840.00 | 3,040.00 | 62.30 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 18,623.06 | 9,819.90 | 8,803.16 | 47.27 |
| Approved Total (Overridden) (S\$) | | 7,750.00 | | |
| Nett Amount (S\$) | 18,623.06 | 7,750.00 | 10,873.06 | 58.38 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 03/09/2019
 Date Inspected: 03/09/2019 Inspected At: Tick Hai Motor & Welding Services - Kaki Bukit (HQ)
 BLK 1 KAKI BUKIT AVE 6, #01-54
 AUTOBAY @ KAKI BUKIT
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|--|
| Reference | | |
| Part Source: | (Last Synchronised: 15 Oct 2019) | |
| Parts: | N/A | MERCEDES-BENZ E200 1.8 CGI (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SBC8222J) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|-------------------------|-------------|--------------|
| 1 | 1 | | *REAR BOOTLID | Bent / Buckled | 2,327.25 FL | *2,102.32 FL |
| 2 | 1 | | *REAR BOOT RUBBER | Twisted | 138.03 FL | *138.03 FL |
| 3 | 1 | | *REAR BOOT LOCK (TOP) | Serviceable | 221.49 FL | *- FL |
| 4 | 1 | | *REAR BOOT LOCK (BOTTOM) | Not Necessary | 361.13 FL | *- FL |
| 5 | 1 | | *REAR BOOT TRIMBOARD | Not Necessary | 825.40 FL | *- FL |
| 6 | 2 | | *REAR BOOT TAILLAMP | Not Necessary | 914.85 FL | *- FL |
| 7 | 2 | | *REAR BOOT HINGE | Not Necessary | 240.75 FL | *- FL |
| 8 | 1 | | *REAR BOOT SWITCH | Not Necessary | 160.50 FL | *- FL |
| 9 | 1 | | *E200 EMBLEM | Necessary | 90.25 FL | *90.25 FL |
| 10 | 1 | | *CGI EMBLEM | Necessary | 84.20 FL | *84.20 FL |
| 11 | 1 | | *C&C EMBLEM | Necessary | 48.00 FL | *48.00 FL |
| 12 | 1 | | *MERCEDES CENTRE LOGO | Necessary | 51.70 FL | *51.70 FL |
| 13 | 1 | | *NUMBER PLATE TOP CHROME GARNISH | Necessary | 99.51 FL | *99.51 FL |
| 14 | 2 | | *TAILLAMP | Cracked | 1,187.70 FL | *1,187.70 FL |
| 15 | 1 | | *TAILLAMP LOWER BRACKET (2 PCS) | Cracked | 118.77 FL | *118.77 FL |
| 16 | 1 | | *REAR BUMPER | Distorted | 1,203.75 FL | *1,203.75 FL |
| 17 | 2 | | *REAR BUMPER SIDE RETAINER | Not Necessary | 84.20 FL | *- FL |
| 18 | 1 | | *REAR BUMPER CENTRE BRACKET | Cracked | 256.85 FL | *256.85 FL |
| 19 | 1 | | *REAR BUMPER LOWER BRACKET (3 PCS) | Cracked (2 PCS ONLY) | 52.97 FL | *22.40 FL |
| 20 | 1 | | *REAR BUMPER LOWER DIFFUSER | Distorted | 393.23 FL | *245.32 FL |
| 21 | 2 | | *REAR BUMPER SIDE CHROME | Necessary | 224.70 FL | *224.70 FL |
| 22 | 1 | | *REAR BUMPER CENTRE CHROME | Necessary | 141.24 FL | *141.24 FL |
| 23 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 601.88 FL | *601.88 FL |
| 24 | 1 | | *REVERSE SENSOR WIRE | Not Necessary | 128.40 FL | *- FL |
| 25 | 1 | | *REAR EXHAUST | Repair | 1,540.80 FL | *- FL |
| 26 | 1 | | *REAR EXHAUST COVER | Not Necessary | 36.92 FL | *- FL |
| 27 | 1 | | *END PANEL | Dented / Bent | 979.05 FL | *979.05 FL |
| 28 | 1 | | *END PANEL TOP GARNISH | Twisted | 104.33 FL | *104.33 FL |
| 29 | 1 | | *REAR FENDER INNER TRIMBOARD (LH) | Not Necessary | 184.20 FL | *- FL |
| 30 | 1 | | *HEADREST | N/S Activated / Cracked | 1,540.80 FL | *681.00 FL |
| 31 | 4 | | *REVERSE SENSOR | Shorted (2 PCS ONLY) | 802.50 F | *430.00 FN |
| 32 | 1 | | *END PANEL SEALANT | Necessary | 50.00 FS | *50.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (\$\$) | 15,175.35 | 8,861.00 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 1,432.29 | 838.10 |
| - Nett Item Discount on N Items 0.00/10.00% (\$\$) | 0.00 | 43.00 |

| | | |
|---------------------------|------------------|-----------------|
| Total Parts (\$\$) | 13,743.06 | 7,979.90 |
|---------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO COMPUTER DIAGNOSTIC AND RESETTNG | New | 380.00 | 0.00 |
| 2 | TO CHECK REAR ELECTRICAL WIRING SYSTEM | New | 180.00 | 30.00 |
| 3 | TO REMOVE & REINSTALL COMPONENTS FROM OLD BOOT TO NEW BOOT | New | 200.00 | 60.00 |
| 4 | TO REMOVE INTERIOR TRIM & GARNISHES TO FACILITATE REPAIR | New | 220.00 | 80.00 |
| 5 | TO REMOVE,AND REINSTALL REVERSE SENSORS | New | 120.00 | 50.00 |
| 6 | TO REMOVE & REINSTALL EXHAUST | New | 280.00 | 60.00 |
| 7 | TO SPRAY ANTI-RUSTING COATING ON AFFECTED AREAS | New | 150.00 | 60.00 |
| 8 | LABOUR TO REMOVE,CUT ,CHARGE & PANEL BEATING | New | 1,850.00 | 600.00 |
| 9 | TO PUTTY AND RESPRAY AFFECTED AREAS | New | 1,500.00 | 900.00 |
| Gross Labour Cost (S\$) | | | 4,880.00 | 1,840.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >