

larger case

9

Not Authorized
Hak
1/5 \$ 7750
3/9/19
The No. of the
Sday

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

Vehicle Number: SBC8222J
Vehicle Model : Merc. E200CGI
Chassis : WDD2120482A221074

S/N.	Item Description	Amount (\$)
1	Rear Boot Lid 2102.32 Bmt/Suc	\$ 2,327.25
2	Rear Boot Rubber Tw/	\$ 138.03
3	Rear Boot Lock (Top) su	\$ 221.49
4	Rear Boot Lock (Bottom) 11	\$ 361.13
5	Rear Boot Trimboard 111	\$ 825.40
6	Rear Boot Taillamp x 2 pcs 11	\$ 914.85
7	Rear Boot Hinge x 2 pcs 11	\$ 240.75
8	Rear Boot Switch 11	\$ 160.50
9	"E200" Emblem nu	\$ 90.25
10	"CGI" Emblem nu	\$ 84.20
11	C&C Emblem nu	\$ 48.00
12	Mercedes Centre Logo nu	\$ 51.70
13	Number Plate Top Chrome Garnish nu	\$ 99.51
14	Taillamp x 2 pcs nu	\$ 1,187.70
15	Taillamp Lower Bracket x 2 pcs nu	\$ 118.77
16	Rear Bumper DLS	\$ 1,203.75
17	Rear Bumper Side Retainer x 2 pcs 11	\$ 64.20
18	Rear Bumper Centre Bracket nu	\$ 256.85
19	Rear Bumper Lower Bracket x 3 pcs 11-20x22 nu	\$ 52.97
20	Rear Bumper Lower Diffuser 246.32 DLS	\$ 393.23
21	Rear Bumper Side Chrome x 2 pcs nu	\$ 224.70
22	Rear Bumper Centre Chrome nu	\$ 141.24
23	Rear Bumper Reinforcement Bul	\$ 601.88
24	Reverse Sensor Wire 11	\$ 128.40
25	Rear Exhaust n	\$ 1,540.80
26	Rear Exhaust Cover 11	\$ 36.92
27	End Panel m/suf	\$ 979.05
28	End Panel Top Garnish tw/	\$ 104.33
29	Rear Fender Inner Trimboard (LH) 11	\$ 184.20
30	Headrest x 2 pcs 68/ n/s Achd cre	\$ 1,540.80
Total :		\$ 14,322.82
Less 10% :		\$ 1,432.28
Amount :		\$ 12,890.54

2 pcs 22.40

12C

ARIDAS & ASSOCIATES

ACRA REG. NO : 53131060D

NOTARY PUBLIC

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

NO. 75 BUKIT TIMAH ROAD, #03-13, BOON SIEW BUILDING, SINGAPORE 229833
TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713
E-mail : aridasv @ singnet.com.sg


VYTINGAM ARIDAS

LLB (Hons) Lond. M.A.
Barrister, (Lincoln's Inn)

Service of Court Documents
By Fax
Is Not Acceptable

Our Ref : AA.21582.19.159
Your Ref : Please advise

2 SEPTEMBER 2019

**INDIA INTERNATIONAL INS PTE LTD**

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLES SBC 8222J AND SHD 4063B
ALONG ROBINSON ROAD/CECIL ST JUNCTION ON 28 AUGUST 2019 AT
21:10.**

We are instructed by **TAN BOON GUAN@CHEN WEN PAN** to notify you of a road traffic accident on 02/05/19 at 14:30 involving our client's vehicle registration number **SBC 8222J** and vehicle registration number **SHD 4063B** driven by your insured at the material time.

Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Our client's motor vehicle **SBC 8222J**.

Please contact Ms Connie at office number: 6842 9089. Vehicle can be inspected at:

**M/s Tick Hai Motor & Welding Services,
Block 1 Kaki Bukit Avenue 6,
#01-54 Auto @ Kaki Bukit, Singapore 417883.**

Yours faithfully,
ARIDAS & ASSOCIATES

2 pcs. 430 10%
✓ S.N

α
 30
 60
 80
 50
 60
 60
 600
 900

1. The purpose of the following:

- a. The information is provided.
- b. The damaged part(s); during result.
- c. The part(s) are subject to confirmed.
- d. The survey is on a "Without prejudice" basis.
- e. The modification(s) is allowed.

2. The temporary item(s) must be resurveyed and the results must be final approval from Insurance Company.

Signature:

9-8811
 102

 7529.90
 9819.5
 7815