

not Authorized
 HBL
 3/9/19
 4/5 @ 12.600
 8 day.

FASTECT AUTO PTE LTD
 BLK1 KAKI BUKIT AVE 6
 #01-46,48,50 AUTOBAY
 SINGAPORE 417883

VEHICLE NO:SKZ 8947Z

QTY	PARTICULAR				
1 PCS	BOOTLID	957.40		20/Seat	\$1,255.20
1 PCS	BOOTLID REAR LOGO			MR	\$65.80
1 PCS	BOOTLID 'MAZDA' EMBLEM			MR	\$45.00
1 PCS	BOOTLID '3' EMBLEM			MR	\$62.20
1 PCS	BOOTLID 'SKYACTIVE' EMBLEM			MR	\$65.50
2 PCS	BOOTLID REFLECTORS @\$650.00			11	\$1,300.00
1 PCS	BOOTLID INNER LOCK			1wi	\$288.20
1 PCS	BOOTLID WEATHERSTRIP			1wi	\$291.40
1 PCS	REAR BUMPER	1074.60		20/DE	\$1,215.30
1 PCS	REAR BUMPER REINFORCEMENT	537.30		20	\$611.20
2 PCS	REAR BUMPER SIDE RETAINERS @\$55.60			11	\$111.20
1 SET	REAR BUMPER CLIPS			MR	\$50.00
2 PCS	REAR BUMPER REFLECTORS @\$67.50			0/s/cne	\$135.00
2 PCS	REAR BUMPER SPLASH SHIELDS @\$88.20			11	\$176.40
2 PCS	TAILLAMPS @\$1051.00	915.00		0/s/cne	\$2,102.00
2 PCS	TAILLAMP HOUSING PANELS @\$205.00			11	\$410.00
1 PCS	REAR END PANEL	505.10		20/Seat	\$635.00
1 PCS	REAR END PANEL TOP GARNISH			11	\$366.50
2 PCS	REAR FENDERS @\$1205.00			11	\$2,410.00
2 PCS	REAR FENDER INNER TRIMS @\$388.00			11	\$776.00
1 PCS	REAR WINDSCREEN MOULDING			11	\$145.30
1 PCS	REAR FLOOR PANEL TOP BOARD			11	\$615.00
2 PCS	REAR BUMPER ULTRASONIC SENSORS @\$193.90			shhd	\$387.80
2 PCS	REAR BUMPER TOWING COVERS @\$15.50			Sur	\$31.00
1 PCS	BONNET	1067.30		20/Seat	\$1,285.20
1 PCS	BONNET RUBBER			MR	\$63.00
1 PCS	BONNET INSULATOR			11	\$241.50
1 SET	BONNET INSULATOR CLIPS			11	\$50.00
2 PCS	BONNET HINGES @\$105.00			11	\$210.00
1 PCS	BONNET LOCK			1wi	\$197.00
1 PCS	FRONT BUMPER	1031.70		20	\$1,285.30
2 PCS	FRONT BUMPER SIDE RETAINERS @\$90.50			11	\$181.00
1 PCS	FRONT BUMPER CENTRE GRILLE			CRU	\$121.00
1 SET	FRONT BUMPER CLIPS			MR	\$60.00
2 PCS	FRONT BUMPER LOWER COVER SIDES @\$35.00			MR	\$70.00
1 PCS	FRONT BUMPER REINFORCEMENT	444.50		20	\$751.00
1 PCS	FRONT BUMPER REINFORCEMENT PROTECTOR			205	\$189.00
2 PCS	FRONT BUMPER FOG LAMPS @\$650.00			11	\$1,300.00
2 PCS	FRONT BUMPER FOG LAMP SIDE GARNISHS @\$165.00			n/s de 0/s/m 15	\$330.00
2 PCS	FRONT BUMPER LAMPS @\$288.00			0/s/m 19	\$576.00
1 PCS	FRONT BUMPER TOWING COVER			11	\$38.00
1 PCS	FRONT GRILLE	581.60		CRU	\$688.00
1 PCS	FRONT GRILLE LOGO	82.00		CRU	\$105.00
1 PCS	FRONT GRILLE TOP GARNISH	335.00		DD	\$355.00
2 PCS	FRONT GRILLE INNER BRACKETS @\$32.00			CRU	\$64.00
2 PCS	FRONT GRILLE OUTER CHROME MOULDINGS @\$265.00			176.70 x 2 = 353.40	\$530.00

20%

353.40

7 PCS	FRONT GRILLE RIVETS @\$3.50	mm	\$24.50	✓
1 PCS	FRONT GRILLE TOP BRACKET	mm	\$161.00	X
2 PCS	HEADLAMP HIDS @\$2880.00	cm	\$5,760.00	✓
1 PCS	FRONT SUPPORT PANEL	cm	\$705.00	✓
1 PCS	FRONT SUPPORT PANEL TOP	mm	\$299.00	X
2 PCS	AIR GUIDES @\$99.50	o/s De	\$199.00	lpc
1 PCS	AIR CON CONDENSER	mm	\$1,019.00	X
1 PCS	AIR CON SUCTION HOSE	mm	\$322.00	X
1 PCS	AIR CON DISCHARGE HOSE	mm	\$355.00	X
1 PCS	RADIATOR	mm	\$1,465.00	X
1 PCS	RADIATOR FAN ASSY	mm	\$1,850.00	X
2 PCS	FRONT FENDERS @\$485.00	2	\$970.00	X
2 PCS	FRONT FENDER INNERSHIELDS @\$211.00	mm	\$422.00	X
1 SET	FRONT FENDER INNERSHIELD CLIPS	mm	\$50.00	X
1 PCS	FRONT LICENCE PLATE	cm	\$25.00	15.5.2
1 PCS	REAR END PANEL SEALANT	mm	\$50.00	✓ 5.2
1 PCS	REAR WINDSCREEN SEALANT	mm	\$50.00	X
1 PCS	REAR LICENCE PLATE	mm	\$50.00	X
			\$36,017.50	

2357.30 x 2 = 4714.60
493.70

(207)

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING REAR PDC SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	\$80.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN	mm \$150.00	X
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$120.00	90
TO REFILL AIR CON GAS	mm \$150.00	X
TO MOUNT VEHICLE ON CAR O-LINER	mm \$380.00	X
TO DISMANTLE & REFIX FUEL TANK	mm \$100.00	X
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$2,600.00	1200
TO PUTTY & SPRAY PAINTING	\$2,500.00	1600
TOTAL	\$42,377.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15731.9
12585.52