

INSURANCE

INS. CASE OWNER:

CC 3 / AIG1901 5549, Udaipur

LKK

IDAC

Surveyor:

MARVINS

DOI:

ASSIGNMENT

7/9/19

Date / Time:

7/11/19

Registered in Meriten:

7/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUC 9710A

Name of Insured:

RAKESH MISHRA

Insured Tel No.:

HP:

Express Sec II :SS

D.O.A.:

7/11/19

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident:

Claim No.:

043205600V59

Policy No.:

210150018

Make / Model:

TOYOTA

Place of Accident:

NAST CONSTRUCTION

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SKZ 89472



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Fartech



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	
	After call Itr to OI:	
11/10/19 - FILE PAS TO TYPE MANDATE	Documentation Check List: Handler	Typist
21/2/2020 - FILE PAS TO HMK TO CLOSE	Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: Email  Call

Repair Cost: \$\$ ( days) Reduction: %

FINAL SETTLEMENT Date/Time: 7/1/2020 Confirm with: Jason Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 28

Repair Cost: (with tax) \$\$ 13482.00

Loss of Rental (LOR): \$\$ - ( days)

Loss of Use (LOU): \$\$ 540.00 (5 60 x 9 days)

Loss of Income (LOI): \$\$ - (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LO  (Tick only one)

GIA/LTA Search: \$\$ 2.00

Medical: \$\$ -

Disbursement: \$\$ - (e.g. Tow/ Independent )

Legal Cost: \$\$ -

Total: \$\$ 14024.00 Global Sum \$\$:

FINAL PAYMENT Date/Time: Confirm with: Email  Call

Payee 1: \$\$ 14024.00 Name 1: Fartech Auto Pte Ltd

Payee 2: (Strike if N.A.) \$\$ Name 2:

Payee 3: (Strike if N.A.) \$\$ Name 3:

COPY SENT 21/2/2020

- 1) Claim status: No Mandate/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$320



FASTECT AUTO PTE LTD  
 BLK1 KAKI BUKIT AVE 6  
 #01-46,48,50 AUTOBAY  
 SINGAPORE 417883

not Authorized  
 Hble  
 3/9/19  
 4/5 @ 12.600  
 8 day.

VEHICLE NO: SKZ 8947Z

QTY	PARTICULAR				
1 PCS	BOOTLID	957.40		20/seat	\$1,255.20
1 PCS	BOOTLID REAR LOGO			RM	\$65.80
1 PCS	BOOTLID 'MAZDA' EMBLEM			RM	\$45.00
1 PCS	BOOTLID '3' EMBLEM			RM	\$62.20
1 PCS	BOOTLID 'SKYACTIVE' EMBLEM			RM	\$65.50
2 PCS	BOOTLID REFLECTORS @\$650.00			11	\$1,300.00
1 PCS	BOOTLID INNER LOCK			1W1	\$288.20
1 PCS	BOOTLID WEATHERSTRIP			1W1	\$291.40
1 PCS	REAR BUMPER	1074.60		20/oe	\$1,215.30
1 PCS	REAR BUMPER REINFORCEMENT	537.30		10	\$611.20
2 PCS	REAR BUMPER SIDE RETAINERS @\$55.60			11	\$111.20
1 SET	REAR BUMPER CLIPS			RM	\$50.00
2 PCS	REAR BUMPER REFLECTORS @\$67.50			o/s cne	\$135.00
2 PCS	REAR BUMPER SPLASH SHIELDS @\$88.20			11	\$178.40
2 PCS	TAILLAMPS @\$1051.00	815.00		o/s cne	\$2,102.00
2 PCS	TAILLAMP HOUSING PANELS @\$205.00			11	\$410.00
1 PCS	REAR END PANEL	105.10		20/seat	\$635.00
1 PCS	REAR END PANEL TOP GARNISH			11	\$366.50
2 PCS	REAR FENDERS @\$1205.00			11	\$2,410.00
2 PCS	REAR FENDER INNER TRIMS @\$388.00			11	\$776.00
1 PCS	REAR WINDSCREEN MOULDING			11	\$145.30
1 PCS	REAR FLOOR PANEL TOP BOARD			11	\$615.00
2 PCS	REAR BUMPER ULTRASONIC SENSORS @\$193.90			shhh	\$387.80
2 PCS	REAR BUMPER TOWING COVERS @\$15.50			Sur	\$31.00
1 PCS	BONNET	1067.30		20/Seat	\$1,285.20
1 PCS	BONNET RUBBER			RM	\$63.00
1 PCS	BONNET INSULATOR			11	\$241.50
1 SET	BONNET INSULATOR CLIPS			11	\$50.00
2 PCS	BONNET HINGES @\$105.00			11	\$210.00
1 PCS	BONNET LOCK			1W1	\$197.00
1 PCS	FRONT BUMPER	1031.70		20	\$1,285.30
2 PCS	FRONT BUMPER SIDE RETAINERS @\$90.50			11	\$181.00
1 PCS	FRONT BUMPER CENTRE GRILLE			CN	\$121.00
1 SET	FRONT BUMPER CLIPS			RM	\$60.00
2 PCS	FRONT BUMPER LOWER COVER SIDES @\$35.00			11.5	\$70.00
1 PCS	FRONT BUMPER REINFORCEMENT	444.50		20	\$751.00
1 PCS	FRONT BUMPER REINFORCEMENT PROTECTOR			20.5	\$189.00
2 PCS	FRONT BUMPER FOG LAMPS @\$650.00			11	\$1,300.00
2 PCS	FRONT BUMPER FOG LAMP SIDE GARNISHS @\$165.00			n/s oe o/s m 15	\$330.00
2 PCS	FRONT BUMPER LAMPS @\$288.00			o/s m	\$576.00
1 PCS	FRONT BUMPER TOWING COVER			11	\$38.00
1 PCS	FRONT GRILLE	581.60		CN	\$688.00
1 PCS	FRONT GRILLE LOGO	85.00		CN	\$105.00
1 PCS	FRONT GRILLE TOP GARNISH	335.00		DD	\$355.00
2 PCS	FRONT GRILLE INNER BRACKETS @\$32.00			CN	\$64.00
2 PCS	FRONT GRILLE OUTER CHROME MOULDINGS @\$265.00			176.70 x 2 = 353.40	\$530.00

20%

7 PCS	FRONT GRILLE RIVETS @\$3.50
1 PCS	FRONT GRILLE TOP BRACKET
2 PCS	HEADLAMP HIDS @\$2880.00
1 PCS	FRONT SUPPORT PANEL
1 PCS	FRONT SUPPORT PANEL TOP
2 PCS	AIR GUIDES @\$99.50
1 PCS	AIR CON CONDENSER
1 PCS	AIR CON SUCTION HOSE
1 PCS	AIR CON DISCHARGE HOSE
1 PCS	RADIATOR
1 PCS	RADIATOR FAN ASSY
2 PCS	FRONT FENDERS @\$485.00
2 PCS	FRONT FENDER INNERSHIELDS @\$211.00
1 SET	FRONT FENDER INNERSHIELD CLIPS
1 PCS	FRONT LICENCE PLATE
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR LICENCE PLATE

2357.30 x 2 = 4714.60  
493.70

(202)

net	\$24.50	✓
11	\$161.00	X
CRU	\$5,760.00	✓
CRQ	\$705.00	✓
11	\$299.00	X
o/s De	\$199.00	PC
11	\$1,019.00	X
11	\$322.00	X
11	\$355.00	X
11	\$1,465.00	X
11	\$1,850.00	X
2	\$970.00	X
11	\$422.00	X
11	\$50.00	X
CRU	\$25.00	15.5.2
net	\$50.00	✓ 5.2
11	\$50.00	X
11	\$50.00	X
\$36,017.50		

LABOUR CHARGES:

- TO CHECK WIRING
- TO DISMANTLE & REPLACING REAR PDC SENSOR
- TO TRANSFER BOOTLID MECHANISM
- TO DISMANTLE & REFIX REAR WINDSCREEN
- TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY
- TO SPRAY RUST PROOFING
- TO REFILL AIR CON GAS
- TO MOUNT VEHICLE ON CAR O-LINER
- TO DISMANTLE & REFIX FUEL TANK
- LABOUR FOR PANEL BEATING & REPLACING PARTS
- TO PUTTY & SPRAY PAINTING

	\$80.00	30
	\$80.00	50
	\$80.00	60
11	\$150.00	X
	\$120.00	80
	\$120.00	90
11	\$150.00	X
11	\$380.00	X
11	\$100.00	X
	\$2,600.00	1200
	\$2,500.00	1600
TOTAL	\$42,377.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before water spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No further modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

15731-9  
12585.52


> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	584H
<b>Vehicle Details</b>	
Vehicle No.:	SKZ8947Z
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	P520338358
Chassis No.:	JM6BM42A8G0329200
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,812.00
Original Registration Date:	12 Feb 2016
First Registration Date:	12 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$12,812.00 <i>6406</i>
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Feb 2026
PARF Rebate Amount:	\$9,609.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	11 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,301.00
COE Rebate Amount:	\$33,040.00
<b>Total Rebate Amount:</b>	<b>\$42,649.00</b>

The information contained herein is correct as at 03 Sep 2019

OK



Mazda 3 Price Range Depreciation 2016 Vehicle Type Search

Home > Used Cars > Qin Cheng Cars Enterprise > Mazda 3 HB 1.5A Sunroof

Mazda 3 HB 1.5A Sunroof

Overview Financial Insurance Accessories Similar Research Photos Map

<b>Price</b>	\$63,000	<b>Reg Date</b>	22-Feb-2016 (6yrs Smiths 18days COE left)
<b>Depreciation</b>	\$8,710 /yr <small>View models with similar depn</small>	<b>Manufactured</b>	2015
<b>Mileage</b>	63,000 km (17.6k /yr)	<b>Transmission</b>	Auto
<b>Road Tax</b>	\$682 /yr	<b>OMV</b>	\$18,265
<b>Dereg Value</b>	\$40,150 as of today (change)	<b>ARF</b>	\$13,265
<b>COE</b>	\$46,651	<b>Power</b>	88.0 kW (118 bhp)
<b>Engine Cap</b>	1,496 cc	<b>No. of Owners</b>	1
<b>Curb Weight</b>	1,324 kg		
<b>Type of Vehicle</b>	Hatchback		



Shortlist Compare Add new Report Error More Actions

Features

4 Cylinder Inline 16 Valve DOHC SkyActiv-G, 8 Speed(A) SkyActiv-Drive, Traction/Cruise Control, Sunroof, Keyless Entry/Start, Daytime Running Lights. View specs of the Mazda 3 Hatchback (2014-2019)

Accessories

Sunroof, 17" Sports Rims, Solar Film, Factory Fitted Audio System, Electrical Retractable Side Mirrors With Indicators, Upholstery Leather Seats

Description

1 Owner, Sunroof, Fuel Efficient And Reliable Hatchback, Keyless Entry/Start, Bluetooth, Well Maintained, Excellent Condition.

Category

MPV Car

Status

Available

Resources

**STA** Vehicle Evaluation  
Afraid of lemons? Request to have this car evaluated professionally. Find out more

**Car Valuation - Free**  
Find out the market value of your existing car for free. Get started

Seller Information

<b>Company</b>	Qin Cheng Cars Enterprise * dealer's profile * 4 units sold   4 units available	
<b>Address</b>	60 Jalan Lam Huat #03-14/15 <small>Search cars nearby the location</small>	
<b>Location</b>	Carica Centre	
<b>Office No</b>	66725855	
<b>Contact Person(s)</b>	Kent	93874432
	Johnny	98553733
	Anthony	98553555

Posted on: 11-Aug-2019 | Last Updated on: 21-Aug-2019

Upfront Payment		<a href="#">View Financial Info</a>
<b>Transfer Fee</b>	\$25	
<b>Down Payment</b>	\$18,900 (change)	Maximum 10% Loan
<b>1st Instalment</b>	\$682	Based on 2.99% interest rate
<b>Insurance</b>	\$1,372 onwards Not at fault? No upfront payment required! (Get a quote) <small>Quote assumes a standard profile. "Get a quote" for exact figure</small>	
<b>Total Upfront Payment</b>	\$20,879	Click with seller for exact figure

Products and Services [View All](#)



The Largest Car No. Plate market in SG Company



Customised Upholstery For Mazda 3 Pro S280



Fog Light

# Japanese Luxurious Barber

Open All Year Round. Weekday:  
12:00-20:00 / Sat-Sun  
(Holiday):10:00-19:00.

Mazda 3 Price Range Depreciation 2016 Vehicle Type Submit Advanced Search

Home > Used Cars > Presto Expat Motoring Services Pte Ltd > Mazda 3 1.5A Sunroof

## Mazda 3 1.5A Sunroof

Overview Financial Insurance Accessories Similar Research Photos Map

<b>Price</b>	\$61,800		
<b>Depreciation</b>	\$8,570 /yr <small>View models with similar depre</small>	<b>Reg Date</b>	31-Mar-2016 (6yrs 6mths 27days COE left)
<b>Mileage</b>	27,000 km (7.9k /yr)	<b>Manufactured</b>	2015
<b>Road Tax</b>	\$682 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b>	\$38,812 as of today (change)	<b>OMV</b>	\$15,836
<b>COE</b>	\$46,667	<b>ARF</b>	\$10,836
<b>Engine Cap</b>	1,496 cc	<b>Power</b>	88.0 kW (118 bhp)
<b>Curb Weight</b>	1,321 kg	<b>No. of Owners</b>	1
<b>Type of Vehicle</b>	Mid-Sized Sedan		



### Features

1.5L 4-Cylinder In-Line 16-Valve DOHC SKYACTIV-G Engine. 6 Speed Automatic Transmission. SRS Airbags. Keyless Start, I-Stop. View specs of the Mazda 3 Sedan (2014-2019)

### Accessories

Sunroof, Factory Fitted Audio System, Multi Function Steering, Reverse Sensors And Camera, Retractable Side Mirror With Indicator

### Description

1 Owner, Low Mileage, Pristine Condition! Popular Sedan Know For Its Fuel Efficiency And Comfort. Call Now To View!

### Category

PARF Car, Low Mileage Car

### Status

Available

### Resources



**Vehicle Evaluation**  
Afraid of lemons? Request to have this car evaluated professionally. Find out more.



**Car Valuation - Free**  
Find out the market value of your existing car for free. Get started

Posted on: 10-Aug-2019 | Last Updated on: 10-Aug-2019

Upfront Payment Compare

> more Financial info



### Seller Information

**Company** Presto Expat Motoring Services Pte Ltd  
 • dealer's pricelist  
 • 40 vehs sold | 30 vehs available

**Address** 491 River Valley Road #01-04

## View Received Message

This mail is associated with :

**\*SKZ8947Z (04326560025G)  
[SLK9710A]**

TP  
LUI SING WING  
Sep 3 2019 9:00AM  
[RAKESH MISHRA]  
Fastech Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 03/01/2020 10:38 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$14024.00) - SKZ8947Z - Claim Handler: Ler, Bernard-JQ

Approved:14024.00:Cost of Repair \$13,482.00 As per surveyor finalization Loss of Use \$540.00 9 days @ S\$ 60/day LTA/ GIA Search Fee \$2.00 Total \$14,024.00

### DOCUMENTS SUMMARY

There are no documents.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2019 <a href="#">Edit Reg</a>		03 Sep 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$12,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$12,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>RAKESH MISHRA</b> , ID: S27250608								
Main Claimant:	<b>LUI SING WING</b> , ID: S0157584H								
Vehicle Reg. No.:	<b>SKZ8947Z</b>	Date of Loss:	03/09/2019 09:00 - :59 [42 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 0432656002SG</b>	Policy/Cover Note No.:	2100500018 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLK9710A</b>	Policy No. (Claimant):	2100450772-03						
		Excess:							
Repairer:	<b>Fastech Auto Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 12/09/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (03/01/2020): Alert - Adj Mandate Approved (S\$14024.00) - SKZ8947Z - Claim Handler: Ler, Berna...</li> <li>AIG_SG (04/09/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKZ8947Z (0432656002SG)  
 [SLK9710A]  
 TP  
 LUI SING WING  
 Sep 3 2019 9:00AM  
 [RAKESH MISHRA]  
 Fastech Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
<b>Letters/Correspondences</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	03/09/19 17:39	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
2	03/09/19 17:39	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
3	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
4	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
5	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
6	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
7	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
8	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
9	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
10	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
11	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
12	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
13	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
14	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
15	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
16	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
17	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
18	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
19	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
20	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
21	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
22	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
23	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
24	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
25	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
26	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
27	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
28	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
29	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
30	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
31	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
32	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
33	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
34	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
35	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
36	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
37	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
38	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
39	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	
40	03/09/19 17:39	General View							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	03/09/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/09/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/09/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/09/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/09/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/09/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
68	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
69	03/09/19 17:40	General View	 Load JPG	<input checked="" type="checkbox"/>
70	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	03/09/19 17:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
97	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
98	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
99	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
100	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
101	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
102	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
103	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
104	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
105	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
106	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
107	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
108	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
109	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
110	03/09/19 17:40	Reinspection Photo		<input checked="" type="checkbox"/>
111	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
112	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
113	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
114	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
115	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
116	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
117	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
118	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
119	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
120	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
121	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
122	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
123	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
124	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
125	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
126	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
127	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
128	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
129	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
130	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
131	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
132	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
133	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
134	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
135	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
136	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
137	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
138	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
139	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
140	03/09/19 17:41	Reinspection Photo		<input checked="" type="checkbox"/>
141	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
142	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
143	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
144	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
145	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
146	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
147	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
148	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
149	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>
150	23/09/19 16:23	After Repair Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/19 17:30	<b>TP GIA REPORT</b>	 Load PDF	
2	04/12/19 15:49	<b>GIA SEARCH</b>	 Load PDF	
3	04/12/19 15:49	<b>LOD</b>	 Load PDF	
4	05/12/19 12:53	<b>TP ESTIMATE - MARKED</b>	 Load PDF	
5	25/02/20 10:35	<b>WORKSHOP INVOICE</b>	 Load PDF	
6	25/02/20 10:35	<b>AUTHORISATION TO ACT FORM</b>	 Load PDF	
7	25/02/20 10:35	<b>Release Voucher</b>	 Load PDF	
8	25/02/20 10:35	<b>LETTER TO OI</b>	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/09/19 11:34	<b>OI GIA REPORT</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	SLK9710A (Insd veh)	<b>Model:</b>	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A)
	SKZ8947Z (TP veh)		
<b>Date of Accident:</b>	03/09/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	45,343.93	
Final Repair Cost	:	\$	13,482.00	
Loss of Use	:	\$	540.00	9.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	14,024.00	
<b>Is Third Party Workshop GIA Registered?</b> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
<b>A) For Non GIA Registered Workshop:</b>		Agreed Liability ___100___(%)		
<b>B) For GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____(%)		Assessed Liability (*):___100___(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 14,024.00
2)		:	\$
3)		:	\$

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
25 Feb  
2020

Date

**Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))**

## LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19015549/UDS3Q2

Date: 25/02/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100500018  
 Claimant  
 Vehicle No : SKZ8947Z Insured Vehicle No : SLK9710A  
 Date of Loss: 03/09/2019 Nature of Claim: TP Claim No: 0432656002SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKZ8947Z  
 Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520338358  
 Reg. Date: 12/02/2016 (Man. Year: 2015) Chassis No: JM6BM42A8G0329200  
 Colour: Blue Odometer: 31208 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,017.50	12,650.52	23,366.98	64.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,360.00	3,110.00	3,250.00	51.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>42,377.50</b>	<b>15,760.52</b>	<b>26,616.98</b>	<b>62.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>12,600.00</b>		
(S\$)	42,377.50	12,600.00	29,777.50	70.27
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,966.43</b>	<b>882.00</b>	<b>2,084.43</b>	<b>70.27</b>
<b>Nett Amount (S\$)</b>	<b>45,343.93</b>	<b>13,482.00</b>	<b>31,861.93</b>	<b>70.27</b>
<b>+ Loss of Use (9.0 x S\$60.00/day) (S\$)</b>		<b>540.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>14,024.00</b>		

## INSPECTION

Date of Assignment: 03/09/2019  
 Date Inspected: 03/09/2019 Inspected At: Fastech Auto Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, #01-46/48/50  
 Autobay  
 Singapore 417883  
 Estimated Period of Repair: 8.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	1,255.20 F	*957.40 FL
2	1		*BOOTLID REAR LOGO	Necessary	65.80 F	*65.80 FL
3	1		*BOOTLID MAZDA EMBLEM	Necessary	45.00 F	*45.00 FL
4	1		*BOOTLID 3 EMBLEM	Necessary	62.20 F	*62.20 FL
5	1		*BOOTLID SKYACTIVE EMBLEM	Necessary	65.50 F	*65.50 FL
6	2		*BOOTLID REFLECTORS	Not Necessary	1,300.00 F	*- FL
7	1		*BOOTLID INNER LOCK	Twisted	288.20 F	*288.20 FL
8	1		*BOOTLID WEATHERSTRIP	Twisted	291.40 F	*291.40 FL
9	1		*REAR BUMPER	Dented / Deformed	1,215.30 F	*1,074.80 FL
10	1		*REAR BUMPER REINFORCEMENT	Dented	611.20 F	*537.30 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	111.20 F	*- FL
12	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
13	1		*REAR BUMPER REFLECTORS	O/S Cracked	135.00 F	*67.50 FL
14	2		*REAR BUMPER SPLASH SHIELDS	Not Necessary	176.40 F	*- FL
15	1		*TAILLAMP	O/S Cracked	2,102.00 F	*915.00 FL
16	2		*TAILLAMP HOUSING PANELS	Repair	410.00 F	*- FL
17	1		*REAR END PANEL	Dented / Bent	635.00 F	*505.10 FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	366.50 F	*- FL
19	2		*REAR FENDERS	Repair	2,410.00 F	*- FL
20	2		*REAR FENDER INNER TRIMS	Not Necessary	776.00 F	*- FL
21	1		*REAR WINDSCREEN MOULDING	Not Necessary	145.30 F	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	615.00 F	*- FL
23	2		*REAR BUMPER ULTRASONIC SENSORS	Shorted (1 PCS ONLY)	387.80 F	*193.90 FL
24	2		*REAR BUMPER TOWING COVERS	Serviceable	31.00 F	*- FL
25	1		*BONNET	Dented / Buckled	1,285.20 F	*1,067.30 FL
26	1		*BONNET RUBBER	Necessary	63.00 F	*63.00 FL
27	1		*BONNET INSULATOR	Not Necessary	241.50 F	*- FL
28	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
29	2		*BONNET HINGES	Not Necessary	210.00 F	*- FL
30	1		*BONNET LOCK	Twisted	197.00 F	*197.00 FL
31	1		*FRONT BUMPER	Dented	1,285.30 F	*1,031.70 FL
32	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	181.00 F	*- FL
33	1		*FRONT BUMPER CENTRE GRILLE	Cracked	121.00 F	*121.00 FL
34	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
35	2		*FRONT BUMPER LOWER COVER SIDES	Missing	70.00 F	*70.00 FL
36	1		*FRONT BUMPER REINFORCEMENT	Dented	751.00 F	*444.50 FL
37	1		*FRONT BUMPER REINFORCEMENT PROTECTOR	Distorted	189.00 F	*189.00 FL
38	2		*FRONT BUMPER FOG LAMPS	Not Necessary	1,300.00 F	*- FL
39	2		*FRONT BUMPER FOG LAMP SIDE GARNISHES	N/S Deformed / O/S Missing	330.00 F	*330.00 FL
40	1		*FRONT BUMPER LAMPS	O/S Cracked	576.00 F	*288.00 FL
41	1		*FRONT BUMPER TOWING COVER	Not Necessary	38.00 F	*- FL
42	1		*FRONT GRILLE	Cracked	688.00 F	*581.60 FL
43	1		*FRONT GRILLE LOGO	Cracked	105.00 F	*85.00 FL
44	1		*FRONT GRILLE TOP GARNISH	Dented	355.00 F	*335.00 FL
45	2		*FRONT GRILLE INNER BRACKETS	Cracked	64.00 F	*64.00 FL
46	2		*FRONT GRILLE OUTER CHROME MOULDINGS	Scratched / Cracked	530.00 F	*353.40 FL
47	7		*FRONT GRILLE RIVETS	Necessary	24.50 F	*24.50 FL
48	1		*FRONT GRILLE TOP BRACKET	Not Necessary	161.00 F	*- FL
49	2		*HEADLAMP HIDS	Cracked	5,760.00 F	*4,714.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*FRONT SUPPORT PANEL	Cracked	705.00 F	*493.70 FL
51	1		*FRONT SUPPORT PANEL TOP	Not Necessary	299.00 F	*- FL
52	1		*AIR GUIDES	O/S Deformed	199.00 F	*99.50 FL
53	1		*AIR CON CONDENSER	Not Necessary	1,019.00 F	*- FL
54	1		*AIR CON SUCTION HOSE	Not Necessary	322.00 F	*- FL
55	1		*AIR CON DISCHARGE HOSE	Not Necessary	355.00 F	*- FL
56	1		*RADIATOR	Not Necessary	1,465.00 F	*- FL
57	1		*RADIATOR FAN ASSY	Not Necessary	1,850.00 F	*- FL
58	2		*FRONT FENDERS	Repair	970.00 F	*- FL
59	2		*FRONT FENDER INNERSHIELDS	Not Necessary	422.00 F	*- FL
60	1		*SET FRONT FENDER INNERSHIELD CLIPS	Not Necessary	50.00 F	*- FL
61	1		*FRONT LICENCE PLATE	Cracked	25.00 FS	*15.00 FS
62	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
63	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 F	*- FL
64	1		*REAR LICENCE PLATE	Not Necessary	50.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>36,017.50</b>	<b>15,796.90</b>
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	3,146.38
<b>Total Parts (S\$)</b>	<b>36,017.50</b>	<b>12,650.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REAR PDC SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
6	TO SPRAY RUST PROOFING	New	120.00	90.00
7	TO REFILL AIR CON GAS	New	150.00	0.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
10	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,600.00	1,200.00
11	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,600.00
<b>Gross Labour Cost (S\$)</b>			<b>6,360.00</b>	<b>3,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >