

H31A0 TUN



AUTOCLINIC PTE LTD

48 TOH GUAN ROAD EAST #02-136 Enterprise Hub Singapore 608586
TEL: 6686 2511 FAX: 6686 2509 Email: info@autoclinicgroup.com.sg
GST:201801145H RCB NO:201801145H

M/S : CHENG MUN YI MANDY 81805474
BLK 182 YUNG SHENG ROAD #17-51

SINGAPORE 610182
TEL: 81805474
ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 27/08/2019

Estimate No: QUO1800027
Date: 11 Sep 2019
Policy No:
Veh Reg No: SGX7879B
Make/Model: HONDA CIVIC 2.0L A
Chassis No: JHMFD26407S201662
Engine No: K20Z22501661
Reg. Date: 12/11/2007

Estimate Repair Cost to Vehicle No : SGX7879B

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Others				
1 #24 REAR BOOT LOCK <i>scr</i>	0.00	1PC	194.50	767.46
2 #27 REAR BOOT RUBBER <i>cut</i>	0.00	1PC	115	
3 #15 REAR BUMPER <i>de</i>	0.00	1PC	457.96	613.96
4 LABOUR WORKS FOR SPRAY PAINTING	0.00	1PC	680.00	
5 CHECK WIRING AND LIGHTING	0.00	1PC	60.00	990
6 REMOVE AND REFIT REAR UNDERCARRIAGE PANEL PARTS	0.00	1PC	320.00	
7 PANEL BEATING (LABOUR CHARGES)	0.00	1PC	120.00	2,146.21

Total Amount Payable S\$ 2,146.21

Include GST @ 7% For 2,005.80 = \$140.41

TOTAL: SINGAPORE DOLLAR TWO THOUSAND ONE HUNDRED FORTY SIX AND CENTS TWENTY ONE ONLY

For AUTOCLINIC PTE LTD

AUTHORISED SIGNATURE

Rasul
Hp 90010068
4 days
4/8
04/09/12 @ 1430
Resurvey after repair

613.96
990.00
1603.96
20%
1283.16
4/8-1300
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: