



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGC1308H*RA

Chew Chee Boon

Blk 80A Telok Blangah Street 31
#36-105
Singapore 101080

Mobile: 97331640

Vehicle & Document Information

WIP No **36648**
Reg No/Reg Date **SGC1308H*RA / 20/05/2013**
Date In/Mileage **1 / 0**
Chassis No **WDD2040312A838150**
Engine No **27491030041500**
Make/Model **MB/C 180 CGI BlueEFFICIENCY**
Colour/Trim **021 183 Magnetite B/ 042 228 Leather Alp**

Account No	Terms	Date/Time Printed	CSE	Operator	
CSM00128	Cash	02/09/2019/ 15:44	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : GA417040 // 01-09-2019
DRIVE IN/02-09-2019 // TP CAR NO: SLP9769E (AXA INSURANCE)

DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT

A BPILAB

REMOVE & REPLACE FRONT LEFT DOOR & REMOVE FRONT LEFT FENDER AND
LEFT RUNNING BOARD

A BPIRES

RESPRAY FRONT LEFT DOOR, FRONT LEFT FENDER & LEFT RUNNING BOARD

M LH/F DOOR SHELL

1.00 1811.08 00.00 1811.08

M LH/F DOOR WEATHERSTRIP

1.00 305.97 00.00 305.97

M LH/F DOOR ORNAMENTAL

1.00 126.28 00.00 126.28

M LH/F DOOR BOTTOM SEAL

1.00 57.33 00.00 57.33

M LH/F DOOR TOP INSULATION

1.00 35.87 00.00 35.87

M LH/F DOOR WINDOW GUIDE RAIL

1.00 106.62 00.00 106.62

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **6,943.15**
7% GST on **6943.15** **486.02**

Authorized signatory and company stamp

Total Payable 7,429.17

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

