



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 60 Woodlands Industrial Park E4, Singapore 757705  
 FAX Number: 8388592  
 Estimator Telephone Number: 66662623  
 Accident Reporting Number: 88682672

Date Generated: 24/08/2019  
 User ID: PehSuan

| Section A - Accident Details       |                    |
|------------------------------------|--------------------|
| Registration Number                | SHB1642K           |
| Case Reference Number              | TAX/08/19/2128     |
| Registration Date                  | 9/7/2014           |
| Company Type                       | SMRT Taxis Pte Ltd |
| Make                               | TOYOTA             |
| Model                              | PRIUS              |
| Name of Driver                     | GOAY KOK CHUAN     |
| Type of Accident                   | Head to Rear       |
| Accident Date and Time             | 29/8/2019 9:20 PM  |
| Accident Reported Date and Time    | 30/8/2019 12:30 PM |
| Is Surveyor Required?              | Yes                |
| Survey by                          |                    |
| Vehicle is Towed Back?             | No                 |
| Towed Back Date and Time           |                    |
| Replacement Vehicle issued?        | No                 |
| Job Card Number                    | 24103117           |
| Special Instruction to ARC, if any | TP/ REAR PORTION   |
| Prepared Date and Time             | 31/8/2019 9:41 AM  |
| Chassis Number                     |                    |
| Mileage                            |                    |
| Work Shop                          |                    |
| Repair Completion Date and Time    |                    |

| Section B - Summary of Repair Estimates |                    |  |
|---|--------------------|--|
| Summary of Repair Estimates             |                    |  |
|   | Quotation from ARC | Adjusted by Surveyor, if applicable                                  |
| Total Labour Cost                       | \$676.00           | \$300.00   |
| Total Spray Cost                        | \$936.00           | \$300.00   |
| Total Spare Part Cost                   | \$2,664.74         | \$383.76   |
| Total Other Cost                        | \$360.00           | \$40.00  |
| <b>TOTAL COST</b>                       | <b>\$4,636.74</b>  | <b>\$1,023.76</b>  |
| Lump Sum Total                          | \$4,650.00         | \$1,000.00 (L/S)   |
| Number of Repair Days                   | 5.0                | 3.0  |
| Prepared / Adjusted By                  | Ang Bang Kien      | STEVE CHEN (LKK) / AXA   |
| ARC / Surveyor Sign Off Date            | 02/09/2019 3:18 PM | 02/09/2019 11:58 AM  |
| Signature                               |                    |  |
| Remarks                                 |                    | L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com |

| Section C - Quotation and Accident Invoice Details |              |                |  |
|--|--------------|----------------|--|
| Quotation Number                                   | QN-1909-0260 | Invoice Number |  |
| Quotation Date                                     | 17.09.2019   | Invoice Date   |  |
| Invoice Amount                                     |              | Prepared Date  |  |

| Section D - Details of Repair Estimates |                   |                                     |
|---|-------------------|-------------------------------------|
| Part 1 - Labour Works                   |                   |                                     |
| Job Scope                               | Quotation from AR | Adjusted by Surveyor, if applicable |
| TO REPAIR REAR PORTION                  | \$676.00          | \$300.00                            |
| <b>Total Labour</b>                     | <b>\$676.00</b>   | <b>\$300.00</b>                     |

| Part 2 - Spray Painting & Panel Beating Related Works |                    |                                     |
|---|--------------------|-------------------------------------|
| Job Scope   | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO RESPRAY REAR BUMPER                                | \$378.00           | \$200.00                            |
| TO RESPRAY BUMPER BEAM                                | \$180.00           | \$0.00                              |
| TO RESPRAY REAR PANEL                                 | \$378.00           | \$100.00                            |
| <b>Total Spray Painting &amp; Panel Beating</b>       | <b>\$936.00</b>    | <b>\$300.00</b>                     |

| Part 3 - Other Costs - Accident and Accident Repair Related Expense |                    |                                     |
|---|--------------------|-------------------------------------|
| Job Scope   | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                             | \$120.00           | \$0.00                              |
| TO REPLACE SUNDRY PARTS   | \$100.00           | \$20.00                             |
| TO CHECK WIRING AND SYSTEM FUNCTION                                 | \$80.00            | \$20.00                             |
| TO WASH AND VACUUM  | \$60.00            | \$0.00                              |
| <b>Total Other Costs</b>  | <b>\$360.00</b>    | <b>\$40.00</b>                      |

| Part 4 - Spare Parts / Material Usage |         |              |                            |          |                 |              |                  |                    |                   |
|---------------------------------------|---------|--------------|----------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| Part Number                           | Portion | Stock Number | Part Name                  | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|                                       |         | 52159-47905  | BUMPER REAR                | 1.00     | \$458.60        | 25.00        | \$343.95         | Replace            | Replace           |
|                                       |         | 90467-07211  | BUMPER CLIPS               | 10.00    | \$2.10          | 25.00        | \$15.75          | Replace            | Replace           |
|                                       |         | 52023-12240  | BUMPER REINFORCEME         | 0.00     | \$205.70        | 0.00         | \$0.00           | Replace            | Check             |
|                                       |         | 52018-47030  | ARM SUB-ASSY, RR BUMPER RH | 0.00     | \$139.60        | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 52016-47030  | ARM SUB-ASSY, RR BUMPER LH | 0.00     | \$139.60        | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 89997-30070  | ANTENNA,ELEC TRICAL LOWER  | 0.00     | \$157.40        | 0.00         | \$0.00           | Replace            | Check             |
|                                       |         |              | SENSOR REVERSE             | 0.00     | \$180.00        | 0.00         | \$0.00           | Replace            | Check             |
|                                       |         | 52578-47020  | BUMPER SIDE RETAINER       | 0.00     | \$94.80         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 52575-47020  | BUMPER SIDE RETAINER       | 0.00     | \$94.80         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 52592-47021  | BUMPER SEAL, RR LH         | 0.00     | \$88.90         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 52591-47021  | BUMPER SEAL, RR RH         | 0.00     | \$65.70         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 76088-47020  | BUMPER LIP COVER RR/LH     | 0.00     | \$72.20         | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 76087-47020  | BUMPER LIP COVER RR/RH     | 0.00     | \$118.10        | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 76891-47020  | BUMPER LIP REAR            | 0.00     | \$228.90        | 0.00         | \$0.00           | Replace            | Not Given         |
|                                       |         | 81561-47170  | TAIL LAMP LH               | 0.00     | \$548.40        | 0.00         | \$0.00           | Replace            | Not Given         |



SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 80 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number: 63685502                              |
| Estimator Telephone Number: 68662023              |
| Accident Reporting Number: 68662672               |

Date Generated : 24/09/2018

User ID : FahSuan

|              |             |                       |      |                   |        |                 |         |           |   |
|--------------|-------------|-----------------------|------|-------------------|--------|-----------------|---------|-----------|---|
|              | 58307-47060 | END PANEL             | 1.00 | \$602.10          | 100.00 | \$0.00          | Replace | Repair    | ✓ |
|              |             | SEALANT SIKAFLEX      | 0.00 | \$37.00           | 0.00   | \$0.00          | Replace | Not Given | X |
|              | 67881-47022 | TAILGATE DOOR WEATHER | 0.00 | \$353.40          | 0.00   | \$0.00          | Replace | Not Given | X |
|              | 69350-47030 | TAILGATE DOOR LOCK    | 0.00 | \$444.10          | 0.00   | \$0.00          | Replace | Not Given | X |
|              | 69431-47010 | STRIKER, BACK DOOR    | 0.00 | \$48.90           | 0.00   | \$0.00          | Replace | Not Given | X |
|              |             | PIXEL STICKER         | 2.00 | \$60.00           | 0.00   | \$120.00        | Replace | Replace   | ✓ |
| <b>Total</b> |             |                       |      | <b>\$4,140.30</b> |        | <b>\$479.70</b> |         |           |   |

| Added Spare Parts / Material Usage After Surveyor Signed off |         |              |           |          |               |              |                  |           |                |
|--|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Part Number  | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
| Total  |         |              |           |          |               |              |                  |           |                |

479.70  
 - 202  
 383.76  
 + 300.00  
 + 340.00  


---

 1023.76  
 4s \$1000/-



### SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number 63685592                               |
| Estimator Telephone Number 68662623               |
| Accident Reporting Number 68662672                |

Date Generated : 02/09/2019

User ID : kimmingshin

| Section A - Accident Details       |                    |
|------------------------------------|--------------------|
| Registration Number                | SHB1642K           |
| Case Reference Number              | TAX00B/19/212B     |
| Registration Date                  | 9/7/2014           |
| Company Type                       | SMRT Taxis Pte Ltd |
| Make                               | TOYOTA             |
| Model                              | PRIUS              |
| Name of Driver                     | GQAY KOK CHUAN     |
| Type of Accident                   | Head to Rear       |
| Accident Date and Time             | 29/8/2019 9:20 PM  |
| Accident Reported Date and Time    | 30/9/2019 12:30 PM |
| Is Surveyor Required?              | Yes                |
| Survey by                          |                    |
| Vehicle is Towed Back?             | No                 |
| Towed Back Date and Time           |                    |
| Replacement Vehicle issued?        | No                 |
| Job Card Number                    | 24103117           |
| Special Instruction to ARC, if any | TP/ REAR PORTION   |
| Prepared Date and Time             | 31/8/2019 9:41 AM  |
| Chassis Number                     |                    |
| Mileage                            |                    |
| Work Shop                          |                    |
| Repair Completion Date and Time    |                    |

| Section B - Summary of Repair Estimates |   |   |
|---|---|---|
| Summary of Repair Estimates             |   |   |
|   | Quotation from ARC  | Adjusted by Surveyor, if applicable   |
| Total Labour Cost                       | \$475.00  | \$300.00  |
| Total Spray Cost                        | \$936.00  | \$700.00  |
| Total Spare Part Cost                   | \$2,664.74  | \$479.70  |
| Total Other Cost                        | \$360.00  | \$40.00   |
| <b>TOTAL COST</b>                       | <b>\$4,838.74</b>   | <b>\$1,119.70</b>   |
| Lump Sum Total                          | \$4,850.00  | \$1,000.00  |
| Number of Repair Days                   | 5.0   | 3.0   |
| Prepared / Adjusted By                  | Ang Bang Kien   | STEVE CHEN  |
| ARC / Surveyor Sign Off Date            | 31/08/2019 9:56 AM  | 02/09/2019 11:58 AM   |
| Signature                               |  |  |
| Remarks                                 |   | US repair, take after spray. Finalize sent to stevechen@tkauto.com                  |

| Section C - Quotation and Accident Invoice Details |  |                |  |
|--|--|----------------|--|
| Quotation Number                                   |  | Invoice Number |  |
| Quotation Date                                     |  | Invoice Date   |  |
| Invoice Amount                                     |  | Prepared Date  |  |

Date Generated : 02/09/2018

User ID : kimmingchin

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Job Scope              | Quotation from AR | Adjusted by Surveyor, if applicable |
|------------------------|-------------------|-------------------------------------|
| TO REPAIR REAR PORTION | \$878.00          | \$300.00                            |
| <b>Total Labour</b>    | <b>\$878.00</b>   | <b>\$300.00</b>                     |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO RESPRAY REAR BUMPER                          | \$378.00           | \$200.00                            |
| TO RESPRAY BUMPER BEAM                          | \$180.00           | \$0.00                              |
| TO RESPRAY REAR PANEL                           | \$378.00           | \$100.00                            |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$936.00</b>    | <b>\$300.00</b>                     |

Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | \$120.00           | \$0.00                              |
| TO REPLACE SUNDRY PARTS                 | \$100.00           | \$20.00                             |
| TO CHECK WIRING AND SYSTEM FUNCTION     | \$80.00            | \$20.00                             |
| TO WASH AND VACUUM                      | \$90.00            | \$0.00                              |
| <b>Total Other Costs</b>                | <b>\$380.00</b>    | <b>\$40.00</b>                      |

Part 4 - Spare Parts / Material Usage

| Part Number  | Portion | Stock Number | Part Name                     | Quantity | List Price (\$)   | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|--------------|---------|--------------|-------------------------------|----------|-------------------|--------------|------------------|--------------------|-------------------|
|              |         | 52159-47905  | BUMPER REAR                   | 1.00     | \$458.60          | 25.00        | \$343.95         | Replace            | Replace           |
|              |         | 90467-07211  | BUMPER CLIPS                  | 10.00    | \$2.10            | 25.00        | \$15.75          | Replace            | Replace           |
|              |         | 52023-12240  | BUMPER REINFORCEMENT REAR     | 0.00     | \$205.70          | 0.00         | \$0.00           | Replace            | Check             |
|              |         | 52016-47030  | ARM SUB-ASSY. RR BUMPER RH    | 0.00     | \$139.60          | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 52016-47030  | ARM SUB-ASSY. RR BUMPER LH    | 0.00     | \$139.60          | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 89907-30070  | ANTENNA ELECTRICAL LOWER REAR | 0.00     | \$157.40          | 0.00         | \$0.00           | Replace            | Check             |
|              |         |              | SENSOR REVERSE                | 0.00     | \$180.00          | 0.00         | \$0.00           | Replace            | Check             |
|              |         | 52576-47020  | BUMPER SIDE RETAINER R/LH     | 0.00     | \$94.80           | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 52575-47020  | BUMPER SIDE RETAINER R/RH     | 0.00     | \$94.80           | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 52592-47021  | BUMPER SEAL, RR LH            | 0.00     | \$68.90           | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 52591-47021  | BUMPER SEAL, RR RH            | 0.00     | \$65.70           | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 76088-47020  | BUMPER LIP COVER R/LH         | 0.00     | \$72.20           | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 76087-47020  | BUMPER LIP COVER R/RH         | 0.00     | \$118.10          | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 78891-47020  | BUMPER LIP REAR               | 0.00     | \$228.90          | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 81561-47170  | TAIL LAMP LH                  | 0.00     | \$548.40          | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 58307-47060  | END PANEL                     | 1.00     | \$802.10          | 100.00       | \$0.00           | Replace            | Repair            |
|              |         |              | SEALANT SIKAFLEX              | 0.00     | \$37.00           | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 87881-47022  | TAILGATE DOOR WEATHER STRIP   | 0.00     | \$353.40          | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 89350-47030  | TAILGATE DOOR LOCK            | 0.00     | \$444.10          | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         | 69431-47010  | STRIKER, BACK DOOR            | 0.00     | \$48.90           | 0.00         | \$0.00           | Replace            | Not Given         |
|              |         |              | PIXEL STICKER                 | 2.00     | \$60.00           | 0.00         | \$120.00         | Replace            | Replace           |
| <b>Total</b> |         |              |                               |          | <b>\$4,140.30</b> |              | <b>\$478.76</b>  |                    |                   |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



# SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 02/08/2019  
User ID : kimmingchin

### Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Total       |         |              |           |          |               |              |                  |           |                |