

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

EQ Insurance Co. Ltd
 22 Gemmill Lane
 Singapore 069257
 Tel : 6223 - 9433
 Fax : 6224 - 3903

Vivian

Quotation
 DATE : 18.09.2019
 VEH NO : SKS3755E
 MODEL : Honda Vezel
 D O A : 30.08.2019
 YR REF : SJH3334G

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKS3755E (HONDA VEZEL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>NO LIST ITEMS - FRONT PORTION</u>			
1	Front Bumper <i>Dr</i>	1	880.00 ✓
2	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>new</i>	2	46.00 ✓
4	Front Bumper Lower Grille <i>new</i>	1	150.00 ✓
5	Front Bumper Reinforcement <i>Best</i>	1	327.70 ✓
6	Front Bumper Towing Cover <i>Del</i>	1	45.00 ✓
7	Front Bumper Lower Spoiler <i>Del</i>	1	396.10 ✓
8	Front Bumper Fog Lamp - LH & RH <i>new</i>	2	655.40 ✓
9	Front Bumper Fog Lamp Cover - LH & RH <i>new</i>	2	90.00 ✓
10	Front Grille <i>new</i>	1	395.40 ✓
11	Front Grille Logo <i>new</i>	1	35.40 ✓
12	Front Grille Chrome Moulding x 2 <i>at</i>	2	190.00 ✓
13	Head Lamp - LH & RH <i>new</i>	2	3,518.80 ✓
14	Head Lamp Lower Bracket - LH & RH <i>new</i>	2	91.00 ✓
15	Front Grille Inner Bracket <i>new</i>	1	69.40 ✓
16	Front Support Panel <i>Repair</i>	1	476.00 ✓
17	Front Support Panel Top Garnish <i>new</i>	1	95.20 ✓
18	Front Support Panel Top Garnish Clips <i>new</i>	1 set	30.00 ✓
19	Air Con Condenser <i>Dented</i>	1	898.00 ✓
20	Air Con Condenser Side Garnish <i>RH Del</i>	2	141.00 70.50
21	Air Con Condenser Side Garnish Clips <i>new</i>	1 set	20.00 10
22	Radiator <i>new</i>	1 set	1,250.00 ✓
<u>LIST ITEMS - REAR PORTION</u>			
23	Rear Bumper <i>Distorted</i>	1	865.00 ✓
24	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
25	Rear Bumper Side Holder - LH & RH <i>new</i>	2	64.00 ✓
26	Rear Bumper Reflector - LH & RH <i>RH new</i>	2	392.00 151
27	Rear Bumper Side Cover - LH & RH <i>Repair</i>	2	390.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SKS3755E (HONDA VEZEL)

28	Rear End Panel	Distorted	1	580.00	✓
29	Rear End Panel Top Garnish	Defend	1	122.30	✓
30	Rear End Panel Top Garnish Clips		1 set	20.00	✓
31	Rear End Panel Smart Sensor	Cracked	1	85.00	✓
32	Rear End Panel Antenna Sensor		1	105.00	✓
33	Tailgate	Distorted	1	1,100.00	✓
34	Tailgate Lock	Damaged	1	180.40	✓
35	Tailgate Weatherstripe	at	1	165.90	✓
36	Tailgate Inner Trim Board	Cracked	1	285.90	✓
37	Tailgate Inner Trim Board Clips	new	1 set	30.00	✓
38	Tailgate Reflector - LH & RH	RH at	2	710.00	355
39	Tailgate Outer Garnish	new	1	325.00	+
40	Tailgate Glass Moulding	new	1	120.90	✓
41	Honda Logo	new	1	32.50	+
42	Vezel Emblem	new	1	48.60	✓
43	Tail Lamp - LH & RH	RH at	2	920.00	460
44	Rear Fender Inner Trim Board x2	RH Defend	2	650.00	325
45	Rear Fender Inner Trim Board Clips	new	1 set	60.00	30
46	Spare Tyre Panel	Distorted	1	1,130.00	✓
47	Spare Tyre Panel Top Cover	new	1	305.40	+
48	Spare Tyre Panel Under Cover	Defend	1	215.80	✓
49	Spare Tyre Panel Under Cover Clips	new	1	80.00	30
50	Rear Exhaust Pipe	Rep	1	868.00	+
51	Rear Exhaust Mounting	new	1	45.00	+
52	Rear Exhaust Heat Shield		1	165.00	+
53	Tools Tray Sponge	new	1	225.00	+

Less 20%

\$	20,057.10
	(4,011.42)
\$	16,045.68

S/NET ITEMS

1	Front Number Plate	Cracked	1	30.00	✓
2	Front Number Plate Holder		1	30.00	✓
3	Rear Number Plate	new	1	30.00	+
4	Rear Number Plate Holder		1	30.00	+
5	Reverse Sensor	Damaged	1	280.00	200
6	Rear End Panel Sealant	new	1	60.00	✓
7	Tailgate Glass Sealant	new	1	60.00	✓
8	Rear Camera	new	1	480.00	+

1,000.00

Total Parts

\$	17,045.68
----	-----------

LABOUR CHARGE

RE : ESTIMATE FOR ACCIDENT REPAIR SKS3755E (HONDA VEZEL)

1	To knocking & pull out front & rear portion & renew above parts	\$	3,000.00 2000
2	To putty & spray up paint works	\$	2,200.00 1200
3	To check wiring	\$	100.00 60
4	To under seal	\$	200.00 100
5	To remove upholstery & rear seats	\$	300.00 250
6	To remove exhaust pipe	\$	150.00 x
7	To transfer tailgate fittings	\$	150.00 80
8	To remove tailgate glass	\$	180.00 120
9	To remove rear camera	\$	100.00 60
10	To remove reverse sensor	\$	100.00 60
11	To remove condenser, radiator and to top up air con gas	\$	180.00 120
Total Labour		\$	6,660.00
Grand Total		\$	<u>23,705.68</u>

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 15376.96
L/s: 12.3K
11 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: