Name 3:

Payer 3: (Strike if N.A.)

55

24/12 OLL

(06/11/13) REF:	
ameur: Kalvin	ASSICNMENT
From: Date:	Veh No: SHB 6349 A Yr Regn: 27 F66 , 2019 Type: M.Carl M.Cycle / Bus / Van / Lorry / Toll / Prime Mover /
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	/ Truck / Traller or
To Insped Vehicle No:	Make: Wadai Ionia cc 1580
at Workshop m/s OGE Cloyang) -	Colour Ble A/C: Insufati / Std / NI / NA
of	Sp.Reading 5 6050 T/Radio: Inst/Red / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: KNU C85/(VK4/40826
Claims No.	Gen. Cond: Good / Fafr / Poor / Burnt
Sum in swed: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh.	Modi: Nil / S/Rim / STD €/Rim or
	Tyre Size; F: 145/65R-5
(Policy Condition)	
	R:
repair at the time of inspection.	DIS BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value:	
IDAC Accident Rport: Consistent? : Yes or No	Front Rear
GIA / PR Seen: Consistent?: Yes or No	R/Bal. 7 mm R/Bal. 9 mm .
Tarvarian and the same of	mm
	D.O.A. 2/9/19 D.O.I. 2/9/19
Lum Sum: 1-15-1 % 3 Val.: Yes or No	Survey held at C 96E (Lyang)
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / 0	
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
1	EQ
	119
P/P \$2066-38 -	(Red - \$1231.12 / 37 1-)
	•
Date/line, File Pass to? : Prell. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
DaleTime, File Return to7	Transportation:
Add F	
	: Interview (S. ) Pholos
	119
	T(C)
	West

Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBLAYE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL.; (065) 62563561 FAX: (065) 62564315

Your ref:

To Be Advised

Our ref:

CC3/EQI19015572/K1wb3

Date:

03.09.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

#### PRELIMINARY ADVICE OF VEHICLE NO.

SHB6349A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on <u>02.09.2019</u> at the premises of M/s <u>ComfortDelGro Engineering Pte Ltd</u> and have the following to report:-

Workshop Estimate Amount	: S\$	3,297.50
Revised Estimate Amount	: S\$	2,066.38
"Check" Items Amount	: S\$	346,32
Market Value	: S\$	
LTA Reimbursement Value	: SS	
Nett Value	: SS	

Description of Damage:

The vehicle sustained damages at the

Rear N/S portion

rear from

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

days

Yours faithfully,

KALVIN ANG

Licensed Appraiser

# COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

### ComfortDelGro Engineering Pte Ltd

no tenansi Road Singapore \$79701

Workstrops 56 Loseng Drive Birgappes Scottill

34 Serono Loco Singapore 1981 SE 1 Surger Kerkil War Brigapore 198191 501 Vahuri Industria Park A Singapore 7667%

Date/Time: 02.09.2019 14:37

Page : 1

JOB CARD JC NO.: 305329457 Sales Order: ARC Repair TP(CLSO)1 Team: MILEAGE REGN NO: STOMER SHB6349A COMFORT TRANSPORTATION PTE LTD EUE. MAKE 7010045 HYUNDAI STOMER NO. 383 SIN MING DRIVE E 1/2 F 02.09.2019 11:40 MODEL IONIQ(G2) Singapore SINGAPORE 575717 65508755 YR OF MANU 27.02.2019 \_ (R) TARGET DATE P CHASSIS CODE RMHC851CVKU140826 COMPLETION DATE:TIME COUNT CARD NO.


JOB DESCRIPTION

Accident Date: 02.09.2019 NATURE: 3P 02.09.2019

S/NO

LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:				
SERVICE ADVISOR			CUSTOMER'S SIGNATURE	
wiedgement Slip		Exit Pass		
e No.: SHB6349A	CHIANG	Venicie No.: SHB6349A		
of Service Advisor returned to Service Raception upon collec	Signature/Date	Name of Service Advisor  To be kept by Security Guard	Date	

## REPAIR ESTIMATE\*

VEHICLE NO: SHB 6349A

DATE 2/9/2019 13:06

MAKE

: HYUNDAI IONIQ

	: HYUNDAI IONIQ				_
Qty	Parts Description/ Labour	Type	Unit Price	Amount	_
	Rear Bumper			\$ 459.4	
	Rear Bumper Reinforcement & NN			\$ 294.8	30
	Rear Bumper Reinforcement Bracket (LH)			\$ 138.1	0
	Rear Bumper Centre Moulding Assy			\$ 451.2	25
	Rear Bumper Side Bracket (LH)			\$ 2 33.1	0
	Rear Bumper Cover Clips			\$ 22.0	00
	Rear Bumper Side Under(LH)			\$ 27.5	
	Rear Bumper Reflector Lamp (LH)			\$ 31.9	- 1
	Rear Bumper Towing Cover			\$ 98.8	
				S J 870.4	0.6
	Tail Lamp (LH)			3 2 370.4	10
	Pen Fender (44) x 1497 SUB TOTAL				_
	Our Toilhote x 1907 SUBTOTAL			\$ 2,427.2	
	LESS 20%			\$ 485.4	
	DISCOUNTED TOTAL			\$ 1,941.8	30
	Rear Bumper Reverse Sensor			\$ 135.7	70
	Rear Bumper Rubber Mat			\$ 50.0	
				\$ 185.7	70
				3 105.7	-
		- wante f	outy		
	Lyoc Anto Consult	- ENWOYAN			
	Labour Charge	test sorter pare	Ing Inggreet	400	.
	Panel Beating-Repair Rear LH Fender	sants (send	Plant - Political	\$ 500.0	
	Spray Bainting Change	in the street	Senator basis		-
				\$ 50.0	-
	Remove/Refix Reverse Sensor	med tempt by	Invariance Company	5 120.0	
	-0.3111		Insurance Company	3 1294	10
	Tomas V	Replied			
	TOTAL LABOUR			\$ 1,170.0	00
	Kein King				
	ESTIMATE TOTAL			\$ 3,297.5	0
	1 2/1/19 1525 hors.				
	Kalmi (LICh)  ESTIMATE TOTAL  2/9/19 1525 hrs.  3 Pays.				
	Befor Pary phto				
	3 . //				- 1
	0.1 - 0 1 1 1 1				- 1

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305329457

Date : 05/09/19

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508989 Fax: 6546 8156

#### FINALIZATION FORM

#) <u></u>	LKK	Fax:		
ŝ	KALVIN			
	SHB6349A		_	02/09/19
urvey	and estimates of the repairs of the abo	ove-mentioned ve	ehicle are as follows:-	
The	repair job shall bill to:	EQ INS		SKL2157A
Thef	finalized amount shall be:			
(a)	Spare Parts after List discount			\$1,036.38
(b)	Labour Charges			\$1,030.00
	Total for Part-By-Part Repair Cost			\$2,066.38
Estin	Total for Lumpsum repair cost after I Final Lumpsum Repair cost		working days.	
We s work	shall treat the above amount as Correcing days	ect and Confirm	ed if there is no repl	y from you within
Than	ok you for your assistance		We confirm the est finalized amount	imates and
Signa	sture;		Signature :	//
Name	e : CHIANG		Name :	Kalonh
Tel	62148314		Date :	9/4/19

#### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:				
_			 	

Date: 05:09.2019 Time: 13:24:07

Page: 1

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

: 305329457

REGN NO MILEAGE : SHB6349A

MAKE

: 0000000000

MODEL

: HYUNDAI ! IONIQ(G2)

DATE OF REGN

27.02.2019

DATE/TIME IN

: 02.09.2019 11:40

ACCIDENT DATE

: 02.09.2019

#### JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

#### PART REQUISITION

0001 04-01-0104-2282-G IONIQVC COVER-RR BUMPER# 1 459.40 20.00 367.52

0002 04-01-0104-2533-G IONIOV2 MOULDING ASSY-RR 1 451.25 20.00 361.00

0003 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP 10 L 22.00 20.00 17.60

0004 04-01-0104-0851-G IONIQVC REFLECTOR/REFLEX 1 31.90 20.00 25.52

0005 04-01-0104-2544-G IONIQVC CAP-RR HOOK 1 98.80 20.00 79.04

0006 09-01-9999-0068-A HYUNDAI REVERSE SENSOR AS 1 135.70 2.00- 135.70

0007 04-01-0104-1150-A IONIQVC PROTECTOR MAT 1 50.00 0.20 50.00

SUB-TOTAL : 1,036.38

#### JOB NATURE

0000 PB PANEL BEATING 400.00

0001 SP

SPRAYPAINT CHARGE

600.00

0002 20-22

REMOVE/REFIX REVERSE SENSOR

30.00

SUB-TOTAL : 1,030.00

Date: 05.09.2019 Time: 13:24:07

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

: 305329457 : SHB6349A : 0000000000

MAKE MODEL

: HYUNDAI : IONIQ(G2)

DATE OF REGN DATE/TIME IN

: 27.02.2019 : 02.09.2019 11:4

ACCIDENT DATE : 02.09.2019

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,066.38

MVA NAME & SIGNATURE

DATE:

AUTHORISED: YES / NO SURVEYOR NAME & SIGNATURE

DATE:

REPAIR ESTIMATE\*

VEHICLE NO: SHB 6349A

DATE 2/9/2019 13:06

MAKE

Qty	Parts Description/ Labour	Type	Unit Price	- 4	Amount
2.6	n n 4			S	459.40
	Rear Bumper Reinforcement			S	294.80
	Rear Bumper Reinforcement Bracket (LH)			\$	138.10
	Rear Bumper Centre Moulding Assy			\$	451.25
	Rear Bumper Side Bracket (LH) X			S	33.10
	Rear Bumper Cover Clips			5	22.00
	Rear Bumper Side Under(LH)			S	27.50
	Rear Bumper Reflector Lamp (LH)			S	31.90
	Rear Bumper Towing Cover			S	98.80
	Tail Lamp (LH) X			\$	870.40
	Per Fender (41) x 1494 SUB TOTAL LESS 20%			s	2,427.25
	Per To: / hate x mis SUBTOTAL			S	485.45
	DISCOUNTED TOTAL			S	1,941.80
	111	/			
	Rear Bumper Reverse Sensor	/		S	135.70
	Rear Bumper Rubber Mat	1/2		S	50.00
	- Construction of the Production of Manager Englishment	13	0 3		
				7	185.70
	Labour Channe	331	3 /		
	Labour Charge Panel Beating-Repair Rear LH Fender	3 14	1 /	8	50000
			18/ 6	0 5	3,0.00
	Spray Painting Charge Wiring Charge	1 4	84/	5	SOLANT
	Remove/Refix Reverse Sensor		7	5	120.00
	Remove Rena Reverse Sensor		~	3	
	TOTAL LABOUR	3		\$	1,170.00
	Kalmi (Cick)  ESTIMATE TOTAL  A 2/9/19 1525 hrs.  3 Pays.  PIP  Before Pay photo			S	3,297.50
	Befor Pay phto				
	This is an initial estimate based on a visual inspection of the	he above ve	hicle. The final repair	quant	um will

#### Shu Pei (LKKAuto)

From:

Janet Tan <janet.tan@eqinsurance.com.sg>

Sent:

Wednesday, 4 September 2019 8:39 AM

To:

Shu Pei (LKKAuto)

Cc:

Admin A; Vivian Lau (LKKAuto)

Subject:

FW: Direct Settlement - Accident Involving SKL2157A (OI: EQI -DM19HO02435/JT) AND

SHB6349A (TP: LKK REF-CC3/EQI19015572/K1wb3) on 02.09.2019

Attachments:

TP ESTIMATE- MARKED.pdf; TP GIA REPORT.pdf; Preliminary\_Advice.pdf;

SAS2662529.PDF

Dear Shu Pei

As attached.

Regards,

Janet Tan

Senior Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg



a Do

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sent

From: Shu Pei (LKKAuto) [mailto:shupei@lkkauto.com]

Sent: Tuesday, September 3, 2019 4:53 PM To: Joel Goh <joel.goh@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: Direct Settlement - Accident Involving SKL2157A (OI : EQI - TBA) AND SHB6349A (TP : LKK REF -

CC3/EQI19015572/K1wb3) on 02.09.2019

#### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHB 6349A at M/s ComfortDelGro Engineering Pte Ltd – Loyang on a WP basis and TP repairer proposed for a direct settlement.

### Cecilia Chong (LKK Auto)

From:

Jim Wong See Pah <jimwong@cdge.com.sg>

Sent:

Thursday, 17 October 2019 4:12 PM

To:

Cecilia Chong (LKK Auto)

Subject:

Re: YOUR REF: T0919/SHB6349A (OUR REF: CC3/EQI19015572/K1gb3) \*\*\* ACCIDENT

INVOLVING SKL 21575 & SHB 6349A ON 02/09/2019 \*\*\*

Dear Ms Chong

Please process settlement in sum \$2919.28 to resolve our property damage claim amicably.

Additionally, it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Thank you.

Best Regards Jim Wong

Claims Dept / ComfortDelgro Engineering Pte Ltd

From: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Sent: Thursday, 17 October 2019 2:49 PM

To: Jim Wong See Pah <jimwong@cdge.com.sg>

Subject: YOUR REF: T0919/SHB6349A (OUR REF: CC3/EQI19015572/K1gb3) \*\*\* ACCIDENT INVOLVING SKL 2157S & SHB

6349A ON 02/09/2019 \*\*\*

WITHOUT PREJUDICE

Dear Jim,

We are pleased to offer total amount of \$2,919.28 (all-in).

Kindly confirm acceptance.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

RECEIVED 2.7 SEP 2019 EO insurance Admin Dept.

of Prive 4th Fir

Singapore 508969

COMFORTDELGRO ENGINEERING

> ComfortDelGro Engineering Pte Ltd. 205 Braddell Road Singapore 579701

> > Maintine +65 6383 6280 Facsimilie +65 6280 9755

> > > www.cdga.com.su

Company Replacetor for Establish

Workshops

Braddell Singapore 579701

Loyang 59 Loyeng Drive Singapore 508969

383 Sin Ming Drive Singapore \$75717

45 Fandan Road Singapore 600236

320 Libi Road Singapore 408649

24 Senako Loop Singapore 758158

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Vishun Industrial Park A Singapore 758732

T 0919 / SHB6349A /JW(st) Your ref:

Date 24-Sep-19

EQ Insurance Company Limited 5 Maxwell Road, MND Complex #17-00 Tower Block Singapore 069110

Attn: Motor Claims Department

Dear Sir

WITHOUT PREJUDICE

ACCIDENT INVOLVING OUR TAXI SHB6349A YOUR INSURED SKL2157A ON 02.09.19 AND OTHER FBE5185S

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No: SHB6349A which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SKL2157A we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1 Cost of Repair 2 days Loss of Rental @ \$ 125.19 per day 3 Survey Report Fees (Surveyed by M/s LKK) 4 LTA Search Fees

5 GIA / Police Report Fees

Towing / Medical / Transporation Fees

HIRER'S CLAIM

4 days Loss of Income @

80.00 perday

320.00 \$

2,211.03 500.76

2,719.28

7.49

Total Claims: \$ 3,039.28

Sub Total: \$

\$

S

\$

\$

S

We enclose herewith the following documents to support the claims: -

a) Original repair bill :

b) LTA search slip/s of :

SKL2157A

c) GIA / Police report/s of :

SHB6349A

d) Letter of authority from owner / hirer / operator

( ) Witness statement/s ( ) Towing/Medical bill/receipts ( ) Certificate of Insurance ( ) Photograph/s of Accident Scene (x) Downtime/Mileage record

(x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Jim Wong

CDGE Claims Department

Tel: 6214 8374 Fax: 6214 1843 Email: jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.

SEND TO FILE

CLAIM NO. DMI 9 HOD 2 431/JI

DOCUMENT TYPE: LOK

A member of







## Cecilia Chong (LKK Auto)

From:

Cecilia Chong (LKK Auto)

Sent:

Monday, 7 October 2019 1:10 PM

To:

andy\_khew@hotmail.com

Subject:

<STANDARD NOTIFICATION LETTER> OUR REF: CC3/EQI19015572/K1gb3 \*\*\*

ACCIDENT INVOLVING SKL 2157A & SHB 6349A ON 02/09/2019 \*\*\*

Our Ref: CC3/EQI19015572/K1gb3

07 OCTOBER 2019

#### ZHANG YAN

Dear Sir/Madam,

### ACCIDENT INVOLVING SKL 2157A AND SHB 6349A ON 02/09/2019

We refer to the above accident. We are the Appointed Surveyor and Loss Adjuster Company by your Motor Insurer (EQ INSURANCE COMPANY LIMITED) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

This is to inform you that we received a Third Party Claim from SHB 6349A.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IKK Save the Earth Print only when necessary

#### LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

Hyundai Ioniq SHB6349A , SKL2157A , F... ON 02-Sep-19 09:00

ALONG

AYE TWDS NUS B4 NORMANTON PARK ENTRANCE

I / We

MOHD ZIN BIN SAMSU ... (Hirer) NRIC No.: \$1309399G

and/or

ISMAIL BIN ANWAR

(Relief) NRIC No.: SXXXX077B

Taxi Number

SHB6349A

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

02-Sep-2019

Name of Hirer

MOHD ZIN BIN SAMSUDIN

Hirer NRIC

SXXXX399G

Signature:

Address

106A CANBERRA STREET #04-429

751106

Contact No.

98287121

Name of Relief

ISMAIL BIN ANWAR

Relief NRIC

SXXXX077B

Signature :

Address

137 YISHUN RING ROAD 02-162

760137

Contact No.

91372636

# COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

## TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Bradder Rued Bingspore 579701 Mareire + 55 6383 6280 Faceledis - 65 6290 5725

Werkshops
65 Layeng Delvis Simpapore 500009
165 Lan Meig Delvis Simpapore 505711
15 San Meig Delvis Simpapore 505066
15 Ups Fixed 3 Simpapore 400046 Werkshoes

COMPANY REG. NO.: 199506048W Pages 1

	5 MAXW SINGAR	SURANCE COMPANY LI		VEHILE SHE6349/ MAKE HYUNDAI MODEL IONIO(G		INV. NO// 91466476 JOB NO. 305329457 ODOMETER	DATE 13.09.2019 READING
0		iption : 3P 02.09.		DATE OF 27.02.	P REG 2019	DATE/TIM 02.09.20	E IN 19 11:40
	S/No	Part No.		Qty	Unit Price	%Disc	Net
	PART I	REQUISITION					
	0001	04-01-0104-2282	IONIQVC COVER-RR BUMPER#	1	459.40	20,00	367.52
	0002	04-01-0104-2533	IONIOV2 MOULDING ASSY-RR BUMPER CTR	. 1	451.25	20.00	361.00
	0003	04-01-0101-0111	HYUNDAI BUMPER COVER CLIP REAR	10	2.20	20.00	17.60
	0004	04-01-0104-0851	IONIQUE REFLECTOR/REFLEX ASSY-RE LH	1	31.90	20.00	25.52
	0005	04-01-0104-2544	IONIQUE CAP-RE HOOK	1	98.80	20.00	79.04
	0006	09-01-9999-0068	HYUNDAI REVERSE SENSOR ASSY*	1	135.70	0.00	135.70
3	0007	04-01-0104-1150	IONIQUE PROTECTOR MAT	1	50.00	0.00	50.00
0				SUB-TOTAL	1		1,036.38

WHILE I TAKING ALL READONABLE PLUCKULING - I SHELL THE TIME ACCURATE AND POST OF THE TIME AND THE PARTY AND THE PA

ComfortDelGro Engineering Pte Ltd A member of ComfoRtDucag

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No. AMOUNT ACCOUNT No. INVOICE No. 91456476

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

# COMFORTDELGRO ENGINEERING

A member of COMFORTDELCRO

GST REG. NO. M2-8921817-3

## TAX INVOICE

### ComfortDelGro Engineering Pte Ltd

205 Braddel Plod Singspres 579701 Majnine + CS 6363 6260 Paparete + 61 6290 9755

Mannes e CS simple Salarine 2 de company de la Mannes e CS simple Salarine 2 de company de la Serie Loren Sergapore 758156.

202 Lis Mary Drive Sirigiagnoù 2572172.

203 Lis Mary Drive Sirigiagnoù 2572172.

204 Parista Paud Sirigiagnoù 400649.

205 Lis Road 3 Sirigiagnoù 400649.

COMPANY REG. No.: 199506048W

Page: 2

8010325

EO INSURANCE COMPANY LIMITED

5 MAXWELL ROAD TOWER BLOCK #17-00 SINGAPORE SG 069110

CONTACT NO: 62239433

VEHCLE NO SHB6349A

INV. NO/DATE 91466476 13.09.2019

MAKE HYUNDAI

MODEL IONIQ(G2)

ODOMETER READING

CHASSIS CODE KNHC851CVKU140826

8/No	Part No.		Qty	Unit Price 8	Disc	Net
JOB N	ATURE					
0001	PB	PANEL BEATING		400.00		400.00
0002	SP	SPRAYPAINT CHARGE		600.00		600.00
0003	20-22	REMOVE/REFIX REVERSE SENSOR	,	30.00		30.00
			SUB-TOTAL	1		1,030.00

2,066.38 Items total 7,000 % 144.65 Add GST @ 2,211.03 Invoice amount

Issued by Repair type Payment Type/Term:

: CHEWBEELENG 13.09.2019 12:05:12

THE RESIDENCE OF THE PROPERTY OF THE PROPERTY

#### ComfortDelGro Engineering Pte Ltd A member of COMFORDELORD

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. AMOUNT BANK/CHO No. 91466476

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT19090011

Date: 12 September 2019



### TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

02/09/2019 @ 09:00 hrs

ALONG

AYE TWDS NUS B4 NORMANTON PARK ENTRANCE

INVOLVING

SKL2157A, FBE5185S

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHB6349A (the "Taxi"). The Taxi was hired to MOHD ZIN BIN SAMSUDIN IC NO SXXXX399G a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.19 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Manager, Fleet Safety

This is a computer generated letter. No signature is required.

25.30 1230

17/31/19/

Enquire Vehicle Insurance Details .

Vehicle No. Incident Date/Time

Search Status Insurance Company Code

Insurance Company Name

SKL2157A

02 Sep 2019 / 09:00:00

Successful

E04

EQ INSURANCE COMPANY LTD

Previous

OK



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

# To: M/s EQ INSURANCE COMPANY LTD

Date: 30/10/2019

# THIRD PARTY DIRECT SETTLEMENT

	SKL 2157A	(Insd Veh)	Your Ref. No. : DM19HO02435/JT
Vehicle No.	SHB 6349A	(TP Veh)	Our Ref. No.: CC3/EQI19015572/K1gb3q2
Date of Accident	2/9/2019		- 2

Liability		100%				
Final Repair Cost	: \$	2,211.03				
Loss of Income	: \$	200.00	4 days			
Rental (If any)	: \$	500.76	4 days			
Others;	: \$	7.49				
	: \$					
		2,919.28				
Final Settlement Sum	: \$	2,919.28				
Remarks	marks :					

	ment Instruction: Payee's Breakdown	. ¢	2,919.28
1)	COMFORTDELGRO ENGINEERING PTE LTD	. 5	2,010,20
	/	: S	

JOANNE LEE LKK Auto Consultants Pte Ltd



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

THE RESERVE	Affiliated to Federation Intern	ationale Des Experts En Auton	nobile		
Q INSURANCE COM	PANY LTD	Ref : CC3/EQI19015572/K1gb3q2			
MAXWELL ROAD 17-00 TOWER BLOC MND COMPLEXSING		Date: 30-10-2019 Code: EQI			
	Policy Particula	ars :- THIRD PARTY CLA	IM		
Insured Veh.	SKL 2157A	Veh. Inspected	SHB 6349A		
Policy No.	DMPPHQ18-006948	Coverage (\$)	0.00		
Claim No.	DM19HO02435/JT	Excess (\$)	0.00		
Assign From	Last Programme and a street manager	Assign Date	02/09/2019		
	Vehicle P	articulars & Condition			
Make & Model	HYUNDAI IONIQ	c.c	1580		
Engine No.	HIDDEN	Year of Reg.	2019		
Chassis No.	KMHC851CVKU140826	Colour	BLUE		
Odometer	56050	Steering	IN ORDER		
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
General	FAIR				
	Con	ditions of Tyres			
	Size	Make	Balance		
R/H Front Tyre	195/65 R15	MICHELIN	9 mm		
L/H Front Tyre	195/65 R15	MICHELIN	9 mm		
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm		
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm		
	Descr	iption of Damages			
THE VEHICLE SU	STAINED DAMAGES AT THE	REAR N/S PORTION.			
5.	Table 1	eral Information	urla lift in it is a		
Accident Date	02/09/2019	Inspection Date	02/09/2019		
Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
	59 LOYANG DRIVE SINGAPORE 508969				
ia.		Remarks			
	ON WAS CONDUCTED ON A' CE TO YOUR INSTRUCTION				
5b.		ate Days of Repair			
ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Da	ys		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6349A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
-1	REAR BUMPER REINFORCEMENT	SERVICEABLE	294.80	9
-1	REAR BUMPER REINFORCEMENT BRACKET (LH)	SERVICEABLE	138.10	
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
-1	REAR BUMPER SIDE BRACKET (LH)	SERVICEABLE	33.10	3
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE UNDER (LH)	SERVICEABLE	27.50	9
-1	REAR BUMPER REFLECTOR LAMP (LH)	CRACKED	31.90	31.90
1	REAR BUMPER TOWING COVER	CRACKED	98.80	98.80
1	TAIL LAMP (LH)	SERVICEABLE	870.40	9
-1	REAR FENDER (LH) (NPA)	TO REPAIR SEE LABOUR		9
1	REAR TAIL GATE (NPA)	TO REPAIR SEE LABOUR		3
	LESS 20% DISCOUNT		-485.45	-212.6
			1,941.80	850.68
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
	* *		185.70	185.70
	LABOUR			
	PANEL BEATING -REPAIR REAR LH FENDER.INCLUSIVE OF THE REPAIR OF REAR FENDER (LH) AND REAR TAIL GATE.		500.00	400.00
	SPRAY PAINTING CHARGE.		800.00	600.00
	WIRING CHARGE.	NOT NECESSARY	50.00	
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			1,470.00	1,030.00
	GRAND TOTAL		3,597.50	2,066.38

RECOMMENDED COST OF REPAIRS 2,066.38

Report Ref No. CC3/EQI19015572/K1gb3q2





Report Ref No. CC3/EQI19015572/K1gb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

## Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>

Sent: Thursday, 31 October 2019 4:12 PM

To: 'eqiprs@eqinsurance.com.sg'
Cc: 'CeciliaChong@lkkauto.com'

Subject: TP Direct Settlement - Accident Involving SKL 2157A (OI) and SHB 6349A (TP) on

02/09/2019

Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933