

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5409G**AAD1908-238***Not Notified
Passing B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

02 SEP 2019

SHD 5409G

JTDKB3FU403076995

TOYOTA

PRIUS

30.8.19

CHINA TAIPING

22/11/2018

		PART	LIST	
1	1	FRONT BUMPER	\$ Bu 1/2	509.10 ✓
2	1	REINFORCEMENT, FRONT BUMPER	\$ R	708.10
3	1	REINFORCEMENT, FRONT BUMPER, NO.2	\$ S	242.80
4	1	COVER, FRONT BUMPER HOLE, RH	\$ S	29.00
5	1	ABSORBER, FRONT BUMPER, LOWER	\$ S	130.20
6	1	ABSORBER, FRONT BUMPER ENERGY	\$ S	78.10
7	1	FRONT BUMPER SIDE RETAINER RH	\$ S	112.70
8	1	FRONT BUMPER SUPPORT	\$ S	81.70
9	1	EXTENSION, FRONT BUMPER, RH	\$ S	118.50
10	1	EXTENSION, FRONT BUMPER, LH	\$ S	118.50
11	1	FRONT LED LAMP (LOWER) RH	\$ S	907.75 7
12	1	FRONT HEADLAMP RH	\$	2,909.04 2
13	1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$ S	492.30 X
14	1	MOTOR, HEADLAMP LEVELING, RH	\$ S	413.10 X
15	1	FRONT FENDER RH	\$ R	963.80 X
16	1	EXTENSION, FRONT FENDER, RH	\$ S	48.80 X
17	1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$ S	98.30 X
18	1	LINER, FRONT FENDER, RH	\$ S	200.70 X
19	1	FRONT FENDER EMBLEM RH	\$ R	86.50 ✓
20	1	SEAL, FENDER APRON MUDGUARD, RH	\$ S	50.90 X
21	1	PROTECTOR, FRONT FENDER SIDE PANEL, RH	\$ S	92.30 X
TOTAL			\$	8,392.19
25%			\$	2,098.05
			\$	6,294.14

Trans-cab Auto Services Pte Ltd

AAD1908-238

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5409G

Special Nett

1	1	FRONT WHEEL RIM	\$	sn	1,570.55	X
2	1	FRONT WHEEL RIM COVER	\$	sn	175.80	X
3	1	FRONT TYRE 195/65/15	\$	sn	350.00	X
4	1	CLIP, FRONT FENDER LINER	\$	na	33.00	X
5	1	BUMPER CLIP FRT	\$	wee	66.00	✓
6	1	WINDSCREEN SEALANT	\$	na	253.80	X
7	1	FRONT WINDSCREEN MOULDING	\$	na	120.00	X
8	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
TOTAL			\$		2,669.15	

TOTAL PARTS \$ 8,963.29**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	3001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	4	170.00 X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	4	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	4	170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4	380.00 X
To check steering geometry and computer wheel alignment	\$	4	220.00 X

Trans-cab Auto Services Pte Ltd**AAD1908-238**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5409G

To remove and refit interior fittings, trimmings, garnish,
fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To transfer of front windscreen glass to facilitate bodywork
repair.

\$ *nn* 170.00 *X***TOTAL \$ 11,000.00****Over All Total \$ 19,963.29****(PART-BY-PART) Repair Days***15 days**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: