

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y**AAD1908-236***Not Authoised**1/1/2019*

Vehicle No.: 02 SEP 2019
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 9723Y

VF1ABL15AUC276073

RENAULT

LATITUDE

29.8.19

CHINA TAIPING

4/12/2013

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 811.44	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 196.00	✓
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 161.73	✓
5	1	BUMPER RETAINER RH REAR	\$	<i>Sn</i> 108.40	✓
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	✓
7	1	BUMPER BEAM REAR	\$	<i>N</i> 1,068.21	✓
8	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95	✓
9	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45	✓
10	1	FENDER PANEL REAR RH	\$	<i>Bu</i> 3,866.40	✓
11	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	✓
12	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 547.07	✓
13	1	TAILLAMP RH	\$	616.81	?
14	1	TAILLAMP PANEL RH	\$	<i>N</i> 986.70	✓
15	1	KNUCKLE ARM REAR RH L70Y	\$	930.04	?
16	1	BRAKE DISC REAR L70Y	\$	525.91	?
17	1	WHEEL HUB NUT L70Y	\$	83.60	?
18	1	WHEEL HUB CAP L70Y	\$	61.00	?
19	1	ABS SENSOR REAR RH L70Y	\$	255.75	?
20	1	REAR AXLE L70Y	\$	<i>Sn</i> 6,851.28	✓
21	1	AXLE ARM RH L70Y	\$	139.00	?
22	1	LOWER ARM REAR RH L70Y	\$	1,070.70	?
23	1	ABSORBER REAR	\$	428.08	?
24	1	STABILIZER BAR REAR RH	\$	<i>Sn</i> 843.00	✓
25	1	BRAKE CALIPER REAR RH	\$	<i>Sn</i> 1,300.67	✓
26	1	DOOR PANEL REAR RH	\$	<i>N</i> 2,844.66	✓
27	1	DOOR LOCK REAR RH	\$	<i>N</i> 922.92	✓
28	1	DOOR CATCH REAR RH	\$	<i>N</i> 179.10	✓
29	1	DOOR PANEL FRONT RH	\$	<i>N</i> 2,844.66	✓
30	1	DOOR MIRROR ASSY RH	\$	1,483.40	?

Trans-cab Auto Services Pte Ltd

AAD1908-236

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y

31	1	BUMPER COVER FRT	\$	<i>N</i> 1,494.40 X
32	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 199.76 X
33	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
34	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
35	1	HEADLAMP RH	\$	<i>Sn</i> 1,468.61 X
36	1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 251.60 X
37	1	BONNET	\$	<i>N</i> 2,586.02 X
38	1	BONNET HINGE RH	\$	<i>N</i> 467.68 X
39	1	FENDER INSULATOR RH	\$	<i>Sn</i> 132.60 X
40	1	FENDER PANEL FRT RH	\$	<i>Bh</i> 828.80 ✓
41	1	WHEELARCH FRT RH	\$	<i>Sn</i> 442.46
42	1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 23.60
43	1	WIPER RESERVOIR	\$	<i>Sn</i> 497.50
44	1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 218.29
45	1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 627.76
46	1	ROCKER PANEL INNER GARNISH RH	\$	<i>Sn</i> 466.51
47	1	ROCKER PANEL INNER RH	\$	<i>N</i> 1,024.79
48	1	ROCKER PANEL OUTER RH	\$	<i>N</i> 1,184.99
49	1	ROCKER PANEL CENTER RH	\$	<i>N</i> 990.25
50	1	LOWER ARM RH L70Y	\$	<i>Sn</i> 685.76
51	1	KNUCKLE ARM RH L70Y	\$	<i>Sn</i> 948.60
52	1	ABSORBER FRT RH L70Y	\$	<i>Sn</i> 400.90
53	1	DRIVESHAFT RH	\$	<i>N</i> 2,670.73
54	1	STABILIZER BAR FRT	\$	<i>Sn</i> 843.00
55	1	DOOR HARNESS WIRE RH	\$	<i>Sn</i> 2,670.00

TOTAL \$ 53,175.18**10% \$ 5,317.52****\$ 47,857.66****Special Nett**

1	1SET PARKING AID	\$	<i>Sn</i> 700.00 X
2	1SET REAR BUMPER CLIP	\$	<i>N</i> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>N</i> 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>N</i> 10.00 X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>N</i> 20.00 X
6	1SET BUMPER LOWER REAR CLIP	\$	<i>N</i> 66.00 X
7	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>N</i> 35.00 X
8	1 FENDER INNER TRIM CLIP RH	\$	<i>N</i> 28.00 X

Trans-cab Auto Services Pte Ltd

AAD1908-236

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y

9	1	TAILLAMP CLIP RH	\$	nn	5.00	X	
10	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	40sn	
11	1	WINDSCREEN MOULDING	\$	nn	100.00	✓	
12	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn	
13	1SET	BUMPER CLIP FRT	\$	nn	66.00	} X	
14	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00		
15	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50		
16	1	WHEELARCH CLIP FRT RH	\$	nn	30.50		
17	1	BONNET STRUT L70Y	\$	sn	106.60		
18	1	REAR RH DOOR STICKER '6555-3333'	\$	nn	80.00		
19	1	FRONT DOOR STICKER 'Trans-Cab'	\$	nn	80.00		
20	1	FRONT DOOR STICKER 'Classic'	\$	nn	80.00	} X	
21	1	FRONT RIGHT TYRE	\$	sn	300.00		
22	1	FRONT RIGHT TYRE RIM	\$	sn	380.00		
23	1	REAR RIGHT TYRE	\$	rd0	sn	300.00	803sn
24	1	REAR RIGHT TYRE RIM	\$	sn	380.00	✓	
25	1	FRONT RH HUB CAP	\$	nn	61.00	✓	
TOTAL			\$		3,129.60		

TOTAL PARTS	\$	50,987.26
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	9401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	9001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00	?

Trans-cab Auto Services Pte Ltd

AAD1908-236

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y

To Check Electrical Lighting Concerned.	\$	170.00	201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
Towing Fees	\$	170.00	601 501
To check steering geometry and computer wheel alignment	\$	220.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	} 1001
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	340.00	
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 180.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 180.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	4 170.00	X
To Transfer Of Rear Fender Fittings, Attachments And Perform Water Seepage Test.	\$	4 340.00	X
To check ABS and brake efficiency, final checking and testing.	\$	4 380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	4 380.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	?
To transfer of rear door fittings, attachment and perform water seepage test.	\$	4 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1908-236**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y

To transfer of tire, rim and on wheel balancing.	\$	170.00	201
TOTAL	\$	19,900.00	

Over All Total	\$	70,887.26
-----------------------	-----------	------------------

Repair Days (LUMP SUM)**25 DAYS**
7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: