

REF: CC3/A19 19015586/A9f312

Adrian Merimen

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 2100471509-03

Claims No. 773598937256

Sum Insured: \_\_\_\_\_ Excess: 500 04/9/19

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|   |     |
|---|-----|
|  |     |
| N/S   | O/S |
|   |     |

Bal. or Market Value: 1261c.

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 03 8/8 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLD6542A Yr Regn: 2016, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q5 c.c. 1984

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 72874 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAU2228R6GA139558

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRIM / STD A/Rim or

Tyre Size: F: 235/60R18

R: 235/60R18

B / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 03/09/19

Survey held at Premium

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time        | Action / Instruction                               |
|--------------------|--|
|                    | ODA19.   |
|                    | SLD 6542A - X                                      |
| 03/9/19 @ 5.20pm   | revert to Victor via Merimen.                      |
| 04/9/19 @ 10.44a   | Victor informed CIA via Merimen.                   |
|                    | MV:  |
|                    | PV:  |
|                    | Nett:  |
| 04/9/19 @ 1.56pm   | Informed Kevin CIA @ Ex: \$ 500 by email.          |
| 23/10/19 @ 11.22am | Confirmed with Mr Bos final Ag \$ 6954.08, 3 days. |
|                    | CPed \$ 13385.92, 667.7                            |

RECEIVED 27 NOV 2019

| Date/Time, File Pass to? | Date/Time, File Return to? |
|--------------------------|----------------------------|
| 1) 26/10/19              | 2)                         |
| 3)                       | 4)                         |
| 5)                       | 6)                         |
| Prat. Report:            |                            |
| Final Report:            |                            |

| Part Prices Check: |     |
|--------------------|-----|
| IN                 | OUT |
|                    |     |

| Survey Fee:  | Date:      |
|--------------|------------|
| Basic & Add. | <u>200</u> |
| S + RS, SI   | <u>11</u>  |
| Photos       |            |
| Others       |            |
| TOTAL        | <u>211</u> |

Note: This document has not been finalised.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ler, Bernard-JQ

Date: 03 Sep 2019

### Preliminary Advice

|                    |  |                         |                 |
|--------------------|--|-------------------------|-----------------|
| Vehicle No         | : SLD6542A   | Accident Date           | : 06/08/2019    |
| Make               | : AUDI Q5  | Policy No.              | : 2100471809-03 |
| Assignment Date    | : 03/09/2019   | Excess                  | : S\$0.00       |
| Date of Inspection | : 03/09/2019   | Est. Duration of Repair | : 3.00          |
| Inspection At      | : PREMIUM AUTOMOBILES PTE LTD (UBI)<br>55 UBI ROAD 1<br>SINGAPORE 408699 |                         |                 |

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 20,340.00 |
| Revised Amount              | :S\$ | 7,695.00  |
| Check Items (Estimated)     | :S\$ | 1,487.00  |
| Total                       | :S\$ | 9,182.00  |

Lump Sum Repair :S\$

### Total Loss Consideration

|                    |      |            |
|--------------------|------|------------|
| New for Old Value  | :S\$ |            |
| Pre-Accident Value | :S\$ | 126,000.00 |
| COE / PARF Rebate  | :S\$ | 70,850.00  |
| Salvage Value      | :S\$ |            |
| Margin for Repair  | :S\$ | 55,150.00  |

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 4 September 2019 1:56 PM  
**To:** claims@premiumauto.com.sg; SUR  
**Subject:** RE: OD CLAIM FOR SLD 6542 A ON 6/8/2019

Dear Kelvin,

As instructed by our client, please proceed to repair the insured vehicle **SLD 6542A (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Wednesday, 4 September 2019 10:08 AM  
**To:** claims@premiumauto.com.sg; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: OD CLAIM FOR SLD 6542 A ON 6/8/2019

Dear Kelvin,

Please be informed that we are pending for insurance's approval. Once approve, we will send you an email.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>  
**Sent:** Wednesday, 4 September 2019 8:28 AM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)  
**Subject:** RE: OD CLAIM FOR SLD 6542 A ON 6/8/2019

Dear All,

Attached is the marking estimate for your kind reference, kindly advise who is the OIC to follow up repair approval.

Thank you.

## Claim Audit

| AUDIT TRAIL |                      |                                  |  |                           |
|-------------|----------------------|----------------------------------|--|---------------------------|
| No.         | On                   | Audit                            | Remarks  | By                        |
| 1           | 07 Aug 2019<br>13:50 | <b>Cim Veh Model Changed</b>     | (201613) AUDI Q5 2.0 TFSI Quattro (A).   | [ ] Merimen Administrator |
| 2           | 07 Aug 2019<br>13:50 | <b>Cim Created</b>               | Reg No: SLD6542A, Policy No: 2100471809-03, Acct Date: 2019/08/06, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119103643 | [I] Merimen Administrator |
| 3           | 03 Sep 2019<br>16:51 | <b>Cim Registration Modified</b> | Setl.Type:3->0, Claim Type:SC->OD.   | [ ] LEE SU THING          |
| 4           | 03 Sep 2019<br>16:51 | <b>Adj Cim Retrieved</b>         | Adj: LKK Auto Consultants Pte Ltd (HQ)   | [ ] LEE SU THING          |
| 5           | 03 Sep 2019<br>16:51 | <b>Adj Co Assigned</b>           | LKK Auto Consultants Pte Ltd (HQ):   | [A] LEE SU THING          |
| 6           | 03 Sep 2019<br>16:51 | <b>Adj Next Rpt Changed</b>      | Next Rpt:Final Rpt.Due Date:2019/09/12   | [A] LEE SU THING          |
| 7           | 03 Sep 2019<br>16:51 | <b>Adj Mandate Set</b>           | Approved:8000.00.Reinsp:Adj decides.   | [A] LEE SU THING          |
| 8           | 03 Sep 2019<br>16:51 | <b>Cim Registration Modified</b> | Rep:1137->200611.  | [A] LEE SU THING          |
| 9           | 03 Sep 2019<br>16:51 | <b>Adj Adjuster Assigned</b>     | [None] -> ADRIAN LING  | [A] LEE SU THING          |
| 10          | 03 Sep 2019<br>17:19 | <b>Adj Rpt Initiated</b>         |  | [A] SHIAU CHAN            |
| 11          | 03 Sep 2019<br>17:19 | <b>Cim Dtl Modified</b>          | JPJ Reg. Date: -> 2016/06/24.  | [A] SHIAU CHAN            |
| 12          | 03 Sep 2019<br>17:19 | <b>Cim Details Notified</b>      |  | [A] SHIAU CHAN            |
| 13          | 03 Sep 2019<br>17:23 | <b>Adj Im. Advice Submitted</b>  | Next Rpt:Final Rpt.Due Date:2019/09/12   | [A] SHIAU CHAN            |
| 14          | 03 Sep 2019<br>17:23 | <b>Adj Mandate Request</b>       | Cur.Req:9182.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.  | [A] SHIAU CHAN            |
| 15          | 04 Sep 2019<br>09:51 | <b>Cim Registration Modified</b> | Init.Est.->5,000 - 6,000.  | [I] Chan, Yoke Shi        |
| 16          | 04 Sep 2019<br>10:13 | <b>Cim Registration Modified</b> | Excess: -> 500.00, Excess Waived: -> 500.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.  | [I] Chan, Yoke Shi        |
| 17          | 04 Sep 2019<br>10:13 | <b>Label Added</b>               | (20226):Coverage Confirmed.  | [A] Merimen Administrator |
| 18          | 04 Sep 2019<br>10:44 | <b>Adj Next Rpt Changed</b>      | Next Rpt:Final Rpt.Due Date:2019/09/12, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.   | [I] Koh, Victor-CK        |
| 19          | 04 Sep 2019<br>10:44 | <b>Adj Mandate Set</b>           | Approved:7695.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.   | [I] Koh, Victor-CK        |

Date From



Date To



Audit Type

None

Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

| Bill Ref No | Bill Date               | Bill Type             | Acc Type | Acc Name                     | Co Name (Branch)                  | Ref 1    | Ref 2 | Amount |
|-------------|-------------------------|-----------------------|----------|------------------------------|-----------------------------------|----------|-------|--------|
| 2268288     | 03 Sep 2019<br>17:19:30 | OD/TP Case (Adjuster) | Motor    | LKK Auto Consultants Pte Ltd | LKK Auto Consultants Pte Ltd (HQ) | SLD6542A |       | 11.77  |

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 23 October 2019 11:22 AM  
**To:** Boo seng yak; SUR; Carrine Leong; Chang Chee Sing;  
jiayee.yap@premiumauto.com.sg  
**Subject:** RE: FINAL REVISION - SLD6542A - OD AIG - SURVEYED 3 SEP 19

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final Fig \$6,954.08 before excess \$500.00 & GST and 3 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Boo seng yak <boojohnny@gmail.com>  
**Sent:** Monday, 21 October 2019 3:22 PM  
**To:** Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg  
**Subject:** FINAL REVISION - SLD6542A - OD AIG - SURVEYED 3 SEP 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$6854.08 @ 3 days of repairs.

Your early closure is well appreciated.

Best regards - jb

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                       |
|-------------------------------|---------------------------------------|
| Owner ID Type:                | Singapore NRIC                        |
| Owner ID:                     | 893F                                  |
| Vehicle Details               |                                       |
| Vehicle No.:                  | SLD6542A                              |
| Vehicle to be Exported:       | No                                    |
| Intended Deregistration Date: | 03 Sep 2019                           |
| Vehicle Make:                 | AUDI                                  |
| Vehicle Model:                | Q5 2.0 TFSI QU (180 BHP)              |
| Primary Colour:               | Blue                                  |
| Manufacturing Year:           | 2016                                  |
| Engine No.:                   | CNC168546                             |
| Chassis No.:                  | WAUZZZ8R6GA139958                     |
| Maximum Power Output:         | 132.0 kW (177 bhp)                    |
| Open Market Value:            | \$36,895.00                           |
| Original Registration Date:   | 24 Jun 2016                           |
| First Registration Date:      | 24 Jun 2016                           |
| Transfer Count:               | 0                                     |
| Actual ARF Paid:              | \$43,653.00                           |
| Intended PARF Rebate Details  |                                       |
| PARF Eligibility:             | Yes                                   |
| PARF Eligibility Expiry Date: | 23 Jun 2026                           |
| PARF Rebate Amount:           | \$32,739.00                           |
| Intended COE Rebate Details   |                                       |
| COE Expiry Date:              | 23 Jun 2026                           |
| COE Category:                 | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):            | 10                                    |
| QP Paid:                      | \$56,000.00                           |
| COE Rebate Amount:            | \$38,111.00                           |
| <b>Total Rebate Amount:</b>   | <b>\$70,850.00</b>                    |

The information contained herein is correct as at 03 Sep 2019

OK



# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : SHETTY RAJENDRA KUMAR  
 Period of Insurance : 24 Jun 2019 To 23 Jun 2020  
 Engine No. : CNC168546  
 Chassis No. : WAUZZZ8R6GA139958

Vehicle No. : SLD6542A  
 Policy No. : 2100471809-03  
 Endorsement No. :  
 Issued Date : 18 Jun 2019

### ABOUT THE COVER

Make/Model : AUDI Q5 2.0 TFSI (180 bhp) Qu  
 Engine Capacity/Tonnage : 1,984.00 CC Sum Insured : Market Value First Year of Registration : 2016  
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

#### Person or Classes of Persons Entitled to Drive\* :

- a) The Policyholder
  - b) Any other person who is driving on the Policyholder's order or with his/her permission.
- This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

\* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 55 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

**Section 1**  
 Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

**Section 2**  
 Property Damage - \$0

Windscreen : \$100

#### Named Driver and Excess (where applicable)

SHETTY RAJENDRA KUMAR - \$1000 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP  
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
 AUTHORISED REPRESENTATIVE

SSPGMM

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

**Telefax**

**Material List for Accident Vehicle Regn No. SLD 6542 A**

| S/N                          | Parts Description                             | Damaged Parts & Prices |                       | Remark |
|------------------------------|---|------------------------|-----------------------|--------|
|                              |   | S/Nett                 |                       |        |
| ✓                            | FRONT BUMPER <i>deformed</i>                  | S                      | 2,353.00 ✓            |        |
| 2                            | FRONT BUMPER FIXING PARTS <i>new</i>          | S                      | 249.00 <sup>+</sup>   |        |
| 3                            | FRONT BUMPER BUMPER SPOILER <i>Repair</i>     | S                      | 569.00 <sup>+</sup>   |        |
| 4                            | FRONT BUMPER CLOSING ELEMENT <i>new</i>       | S                      | 191.00 <sup>+</sup>   |        |
| 5                            | FRONT BUMPER FOAM FILLER PIECE ?              | S                      | 103.00 ?              |        |
| 6                            | FRONT BUMPER PULL STRAP <i>new</i>            | S                      | 47.00 <sup>+</sup>    |        |
| 7                            | FRONT BUMPER SECURING STRIP-LH/RH ?           | S                      | 68.00 ?               |        |
| 8                            | FRONT BUMPER COVER <i>new</i>                 | S                      | 116.00 <sup>+</sup>   |        |
| ✓                            | FRONT BUMPER AIR GUIDIE GRILLE- RH <i>cut</i> | S                      | 319.00 ✓              |        |
| 10                           | FRONT BUMPER REINFORCEMENT BEAM ?             | S                      | 598.00 ?              |        |
| 11                           | FRONT BUMPER REINFORCEMENT COVER ?            | S                      | 59.00 ?               |        |
| 12                           | FRONT BUMPER GUIDE SECTION - RH ? <i>new</i>  | S                      | 34.00 <sup>+</sup>    |        |
| 13                           | FRONT BUMPER SUPPORT - LH (RR) <i>de</i>      | 2 S                    | 54.00 <sup>+</sup>    |        |
| 14                           | SIGN 'CAUTION' <i>new</i>                     | NEC S                  | 13.00 <sup>+</sup>    |        |
| 15                           | AIR CONDITIONER STICKER <i>new</i>            | NEC S                  | 7.00 <sup>+</sup>     |        |
| 16                           | RADIATOR GRILLE                               | S                      | 1,751.00 <sup>+</sup> |        |
| 17                           | INSCRIPTION 'QUATTRO'                         | S                      | 87.00 <sup>+</sup>    |        |
| 18                           | RADIATOR GRILLE STRIKER PLATE <i>not new</i>  | S                      | 111.00 <sup>+</sup>   |        |
| 19                           | FRONT PARKING AID SENSOR                      | 2 S                    | 462.00 <sup>+</sup>   |        |
| 20                           | LOW TONE SIGNAL HORN - RH                     | S                      | 184.00 <sup>x</sup>   |        |
| <b>SUB FRONT SPARE PARTS</b> |   |                        | <b>\$ 7,375.00</b>    |        |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

*Signature* 26/9

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax**

**Material List for Accident Vehicle Regn No. SLD 6542 A**

| S/N                         | Parts Description                             | Damaged Parts & Prices |                     |
|-----------------------------|---|------------------------|---------------------|
|                             |   | S/Nett                 | Remark              |
| 21                          | LOW TONE HORN BRACKET - RH <i>new</i>         | \$                     | 23.00 <i>+</i>      |
| 22                          | FENDER - RH <i>new</i>                        | \$                     | 913.00 <i>x</i>     |
| 23                          | FENDER ATTACHMENT PARTS                       | \$                     | 61.00 <i>+</i>      |
| 24                          | FRONT FENDER BRACKET - RH                     | \$                     | 49.00 <i>x</i>      |
| 25                          | FRONT FENDER CENTER BRACKET                   | \$                     | 45.00 <i>+</i>      |
| 26                          | FRONT FENDER REAR BRACKET                     | \$                     | 45.00 <i>+</i>      |
| 27                          | POP RIVET                                     | 6 \$                   | 18.00 <i>+</i>      |
| 28                          | FRONT FENDER BRACE-RH                         | \$                     | 79.00 <i>x</i>      |
| 29                          | FRONT WHEEL HOUSING LINER-RH                  | 2 \$                   | 246.00 <i>+</i>     |
| 30                          | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH | 2 \$                   | 94.00 <i>+</i>      |
| 31                          | FRONT WHEEL SPOILER-RH <i>new</i>             | \$                     | 60.00 <i>+</i>      |
| 32                          | HEADLIGHT MOUNTING-RH <i>new</i>              | \$                     | 107.00 <i>?</i>     |
| 33                          | HEADLIGHT RETAINING PLATE-RH <i>?</i>         | \$                     | 71.00 <i>?</i>      |
| 34                          | HEADLIGHT - RH <i>cracked</i>                 | \$                     | 2,501.00 <i>✓</i>   |
| 35                          | HALOGEN FOG LAMP - RH <i>new</i>              | \$                     | 238.00 <i>+</i>     |
| 36                          | HEADLIGHT LIFT CYLINDER - RH <i>? dis</i>     | \$                     | 181.00 <i>?</i>     |
| 37                          | RADIATOR AIR DUCT <i>new</i>                  | \$                     | 22.00 <i>+</i>      |
| 38                          | FRONT NO. PLATE <i>new</i>                    | S/N \$                 | 40.00 <i>+</i>      |
| 39                          | SUNDRIES <i>?</i>                             | \$                     | 300.00 <i>?</i>     |
| <b>TOTAL SPARE PARTS</b>    |   | :                      | <b>\$ 12,468.00</b> |
| <b>TOTAL LABOUR CHARGES</b> |   | :                      | <b>\$ 7,872.00</b>  |
| <b>GRAND TOTAL</b>          |   |                        | <b>\$ 20,340.00</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0959/2019/NS  
**Date** : 8-Aug-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : MR SHETTY RAJENDRA KUMAR  
**Address** : BLK 217 YISHUN ST 21  
#07-337  
Singapore 760217  
**Telephone** : 98389904  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 2100471809-03  
**Vehicle No** : **SLD 6542 A**  
**Model Code** : Audi Q5 2.0 TFSI QU  
**Model / Year** : 24/6/2016  
**Engine No** : CNC 168546  
**Chassis No** : WAUZZZ8R6GA139958  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 6-Aug-19  
**Place of Accident** : ANG MO KIO CARPARK

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLD 6542 A

| S/n                         | Nature of Jobs   | Estimated Charges             | Surveyor's Recommendation |
|-----------------------------|--|-------------------------------|---------------------------|
| 1                           | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.                | S/N \$ 480.00 ✓               |                           |
| 2                           | To dismantle and renew front bumper, rhs front fender and rhs headlight. To repair bonnet. Re-organise crash management components. Reinstall all parts removed. | \$ <del>3,200.00</del> 850 ✓  |                           |
| 3                           | To respray front bumper, front bumper spoiler, bonnet and rhs front fender.  | \$ <del>4,000.00</del> 1100 ✓ |                           |
| 4                           | To carry out diagnostic check.   | S/N \$ 192.00 ✓               |                           |
| <b>TOTAL LABOUR CHARGES</b> |  | <b>: \$ <u>7,872.00</u></b>   |                           |

## Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

### Telefax

### Material List for Accident Vehicle Regn No. SLD 6542 A

| S/N                          | Parts Description   | Damaged Parts & Prices |                    |
|------------------------------|---|------------------------|--------------------|
|                              |   | S/Nett                 | Remark             |
| 1                            | FRONT BUMPER <i>deformed</i>                                      | S                      | 2,353.00 ✓ 1582.40 |
| 2                            | FRONT BUMPER FIXING PARTS <i>new</i>                              | S                      | 249.00 +           |
| 3                            | FRONT BUMPER BUMPER SPOILER <i>Repair</i>                         | S                      | 569.00 +           |
| 4                            | FRONT BUMPER CLOSING ELEMENT <i>new</i>                           | S                      | 191.00 +           |
| 5                            | FRONT BUMPER FOAM FILLER PIECE <i>Not Nec</i>                     | S                      | 103.00 ? X         |
| 6                            | FRONT BUMPER PULL STRAP <i>new</i>                                | S                      | 47.00 +            |
| 7                            | FRONT BUMPER SECURING STRIP-LH/RH <i>Not Nec</i>                  | S                      | 68.00 ? X          |
| 8                            | FRONT BUMPER COVER <i>new</i>                                     | S                      | 116.00 +           |
| 9                            | FRONT BUMPER AIR GUIDIE GRILLE- RH <i>cut</i>                     | S                      | 319.00 ✓ 255.20    |
| 10                           | FRONT BUMPER REINFORCEMENT BEAM <i>Not Nec</i>                    | S                      | 598.00 ? X         |
| 11                           | FRONT BUMPER REINFORCEMENT COVER <i>Not Nec</i>                   | S                      | 59.00 ? X          |
| 12                           | FRONT BUMPER GUIDE SECTION - RH <i>2 from new new RH damaged.</i> | S                      | 34.00 +            |
| 13                           | FRONT BUMPER SUPPORT - LH / RH <i>2</i>                           | S                      | 54.00 + 21.20 ✓    |
| 14                           | SIGN 'CAUTION' <i>3 new</i>                                       | NEC S                  | 13.00 +            |
| 15                           | AIR CONDITIONER STICKER <i>3 new</i>                              | NEC S                  | 7.00 +             |
| 16                           | RADIATOR GRILLE <i>2</i>  | S                      | 1,751.00 +         |
| 17                           | INSCRIPTION 'QUATTRO' <i>2</i>                                    | S                      | 87.00 +            |
| 18                           | RADIATOR GRILLE STRIKER PLATE <i>NOT new</i>                      | S                      | 111.00 +           |
| 19                           | FRONT PARKING AID SENSOR <i>2</i>                                 | S                      | 462.00 X           |
| 20                           | LOW TONE SIGNAL HORN - RH <i>1</i>                                | S                      | 184.00 X           |
| <b>SUB FRONT SPARE PARTS</b> |   |                        | <b>\$ 7,375.00</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

## Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

### Telefax

### Material List for Accident Vehicle Regn No. SLD 6542 A

| S/N                         | Parts Description                             | Damaged Parts & Prices |                     |
|-----------------------------|---|------------------------|---------------------|
|                             |   | S/Nett                 | Remark              |
| 21                          | LOW TONE HORN BRACKET - RH <i>not on</i>      | \$                     | 23.00 *             |
| 22                          | FENDER - RH <i>not on</i>                     | \$                     | 913.00 *            |
| 23                          | FENDER ATTACHMENT PARTS                       | \$                     | 61.00 *             |
| 24                          | FRONT FENDER BRACKET - RH                     | \$                     | 49.00 *             |
| 25                          | FRONT FEDNER CENTER BRACKET                   | \$                     | 45.00 *             |
| 26                          | FRONT FENDER REAR BRACKET                     | \$                     | 45.00 *             |
| 27                          | POP RIVET                                     | 6 \$                   | 18.00 *             |
| 28                          | FRONT FENDER BRACE-RH                         | \$                     | 79.00 *             |
| 29                          | FRONT WHEEL HOUSING LINER-RH                  | \$                     | 246.00 *            |
| 30                          | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH | \$                     | 94.00 *             |
| 31                          | FRONT WHEEL SPOILER-RH <i>not on</i>          | \$                     | 60.00 *             |
| 32                          | HEADLIGHT MOUNTING-RH <i>cracked</i>          | \$                     | 107.00 ? 85.60 ✓    |
| 33                          | HEADLIGHT RETAINING PLATE-RH <i>not on</i>    | \$                     | 71.00 ? X           |
| 34                          | HEADLIGHT - RH <i>cracked</i>                 | \$                     | 2,501.00 ✓ 2000.80  |
| 35                          | HALOGEN FOG LAMP - RH <i>not on</i>           | \$                     | 238.00 *            |
| 36                          | HEADLIGHT LIFT CYLINDER - RH <i>cracked.</i>  | \$                     | 181.00 ? 146.80 ✓   |
| 37                          | RADIATOR AIR DUCT <i>not on</i>               | \$                     | 22.00 *             |
| 38                          | FRONT NO. PLATE <i>not on</i>                 | S/N \$                 | 40.00 *             |
| 39                          | SUNDRIES <i>Rec</i>                           | \$                     | 300.00 ? 42.08 ✓    |
| <b>TOTAL SPARE PARTS</b>    |   | :                      | <b>\$ 12,468.00</b> |
| <b>TOTAL LABOUR CHARGES</b> |   | :                      | <b>\$ 7,872.00</b>  |
| <b>GRAND TOTAL</b>          |   |                        | <b>\$ 20,340.00</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian King  
**Surveyed Date** : 03/09/19.0  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0959/2019/NS  
**Date** : 8-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

*Hi Adrian*

*3 days - ok - jb - 21 Oct 19*

**Attn: Mr. Adrian Ling - Motor Claims Dept**  
**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : MR SHETTY RAJENDRA KUMAR  
**Address** : BLK 217 YISHUN ST 21  
#07-337  
Singapore 760217  
**Telephone** : 98389904  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 2100471809-03  
**Vehicle No** : **SLD 6542 A**  
**Model Code** : Audi Q5 2.0 TFSI QU  
**Model / Year** : 24/6/2016  
**Engine No** : CNC 168546  
**Chassis No** : WAUZZZ8R6GA139958  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 6-Aug-19  
**Place of Accident** : ANG MO KIO CARPARK

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLD 6542 A

| <u>S/n</u>                  | <u>Nature of Jobs</u>  |     | <u>Estimated<br/>Charges</u> | <u>Surveyor's<br/>Recommendation</u> |
|-----------------------------|--|-----|------------------------------|--------------------------------------|
| 1                           | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.                | S/N | \$ 480.00                    | \$ 480.00                            |
| 2                           | To dismantle and renew front bumper, rhs front fender and rhs headlight. To repair bonnet. Re-organise crash management components. Reinstall all parts removed. |     | \$ 3,200.00                  | \$ 750.00                            |
| 3                           | To respray front bumper, front bumper spoiler, bonnet and rhs front fender.  |     | \$ 4,000.00                  | \$ 1,100.00                          |
| 4                           | To carry out diagnostic check.   | S/N | \$ 192.00                    | \$ 192.00                            |
| <b>TOTAL LABOUR CHARGES</b> |  | :   | <u>\$ 7,872.00</u>           | <u>\$ 2,522.00</u>                   |

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SLD 6542 A**

| S/N                          | Parts Description                 | Damaged Parts & Prices |                    |
|------------------------------|-----------------------------------|------------------------|--------------------|
|                              |                                   | S/Nett                 | Remark             |
| 1                            | FRONT BUMPER                      | \$ 2,353.00            | \$ 1,882.40        |
| 2                            | FRONT BUMPER FIXING PARTS         | \$ 249.00              |                    |
| 3                            | FRONT BUMPER BUMPER SPOILER       | \$ 569.00              |                    |
| 4                            | FRONT BUMPER CLOSING ELEMENT      | \$ 191.00              |                    |
| 5                            | FRONT BUMPER FOAM FILLER PIECE    | \$ 103.00              |                    |
| 6                            | FRONT BUMPER PULL STRAP           | \$ 47.00               |                    |
| 7                            | FRONT BUMPER SECURING STRIP-LH/RH | \$ 68.00               |                    |
| 8                            | FRONT BUMPER COVER                | \$ 116.00              |                    |
| 9                            | FRONT BUMPER AIR GUDIE GRILLE- RH | \$ 319.00              | \$ 255.20          |
| 10                           | FRONT BUMPER REINFORCEMENT BEAM   | \$ 598.00              |                    |
| 11                           | FRONT BUMPER REINFORCEMENT COVER  | \$ 59.00               |                    |
| 12                           | FRONT BUMPER GUIDE SECTION - RH   | \$ 34.00               |                    |
| 13                           | FRONT BUMPER SUPPORT - LH / RH    | 2 \$ 54.00             | \$ 21.20           |
| 14                           | SIGN 'CAUTION'                    | NEC \$ 13.00           |                    |
| 15                           | AIR CONDITIONER STICKER           | NEC \$ 7.00            |                    |
| 16                           | RADIATOR GRILLE                   | \$ 1,751.00            |                    |
| 17                           | INSCRIPTION ' QUATTRO '           | \$ 87.00               |                    |
| 18                           | RADIATOR GRILLE STRIKER PLATE     | \$ 111.00              |                    |
| 19                           | FRONT PARKING AID SENSOR          | 2 \$ 462.00            |                    |
| 20                           | LOW TONE SIGNAL HORN - RH         | \$ 184.00              |                    |
| <b>SUB FRONT SPARE PARTS</b> |                                   | <b>\$ 7,375.00</b>     | <b>\$ 2,158.80</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SLD 6542 A**

| S/N                         | Parts Description                             | c/f | Damaged Parts & Prices |                    |
|-----------------------------|---|-----|------------------------|--------------------|
|                             |   |     | S/Nett                 | Remark             |
|                             |   |     |                        | \$ 2,158.80        |
| 21                          | LOW TONE HORN BRACKET - RH                    |     | \$ 23.00               |                    |
| 22                          | FENDER - RH                                   |     | \$ 913.00              |                    |
| 23                          | FENDER ATTACHMENT PARTS                       |     | \$ 61.00               |                    |
| 24                          | FRONT FENDER BRACKET - RH                     |     | \$ 49.00               |                    |
| 25                          | FRONT FEDNER CENTER BRACKET                   |     | \$ 45.00               |                    |
| 26                          | FRONT FENDER REAR BRACKET                     |     | \$ 45.00               |                    |
| 27                          | POP RIVET                                     | 6   | \$ 18.00               |                    |
| 28                          | FRONT FENDER BRACE-RH                         |     | \$ 79.00               |                    |
| 29                          | FRONT WHEEL HOUSING LINER-RH                  |     | \$ 246.00              |                    |
| 30                          | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH |     | \$ 94.00               |                    |
| 31                          | FRONT WHEEL SPOILER-RH                        |     | \$ 60.00               |                    |
| 32                          | HEADLIGHT MOUNTING-RH                         |     | \$ 107.00              | \$ 85.60           |
| 33                          | HEADLIGHT RETAINING PLATE-RH                  |     | \$ 71.00               |                    |
| 34                          | HEADLIGHT - RH                                |     | \$ 2,501.00            | \$ 2,000.80        |
| 35                          | HALOGEN FOG LAMP - RH                         |     | \$ 238.00              |                    |
| 36                          | HEADLIGHT LIFT CYLINDER - RH                  |     | \$ 181.00              | \$ 144.80          |
| 37                          | RADIATOR AIR DUCT                             |     | \$ 22.00               |                    |
| 38                          | FRONT NO. PLATE                               | S/N | \$ 40.00               |                    |
| 39                          | SUNDRIES                                      |     | \$ 300.00              | \$ 42.08           |
| <b>TOTAL SPARE PARTS</b>    |   |     | <b>\$ 12,468.00</b>    | <b>\$ 4,432.08</b> |
| <b>TOTAL LABOUR CHARGES</b> |   |     | <b>\$ 7,872.00</b>     | <b>\$ 2,522.00</b> |
| <b>GRAND TOTAL</b>          |   |     | <b>\$ 20,340.00</b>    | <b>\$ 6,954.08</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SLD 6542 A**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/0959/2019/NH

20 Nov 2019

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

Dear Sir,

**RE: INSURANCE CLAIM FOR SLD 6542 A, Audi Q5 2.0 TFSI QU.**

With reference to the above-mentioned vehicle, no. **SLD 6542 A**, claimant, **Mr. Shetty Rajendra Kumar**, please find the related document per attached.

1. A copy of the Original invoice no. 85014490 – S\$ 6,905.87.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encl  
AIG – SLD 6542 A

total pages

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 11183

# Premium Automobiles Pte Ltd



**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6836 2223  
Main Telefax 6471 3733

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6388 2223  
Main Telefax 6475 1023

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 408699  
Main Telephone 6388 2323  
Main Telefax 6841 1183

**Customer Service**  
Service Appointment 6366 2323  
24-hour Breakdown Service 9828 1233  
Email customer.care@premiumauto.com.sg

## INS TAX INVOICE

Page 1 14:08

Company Reg. No. 199902271W  
GST Reg. No. 199902271W

|   |  |   |                       |
|---|--|---|-----------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD<br>MOTOR CLAIM DEPT<br>AIG BUILDING<br>78 SHENTON WAY<br>#07-16<br>SINGAPORE 079120 079120 | <b>Invoice No:</b> 85014490<br><b>Date :</b> 18/11/2019<br><b>Order :</b> SLD6542A<br><b>Term :</b> 30 | <b>Account:</b> A0006 IT 01<br>AIG ASIA PACIFIC INSURANCE PTE LTD<br>MOTOR CLAIM DEPT<br>AIG BUILDING<br>78 SHENTON WAY<br>#07-16<br>SINGAPORE 079120 |                       |
| <b>Regn No:</b> SLD6542A (V 30386)  | <b>Regn Date:</b> 24/06/2016   | <b>Mileage:</b> 76604   | <b>WIP No.:</b> 63438 |
| <b>Model:</b> Q5 2.0 TFSI quattro (180 bhp)   | <b>Chassis:</b> WAUZZZ8R6GAL39958  | <b>Engine:</b> CNC 168546   | <b>Dept:</b> U        |
| <b>You have been assisted by :-</b> UB-Tony Foong ( 33 )  |  |   |                       |

|   |                 | Details  | Qty       | Unit Price | Amount   |          |
|---|-----------------|--|-----------|------------|----------|----------|
| Q | EXC             | M: 8888<br>Insurance Excess/Liability  | -500.00   | 1.00       | -500.00  |          |
| S | BODYWORK        | M:<br>TO REMOVE,CHECK AND REINSTALL FRONT WIRE<br>HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE<br>TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY<br>AND FRONT PARKING AID. | 480.00    | 1.00       | 480.00   |          |
| S | BODYWORK        | M:<br>TO DISMANTLE AND RENEW FRONT BUMPER AND RHS<br>HEADLIGHT.TO REPAIR BONNET.REORGANISE<br>CRASH MANAGEMENT COMPONENTS.REINSTALL ALL<br>PARTS REMOVED     | 750.00    | 1.00       | 750.00   |          |
| S | BODYWORK        | M:<br>TO RESPRAY FRONT BUMPER AND FRONT BUMPER<br>SPOILER  | 1100.00   | 1.00       | 1,100.00 |          |
| S | BODYWORK        | M:<br>TO CARRY OUT DIAGNOSTIC CHECK  | 192.00    | 1.00       | 192.00   |          |
| X | A8R0941044D     | HEADLAMP(LAST)   | Less 020% | 1.00       | 2501.00  | 2,000.80 |
| X | A8R0807065C GRU | COVER(LAST)  | Less 020% | 1.00       | 2353.00  | 1,882.40 |
| X | AN 90765701     | POP-RIVET  | Less 020% | 2.00       | 1.40     | 2.24     |
| X | A8R0807333A     | SUPPORT(LAST) AP   | Less 020% | 1.00       | 26.50    | 21.20    |
| X | A8R0805608B     | MOUNTING AP  | Less 020% | 1.00       | 107.00   | 85.60    |
| X | A8R0807682J BJI | GRILL  | Less 020% | 1.00       | 319.00   | 255.20   |
| X | A8R0953102A     | CYLINDER (LAST) AP   | Less 020% | 1.00       | 181.00   | 144.80   |
| X | A3C0973737      | HOUSING AP   | Less 020% | 1.00       | 28.40    | 22.72    |
| X | A8R0121284R     | (5K)AIR DUCT AP  | Less 020% | 1.00       | 21.40    | 17.12    |

Parts 4,432.08  
Labour 0.00  
Sublet 2,522.00  
Menus 0.00  
Lubricant 0.00

**Sub-Total** 6,454.08

**7% GST** 451.79

**Grand Total** 6,905.87



Received by

For & on behalf of  
Premium Automobiles Pte Ltd

# Premium Automobiles

## Telefax

to **AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Motor Claims Dept**  
**Yr Ref: SLD 6542 A**

Norah Khai  
6768 9828  
6841 1183

Body Repair

PA/OD/0959/2019/EH  
27 September 2019

from  
Telephone +65-  
Telefax +65-  
Mobile +65-  
Our department  
Your Claim Ref  
Our Ref  
Date

**RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER**

1

total pages

**Make & Model** : Audi Q5 2.0 TFSI QU  
**Vehicle Chassis No.** : WAUZZZ8R6GA139958  
**Vehicle Regn No.** : **SLD 6542 A**  
**Vehicle Mileage** : 74055 KM  
**Vehicle Owner** : Mr. Shetty Rajendra kumar  
**Certificate No** : 2100471809-03  
**Own Damage Excess** : \$535.00 (Inclusive 7% GST)  
**Accident Date** : 06 Aug 2019  
**Place** : Ang Mo Kio Carpark  
**Repair Cost** : \$ 6905.87  
**WIP No.** : 63438  
**Repairer's Name** : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Road 1  
Singapore 408699  
Telephone (65) 6366 2323  
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

**Owner / Insured Signature** :

  
1200 Shetty R.K.  
27/9

**Time** :

**Date** :

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |            |   |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'd | Status  |
| Main                     | 12 Aug 2019 |               | 03 Sep 2019<br>16:51<br><a href="#">Edit Adj Rpt</a> | <b>S\$6,954.08</b><br><a href="#">Edit Estimates</a> | <b>S\$6,954.08</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

  

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

  

| CLAIM SUBFOLDER DETAILS |   | [Created by insurer]   |  |
|-------------------------|---|------------------------|--|
| Insured:                | SHETTY RAJENDRA KUMAR, ID: S2691893F, Tel: +6598389904, Email: RK.SHETTY@SIEMENS.COM                                  |                        |  |
| Vehicle Reg. No.:       | SLD6542A  | Date of Loss:          | 06/08/2019 18:00 - :59<br>[37 Months and 13 Days From LTA Reg Date (Man Yr)] |
| Claim Type:             | OD / 7735989372SG   | Policy/Cover Note No.: | 2100471809-03 (Comprehensive)  |
|                         |   | Excess:                | S\$500.00  |
| Repairer:               | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911                                 |                        |  |
| Handling Insurer:       | AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi]<br>yokeshi.chan@aig.com |                        |  |
| Adjuster:               | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/09/2019]        |                        |  |
| Driver/Custodian:       | SHETTY RAJENDRA KUMAR (57 / Male), NRIC: S2691893F, Tel: +6598389904 Email: RK.SHETTY@SIEMENS.COM                     |                        |  |

  

| ASSOCIATED MAIL RECEIVED  | <a href="#">View All</a> | <a href="#">Compose Case Mail</a> |
|---|--------------------------|-----------------------------------|
| <ul style="list-style-type: none"> <li>• AIG_SG (04/09/2019): Alert - Adj Mandate Approved (S\$7695.00) - SLD6542A - Claim Handler: Chan, Yoke ...</li> <li>• AIG_SG (04/09/2019): SLD6542A / OD / 06/08/2019 / Coverage &amp; Excess update</li> </ul> |                          |                                   |

  

| ALL ASSOCIATED TASKS |          |      |            |         |         |             |              |            |       | <a href="#">View All</a> | <a href="#">Search Tasks</a> | <a href="#">Create New Task</a> | <a href="#">Complete</a> |
|----------------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|--------------------------|------------------------------|---------------------------------|--------------------------|
| Due Date             | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |                          |                              |                                 |                          |
| No results.          |          |      |            |         |         |             |              |            |       |                          |                              |                                 |                          |

## Claim Documents

\*SLD6542A (7735989372SG)  
OD  
Aug 6 2019 6:55PM  
[SHETTY RAJENDRA KUMAR]  
Premium Automobiles Pte Ltd

| Upload Documents          |                 | Upload Photos  |  | Compose New Letter |  | Upload Video |  | Upload Audio |  | View       |                                     | Use Viewer                          |  |  |
|---------------------------|-----------------|--|--|--------------------|--|--------------|--|--------------|--|------------|-------------------------------------|-------------------------------------|--|--|
| <b>Video</b>              |                 |  |  |                    |  |              |  |              |  | 1 per page | <input checked="" type="checkbox"/> |                                     |  |  |
| No                        | Finalized On    | Premium Automobiles Pte Ltd (UBI)  |  |                    |  |              |  |              |  | Thumbnail  | Print                               |                                     |  |  |
| 1                         | 07/08/19 13:33  | <b>Video - Accident</b><br><small>[Linked Accident Report Documents]</small> |  |                    |  |              |  |              |  |            | Load MP4                            |                                     |  |  |
| <b>Assessment Reports</b> |                 |  |  |                    |  |              |  |              |  | 1 per page | <input checked="" type="checkbox"/> |                                     |  |  |
| No                        | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)  |  |                    |  |              |  |              |  | Thumbnail  | Print                               |                                     |  |  |
| 1                         | 03/09/19 17:23  | <b>Adjuster Immediate Advice</b>   |  |                    |  |              |  |              |  |            | Load HTM                            |                                     |  |  |
| <b>Photos/Images</b>      |                 |  |  |                    |  |              |  |              |  | 3 per page | <input checked="" type="checkbox"/> |                                     |  |  |
| No                        | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)  |  |                    |  |              |  |              |  | Thumbnail  | Print                               |                                     |  |  |
| 1                         | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 2                         | 04/09/19 10:00  | <b>Chassis Number</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 3                         | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 4                         | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 5                         | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 6                         | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 7                         | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 8                         | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 9                         | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 10                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 11                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 12                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 13                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 14                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 15                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 16                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 17                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 18                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 19                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 20                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| 21                        | 04/09/19 10:00  | <b>General View</b>  |  |                    |  |              |  |              |  |            | Load JPG                            | <input checked="" type="checkbox"/> |  |  |
| <b>Documentation</b>      |                 |  |  |                    |  |              |  |              |  | 1 per page | <input checked="" type="checkbox"/> |                                     |  |  |
| No                        | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)  |  |                    |  |              |  |              |  | Thumbnail  | Print                               |                                     |  |  |
| 1                         | 04/09/19 10:00  | <b>GIA AND POLICE REPORT</b>   |  |                    |  |              |  |              |  |            | Load PDF                            |                                     |  |  |
| 2                         | 04/09/19 10:00  | <b>Certificate of Insurance</b>  |  |                    |  |              |  |              |  |            | Load PDF                            |                                     |  |  |
| 3                         | 04/09/19 10:00  | <b>Driver's Driving License</b>  |  |                    |  |              |  |              |  |            | Load PDF                            |                                     |  |  |
| 4                         | 04/09/19 10:00  | <b>ESTIMATE</b>  |  |                    |  |              |  |              |  |            | Load PDF                            |                                     |  |  |
| 5                         | 28/11/19 13:41  | <b>WORKSHOP INVOICE</b>  |  |                    |  |              |  |              |  |            | Load PDF                            |                                     |  |  |
| 6                         | 28/11/19 13:41  | <b>DISCHARGE VOUCHER</b>   |  |                    |  |              |  |              |  |            | Load PDF                            |                                     |  |  |

## Linked Accident Report Documents

| Upload Documents          |                | Upload Photos                     |  | Compose New Letter |  | Upload Video |  | Upload Audio |  | View       |                                     | Use Viewer |  |
|---------------------------|----------------|-----------------------------------|--|--------------------|--|--------------|--|--------------|--|------------|-------------------------------------|------------|--|
| <b>Video</b>              |                |                                   |  |                    |  |              |  |              |  | 1 per page | <input checked="" type="checkbox"/> |            |  |
| No                        | Finalized On   | Premium Automobiles Pte Ltd (UBI) |  |                    |  |              |  |              |  | Thumbnail  | Print                               |            |  |
| 1                         | 07/08/19 13:33 | <b>Video - Accident</b>           |  |                    |  |              |  |              |  |            | Load MP4                            |            |  |
| <b>Assessment Reports</b> |                |                                   |  |                    |  |              |  |              |  | 1 per page | <input checked="" type="checkbox"/> |            |  |

| No                   | Finalized On   | Premium Automobiles Pte Ltd (UBI) | Thumbnail  | Print   |
|----------------------|----------------|-----------------------------------|--|---|
| 1                    | 07/08/19 13:50 | <b>Accident Statement</b>         |  Load HTML  |    |
| <b>Photos/Images</b> |                |                                   | 3 per page   |    |
| No                   | Finalized On   | Premium Automobiles Pte Ltd (UBI) | Thumbnail  | Print   |
| 1                    | 07/08/19 13:31 | <b>Police Report</b>              |  Load JPG   |    |
| 2                    | 07/08/19 13:31 | <b>Police Report</b>              |  Load JPG   |    |
| 3                    | 07/08/19 13:31 | <b>Police Report</b>              |  Load JPG   |    |
| 4                    | 07/08/19 13:31 | <b>Police Report</b>              |  Load JPG   |    |
| 5                    | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 6                    | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 7                    | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 8                    | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 9                    | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 10                   | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 11                   | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 12                   | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 13                   | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 14                   | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 15                   | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 16                   | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| 17                   | 07/08/19 13:48 | <b>Accident Photo</b>             |  Load JPG   |    |
| <b>Documentation</b> |                |                                   | 1 per page   |    |
| No                   | Finalized On   | Premium Automobiles Pte Ltd (UBI) | Thumbnail  | Print   |
| 1                    | 07/08/19 13:32 | <b>Sketch Plan</b>                |  Load JPG  |    |
| 2                    | 07/08/19 13:32 | <b>Sketch Plan #2</b>             |  Load JPG |  |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>   |       |      |       |
|  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CC3/AIG19015586/AQF3N2

Date: 28/11/2019

## REFERENCE

Insured/Claimant: SHETTY RAJENDRA KUMAR Policy No: 2100471809-03  
Date of Loss: 06/08/2019 Nature of Claim: OD Claim No: 7735989372SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLD6542A  
Make & Model: AUDI Q5, 2.0 TFSI Quattro (A) Engine No: CNC168546  
Reg. Date: 24/06/2016 (Man. Year: 2016) Chassis No: WAUZZZ8R6GA139958  
Colour: Blue Odometer: 72874 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$126,000.00  
Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                      | Repairer's       | Adjuster's      | Difference       | Diff %       |
|--------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                | 12,468.00        | 4,432.08        | 8,035.92         | 64.45        |
| Miscellaneous Items                  | 0.00             | 0.00            | 0.00             |              |
| Labour                               | 7,872.00         | 2,522.00        | 5,350.00         | 67.96        |
| Paintwork Labour                     | 0.00             | 0.00            | 0.00             |              |
| Towing                               | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (\$\$)</b> | <b>20,340.00</b> | <b>6,954.08</b> | <b>13,385.92</b> | <b>65.81</b> |
| <b>- Excess (\$\$)</b>               | <b>500.00</b>    | <b>500.00</b>   | <b>0.00</b>      | <b>0.00</b>  |
| <b>(\$\$)</b>                        | <b>19,840.00</b> | <b>6,454.08</b> | <b>13,385.92</b> | <b>67.47</b> |
| <b>+ GST 7.00/7.00% (\$\$)</b>       | <b>1,388.80</b>  | <b>451.79</b>   | <b>937.01</b>    | <b>67.47</b> |
| <b>Nett Amount (\$\$)</b>            | <b>21,228.80</b> | <b>6,905.87</b> | <b>14,322.93</b> | <b>67.47</b> |

## INSPECTION

Date of Assignment: 03/09/2019  
Date Inspected: 03/09/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                    | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                                  | Deformed      | 2,353.00 FS | *1,882.40 FS |
| 2   | 1   |          | *FRONT BUMPER FIXING PARTS                     | Not Necessary | 249.00 FS   | *- FS        |
| 3   | 1   |          | *FRONT BUMPER BUMPER SPOILER                   | Repair        | 569.00 FS   | *- FS        |
| 4   | 1   |          | *FRONT BUMPER CLOSING ELEMENT                  | Not Necessary | 191.00 FS   | *- FS        |
| 5   | 1   |          | *FRONT BUMPER FOAM FILLER PIECE                | Not Necessary | 103.00 FS   | *- FS        |
| 6   | 1   |          | *FRONT BUMPER PULL STRAP                       | Not Necessary | 47.00 FS    | *- FS        |
| 7   | 2   |          | *FRONT BUMPER SECURING STRIP-LH/RH             | Not Necessary | 68.00 FS    | *- FS        |
| 8   | 1   |          | *FRONT BUMPER COVER                            | Not Necessary | 116.00 FS   | *- FS        |
| 9   | 1   |          | *FRONT BUMPER AIR GUIDE GRILLE-RH              | Cut           | 319.00 FS   | *255.20 FS   |
| 10  | 1   |          | *FRONT BUMPER REINFORCEMENT BEAM               | Not Necessary | 598.00 FS   | *- FS        |
| 11  | 1   |          | *FRONT BUMPER REINFORCEMENT COVER              | Not Necessary | 59.00 FS    | *- FS        |
| 12  | 1   |          | *FRONT BUMPER GUIDE SECTION-RH                 | Not Necessary | 34.00 FS    | *- FS        |
| 13  | 1   |          | *FRONT BUMPER SUPPORT-LH/RH                    | O/s Damaged   | 54.00 FS    | *21.20 FS    |
| 14  | 1   |          | *SIGN CAUTION                                  | Not Necessary | 13.00 FS    | *- FS        |
| 15  | 1   |          | *AIR CONDITIONER STICKER                       | Not Necessary | 7.00 FS     | *- FS        |
| 16  | 1   |          | *RADIATOR GRILLE                               | Not Necessary | 1,751.00 FS | *- FS        |
| 17  | 1   |          | *INSCRIPTION QUATTRO                           | Not Necessary | 87.00 FS    | *- FS        |
| 18  | 1   |          | *RADIATOR GRILLE STRIKER PLATE                 | Not Necessary | 111.00 FS   | *- FS        |
| 19  | 2   |          | *FRONT PARKING AID SENSOR                      | Not Necessary | 462.00 FS   | *- FS        |
| 20  | 1   |          | *LOW TONE SIGNAL HORN-RH                       | Not Necessary | 184.00 FS   | *- FS        |
| 21  | 1   |          | *LOW TONE HORN BRACKET-RH                      | Not Necessary | 23.00 FS    | *- FS        |
| 22  | 1   |          | *FENDER-RH                                     | Not Necessary | 913.00 FS   | *- FS        |
| 23  | 1   |          | *FENDER ATTACHMENT PARTS                       | Not Necessary | 61.00 FS    | *- FS        |
| 24  | 1   |          | *FRONT FENDER BRACKET-RH                       | Not Necessary | 49.00 FS    | *- FS        |
| 25  | 1   |          | *FRONT FENDER CENTER BRACKET                   | Not Necessary | 45.00 FS    | *- FS        |
| 26  | 1   |          | *FRONT FENDER REAR BRACKET                     | Not Necessary | 45.00 FS    | *- FS        |
| 27  | 6   |          | *POP RIVET                                     | Not Necessary | 18.00 FS    | *- FS        |
| 28  | 1   |          | *FRONT FENDER BRACE-RH                         | Not Necessary | 79.00 FS    | *- FS        |
| 29  | 1   |          | *FRONT WHEEL HOUSING LINER-RH                  | Not Necessary | 246.00 FS   | *- FS        |
| 30  | 1   |          | *FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH | Not Necessary | 94.00 FS    | *- FS        |

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

| No. | Qty | Part No. | Particulars                   | Condition        | Repairer's                | Amount           |                 |
|-----|-----|----------|-------------------------------|------------------|---------------------------|------------------|-----------------|
| 31  | 1   |          | *FRONT WHEEL SPOILER-RH       | Not<br>Necessary | 60.00 FS                  | *- FS            |                 |
| 32  | 1   |          | *HEADLIGHT MOUNTING-RH        | Cracked          | 107.00 FS                 | *85.60 FS        |                 |
| 33  | 1   |          | *HEADLIGHT RETAINING PLATE-RH | Not<br>Necessary | 71.00 FS                  | *- FS            |                 |
| 34  | 1   |          | *HEADLIGHT-RH                 | Cracked          | 2,501.00 FS               | *2,000.80 FS     |                 |
| 35  | 1   |          | *HALOGEN FOG LAMP-RH          | Not<br>Necessary | 238.00 FS                 | *- FS            |                 |
| 36  | 1   |          | *HEADLIGHT LIFT CYLINDER-RH   | Cracked          | 181.00 FS                 | *144.80 FS       |                 |
| 37  | 1   |          | *RADIATOR AIR DUCT            | Not<br>Necessary | 22.00 FS                  | *- FS            |                 |
| 38  | 1   |          | *FRONT NO PLATE               | Not<br>Necessary | 40.00 FS                  | *- FS            |                 |
| 39  | 1   |          | *SUNDRIES                     | Necessary        | 300.00 FS                 | *42.08 FS        |                 |
|     |     |          |                               |                  | <b>Total Parts (\$\$)</b> | <b>12,468.00</b> | <b>4,432.08</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>            |   |          |                 |                 |
| 1                              | TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID                | New      | 480.00          | 480.00          |
| 2                              | TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.TO REPAIR BONNET.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New      | 3,200.00        | 750.00          |
| 3                              | TO RESPRAY FRONT BUMPER,FRONT BUMPER SPOILER,BONNET AND RHS FRONT FENDER  | New      | 4,000.00        | 1,100.00        |
| 4                              | TO CARRY OUT DIAGNOSTIC CHECK   | New      | 192.00          | 192.00          |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>7,872.00</b> | <b>2,522.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >