

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:08

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014490	Account: A0006 (T 0)
	Date : 18/11/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SLD6542A	
	Term : 30	

Regn No: SLD6542A (V 30386) **Regn Date:** 24/06/2016 **Mileage:** 76604 **WIP No.:** 63438

Model: Q5 2.0 TFSI quattro (180 bhp) **Chassis:** WAUZZZ8R6GA139958 **Engine:** CNC 168546 **Dept:** U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-500.00	1.00	-500.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.TO REPAIR BONNET.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND FRONT BUMPER SPOILER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8R0941044D	HEADLAMP(LAST)	Less 020%	1.00	2501.00
X	A8R0807065C GRU	COVER(LAST)	Less 020%	1.00	2353.00
X	AN 90765701	POP-RIVET	Less 020%	2.00	1.40
X	A8R0807333A	SUPPORT(LAST) AP	Less 020%	1.00	26.50
X	A8R0805608B	MOUNTING AP	Less 020%	1.00	107.00
X	A8R0807682J BJI	GRILL	Less 020%	1.00	319.00
X	A8R0955102A	CYLINDER (LAST) AP	Less 020%	1.00	181.00
X	A3C0973737	HOUSING AP	Less 020%	1.00	28.40
X	A8R0121284R	(SK)AIR DUCT AP	Less 020%	1.00	21.40

Parts 4,432.08
Labour 0.00
Sublet 2,522.00
Menus 0.00
Lubricant 0.00

Sub-Total 6,454.08

7% GST 451.79

Grand Total 6,905.87



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLD 6542 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0959/2019/EH
27 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZ8R6GA139958
Vehicle Regn No. : **SLD 6542 A**
Vehicle Mileage : 74055 KM
Vehicle Owner : Mr. Shetty Rajendra kumar
Certificate No : 2100471809-03
Own Damage Excess : \$535.00 (Inclusive 7% GST)
Accident Date : 06 Aug 2019
Place : Ang Mo Kio Carpark
Repair Cost : \$ 6905.87
WIP No. : 63438
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



1200 Shetty R.K

27/9

Time :

Date :