

REF:

ANG CC3 / A1919015589 / ASf3 N2

ASSIGNMENT

Merimen

From:

Date:

03/9/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SML 293D

at Workshop no:

Premium

of

U61

Insured:

Policy No:

Claims No:

Sum Insured:

EXCESS:

\$1,600/-

(Client's Record)

Make of Veh:

100% owner warranty

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

260K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / FR Sett:

Consistent? : Yes or No

Est. Repairs:

06 wks

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Vehicle:

SML 293D.

To Report:

2019 April

Type: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q7

cc: 1984

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp Reading:

5588.

TiRadio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU2224M7KD007714.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inter / Jammed / Leaked / Burnt or

Brake: Inter / Jammed / Leaked / Burnt or

Modi: Nil / SiRim / STD A/Rim or

Tyre Size:

F: 255/55R19.

R: 255/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIS / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A:

D.O.A:

03/09/19

Survey held at:

Premium.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

09 AUG.

SML 293D -X

RECEIVED 23 JAN 2020

04/09/19 @ 09:35 am revised PA to MdNoor. Norsiah via merimen.

04/09/19 @ 09:38 am mandate requested authorize repair to

ATA via merimen

06/09/19 @ 16:15 pm mandate approved by Victor Koh.

06/09/19 @ 17:46 pm informed CHA to Roy (repair) via email.

Adrian Confirmed P/P \$15,395.92 @ 6 days with 2 Bass.

(\$28,619.08 Red - 65%)

Date/Time, File Path to:

23/01/20

11

Type 4

☐ : Prel. Report☒ : Final Report

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS: 3

Phone:

Fax:

TOTAL:

200
11

211

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$

Report Format:

Lump Sum / I.B.: (\$ 15,395.92 P/P)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: MdNoor, Norsiah

Date: 04 Sep 2019

Preliminary Advice

Vehicle No	: SML293D	Accident Date	: 28/08/2019
Make	: AUDI Q7	Policy No.	:
Assignment Date	: 03/09/2019	Excess	: S\$0.00
Date of Inspection	: 03/09/2019	Est. Duration of Repair	: 6 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,957.00
Revised Amount	:S\$	17,787.00
Check Items (Estimated)	:S\$	924.00
Total	:S\$	16,863.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	260,000.00
COE / PARF Rebate	:S\$	106,550.00
Salvage Value	:S\$	
Margin for Repair	:S\$	153,450.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Received Message

This mail is associated with :

***SML293D (9053689552SG)**

OD

Aug 28 2019 3:40PM

[PREMIUM LEASING PTE LTD]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 06/09/2019 16:15 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$16863.00) - SML293D - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Approved:16863.00:Kindly refer to attach.

DOCUMENTS SUMMARY

There are no documents.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 13 December 2019 5:20 pm
To: Boo seng yak
Cc: Adrian Ling (LKKAuto); SUR; Carrine Leong; Chang Chee Sing; jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SML293D - OD AIG - SURVEYED 3 SEP 19

Dear Mr. Boo,

Confirmed final fig \$15,395.92 @ 6 days of repairs before excess \$ 1,600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 11 November 2019 6:11 pm
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SML293D - OD AIG - SURVEYED 3 SEP 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$15,395.92 @ 6 days exclude 1 Sunday.

Your early closure is appreciated.

Best regards - jb

Re: OD CLAIM FOR SML 293 D ON 28/8/2019

Shirley Hiew (LKK Auto)

Fri 6/9/2019 5:46 PM

To: Claims <claims@premiumauto.com.sg>

Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>

 1 attachments (892 KB)

ESTIMATE.pdf;

Hi Troy,

As instructed by our client, please proceed to repair the insured vehicle **SML 293D** (Excess \$ 1,600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>**Sent:** Tuesday, 3 September 2019 2:57 PM**To:** Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>**Cc:** 'Claims' <claims@premiumauto.com.sg>**Subject:** RE: OD CLAIM FOR SML 293 D ON 28/8/2019

Dear all,

Survey was done earlier by Adrian. Herein attached with the estimate repair with marking for your next action.

Kindly assist on the claims for approval and how much is the excess.

Thanks

Best Regards,

T Roy Goh

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Friday, 30 August 2019 3:35 PM

To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'

Cc: 'Claims'

Subject: RE: OD CLAIM FOR SML 293 D ON 28/8/2019

Dear all,

Attached is the estimate for your kind reference.

Best Regards,

Syafiq

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims <claims@premiumauto.com.sg>

Sent: Wednesday, 28 August 2019 6:26 PM

To: 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OD CLAIM FOR SML 293 D ON 28/8/2019

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 3/9/2019, 10am. Owner waiting

Best Regards,

Syafiq

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	676M
Vehicle Details	
Vehicle No.:	SML293D
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	Q7 2.0 TFSI QU (252 BHP)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CYR076615
Chassis No.:	WAUZZZ4M7KD007714
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$60,161.00
Original Registration Date:	30 Apr 2019
First Registration Date:	30 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$80,290.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2029
PARF Rebate Amount:	\$60,217.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$46,333.00
Total Rebate Amount:	\$106,550.00

The information contained herein is correct as at 04 Sep 2019

OK



HOTLINE TEL: (65) 8419 3000

COVER NOTE

Cover Note No. 100875408		Date 26 Apr 2019	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.			
SCHEDULE			
Policyholder	Premium Leasing Pte Ltd		
Age Condition	N/A	Registration No	TBA
Policy Type	COMPREHENSIVE COMMERCIAL MOTOR	Make/Model	Audi Q7 2.0 TFSI Qu
Effective Date	30 Apr 2019	CC/Tonnage	1,984.00
Expiry Date	29 Apr 2020	Engine No	CYR076615
Hire Purchase Company	HONG LEONG FINANCE LTD	Chassis No	WAUZZZ4M7KD007714
		Year of Registration	2019
			
This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions. Usage of vehicle only for the following purposes: 1. Use only for social, domestic and pleasure purposes and for the Policyholder's business. 2. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes. Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy. The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.			
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)			
CERTIFICATE OF INSURANCE			
I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)			

Issued at SINGAPORE

AIG ASIA PACIFIC INSURANCE PTE. LTD.

IMPORTANT NOTICE
THIS COVER NOTE IS VALID FOR
60 DAYS FROM THE FIRST DAY OF
THE POLICY PERIOD.



Authorised Representative

SSPYTP

UNDERTAKING

I, AVANTHSA V L NA RASIMHA RAD, (NRIC No. S2766868B), hereby confirm that the Singapore Accident Statement lodged by me on 28 Aug 2019 at 16.30 hours pertaining to the accident involving motor car Reg. No: SML293 D, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature : 
Name of Insured/ Driver : AVANTHSA V.L. NARASIMHA RAD
Nric No. : S2766868B
Date : 28/08/2019

Signature : _____
Name of Policyholder : _____
Nric No. : _____
Date : _____



AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : AVANTHSA VENKATA LAKSHMI NARASIMHARAO
VEHICLE NUMBER : SML 293 D
DATE/ TIME OF ACCIDENT : 28/08/2019, 15.40 Hrs
PLACE OF ACCIDENT : Base for Park, 110 TANJONG RHU ROAD
THIRD PARTY VEHICLE (IF ANY) : - None - CAMELOT BY THE WATER CONDOMINIUM

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

MARINE PARADE was the starting point and destination
was CAMELOT (home)

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?

- No -

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

No other vehicles involved.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

- No injuries -

NAME: AVANTHSA V.L. NARASIMHA RAO

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10317

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1037/2019/NS
Date	:	30-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Premium Leasing Pte Ltd
Address	:	9 Leng Kee Road Singapore 159090
Telephone	:	(HP)+65 93699238
Type of Claim	:	Own Damage Claims
Policy No.	:	100875408
Vehicle No	:	SML 293 D
Model Code	:	Audi Q7 2.0 TFSI QU
Model / Year	:	30/4/2019
Engine No	:	CYR 076615
Chassis No	:	WAUZZZ4M7KD007714
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Aug-19
Place of Accident	:	Camelot By The Water Condominium Basement Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SML 293 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00 400 ✓	
3	To install rear windscreen solar film.	S/N \$ 400.00 ✓	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipments.	S/N \$ 1,400.00 ✗	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	\$ 1,400.00 ✗ S/N	
SUB TOTAL LABOUR CHARGES		: \$ 4,160.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SML 293 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00 ✓	
7	To dismantle and renew rear bumper and rear lid. Cut out and weld rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 7,000.00	$600 \times 2.5 = 1500$
8	To resoray rear bumper, rear lid and rhs rear fender, hinges, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 6,950.00	1250 . $3 \times 600 = 1800$.
9	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 18,782.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 293 D

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	REAR BUMPER - UPPER / LOWER <i>Reh</i>	2	\$ 2,671.00 ✓	2136.80
2	REAR BUMPER FIXING PARTS <i>new</i>		\$ 188.00 X	
3	REAR BUMPER SPOILER <i>at</i>		\$ 1,151.00 ✓	920.80
4	REAR BUMPER SPOILER LOWER TRIM <i>Not New</i>		\$ 97.00 X	
6	BOOT LID CONTROL UNIT <i>new</i>		\$ 350.00 +	
7	REAR BUMPER GUIDE SECTION - RH <i>new</i>		\$ 58.00 X	
8	REAR BUMPER CARRIER <i>new</i>		\$ 1,238.00 +	
9	REAR BUMPER GUIDE SECTION - CENTRE <i>Damaged</i>		\$ 129.00 ? ✓	102.80
10	REAR BUMPER HOLDING STRAP <i>new</i>		\$ 166.00 X	
11	REAR PARKING AID SENSOR - INNER / OUTER <i>Not New</i>	2	\$ 462.00 +	
12	REAR PARKING AID SEAL RING	4	\$ 12.00 +	
13	TAIL LIGHT - RH <i>Cracked</i>		\$ 326.00 ✓	260.40
14	REAR FENDER SIDE PANEL <i>Rep's</i>		\$ 6,002.00 X	
15	LED TAIL LIGHT - RH <i>Cracked</i>		\$ 1,750.00 ✓	1400.00
16	REAR SIDE WINDOW - RH <i>new</i>		\$ 863.00 +	
17	REAR LID <i>Dented</i>		\$ 4,468.00 ✓	3574.40
18	REAR LID ATTACHMENT PARTS <i>Not New</i>		\$ 140.00 ? X	
19	REAR LID HINGE - LH / RH <i>new</i>	2	\$ 280.00 +	
20	REAR LID LOCK <i>new</i>		\$ 234.00 +	
SUB-TOTAL SPARE PARTS		:	\$ 20,585.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 293 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FLAP COVER CAP	S	11.00 ✓
22	REAR LID LOCK STRIKER	S	78.00 ✓
23	FLAP GASKET	NEC S	268.00 ✓
24	REAR LID CLIP	NEC S	3.00 ✓ 2.24
25	PACKING ADHESIVE	NEC S	18.00 ✓ 13.92
26	AUDI EMBLEM	NEC S	113.00 ✓ 90.60
27	Q7 INSCRIPTION	NEC S	87.00 ✓ 69.28
28	REAR WINDOW	S	1,069.00 ✓ 855.20
29	PRIMER	2 S	19.00 ✓ 14.88
30	REAR WINDSCREEN SIDE COVER - LH / RH	1 S	422.00 ✓ 336.80
31	REAR WHEEL COVER - LH / RH	2 S	358.00 ✓ 286.40
32	SPOILER FIXING PARTS	S	55.00 ✗
33	EXHAUST TAIL PIPE TRIM - RH	S	300.00 ✓
34	VENT TRIM	S	69.00 ✗
35	REAR NO PLATE	S/N S	40.00 ✗
36	ACRYLIC SEALANT	S/N S	180.00 ✗
37	CAVITY WAX	S/N S	140.00 ✗
38	STONE CHIP	S/N S	180.00 ✗
39	METAL FILLER POWDER	S/N S	280.00 ✗
40	REAR WINDSCREEN SEALANT	S/N S	200.00 ✓
	1/4 GLASS SEALANT	S/N S	100.00 ✗
	SUNDRIES	S/N S	600.00 ✗
TOTAL SPARE PARTS		\$ 25,175.00	
TOTAL LABOUR CHARGES		\$ 18,782.00	
GRAND TOTAL		\$ 43,957.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

44015

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *03/09/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorized, 06 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1037/2019/NS 30-Sep-19 Glory Tan 1 of 1 SML 293 D Audi Q7 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Rear bumper guide section LHS <i>RH Done NOT REC</i>	\$ 58.00	A / X
		\$ 58.00	
	TOTAL	\$ 58.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10317

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1037/2019/NS
Date : 30-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days exclude 1 Sunday

jb 11 Nov 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Premium Leasing Pte Ltd
Address : 9 Leng Kee Road
Singapore 159090
Telephone : (HP)+65 93699238
Type of Claim : Own Damage Claims
Policy No. : 100875408
Vehicle No : **SML 293 D**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : 30/4/2019
Engine No : CYR 076615
Chassis No : WAUZZZ4M7KD007714
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Aug-19
Place of Accident : Camelot By The Water Condominium Basement Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SML 293 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	\$ 360.00
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00	\$ 400.00
3	To install rear windscreen solar film.	S/N \$ 400.00	\$ 400.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipments.	S/N \$ 1,400.00	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	\$ 1,400.00 S/N	
SUB TOTAL LABOUR CHARGES		: \$ 4,160.00	\$ 1,160.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SML 293 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
	<i>c/f</i>		\$ 1,160.00
6	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	\$ 480.00
7	To dismantle and renew rear bumper and rear lid. Cut out and weld rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 7,000.00	\$ 1,500.00
8	To resoray rear bumper, rear lid and rhs rear fender, hinges, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 6,950.00	\$ 1,800.00
9	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 18,782.00	\$ 5,132.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 293 D

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	REAR BUMPER - UPPER / LOWER	2	\$ 2,671.00	\$ 2,136.80
2	REAR BUMPER FIXING PARTS		\$ 188.00	
3	REAR BUMPER SPOILER		\$ 1,151.00	\$ 920.80
4	REAR BUMPER SPOILER LOWER TRIM		\$ 97.00	
6	BOOT LID CONTROL UNIT		\$ 350.00	
7	REAR BUMPER GUIDE SECTION - RH		\$ 58.00	
8	REAR BUMPER CARRIER		\$ 1,238.00	
9	REAR BUMPER GUIDE SECTION - CENTRE		\$ 129.00	\$ 102.80
10	REAR BUMPER HOLDING STRAP		\$ 166.00	
11	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 462.00	
12	REAR PARKING AID SEAL RING	4	\$ 12.00	
13	TAIL LIGHT - RH		\$ 326.00	\$ 260.40
14	REAR FENDER SIDE PANEL		\$ 6,002.00	
15	LED TAIL LIGHT - RH		\$ 1,750.00	\$ 1,400.00
16	REAR SIDE WINDOW - RH		\$ 863.00	
17	REAR LID		\$ 4,468.00	\$ 3,574.40
18	REAR LID ATTACHMENT PARTS		\$ 140.00	
19	REAR LID HINGE - LH / RH	2	\$ 280.00	
20	REAR LID LOCK		\$ 234.00	
SUB-TOTAL SPARE PARTS		:	\$ 20,585.00	\$ 8,395.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 293 D

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 8,395.20
21	FLAP COVER CAP		\$ 11.00	
22	REAR LID LOCK STRIKER		\$ 78.00	
23	FLAP GASKET	NEC	\$ 268.00	
24	REAR LID CLIP	NEC	\$ 3.00	\$ 2.24
25	PACKING ADHESIVE	NEC	\$ 18.00	\$ 13.92
26	AUDI EMBLEM	NEC	\$ 113.00	\$ 90.00
27	Q7 INSCRIPTION	NEC	\$ 87.00	\$ 69.28
28	REAR WINDOW - LH		\$ 1,069.00	\$ 855.20
29	PRIMER	2	\$ 19.00	\$ 14.88
30	REAR WINDSCREEN SIDE COVER - LH / RH		\$ 422.00	\$ 336.80
31	REAR WHEEL COVER - LH / RH	2	\$ 358.00	\$ 286.40
32	SPOILER FIXING PARTS		\$ 55.00	
33	EXHAUST TAIL PIPE TRIM - RH		\$ 300.00	
34	VENT TRIM		\$ 69.00	
35	REAR NO PLATE	S/N	\$ 40.00	
36	ACRYLIC SEALANT	S/N	\$ 180.00	
37	CAVITY WAX	S/N	\$ 140.00	
38	STONE CHIP	S/N	\$ 180.00	
39	METAL FILLER POWDER	S/N	\$ 280.00	
40	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
	1/4 GLASS SEALANT	S/N	\$ 100.00	
	SUNDRIES	S/N	\$ 600.00	
TOTAL SPARE PARTS			\$ 25,175.00	\$ 10,263.92
TOTAL LABOUR CHARGES			\$ 18,782.00	\$ 5,132.00
GRAND TOTAL			\$ 43,957.00	\$ 15,395.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SML 293 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1037/2019/NH

21ST JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SML 293 D, Audi Q7 2.0 TFSI QU.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SML 293 D**, claimant, **Premium Leasing Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85014762 – S\$ 14,761.63.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SML 293 D

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6896 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:51

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014762 Date : 20/01/2020 Order : SML0293D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SML0293D (V 39937) Regn Date: 30/04/2019 Mileage: 6481 WIP No.: 10317

Model: Q7 2.0 TFSI QU (252 bhp) 4MB01 Chassis: WAUZZZ4M7RD007714 Engine: CYR 076615 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1600.00	1.00	-1,600.00
S	BODYWORK	M: TO REMOVE AND REINSTAKK REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION.	360.00	1.00	360.00
S	BODYWORK	M: TO RENEW REAR WINDSCREEN	400.00	1.00	400.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM,WIRE HARNESS FOR TAIL LIGHT AND REAR WIPER ASSY	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.CUT OUT AND WELD RHS REAR FENDER. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1500.00	1.00	1,500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,REAR LID AND RHS REAR FENDER.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORK	1800.00	1.00	1,800.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO SUPPLY REAR WINDSCREEN SEALANT	200.00	1.00	200.00
Q	OTHERS	M: TO INSTALL REAR WINDSCREEN SOLAR FILM	400.00	1.00	400.00
X	A4M0807511 GRU	COVER	Less 020%	1.00	1121.00
X	A4M0807067 4W3	(A) (SK)COVER 9/9/19	Less 020%	1.00	1550.00
X	A4M0807434E KAR	SPOILER(LAST)	Less 020%	1.00	1151.00
X	A4M0807458	GUIDE AP	Less 020%	1.00	128.50
X	A4M0945096	TAILLIGHT	Less 020%	1.00	325.50
X	A4M0945094M	TAIL LIGHT	Less 020%	1.00	1750.00
X	A4M0827025D	LID(LAST)	Less 020%	1.00	4468.00
X	A4G0827310	CLIP	Less 020%	2.00	1.40

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6641 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9826 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 14:51

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014762 Date : 20/01/2020 Order : SML0293D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SML0293D (V 39937)	Regn Date: 30/04/2019	Mileage: 6481	WIP No.: 10317
Model: Q7 2.0 TFSI QU (252 bhp) 4MB0I	Chassis: WAUZZZ4M7KD007714	Engine: CYR 076615	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
X	A8D0853419F	PACKING	Less 020%	1.00	17.40
X	A4M0853742 2ZZ	AUDI SIGN(LAST)	Less 020%	1.00	112.50
X	A4M0853741 2ZZ	INSCRIPTION "Q7"	Less 020%	1.00	86.60
X	A4M0845501B NVB	REARWINDOW(LAST)	Less 020%	1.00	1069.00
X	AD 00920002	PRIMER (DG)	Less 020%	1.00	18.60
X	A4M0854871A 5FQ	(A) (SK) SPOILER 25/9/	Less 020%	1.00	210.50
X	A4M0854872A 5FQ	(A) (SK) SPOILER 25/9/	Less 020%	1.00	210.50
X	A4M0853817 4WJ	(A) (SK) COVER 9/9/19	Less 020%	1.00	179.00
X	A4M0853818 4WJ	(A) (SK) COVER 9/9/19	Less 020%	1.00	179.00

Parts 10,063.92
Labour 400.00
Sublet 4,932.00
Menus 0.00
Lubricant 0.00



Sub-Total	13,795.92
7% GST	965.71
Grand Total	14,761.63

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SML 293 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1037/2019/TG
1 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q7 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZ4M7KD007714
Vehicle Regn No. : **SML 293 D**
Vehicle Mileage : 6481 KM
Vehicle Owner : Premium Leasing Pte Ltd
Certificate No : 100875408
Own Damage Excess : S\$ 1,712.00 (Inclusive 7% GST)
Accident Date : 28/08/2019
Place : Camelot By The Water Condominium Basement Carpark
Repair Cost : \$ 14761.63
WIP No. : 10317
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


12.30pm
1/10/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2019		03 Sep 2019 16:57 Edit Adj Rpt	S\$15,395.92 Edit Estimates	S\$15,395.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	PREMIUM LEASING PTE LTD, Co. Reg. No.: 201009676M			
Vehicle Reg. No.:	SML293D	Date of Loss:	28/08/2019 15:00 - :59 [3 Months and 29 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 9053689552SG	Policy/Cover Note No.:	(Comprehensive)	
		Excess:	S\$1,600.00	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur] Aashweenjeetkaur.Mithoosingh@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/09/2019]			
Driver/Custodian:	AVANTHSA VENKATA LAKSHMI NARASIMHA RAO (52 / Male), NRIC: S2766868B, Tel: +6596219646 Email: NARASIMHA.RAO@YAHOO.COM			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (09/09/2019): Alert - Adj Mandate Approved (S\$16863.00) - SML293D - Claim Handler: Mithoo Sing...
- AIG_SG (06/09/2019): Alert - Adj Mandate Approved (S\$16863.00) - SML293D - Claim Handler: Mithoo Sing...
- AIG_SG (06/09/2019): SML293D / OD / 28/08/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SML293D (9053689552SG)
OD
Aug 28 2019 3:40PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Assessment Reports														1 per page				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	04/09/19 09:35	Adjuster Immediate Advice												Load HTM				
Photos/Images														3 per page				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	04/09/19 09:37	General View												Load JPG				
2	04/09/19 09:37	General View												Load JPG				
3	04/09/19 09:37	General View												Load JPG				
4	04/09/19 09:37	General View												Load JPG				
5	04/09/19 09:37	General View												Load JPG				
6	04/09/19 09:37	General View												Load JPG				
7	04/09/19 09:37	General View												Load JPG				
8	04/09/19 09:37	General View												Load JPG				
9	04/09/19 09:37	General View												Load JPG				
10	04/09/19 09:37	General View												Load JPG				
11	04/09/19 09:37	General View												Load JPG				
12	04/09/19 09:37	General View												Load JPG				
13	04/09/19 09:37	General View												Load JPG				
14	04/09/19 09:37	General View												Load JPG				
15	04/09/19 09:37	General View												Load JPG				
16	04/09/19 09:37	General View												Load JPG				
17	04/09/19 09:37	General View												Load JPG				
18	04/09/19 09:37	General View												Load JPG				
19	04/09/19 09:37	General View												Load JPG				
20	04/09/19 09:37	General View												Load JPG				
21	04/09/19 09:37	General View												Load JPG				
22	04/09/19 09:37	General View												Load JPG				
23	04/09/19 09:37	General View												Load JPG				
24	06/12/19 14:50	General View												Load JPG				
25	06/12/19 14:50	General View												Load JPG				
26	06/12/19 14:50	General View												Load JPG				
27	06/12/19 14:50	General View												Load JPG				
Documentation														1 per page				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	04/09/19 09:36	COVER NOTE.pdf												Load PDF				
2	04/09/19 09:36	DRIVING.pdf												Load PDF				
3	04/09/19 09:36	SML 293D GIA.pdf												Load PDF				
4	04/09/19 09:36	UNDERTAKING & INTERVIEW.pdf												Load PDF				
5	04/09/19 09:36	ESTIMATE.pdf												Load PDF				
6	16/12/19 08:48	ESTIMATE & SUPP MARKED.pdf												Load PDF				
7	30/01/20 11:33	WORKSHOP INVOICE												Load PDF				
8	30/01/20 11:33	DISCHARGE VOUCHER												Load PDF				

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 per page	
1	04/09/19 02:45	Accident Statement	1	Load HTM
Photos/Images			3 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/08/19 18:08	Accident Photo	1	Load JPG
2	28/08/19 18:08	Accident Photo	1	Load JPG
3	28/08/19 18:08	Accident Photo	1	Load JPG
4	28/08/19 18:08	Accident Photo	1	Load JPG
5	28/08/19 18:08	Accident Photo	1	Load JPG
6	28/08/19 18:08	Accident Photo	1	Load JPG
7	28/08/19 18:08	Accident Photo	1	Load JPG
8	28/08/19 18:08	Accident Photo	1	Load JPG
9	28/08/19 18:08	Accident Photo	1	Load JPG
10	28/08/19 18:08	Accident Photo	1	Load JPG
11	28/08/19 18:08	Accident Photo	1	Load JPG
12	28/08/19 18:08	Accident Photo	1	Load JPG
13	28/08/19 18:08	Accident Photo	1	Load JPG
14	28/08/19 18:08	Accident Photo	1	Load JPG
15	28/08/19 18:08	Accident Photo	1	Load JPG
16	28/08/19 18:08	Accident Photo	1	Load JPG
17	28/08/19 18:08	Accident Photo	1	Load JPG
18	28/08/19 18:08	Accident Photo	1	Load JPG
19	28/08/19 18:08	Accident Photo	1	Load JPG
20	28/08/19 18:08	Accident Photo	1	Load JPG
21	28/08/19 18:08	Accident Photo	1	Load JPG
22	28/08/19 18:08	Accident Photo	1	Load JPG
23	28/08/19 18:08	Accident Photo	1	Load JPG
Documentation			1 per page	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/08/19 18:14	Sketch Plan	1	Load JPG
2	28/08/19 18:14	Sketch Plan #2	1	Load JPG

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19015589/ASF3N2

Date: 30/01/2020

REFERENCE

Insured/Claimant: PREMIUM LEASING PTE LTD

Policy No:

Date of Loss: 28/08/2019

Nature of Claim: OD Claim No: 9053689552SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML293D**
Make & Model: AUDI Q7, 2.0 TFSI QUATTRO (A)
Reg. Date: 30/04/2019 (Man. Year: 2018)
Colour: Blue
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$260,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CYR076615
Chassis No: WAUZZZ4M7KD007714
Odometer: 5588 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55R19
Front Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm

Rear Tyre Size: 255/55R19
Rear Left Side: Pirelli 6 mm
Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,233.00	10,263.92	14,969.08	59.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,782.00	5,132.00	13,650.00	72.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,015.00	15,395.92	28,619.08	65.02
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	42,415.00	13,795.92	28,619.08	67.47
+ GST 7.00/7.00% (S\$)	2,969.05	965.71	2,003.34	67.47
Nett Amount (S\$)	45,384.05	14,761.63	30,622.42	67.47

INSPECTION

Date of Assignment: 03/09/2019

Date Inspected: 03/09/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR BUMPER-UPPER/LOWER	Deformed	2,671.00 FS	*2,136.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	188.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	1,151.00 FS	*920.80 FS
4	1		*REAR BUMPER SPOILER LOWER TRIM	Not Necessary	97.00 FS	*- FS
5	1		*BOOT LID CONTROL UNIT	Not Necessary	350.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION-RH	Not Necessary	58.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Not Necessary	1,238.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION-CENTRE	Damaged	129.00 FS	*102.80 FS
9	1		*REAR BUMPER HOLDING STRAP	Not Necessary	166.00 FS	*- FS
10	2		*REAR PARKING AID SENSOR-INNER/OUTER	Not Necessary	462.00 FS	*- FS
11	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
12	1		*TAIL LIGHT-RH	Cracked	326.00 FS	*260.40 FS
13	1		*REAR FENDER SIDE PANEL	Repair	6,002.00 FS	*- FS
14	1		*LED TAIL LIGHT-RH	Cracked	1,750.00 FS	*1,400.00 FS
15	1		*REAR SIDE WINDOW-RH	Not Necessary	863.00 FS	*- FS
16	1		*REAR LID	Dented	4,468.00 FS	*3,574.40 FS
17	1		*REAR LID ATTACHMENT PARTS	Not Necessary	140.00 FS	*- FS
18	2		*REAR LID HINGE-LH/RH	Not Necessary	280.00 FS	*- FS
19	1		*REAR LID LOCK	Not Necessary	234.00 FS	*- FS
20	1		*FLAP COVER CAP	Not Necessary	11.00 FS	*- FS
21	1		*REAR LID LOCK STRIKER	Not Necessary	78.00 FS	*- FS
22	1		*FLAP GASKET	Not Necessary	268.00 FS	*- FS
23	1		*REAR LID CLIP	Necessary	3.00 FS	*2.24 FS
24	1		*PACKING ADHESIVE	Necessary	18.00 FS	*13.92 FS
25	1		*AUDI EMBLEM	Necessary	113.00 FS	*90.00 FS
26	1		*Q7 INSCRIPTION	Necessary	87.00 FS	*69.28 FS
27	1		*REAR WINDOW	Necessary	1,069.00 FS	*855.20 FS
28	2		*PRIMER	Necessary	19.00 FS	*14.88 FS
29	2		*REAR WINDSCREEN SIDE COVER-LH/RH	Necessary	422.00 FS	*336.80 FS
30	2		*REAR WHEEL COVER-LH/RH	Necessary	358.00 FS	*286.40 FS
31	1		*SPOILER FIXING PARTS	Not Necessary	55.00 FS	*- FS
32	1		*EXHAUST TAIL PIPE TRIM-RH	Not Necessary	300.00 FS	*- FS
33	1		*VENT TRIM	Not Necessary	69.00 FS	*- FS
34	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
35	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
36	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
37	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
38	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
40	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
41	1		*SUNDRIES	Not Necessary	600.00 FS	*- FS
42	1		*REAR BUMPER GUIDE SECTION RH	Not Necessary	58.00 FS	*- FS

F=Franchise part. S=SpcNetl.

Total Parts (\$\$) **25,233.00** **10,263.92**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	400.00
3	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	400.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENTS	New	1,400.00	0.00
5	TO REMOVE AND REINSTALL REAR SEAT,BACK RESET,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
6	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM,WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.CUT OUT AND WELD RHS REAR FENDER,RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	7,000.00	1,500.00
8	TO RESPRAY REAR BUMPER,REAR LID AND RHS REAR FENDER,HINGES,RHS SILL PANEL,DOOR ENTRANCES,ROOF CHANNEL,DRAIN PANEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,950.00	1,800.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			18,782.00	5,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >