

A.S. REC. BY:

REF: CS/INC/19015595/Kyd3m2 Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Annie Koh of INC Date/Time: 9:41am @ 3/9/19

Estimated Cost: Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 5694U Insured: SJV 4149U

at Workshop m/s Optima Werkz Tel: 64811522

of 9A Serunguan north Ave 5

Policy No: Claim No: MT/106 0418-001

Sum Insured: Excess:

Make of Veh: D.O.A. 30/8/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:40am @ 3/9/19 Person Contacted: Sharon Vehicle: IN/OUT

Date/Time	Action/Instruction
	Estimate ✓
	SMC 5694U-X
	SJV 4149U-NA / CFI / 8015170 / 14
	D.O.A. 17/8/2018
26/9	8 6179-52 email Confirm (Red \$1613-84, 20%)

ASS. REC. BY:

REF:

INC/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or NoLum Sum: 13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Snc 5684U Yr Regn: 07 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Honda Free c.c. 1496Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 56836 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GB7 1067312Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 205/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 30/8/19 D.O.I. 3/9/19

Survey held at _____ 1.30pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ File pass to

RECEIVED 31 OCT 2019

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

31/10/19 Typist

Days Of Repair: 8Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Fuel

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs. (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) P/P = \$6179.52

TOTAL

250

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 3 September 2019 11:13 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 3 September 2019 9:41 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	--------	-----	--------------------

1	Jared Liu	MT/1060401-001	SLK1628H	CH MOTOR REPAIRS AND SERVICES	BLK 10 ANG MO KIO INDUSTRIAL PARK 2A ANG MO KIO AUTOPOINT #05-19	SUSAN / 91004390	SLM822J	30/8/19	
2	Jeff Lin	MT/1059895-002	SKB 1584J	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047	terence loh / 82996103	GX4100J	27/8/19	
3	Eric Tang	MT/1060555-001	SLV2705D	LIAN HER MOTORS	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2	anthony cheong / 91082728	SCV5017T	16/8/19	
4	Serene Lim	MT/1060596-002	SLE4063Z	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	s t sim / 62524991	SDW810K	31/8/19	Please avoid 1pm to 2pm
5	Jeff Lin	MT/1060418-001	SMC5694U	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	sharon ten / 64811522	SJV4149U	30/8/19	
6	Serene Lim	MT/1040823-002	PAB151A	SC AUTO INDUSTRIES (S) PTE LTD	51 SENOKO ROAD #03-01 SENOKO INDUSTRIAL BUILDING SINGAPORE 758133	hamimah / 65719958	SLN1725U	17/4/19	
7	Quek Swee Keng	MT/1060611-001	SHA3654T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	LYNN / 65425119	SJE35E	1/9/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh

Senior Admin Assistant, Motor Insurance

T +65 6430 7899

www.income.com.sg

income
made different



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Yvonne Wong (LKK Auto)

From: sharon@ow.sg
Sent: Thursday, September 26, 2019 4:35 PM
To: Kenneth Kong (LKKAuto)
Cc: SUR; angela.tan@ow.sg; lily.loi@ow.sg; haoling.chong@ow.sg; hockkong.ong@ow.sg
Subject: RE: FINALISE / TP CLAIMS - SMC5694U HONDA FREED DOA: 30/08/2019
Attachments: 26092019155231.pdf

Dear Kenneth,

Our calculation as per below:

S/P - \$3,685.12
S/N - \$240.00
L - \$1,710.00
Supp - \$544.40
Part by Part - \$6,179.52 & 8 days

Please check & confirm.

Thank you.

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department
DID: (+65) 6481 1522 | Fax: (+65) 6481 1011

OPTIMA WERKZ PTE. LTD.

Head office: 6 Kung Chong Road Singapore 159143
Branch: 9A Serangoon North Ave 5 Singapore 554500
Branch: 452 Tagore Industrial Ave Singapore 787823

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person. Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Sent: Thursday, 26 September 2019 11:51 AM
To: Sharon <sharon@ow.sg>
Subject: RE: FINALISE / TP CLAIMS - SMC5694U HONDA FREED DOA: 30/08/2019

Attach finalised for SMC 5694U. Kenneth

From: Sharon [<mailto:sharon@ow.sg>]
Sent: Tuesday, 24 September, 2019 5:37 PM
To: Kenneth Kong (LKKAuto)
Cc: SUR; angela.tan@ow.sg; Lily Loi OW; haoling.chong@ow.sg; hockkong.ong@ow.sg
Subject: FINALISE / TP CLAIMS - SMC5694U HONDA FREED DOA: 30/08/2019

Dear Kenneth,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	666G
Vehicle Details	
Vehicle No.:	SMC5694U
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	LEB5600567
Chassis No.:	GB71067312
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$25,751.00
Original Registration Date:	10 Jul 2018
First Registration Date:	10 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$18,052.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2028
PARF Rebate Amount:	\$13,539.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,000.00
COE Rebate Amount:	\$27,458.00
Total Rebate Amount:	\$40,997.00

The information contained herein is correct as at 30 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/08/2019 15:22
Date Of Accident 30/08/2019 09:00
Exact Location Of Accident PIE TWDS CITY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC5694U
Insured/Policyholder
Name Of Registered Owner TAN KUAN WEI
NRIC No S8846666G
Email Address RAYNENTKW@GMAIL.COM
Mobile Phone No (LOCAL) +65-93837176
Alternative Phone No OTHERS-93837176
Vehicle Particulars
Manufacturer HONDA
Model FREED HYBRID 1.5G AUTO
Exact Purpose for which vehicle was being used at time of accident GOING TO WORK
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5101932768-01
Cover Note Number

Driver

Name of Driver IRENE OOI CAI LING
NRIC No S9529747A
Date Of Birth 25/08/1995
Occupation INDOOR
Date Of Driving Pass 26/06/2015
Driving Experience 4 YEARS AND 2 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-98629231
Fax Number
Contact Number
Email Address SOTRENE0825@GMAIL.COM

Address BLK 903 JURONG WEST STREET 91 #11-129
 Postcode 640903
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - GIRLFRIEND
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : XIAO MEI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN. WILL REPAIR AND CLAIM AT OPTIMA WERKZ PTE LTD.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: PASS TO WORKSHOP
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV4149U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver DU ZIJIAN
 NRIC/Passport Number S8415809G
 Contact Number 82006940
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A: SMC 5694U
B: SJV 4149U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

In 30/08/2019 @ about 1415 hrs, I was travelling on arterial right lane about PIE towards City direction. Vehicles ahead of me slowed down and came to a stop due to heavy traffic. I followed suit. Suddenly, I felt an impact from ~~behind~~ behind and realized a vehicle (B: SJV 4149U) had hit onto my vehicle's ~~rear~~ rear section. No injury arising out of this accident. After the accident, my passenger felt dizzy.

My car will proceed repair at Optima Car & Pie Ltd.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time: 30/8/19

Driver's Signature
(If driver is not the policyholder)
Date & Time: 30/8/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Supplies

Honda Freed

VEHICLE NO.: SMC 5694U

CHASSIS NO.: GBY1067312

NO.	DESCRIPTION	QTY
1	Tail gate lid inner lock striker Dir ✓	
2	Tail gate lid inner closing handle garnish cm ✓	
3	Rear bumper reflector x 2 In x	
4	Rear fender inner trim R/L ?	
5	Rear exhaust box 12 x	
6	- - - front shield 12 x	
7		
8		
9		
10	1) So narrow / split rear seats, carpeting,	
11	trimmings, fitting, further, and others 150	1001
12		
13	2) To pull and jack out rear floor	
14	panel and R/L chassis and correct	
15	to symmetrical position with the	
16	aid of hydraulic pneumatic	5001
17	jack. ✓ 1000.8	
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		
37		
38		
39		
40		

Date: 31.08.2019
 Vehicle No: SMC5694U
 Model: HONDA FREED HYBRID 1.5G - 2018
 Chassis: GB71067312
 Reg.Year: 2018

Third Party Insurer: NTUC
 Third Party Veh No: SJV4149U
 Date of Accident: 30.08.2019

Not Notation

Repairing B4 painting

Today

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Ry</i> \$967.90
2	REAR TAILGATE "FREED" EMBLEM	1		<i>ry</i> \$45.60
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>ry</i> \$55.20
4	REAR TAILGATE INNER LOCK	1		<i>ry</i> \$121.10
5	REAR TAILGATE INNER TRIM	1		\$246.30
6	REAR TAILGATE INNER TRIM CLIP	8	\$7.50	<i>ry</i> \$60.00
7	REAR TAILGATE OUTER HANDLE GARNISH COVER (CHROME)	1		\$181.60
8	REAR WINDSCREEN RUBBER	1		<i>ry</i> \$52.70
9	REAR TAILGATE RUBBER	1		<i>ry</i> \$123.70
10	REAR TAILGATE REVERSE LAMP LH	1		\$340.70
11	REAR TAILGATE REVERSE LAMP RH	1		\$340.70
12	REAR TAIL LAMP LH	1		<i>CM</i> \$613.20
13	REAR TAIL LAMP RH	1		<i>CM</i> \$613.20
14	REAR BUMPER	1		<i>Ry</i> \$783.70
15	REAR BUMPER SIDE BRACKET LH	1		<i>ry</i> \$28.40
16	REAR BUMPER SIDE BRACKET RH	1		<i>ry</i> \$28.40
17	REAR BUMPER CLIP	10	\$5.50	<i>ry</i> \$55.00
18	REAR END PANEL	1		<i>Ry</i> \$388.90
19	REAR END PANEL UPPER COVERING	1		<i>ry</i> \$82.40
20	REAR FLOOR PANEL			REPAIR
21	REAR QUARTER PANEL LH			REPAIR
SUB TOTAL				\$5,128.70
LESS 20%				-\$1,025.74
PARTS TOTAL				\$4,102.96

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>ry</i> \$60.00
2	REAR BUMPER REVERSE SENSOR	1		<i>ry</i> \$350.00
S/N TOTAL				\$410.00

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 Fax: (+65) 6452 9223



Date: 31.08.2019
Vehicle No: SMC5694U
Model: HONDA FREED HYBRID 1.5G - 2018
Chassis: GB71067312
Reg.Year: 2018

Third Party Insurer: NTUC
Third Party Veh No: SJV4149U
Date of Accident: 30.08.2019

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC	\$800.00	600
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC	\$900.00	800
TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT REAR WINDSCREEN RUBBER & ETC	\$150.00	120
TO DISMANTLE, REMOVE & TO REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO PROPER OPERATIONS	\$180.00	60 120
TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	\$80.00	50
TO TUFF KOTE & UNDERSEAL MATERIALS	\$200.00	60
TO CHECK WIRING & ELECTRICAL WIRING	\$80.00	20

LABOUR TOTAL	\$2,390.00
--------------	------------

ONG	TOTAL	\$6,902.96
-----	-------	------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 31.08.2019
Vehicle No: SMC5694U
Model: HONDA FREED HYBRID 1.5G - 2018
Chassis: GB71067312
Reg.Year: 2018

Third Party Insurer: NTUC
Third Party Veh No: SJV4149U
Date of Accident: 30.08.2019

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	TAILGATE LID INNER LOCK STRIKER	1		<i>Dr</i> \$46.40
2	TAILGATE LID "H" EMBLEM BADGE			<i>m</i> \$34.30
3	TAILGATE LID INNER CLOSING HANDLE GARNISH	1		<i>cm</i> \$24.80
4	REAR BUMPER REFLECTOR	2	\$35.20	<i>Pl</i> \$70.40
5	REAR FENDER INNER TRIM RH	1		\$289.70
6	REAR EXHAUST BOX	1		<i>R</i> \$549.20
7	REAR EXHAUST BOX HEAT SHIELD	1		<i>R</i> \$98.20
SUB TOTAL				\$1,113.00
LESS 20%				-\$222.60
PARTS TOTAL				\$890.40

LABOUR CHARGES:

TO REMOVE & REFIX REAR SEATS, CARPETING, TRIMMINGS, FITTING, FIXTURES AND OTHERS

\$150.00 *100%*

TO PULL AND JACK OUT REAR FLOOR PANEL AND RH CHASSIS AND CORRECT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK

\$1,000.00 *500%*

LABOUR TOTAL \$0.00

ONG TOTAL \$890.40

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 31.08.2019
 Vehicle No: SMC5694U
 Model: HONDA FREED HYBRID 1.5G - 2018
 Chassis: GB71067312
 Reg.Year: 2018

Third Party Insurer: NTUC
 Third Party Veh No: SJV4149U
 Date of Accident: 30.08.2019

Not Authorised 86179.20
 Repairing B4 painting 8 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		Ry \$967.90
2	REAR TAILGATE "FREED" EMBLEM	1		re \$45.60
3	REAR TAILGATE "HYBRID" EMBLEM	1		re \$55.20
4	REAR TAILGATE INNER LOCK	1		re \$121.10
5	REAR TAILGATE INNER TRIM	1	mg diy	\$246.30
6	REAR TAILGATE INNER TRIM CLIP	8	\$7.50	re \$60.00
7	REAR TAILGATE OUTER HANDLE GARNISH COVER (CHROME)	1		su \$181.60
8	REAR WINDSCREEN RUBBER	1	re paint	\$52.70
9	REAR TAILGATE RUBBER	1	diy re	\$123.70
10	REAR TAILGATE REVERSE LAMP LH	1	lm	\$340.70
11	REAR TAILGATE REVERSE LAMP RH	1		su \$340.70
12	REAR TAIL LAMP LH	1		cm \$613.20
13	REAR TAIL LAMP RH	1		cm \$613.20
14	REAR BUMPER	1		Ry \$783.70
15	REAR BUMPER SIDE BRACKET LH	1		diy \$28.40
16	REAR BUMPER SIDE BRACKET RH	1		diy \$28.40
17	REAR BUMPER CLIP	10	\$5.50	re \$55.00
18	REAR END PANEL	1		Ry \$388.90
19	REAR END PANEL UPPER COVERING	1		diy \$82.40
20	REAR FLOOR PANEL			REPAIR
21	REAR QUARTER PANEL LH			REPAIR

4,759.60
 - 951.92
 3,807.68

SUB TOTAL	\$5,128.70
LESS 20%	-\$1,025.74
PARTS TOTAL	\$4,102.96

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		re \$60.00
2	REAR BUMPER REVERSE SENSOR	1		re \$350.00
				S/N TOTAL \$410.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 : Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554509
 Tel: (+65) 6484 9919 : Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 : Fax: (+65) 6452 9223



Date: 31.08.2019
 Vehicle No: SMC5694U
 Model: HONDA FREED HYBRID 1.5G - 2018
 Chassis: GB71067312
 Reg.Year: 2018

Third Party Insurer: NTUC
 Third Party Veh No: SJV4149U
 Date of Accident: 30.08.2019

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC	\$800.00	600
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC	\$900.00	800
TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT REAR WINDSCREEN RUBBER & ETC	\$150.00	120
TO DISMANTLE, REMOVE & TO REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO PROPER OPERATIONS	\$180.00	60 120
TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	\$80.00	50
TO TUFF KOTE & UNDERSEAL MATERIALS	\$200.00	60
TO CHECK WIRING & ELECTRICAL WIRING	\$80.00	20
LABOUR TOTAL	\$2,390.00	1710

TOTAL	\$6,902.96
--------------	-------------------

ONG

8943.36

Head office

6 King Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 Fax: (+65) 6452 9223



Third Party Insurer: NTUC
Third Party Veh No: SJV4149U
Date of Accident: 30.08.2019

SUPPLEMENTARY				
NO.	DESCRIPTION	QTY	UNIT \$\$	AMOUNT \$\$
✓ 1	TAILGATE LID INNER LOCK STRIKER ✓	1		017 \$46.40
2	TAILGATE LID "H" EMBLEM BADGE			22 \$34.30
3	TAILGATE LID INNER CLOSING HANDLE GARNISH ✓	1		011 \$24.80
4	REAR BUMPER REFLECTOR	2	\$35.20	52 \$70.40
5	REAR FENDER INNER TRIM RH	1		52 \$289.20
6	REAR EXHAUST BOX	1		22 \$549.20
7	REAR EXHAUST BOX HEAT SHIELD	1		22 \$98.20
			SUB TOTAL	\$1,113.00
			LESS 20%	-\$222.60
			PARTS TOTAL	\$890.40

TO PULL AND JACK OUT REAR FLOOR PANEL AND RH CHASSIS AND CORRECT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK

TOTAL	\$890.40
-------	----------

P - 43,807.68
 SN - \$ 240.00
 L - \$1,710.00
 Supp - \$684.40

P/P ~~\$6,442.08~~ x 8 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19015595/Kyd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 05-11-2019



ATTN: JEFF LIN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 4149U	Veh. Inspected	SMC 5694U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1060418-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	03/09/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA FREED (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GB71067312	Colour	METALLIC PEARL WHITE
Odometer	56936 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	YOKOHAMA	8 mm
L/H Front Tyre	205/50 R16	YOKOHAMA	8 mm
R/H Rear Tyre	205/50 R16	YOKOHAMA	8 mm
L/H Rear Tyre	205/50 R16	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/08/2019	Inspect Date / Time	03/09/2019 (01:30 PM)
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 5694U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BENT	967.90	967.90
1	REAR TAILGATE "FREED" EMBLEM	NECESSARY	45.60	45.60
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	55.20	55.20
1	REAR TAILGATE INNER LOCK	DENTED	121.10	121.10
1	REAR TAILGATE INNER TRIM	MTG DISTORTED	246.30	246.30
8	REAR TAILGATE INNER TRIM CLIP @\$7.50	NECESSARY	60.00	60.00
1	REAR TAILGATE OUTER HANDLE GARNISH COVER (CHROME)	SERVICEABLE	181.60	-
1	REAR WINDSCREEN RUBBER	NECESSARY	52.70	52.70
1	REAR TAILGATE RUBBER	DISTORTED / DENTED	123.70	123.70
1	REAR TAILGATE REVERSE LAMP LH	CUT	340.70	340.70
1	REAR TAILGATE REVERSE LAMP RH	SERVICEABLE	340.70	-
1	REAR TAIL LAMP LH	CRACKED	613.20	613.20
1	REAR TAIL LAMP RH	CRACKED	613.20	613.20
1	REAR BUMPER	BENT	783.70	783.70
1	REAR BUMPER SIDE BRACKET LH	DISTORTED	28.40	28.40
1	REAR BUMPER SIDE BRACKET RH	DISTORTED	28.40	28.40
10	REAR BUMPER CLIP @\$5.50	NECESSARY	55.00	55.00
1	REAR END PANEL	BENT	388.90	388.90
1	REAR END PANEL UPPER COVERING	DISTORTED	82.40	82.40
1	REAR FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR QUARTER PANEL LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE LID INNER LOCK STRIKER (ADDITIONAL)	DISTORTED	46.40	46.40
1	TAILGATE LID "H" EMBLEM BADGE (ADDITIONAL)	NECESSARY	34.30	34.30
1	TAILGATE LID INNER CLOSING HANDLE GARNISH (ADDITIONAL)	DENTED	24.80	24.80
2	REAR BUMPER REFLECTOR @\$35.20 (ADDITIONAL)	SERVICEABLE	70.40	-
1	REAR FENDER INNER TRIM RH (ADDITIONAL)	SERVICEABLE	289.70	-
1	REAR EXHAUST BOX (ADDITIONAL)	TO REPAIR SEE LABOUR	549.20	-

Report Ref No. CS/INC19015595/Kyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST BOX HEAT SHIELD (ADDITIONAL)	TO REPAIR SEE LABOUR	98.20	-
	LESS 20% DISCOUNT		-1,248.34	-942.38
			4,993.36	3,769.52
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED	350.00	200.00
			410.00	240.00
	LABOUR			
	LABOUR CHARGES TO REMOVE,REPLACE,REPAIR,READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,REAR QUARTER PANEL LH,REAR EXHAUST BOX AND REAR EXHAUST BOX HEAT SHIELD.		800.00	600.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC.		900.00	800.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS,REAR WINDSCREEN SEALANT,REAR WINDSCREEN RUBBER & ETC.		150.00	120.00
	TO DISMANTLE,REMOVE & TO REINSTALLED REAR TAILGATE INNER MECHANISM & ETC.BACK TO PROPER OPERATIONS.		180.00	60.00
	TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.		80.00	50.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.		200.00	60.00
	TO CHECK WIRING & ELECTRICAL WIRING.		80.00	20.00
	TO REMOVE & REFIX REAR SEATS,CARPETING,TRIMMINGS,FITTING,FIXTURES AND OTHERS. (ADDITIONAL).		150.00	60.00
	TO PULL AND JACK OUT REAR FLOOR PANEL AND RH CHASSIS AND CORRECT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. (ADDITIONAL).		1,000.00	400.00
			3,540.00	2,170.00
	GRAND TOTAL		8,943.36	6,179.52
RECOMMENDED COST OF REPAIRS (CONFIRMED)				6,179.52

Report Ref No. CS/INC19015595/Kyd3n2



Report Ref No. CS/INC19015595/Kyd3n2

KONG SENG CHEONG
Licensed Appraiser

A handwritten signature in black ink, appearing to be 'K.K. LAU'.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.