

ASS. REC. BY:

REF:

03/INC19015600/Kyd3n2

Special Instructions

Assigner: Kenneth

ASSIGNMENT (Office)

From (Person): Annie Koh

of

INC

Date/Time: 9:41am @ 3/9/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / TNV / MV / CS

To Inspect Vehicle No:

SKB 1584J

Insured:

QX4100J

at Workshop m/s

Jwg International

Tel:

8299 6103.

of

10 Amk Ind. Park 2A #03-08

Policy No:

Claim No:

MT/1059895-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/8/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:17am @ 3/9/19

Person Contacted:

Tenence

Vehicle: IN/OUT

Date/Time

Action/Instruction

Voluntary ✓

SKB 1584J - NA/FWD19015239/1/4

Don: 27/8/2019

QX4100J - NA/FWD19015239/1/4

Don: 27/8/2019

24/10

6/Prp & 335d email & confirm (Red \$20,115-91, 85%)

ASS. REC. BY:

REF: INC1Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____ JWG

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

1 File pass to

Veh No: SKB 15843 Yr Regn: 04, 11Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Alfa Romeo 1388Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 157311 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: EAR 955006 01130859Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD/Rim or

Tyre Size: F: _____

R: 215/45BR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 27/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 8 OCT 2019

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 31/10/19 Typist

Report Format:

Lump Sum / B.I. (\$) \$3350Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

250

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 3 September 2019 11:13 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 3 September 2019 9:41 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	--------	-----	--------------------

1	Jared Liu	MT/1060401-001	SLK1628H	CH MOTOR REPAIRS AND SERVICES	BLK 10 ANG MO KIO INDUSTRIAL PARK 2A ANG MO KIO AUTOPOINT #05-19	SUSAN / 91004390	SLM822J	30/8/19	
2	Jeff Lin	MT/1059895-002	SKB 1584J	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047	terence loh / 82996103	GX4100J	27/8/19	
3	Eric Tang	MT/1060555-001	SLV2705D	LIAN HER MOTORS	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2	anthony cheong / 91082728	SCV5017T	16/8/19	
4	Serene Lim	MT/1060596-002	SLF4063Z	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	s t sim / 62524991	SDW810K	31/8/19	Please avoid 1pm to 2pm
5	Jeff Lin	MT/1060418-001	SMC5694U	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	sharon ten / 64811522	SJV4149U	30/8/19	
6	Serene Lim	MT/1040823-002	PA8151A	SC AUTO INDUSTRIES (S) PTE LTD	51 SENOKO ROAD #03-01 SENOKO INDUSTRIAL BUILDING SINGAPORE 758133	hamimah / 65719958	SLN1725U	17/4/19	
7	Quek Swee Keng	MT/1060611-001	SHA3654T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	LYNN / 65425119	SJE35E	1/9/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg

income
made different



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 609E

Vehicle Details

Vehicle No.: SKB1584J
Vehicle to be Exported: Yes
Intended Deregistration Date: 03 Sep 2019
Vehicle Make: ALFA ROMEO
Vehicle Model: MITO 1.4TB MULTIAIR TCT SMT D/AB 2WD 3DR
Primary Colour: Black
Manufacturing Year: 2010
Engine No.: 955A70001578531
Chassis No.: ZAR95500001130859
Maximum Power Output: 99.0 kW (132 bhp)
Open Market Value: \$22,075.00
Original Registration Date: 29 Apr 2011
First Registration Date: 29 Apr 2011
Transfer Count: 2
Actual ARF Paid: \$22,075.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Apr 2021
PARF Rebate Amount: \$12,141.00

Intended COE Rebate Details

COE Expiry Date: 28 Apr 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$44,000.00
COE Rebate Amount: \$7,272.00
Total Rebate Amount: \$19,413.00

The information contained herein is correct as at 03 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/08/2019 09:05
Date Of Accident	27/08/2019 18:20
Exact Location Of Accident	SLIP RD OF MARYMOUNT RD TO AMK AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB1584J
Insured/Policyholder	
Name Of Registered Owner	TUNG POH LIAN
NRIC No	S2610609E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81701114
Alternative Phone No	OFFICE-81701114

Vehicle Particulars

Manufacturer	ALFA ROMEO
Model	MITO 1.4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00007662-01
Cover Note Number	-

Driver

Name of Driver	TAN WEIREN URIAH
NRIC No	S9746478B
Date Of Birth	24/12/1997
Occupation	INDOOR
Date Of Driving Pass	16/03/2018
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91173398
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 710 WOODLANDS DR 70 #02-35
Postcode	730710
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : TAN PANG KWOK EDMUND GENDER: : MALE
Passenger 2	NAME: : TUNG POH LIAN GENDER: : FEMALE
Passenger 3	NAME: : TIN MAR AYE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX4100J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

VEHICLE NO.: SKB 1584J

INSURER: FWD

DATE & TIME: _____

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/IN No:

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated time and date, I vehicle A (SHB1584J) was travelling on the stated venue, I stop in order for a cyclist to cross the zebra crossing. Suddenly, vehicle B (GX4100J) collided onto my vehicle rear position causing damages.

I wish to state that I've got passengers in my car. (SHB1584J)

- 1) Tan Weiren, Uriah (Male) (Driver) NRIC: S9746478B
- 2) Tan Pang Kuan, Edmund (Male) NRIC: S1730487E
- 3) Tung BH Lian (Female) (Owner) NRIC: S2610609E
- 4) Tin Mar Aye (Female) Fin: G8793532P

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

(We declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time

 Reporting Centre Personnel's Signature
 Name:
 NRIC/Fin No:

☐ Claim Own Policy ☒ Claim Third Party ☐ Reporting Only
☐ Claim ODP at other workshop ()

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H

Blk 10, Ang Mo Kio Ind Park 2A,

#03-08 AMK AutoPoint,

Singapore 568047

H/P: 9069 7882 Fax: 6909 9592

E-Mail: jwg.claims@yahoo.com

Not Authored
6/10/19
Autony After Point
DATE: 1-Oct-19

VEHICLE NO : SKB 1584 J
MODEL : ALFA ROMEO MTO
CHASSIS NO :

Kennerh (LKK)
96810663
4 days

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BOOTLID	1	\$ 1,888.53	\$ 1,888.53	✓
2	BOOTLID LOCK	1	\$ 277.19	\$ 277.19	X
3	BOOTLID WEATHERSTRIP	1	\$ 213.75	\$ 213.75	X
4	BOOTLID LOGO	1	\$ 96.00	\$ 96.00	✓
5	BOOTLID EMBLEM - MTO	1	\$ 88.00	\$ 88.00	✓
6	BOOTLID INNER TRIM	1	\$ 368.90	\$ 368.90	X
7	REAR WINDSCREEN COMPLETE SET WITH MOULDING	1	\$ 1,847.90	\$ 1,847.90	?
8	TAILLAMP	2	\$ 980.70	\$ 1,961.40	X
9	TAILLAMP LOWER BRACKET	2	\$ 245.70	\$ 491.40	X
10	TAILLAMP CHROME MOULDING	2	\$ 198.00	\$ 396.00	X
11	TAILLAMP CLIPS	2	\$ 15.00	\$ 30.00	X
12	REAR BUMPER	1	\$ 1,798.74	\$ 1,798.74	✓
13	REAR BUMPER SIDE RETAINER	2	\$ 87.40	\$ 174.80	X
14	REAR BUMPER BRACKET	2	\$ 98.70	\$ 197.40	X
15	REAR BUMPER REINFORCEMENT	1	\$ 798.30	\$ 798.30	?
16	REAR BUMPER CARRIER	1	\$ 345.60	\$ 345.60	?
17	REAR BUMPER SPONGE	1	\$ 497.10	\$ 497.10	?
18	REAR BUMPER REFLECTOR	2	\$ 189.10	\$ 378.20	X
19	REAR END PANEL	1	\$ 889.50	\$ 889.50	X
20	REAR END PANEL TOP GARNISH	1	\$ 594.10	\$ 594.10	X
21	REAR BUMPER REVERSE SENSOR	2	\$ 485.00	\$ 970.00	X 20052
22	REAR BUMPER REVERSE SENSOR HOLDER	2	\$ 87.40	\$ 174.80	X
23	REAR BUMPER REVERSE SENSOR WIREHARNES	1	\$ 1,847.00	\$ 1,847.00	X
24	REAR BUMPER SENSOR BUZZER	1	\$ 248.00	\$ 248.00	X
25	REAR NUMBER PLATE LAMP	2	\$ 74.70	\$ 149.40	X
26	EXHAUST PIPE	1	\$ 2,890.00	\$ 2,890.00	X
27	EXHAUST PIPE GASKET	1	\$ 59.00	\$ 59.00	X

TOTAL PRICE \$ 19,671.01
LESS 10% \$ 1,967.10

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS	10	\$ 6.80	\$ 68.00
2	REAR NUMBER PLATE	1	\$ 80.00	\$ 80.00
3	BOOTLID SEALANT	1	\$ 80.00	\$ 80.00
4	BOOTLID INSULATOR CLIPS	10	\$ 6.50	\$ 65.00
5	REAR END PANEL TOP GARNISH CLIPS	6	\$ 6.50	\$ 39.00
6	BOOTLID STICKER	1	\$ 100.00	\$ 100.00
7	REAR END PANEL INSULATOR SEAL	1	\$ 150.00	\$ 150.00

TOTAL	\$	582.00
-------	----	--------

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	400/-
2	TO PUTTY AND RESPRAY AFFECTED AREA	\$ 1,400.00	450/-
3	TO TUFF COAT ACCIDENT AFFECTED AREA	\$ 250.00	30/-
4	TO RNR REAR BOOTLID MECHANISM TO ASSIST WORK LOAD	\$ 250.00	60/-
5	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 300.00	X
6	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$ 100.00	20/-
7	TO RNR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00	120/-
8	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 400.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	15/-
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50/-
11	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 150.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 300.00	X

TOTAL	\$	5,180.00
-------	----	----------

TOTAL PARTS COST	:	\$	18,285.91
TOTAL LABOUR COST	:	\$	5,180.00
TOTAL REPAIR COST	:	\$	23,465.91

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

KELVIN WO

HP 9069 7882

JWG INTERNATIONAL PTE. LTD.

Co. & GST Reg. No.: 201837488H
 Blk 10, Ang Mo Kio Ind Park 2A,
 #03-08 AMK AutoPoint,
 Singapore 568047
 H/P: 9069 7882 Fax: 6909 9592
 E-Mail: jwg.claims@yahoo.com

Not Authorised
 611pm 83350/f
 Anthony After Paint
 DATE: 1-Oct-19

VEHICLE NO : SKB 1584 J
 MODEL : ALFA ROMEO MITO
 CHASSIS NO :

Kennerh (Lkk)
 96910663
 4 days

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID 1456.10	1	\$ 1,888.53	\$ 1,888.53
2	BOOTLID LOCK	1	\$ 277.19	\$ 277.19
3	BOOTLID WEATHERSTRIP	1	\$ 213.75	\$ 213.75
4	BOOTLID LOGO	1	\$ 96.00	\$ 96.00
5	BOOTLID EMBLEM - MTO	1	\$ 88.00	\$ 88.00
6	BOOTLID INNER TRIM	1	\$ 368.90	\$ 368.90
7	REAR WINDSCREEN COMPLETE SET WITH MOULDING	1	\$ 1,847.90	\$ 1,847.90
8	TAILLAMP	2	\$ 980.70	\$ 1,961.40
9	TAILLAMP LOWER BRACKET	2	\$ 245.70	\$ 491.40
10	TAILLAMP CHROME MOULDING	2	\$ 198.00	\$ 396.00
11	TAILLAMP CLIPS	2	\$ 15.00	\$ 30.00
12	REAR BUMPER 976.40	1	\$ 1,798.74	\$ 1,798.74
13	REAR BUMPER SIDE RETAINER	2	\$ 87.40	\$ 174.80
14	REAR BUMPER BRACKET	2	\$ 98.70	\$ 197.40
15	REAR BUMPER REINFORCEMENT 448.30 CM	1	\$ 798.30	\$ 798.30
16	REAR BUMPER CARRIER 131.20 CM	1	\$ 345.60	\$ 345.60
17	REAR BUMPER SPONGE 122.30 CM	1	\$ 497.10	\$ 497.10
18	REAR BUMPER REFLECTOR	2	\$ 189.10	\$ 378.20
19	REAR END PANEL	1	\$ 889.50	\$ 889.50
20	REAR END PANEL TOP GARNISH	1	\$ 594.10	\$ 594.10
21	REAR BUMPER REVERSE SENSOR	2	\$ 485.00	\$ 970.00
22	REAR BUMPER REVERSE SENSOR HOLDER	2	\$ 87.40	\$ 174.80
23	REAR BUMPER REVERSE SENSOR WIREHARNES	1	\$ 1,847.00	\$ 1,847.00
24	REAR BUMPER SENSOR BUZZER	1	\$ 248.00	\$ 248.00
25	REAR NUMBER PLATE LAMP	2	\$ 74.70	\$ 149.40
26	EXHAUST PIPE	1	\$ 2,890.00	\$ 2,890.00
27	EXHAUST PIPE GASKET	1	\$ 59.00	\$ 59.00

TOTAL PRICE \$ 19,671.01
 LESS 10% \$ 1,967.10

208

SUB TOTAL PRICE \$ 17,703.91

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS <i>na</i>	10	\$ 6.80	\$ 68.00
2	REAR NUMBER PLATE <i>na</i>	1	\$ 80.00	\$ 80.00
3	BOOTLID SEALANT <i>na</i>	1	\$ 80.00	\$ 80.00
4	BOOTLID INSULATOR CLIPS <i>na</i>	10	\$ 6.50	\$ 65.00
5	REAR END PANEL TOP GARNISH CLIPS <i>na</i>	6	\$ 6.50	\$ 39.00
6	BOOTLID STICKER <i>na</i>	1	\$ 100.00	\$ 100.00
7	REAR END PANEL INSULATOR SEAL <i>na</i>	1	\$ 150.00	\$ 150.00

TOTAL \$ 582.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	400
2	TO PUTTY AND RESPRAY AFFECTED AREA	\$ 1,400.00	450
3	TO TUFF COAT ACCIDENT AFFECTED AREA	\$ 250.00	30
4	TO RNR REAR BOOTLID MECHANISM TO ASSIST WORK LOAD	\$ 250.00	60
5	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ <i>na</i> 300.00	X
6	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	\$ 100.00	20
7	TO RNR WINDSCREEN TO ASSIST WORK LOAD	\$ 250.00	120
8	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ <i>na</i> 400.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	15
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
11	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ <i>na</i> 150.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ <i>na</i> 300.00	X

TOTAL \$ 5,180.00

ESTIMATE REPORT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL PARTS COST : \$ 18,285.91
TOTAL LABOUR COST : \$ 5,180.00
TOTAL REPAIR COST : \$ 23,465.91

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

KELVIN WO

KELVIN WO

HP 9069 7882

Parts \$7,360.17

Less 20% \$5,888.13

S/N \$333.00

Labour \$1,145.00

Total \$7,366.13

L/S \$5,892.90

Kindly confirm the finalised
amount of \$5,800.00/-

4 working days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19015600/Kyd3n2		
73 BRAS BASAH ROAD		Date: 05-11-2019		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: JEFF LIN		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 4100J	Veh. Inspected	SKB 1584J	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1059895-002	Excess (\$)	0.00	
Assign From	ANNIE KOH	Assign Date	03/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	ALFA ROMEO MITO (A)	c.c	1368	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	ZAR95500001130859	Colour	METALLIC BLACK	
Odometer	157311 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	PIRELLI	8 mm	
L/H Front Tyre	215/45 ZR17	PIRELLI	8 mm	
R/H Rear Tyre	215/45 ZR17	PIRELLI	8 mm	
L/H Rear Tyre	215/45 ZR17	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/08/2019	Inspect Date / Time	03/09/2019 (01:04 PM)	
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 1584J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	BENT	1,888.53	1,456.10
1	BOOTLID LOCK	TO REPAIR SEE LABOUR	277.19	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	213.75	-
1	BOOTLID LOGO	NECESSARY	96.00	96.00
1	BOOTLID EMBLEM-MITO	NECESSARY	88.00	88.00
1	BOOTLID INNER TRIM	SERVICEABLE	368.90	-
1	REAR WINDSCREEN COMPLETE SET WITH MOULDING	NOT NECESSARY	1,847.90	-
2	TAILLAMP @\$980.70	SERVICEABLE	1,961.40	-
2	TAILLAMP LOWER BRACKET @\$245.70	SERVICEABLE	491.40	-
2	TAILLAMP CHROME MOULDING @\$198.00	SERVICEABLE	396.00	-
2	TAILLAMP CLIPS @\$15.00	NOT NECESSARY	30.00	-
1	REAR BUMPER	BUCKLED	1,798.74	976.40
2	REAR BUMPER SIDE RETAINER @\$87.40	SERVICEABLE	174.80	-
2	REAR BUMPER BRACKET @\$98.70	SERVICEABLE	197.40	-
1	REAR BUMPER REINFORCEMENT	CRACKED	798.30	448.30
1	REAR BUMPER CARRIER	CRACKED	345.60	231.20
1	REAR BUMPER SPONGE	CRACKED	497.10	122.30
2	REAR BUMPER REFLECTOR @\$189.10	SERVICEABLE	378.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	889.50	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	594.10	-
2	REAR BUMPER REVERSE SENSOR HOLDER @\$87.40	SERVICEABLE	174.80	-
1	REAR BUMPER REVERSE SENSOR WIREHARNES	SERVICEABLE	1,847.00	-
1	REAR BUMPER SENSOR BUZZER	SERVICEABLE	248.00	-
2	REAR NUMBER PLATE LAMP @\$74.70	SERVICEABLE	149.40	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	2,890.00	-
1	EXHAUST PIPE GASKET	SERVICEABLE	59.00	-
	LESS 10% DISCOUNT		-1,870.10	-

Report Ref No. CS/INC19015600/Kyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-583.66
			16,830.91	2,734.64
2	REAR BUMPER REVERSE SENSOR @\$485.00 (SN)	SHORTED	970.00	200.00
	LESS 10% DISCOUNT		-97.00	-
			873.00	200.00
	<u>SPECIAL NETT ITEMS</u>			
10	REAR BUMPER CLIPS @\$6.80 (SN)	NECESSARY	68.00	68.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	80.00	-
1	BOOTLID SEALANT (SN)	NOT NECESSARY	80.00	-
10	BOOTLID INSULATOR CLIPS @\$6.50 (SN)	NOT NECESSARY	65.00	-
6	REAR END PANEL TOP GARNISH CLIPS @\$6.50 (SN)	NOT NECESSARY	39.00	-
1	BOOTLID STICKER (SN)	NECESSARY	100.00	25.00
1	REAR END PANEL INSULATOR SEAL (SN)	NOT NECESSARY	150.00	-
			582.00	93.00
	<u>LABOUR</u>			
	PANEL BEATING,REMOVAL AND REPLACING PARTS,INCLUSIVE OF THE REPAIR OF BOOTLID LOCK,REAR END PANEL AND EXHAUST PIPE.		1,600.00	400.00
	TO PUTTY AND RESPRAY AFFECTED AREA.		1,400.00	450.00
	TO TUFF COAT ACCIDENT AFFECTED AREA.		250.00	30.00
	TO RNR REAR BOOTLID MECHANISM TO ASSIST WORK LOAD.		250.00	60.00
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	NOT NECESSARY	300.00	-
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION.		100.00	20.00
	TO RNR WINDSCREEN TO ASSIST WORK LOAD.		250.00	120.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.	NOT NECESSARY	400.00	-
	CONDUCT WATER LEAKAGE TEST.		100.00	15.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING.	NOT NECESSARY	150.00	-

Report Ref No. CS/INC19015600/Kyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	300.00	-
			5,180.00	1,145.00
GRAND TOTAL			23,465.91	4,172.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,350.00

Report Ref No. CS/INC19015600/Kyd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.