

ASS. REC. BY:

REF: CS/INC19015601/Grd302

Special Instruction:

Quincy: SteveASSIGNMENT (Office)From (Person): Annie Koh

of

INCDate/Time: 9.41am 31/1/19

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK1628H

Insured:

SLM822J

at Workshop m/s

CH Motor

Tel:

91004390of BLK 10 Amk hd. park 2A #05-19

Policy No:

Claim No:

MT/1060401-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.11am 31/1/19

Person Contacted:

susanVehicle IN/OUT

Date/Time

Action/Instruction

Technical ✓SLK1628H-XSLM822J-X

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLK 1628H

Yr Regn: 14/10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estima

C.C 2362

Colour

Grey

N/C: Insured / Std / NI / NA

Sp. Reading

91168

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ACR500194982

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Loaked / Burnt or

Brake: Inorder / Jammed / Loaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

235/52R18

R:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

30/8/19

D.O.A.

3/9/19

0339pm

Survey held at

CH Motor

Des. of Damages

Frnt

Rear

O/S

N/S

U/C

Roof

Top

or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-110K

17/9/19

Finalize confirm \$9800

8 days

Red

RECEIVED 18 SEP 2019

pls. check parts prices

19,541.76, 6790

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

18k-typist

Days Of Repair:

11

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

290

Transportation:

: S + RS, \$1

: Photos

: Others

TOTAL

290

Report Format :

Lump Sum / I.B.I. (\$

TP

9800p

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 3 September 2019 11:13 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 3 September 2019 9:41 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	--------	-----	--------------------

1	Jared Liu	MT/1060401-001	SLK1628H	CH MOTOR REPAIRS AND SERVICES	BLK 10 ANG MO KIO INDUSTRIAL PARK 2A ANG MO KIO AUTOPOINT #05-19	SUSAN / 91004390	SLM822J	30/8/19	
2	Jeff Lin	MT/1059895-002	SKB 1584J	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047	terence loh / 82996103	GX4100J	27/8/19	
3	Eric Tang	MT/1060555-001	SIV2705D	LIAN HER MOTORS	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2	anthony cheong / 91082728	SCV5017T	16/8/19	
4	Serene Lim	MT/1060596-002	SLE4063Z	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	s t sim / 62524991	SDW810K	31/8/19	Please avoid 1pm to 2pm
5	Jeff Lin	MT/1060418-001	SMC5694U	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	sharon ten / 64811522	SJV4149U	30/8/19	
6	Serene Lim	MT/1040823-002	PA8151A	SC AUTO INDUSTRIES (S) PTE LTD	51 SENOKO ROAD #03-01 SENOKO INDUSTRIAL BUILDING SINGAPORE 758133	hamimah / 65719958	SLN1725U	17/4/19	
7	Quek Swee Keng	MT/1060611-001	SHA3654T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	LYNN / 65425119	SJE35E	1/9/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg

income
made different



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	341A
Vehicle Details	
Vehicle No.:	SLK1628H
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	2AZ4A20641
Chassis No.:	ACR500194982
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$30,300.00
Original Registration Date:	14 Oct 2016
First Registration Date:	14 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$34,420.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2026
PARF Rebate Amount:	\$25,815.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$58,201.00
COE Rebate Amount:	\$41,170.00
Total Rebate Amount:	\$66,985.00

The information contained herein is correct as at 03 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/08/2019 13:35
Date Of Accident	30/08/2019 11:00
Exact Location Of Accident	AYE EXIT JURONG TOWN HALL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK1628H
Insured/Policyholder	
Name Of Registered Owner	KEONG CHEE WAI
NRIC No	SXXXX341A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97489467
Alternative Phone No	OFFICE-97489467

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA AERAS 2016
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80442684 QMY
Cover Note Number	

Driver

Name of Driver	KEONG CHEE WAI (JIANG ZHIWEI)
NRIC No	SXXXX341A
Date Of Birth	30/06/1978
Occupation	INDOOR
Date Of Driving Pass	08/04/1997
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97489467
Fax Number	
Contact Number	OFFICE-97489467
Email Address	NOEMAIL

Address	BLK 15 FERNVALE CLOSE #16-28
Postcode	797477
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM822J
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	84682104
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBF4732P
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

REFER ATTACHED

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

90025722

Address

Postcode

Insurance Company Name

Nature Of Damage

REFER ATTACHED

No. Of Passenger (Including Driver)

A. SLK #1628 H B. SLK 8225 C. GBF 4732D

On 30th Aug 2019 @ about 11 o'clock I was travelling on A14 Exit Junction Town Hall Road. Upon exit towards the filter lane, I have slowed down & stopped behind a black Nissan Van (GAF 4732P). A ~~black~~ car (SLM 8225) & came behind me and hit straight into the back of my car. My car has ~~been~~ pushed forward with the impact & hit the back of the van. I drove away & took photos of the damaged. No one was injured except the vehicle & driver has a slight cut on his lip.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries from me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

30/3/19 15:15 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

30/3/19
15:15 hrs

Reporting Centre Personnel's Signature

Name:

NRIC / ID No.:

CH MOTOR REPAIRS AND SERVICES

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #05-19
Singapore 568047 HP 91004390/HP 91254449 Fax 64841482
ROC No: 53030817K Email: chmotoramk@gmail.com

M/s NTUC Income Insurance Co-operative Ltd DATE 30.08.2019
73 Bras Basah Road #05-01 NTUC Trade CAR NO SLK 1628 H
Union House S189556 MAKE Toyota Estima

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED: SLM 822 J

Pc	Pcs	Description	UNIT PRICE	AMOUNT
1	pc	Tail gate <i>DD</i>	1593	\$1,870.92
1	pc	Tail gate "Estima" emblem <i>mpc</i>		\$78.60
1	pc	Tail gate Toyota logo <i>mpc</i>		\$75.90
1	pc	Tail gate "AERAS" emblem <i>mpc</i>		\$88.15
1	pc	Tail gate inner lock button <i>X NNI</i>		\$198.80
1	pc	Tail gate lock <i>BT</i>		\$391.60
1	pc	Tail gate weatherstrip <i>TN</i>		\$395.80
1	pc	Tail gate reflector (right) <i>? BR</i>		\$369.40
1	pc	Rear end panel <i>DD</i>	681	\$875.60
1	pc	Rear end panel top garnish <i>CRU</i>		\$266.50
1	pc	Rear end panel bottom garnish <i>CRU</i>		\$184.20
1	pc	Rear bumper <i>DD</i>	650	\$1,876.91
2	pcs	Rear bumper side retainer <i>BR</i>	\$92.14	\$184.28
2	pcs	Rear bumper side bracket <i>? X NNI</i>	\$98.80	\$197.80
10	pcs	Rear bumper inner sponge <i>? BR</i>	95-60	\$137.60
1	pc	Rear bumper right side tow cover <i>(RH) MIS</i>		\$19.20
2	pcs	Rear bumper reflector (left & right) <i>(RH) CUT</i>	\$56.90	\$113.90
1	pc	Rear bumper absorber <i>? X NNI</i>	\$68.60	\$137.20
2	pcs	Rear bumper side seal (left & right) <i>X NNI</i>	\$113.30	\$226.60
10	pcs	Rear bumper clips <i>mpc</i>	\$5.00	\$50.00
4	pcs	Rear bumper reverse sensor <i>Short</i>	\$128.60	\$514.40
1	pc	Rear floor trim lining <i>(low) CRU</i>		\$385.10
1	pc	Rear floor panel <i>X R</i>		\$774.90
1	pc	Rear wind screen moulding <i>mpc</i>		\$155.00
2	pcs	Rear wind screen guide <i>mpc</i>	\$10.30	\$20.60
1	pc	Front bonnet <i>X R</i>		\$1,780.00
1	pc	Front left side head lamp <i>(LH) CUT</i>	1500	\$2,285.00
1	pc	Front grille <i>CUT</i>		\$355.60
1	pc	Front grille emblem <i>CUT</i>		\$58.60
1	pc	Front support panel <i>X R CUT</i>		\$890.60
1	pc	Front bumper <i>DD</i>	983	\$1,715.00
1	pc	Front bumper lower grille <i>? CUT</i>		\$220.60
			Total	

CH MOTOR REPAIRS AND SERVICES

P- 9457.63 L/S- 7626.57
- 25.16 = 7650
7993.22
L- 2442
a 533.22

Steve (LKK) W/L Principle

3/9/19, 4 pm
8 days
L/S
Ray AL Spg

CH MOTOR REPAIRS AND SERVICES

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #05-19
Singapore 568047 HP 91004390/HP 91254449 Fax 64841482
ROC No: 53030817K Email: chmotoramk@gmail.com

M/s NTUC Income Insurance Co-operative Ltd DATE 30.08.2019
73 Bras Basah Road #05-01 NTUC Trade CAR NO SLK 1628 H
Union House S189556 MAKE Toyota Estima

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLM 822 J

Pc	Pcs	Description	UNIT PRICE	AMOUNT
		Continue from page one		\$16,894.36
10	pcs	Front bumper clips ✓ <i>MC</i>	\$5.00	30/ \$50.00
1	pc	Front bumper top beam (left & right) ? X <i>NN</i>	\$186.40	\$372.80 X
1	pc	Front bumper inner sponge ? / <i>OR</i>		\$95.00 /
2	pcs	Front bumper side retainer (left & right) / <i>OR</i>	\$116.00	\$232.00 /
2	pcs	Front bumper fog lamp X <i>NN</i>	\$490.00	\$980.00 X
2	pcs	Front bumper fog lamp garnish X <i>NN</i>	\$161.20	\$322.40 X
1	pc	Front number plate with casing / <i>CUT</i>		35/ \$60.00
		<i>- Less 25%</i>		
		To spray anti-rust coating on new & affected panel.		50 \$200.00
		To check rear lightings and electrical wiring system include performing water leakage test.		30 \$80.00
		To provide labour, workmanship to cutting rear end panel, spare tyre tank panel, front top panel, dismantle and replace front and rear portion damage parts.	1000	\$2,500.00
		To apply silicon onto rear wind screen.	40	\$80.00
		Labour for dismantle & refix rear wind screen.	120	\$160.00
		To respray front bonnet cover, front bumper, front grille, rear end panel, rear spare tyre tank panel, rear bumper, tail gate & touch up rear two side mudguard.	1200	\$2,300.00

2440 ✓

Total \$24,326.56

29,341.76

CH MOTOR REPAIRS AND SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CH MOTOR REPAIRS AND SERVICES

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #05-19

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

ROC No: 53030817K

Email: chmotoramk@gmail.com

M/s	NTUC Income Insurance Co-operative Ltd	DATE	05.09.2019
	73 Bras Basah Road #05-01 NTUC Trade	CAR NO	SLK 1628 H
	Union House S189556	MAKE	Toyota Estima

SUPPLEMENTARY CLAIMS FOR THE ABOVE MENTIONED VEHICLE.

YOUR INSURED : SLM 822 J

Pc	Pcs	ACR500194982	UNIT PRICE	AMOUNT
1	pc	Air con condenser ✓ 00	1248.20 ✓	\$1,405.30
1	pc	Air con motor X NM		\$439.70 X
1	pc	Tailgate inner board ✓ CR4		\$476.50 ✓
1	pc	Front bumper left side grille ✓ CR4		\$47.90 ✓
1	pc	Front right side head lamp ✓ BR	1500 ✓	\$2,285.00 ✓
1	pc	Tail gate right side inner trim ✓ CR4		\$110.80 ✓
		To top up gas, labour to dismantle & replace new air con condenser.	3387.40 - 2500 = 2537.55 150 ✓	\$250.00
		Main - 7650 Supp - 2150 L/S - 9800		2687.55 L/S - 2150.00 = 2150
Total				\$5,015.20

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CH MOTOR REPAIRS AND SERVICES

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19015601/Evd3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 25-09-2019



ATTN : JARED LIU

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 822J	Veh. Inspected	SLK 1628H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1060401-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	03/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ESTIMA	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ACR500194982	Colour	GREY
Odometer	91168 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	ACHILLES	5 mm
L/H Front Tyre	235/50 R18	ACHILLES	5 mm
R/H Rear Tyre	235/50 R18	ACHILLES	5 mm
L/H Rear Tyre	235/50 R18	ACHILLES	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/08/2019	Inspect Date / Time	03/09/2019 (03:39 PM)
Survey held at	CH MOTOR REPAIRS AND SERVICES 10 ANG MO KIO INDUSTRIAL PARK 2A #05-19 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1628H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	DENTED	1,870.92	1,593.00
1	TAIL GATE "ESTIMA" EMBLEM	NECESSARY	78.60	78.60
1	TAIL GATE TOYOTA LOGO	NECESSARY	75.90	75.90
1	TAIL GATE "AERAS" EMBLEM	NECESSARY	88.15	88.15
1	TAIL GATE INNER LOCK BUTTON	NOT NECESSARY	198.80	-
1	TAIL GATE LOCK	BENT	391.60	391.60
1	TAIL GATE WEATHERSTRIP	TORN	395.80	395.80
1	TAIL GATE REFLECTOR (RIGHT)	BROKEN	369.40	369.40
1	REAR END PANEL	DENTED	875.60	681.00
1	REAR END PANEL TOP GARNISH	CRUSHED	266.50	266.50
1	REAR END PANEL BOTTOM GARNISH	CRUSHED	184.20	184.20
1	REAR BUMPER	DENTED	1,876.91	650.00
2	REAR BUMPER SIDE RETAINER @\$92.14	BROKEN	184.28	184.28
2	REAR BUMPER SIDE BRACKET @\$98.80	NOT NECESSARY	197.80	-
10	REAR BUMPER INNER SPONGE	BROKEN	137.60	95.60
1	REAR BUMPER RIGHT SIDE TOW COVER (RH)	MISSING	19.20	19.20
2	REAR BUMPER REFLECTOR (LEFT & RIGHT) @\$56.90	O/S CUT	113.90	56.90
2	REAR BUMPER ABSORBER @\$68.60	NOT NECESSARY	137.20	-
2	REAR BUMPER SIDE SEAL (LEFT & RIGHT) @\$113.30	NOT NECESSARY	226.60	-
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
4	REAR BUMPER REVERSE SENSOR @\$128.60	SHORTED (2PCS ONLY)	514.40	200.00
1	REAR FLOOR TRIM LINING (LOWER)	CRUSHED	385.10	385.10
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	774.90	-
1	REAR WIND SCREEN MOULDING	NECESSARY	155.00	155.00
2	REAR WIND SCREEN GUIDE @\$10.30	NECESSARY	20.60	20.60
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,780.00	-
1	FRONT LEFT SIDE HEAD LAMP (LH)	CUT	2,285.00	1,500.00
1	FRONT GRILLE	CUT	355.60	355.60
1	FRONT GRILLE EMBLEM	CUT	58.60	58.60

Report Ref No. CS/INC19015601/Evd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	890.60	-
1	FRONT BUMPER	DENTED	1,715.00	983.00
1	FRONT BUMPER LOWER GRILLE	CUT	220.60	220.60
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
2	FRONT BUMPER TOP BEAM (LEFT & RIGHT) @\$186.40	NOT NECESSARY	372.80	-
1	FRONT BUMPER INNER SPONGE	BROKEN	95.00	95.00
2	FRONT BUMPER SIDE RETAINER (LEFT & RIGHT) @\$116.00	BROKEN	232.00	232.00
2	FRONT BUMPER FOG LAMP @\$490.00	NOT NECESSARY	980.00	-
2	FRONT BUMPER FOG LAMP GARNISH @\$161.20	NOT NECESSARY	322.40	-
1	FRONT NUMBER PLATE WITH CASING	CUT	60.00	35.00
1	AIR CON CONDENSER (ADDITIONAL)	DENTED	1,405.30	1,248.20
1	AIR CON MOTOR (ADDITIONAL)	NOT NECESSARY	439.70	-
1	TAILGATE INNER BOARD (ADDITIONAL)	CRUSHED	476.50	476.50
1	FRONT BUMPER LEFT SIDE GRILLE (ADDITIONAL)	CUT	47.90	47.90
1	FRONT RIGHT SIDE HEAD LAMP (ADDITIONAL)	BROKEN	2,285.00	1,500.00
1	TAIL GATE RIGHT SIDE INNER TRIM (ADDITIONAL)	CRUSHED	110.80	110.80
	LESS 25% DISCOUNT		-	-3,203.51
			23,771.76	9,610.52
	LABOUR			
	TO SPRAY ANTI-RUST COATING ON NEW & AFFECTED PANEL.		200.00	50.00
	TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRING SYSTEM INCLUDE PERFORMING WATER LEAKAGE TEST.		80.00	30.00
	TO PROVIDE LABOUR WORKMANSHIP TO CUTTING REAR END PANEL, SPARE TYRE TANK PANEL, FRONT TOP PANEL, DISMANTLE AND REPLACE FRONT AND REAR PORTION DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, FRONT BONNET AND FRONT SUPPORT PANEL.		2,500.00	1,000.00
	TO APPLY SILICON ONTO REAR WIND SCREEN.		80.00	40.00
	LABOUR FOR DISMANTLE & REFIX REAR WIND SCREEN.		160.00	120.00

Report Ref No. CS/INC19015601/Evd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY FRONT BONNET COVER, FRONT BUMPER, FRONT GRILLE, REAR END PANEL, REAR SPARE TYRE TANK PANEL, REAR BUMPER, TAIL GATE & TOUCH UP REAR TWO SIDE MUDGUARD.		2,300.00	1,200.00
	TO TOP UP GAS, LABOUR TO DISMANTLE & REPLACE NEW AIR CON CONDENSER. (ADDITIONAL)		250.00	150.00
			5,570.00	2,590.00
GRAND TOTAL			29,341.76	12,200.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				9,800.00

Report Ref No. CS/INC19015601/Evd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.