

ASS. REC. BY:

REP: es/CTE19015606/ Uvd3n2 Special Instruction:

Surveyor: Marius

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 3/9/19 @ 10.57am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKX 189H Insured: SLN 1836H

at Workshop m/s Trans Eurokars Tel: 9127 7928

of Subiclose

Policy No: _____ Claim No: SNM19D203983

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/8/19
(Car's Record)

CA / REV / REP. / REV 24 HRS _____ H.O.D. Endorsement: _____

Date/Time: 12:36pm @ 3/9/19 Person Contacted: Ronald Vehicle IN / OUT

Date/Time	Action/Instruction	
	<u>3 strength ✓</u>	
	<u>SKX189X-NA/CTE19015001/h4</u>	<u>DOA: 23/8/2019</u>
	<u>SLN1836x-NA/CTE19015001/h4</u>	<u>DOA: 23/8/2019</u>

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 3 September 2019 10:57 AM
To: ronald.yap@eurokars.com.sg
Cc: jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg; assignments
Subject: RE: OUR REF: SNM19D203983-SLN1836H-CBS - FW: ARRANGE FOR SURVEY / YOUR REF: SLN1836H / OUR REF: SKX189H

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]
Sent: Saturday, 31 August, 2019 1:58 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg
Subject: RE: OUR REF: SNM19D203983-SLN1836H-CBS - FW: ARRANGE FOR SURVEY / YOUR REF: SLN1836H / OUR REF: SKX189H

Dear Boon Sen,

Please assign to Marcus Chua.

Thank You,

*Ronald Yap
Insurance Claims*

Trans Eurokars Pte Ltd

5, Ubi Close, Singapore 408605

T: 6395 8899 H: 9127 7928

ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: 29 August 2019 15:15

To: Ronald Yap <ronald.yap@eurokars.com.sg>

Subject: RE: OUR REF: SNM19D203983-SLN1836H-CBS - FW: ARRANGE FOR SURVEY / YOUR REF: SLN1836H / OUR REF: SKX189H

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, 29 August, 2019 2:48 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>;
Chee So Chow <sochow.chee@sg.cntaiping.com>; ronald.yap@eurokars.com.sg
Subject: OUR REF: SNM19D203983-SLN1836H-CBS - FW: ARRANGE FOR SURVEY / YOUR REF:
SLN1836H / OUR REF: SKX189H

Dear Boon Sen,

Please conduct PRS for SKX189H.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]
Sent: Thursday, 29 August, 2019 11:41 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: jess.francis@eurokars.com.sg
Subject: ARRANGE FOR SURVEY / YOUR REF: SLN1836H / OUR REF: SKX189H

Dear Claims Dept – China Taiping,

As attached, kindly arrange the survey of our client's vehicle.

Thank You,

Ronald Yap
Insurance Claims

Trans Eurokars Pte Ltd
5 Ubi Close, Singapore 408605
T: 6395 8899 H: 9127 7928
ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.


From: mazdacanon@mazda.com.sg <transeurokars@eurokars.com.sg>
Sent: 29 August 2019 12:02

To: Ronald Yap <ronald.yap@eurokars.com.sg>

Subject: Attached Image

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



ESCAPE WITH APAC'S BEST LOW COST AIRLINE



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

2009 Toyota Altis at \$32,800. \$0 drive away!



Very good condition! \$0 drive away! Low monthly installment! accept trade in StarAd



Post an Ad Advertiser Login Ways of Selling

Browse by Category ▾

Sort by Date Posted

14 vehicles

mazda 5

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V	
Search Selection	mazda 5	Any	Any	2015	Any	Any		
	Mazda 5 2.0A Sunroof	\$64,800	\$8,950 /yr	23-Nov-2015	1,998 cc	68,000 km		
<p>1 Owner Only, Come With One More Free Servicing! Full Agent Maintained. Cheapest In Market. Careful Owner, Excellent Condition! Dual Power Sliding Doors For Ease Of Entry! Very Well Maintained! No Any Repairs Needed By Next Owner! Hassle-Free. Flexible Loan Scherr</p> <p>Posted: 03-Sep-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda</p>								
	Mazda 5 2.0A Sunroof	\$64,800	\$9,040 /yr	21-Oct-2015	1,998 cc	85,251 km		
<p>Graded B by STA</p> <p>1 Owner! Full Service History With Eurokars! Immaculate Condition! STA Welcome! High Trade In And In House Financing Available! Vie Today!</p> <p>Posted: 03-Sep-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda</p>								
	Mazda 5 2.0A Sunroof	\$63,800	\$9,210 /yr	26-Aug-2015	1,998 cc	92,612 km		
<p>1 Owner Till Date, Low Fuel Consumption.Twin Sliding Doors For Easy Access. Well Maintained Inside Out. Trade In Option Available Here, Call Our Friendly Salesman For A Viewing Appointment Today Now! Don't Miss!</p> <p>Mayfair Motoring</p> <p>Posted: 03-Sep-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda</p>								
	Mazda 5 2.0A Sunroof	\$61,800	\$10,020 /yr	27-Feb-2015	1,998 cc	-		
<p>Elegant White MPV, Serviced, By Agent, With Sunroof And Auto Sliding Doors, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.</p> <p>Prime Motor & Leasing</p> <p>Posted: 02-Sep-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda</p>								
Car Buying	Car Selling	Car Ownership						Buyi
Car Aftermarket	On The Move	Lifestyle						
	Mazda 5 2.0A Sunroof	\$66,500	\$9,630 /yr	28-Aug-2015	1,998 cc	-		
<p>Elegant Red MPV, With Sunroof And Auto Sliding Doors, One Owner Only, Serviced By Agent In May 2019, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.</p> <p>or & Leasing</p> <p>ad: 31-Aug-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda</p>								

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	998C
Vehicle Details	
Vehicle No.:	SKX189H
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	PE10282523
Chassis No.:	JM6CW1071G0122894
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$18,244.00
Original Registration Date:	24 Nov 2015
First Registration Date:	24 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$18,244.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Nov 2025
PARF Rebate Amount:	\$13,683.00
Intended COE Rebate Details	
COE Expiry Date:	23 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,889.00
COE Rebate Amount:	\$37,247.00
Total Rebate Amount:	\$50,930.00

The information contained herein is correct as at 04 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/08/2019 00:23
Date Of Accident	23/08/2019 19:15
Exact Location Of Accident	LOR 6 TOA PAYOH FILTER LANE TO PIE TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX189H
Insured/Policyholder	
Name Of Registered Owner	TANG HONG MENG
NRIC No	S6847998C
Email Address	JOELTANGHM@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97415545
Alternative Phone No	OFFICE-97415545

Vehicle Particulars

Manufacturer	MAZDA
Model	5-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095600922-01
Cover Note Number	

Driver

Name of Driver	TANG HONG MENG
NRIC No	S6847998C
Date Of Birth	28/12/1968
Occupation	INDOOR
Date Of Driving Pass	16/02/1998
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97415545
Fax Number	
Contact Number	OFFICE-97415545
Email Address	JOELTANGHM@HOTMAIL.COM

Address BLK 351A #11-317 CANBERRA ROAD
 Postcode 751351
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : LEE MENG GUEK
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLN1836H
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver HUANG JINHONG
 NRIC/Passport Number S8165033J
 Contact Number 90221606
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or a distorting of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be filed by the officers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms) which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

TANG HONG MING

23/08/2019 22:13

Policyholder's Signature / Date & Time

TANG HONG MING

23/08/2019 22:13

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan #2

Sketch Plan

The sketch plan is based on the closest scenario.
Please refer to "Circumstances of the Accident".



Describe Circumstances of the Accident

BLACK CAR : SLN1836H

WHITE CAR : SKX189H

DESCRIPTION :

After I enter the filter lane, I came to a stop to look for traffic on the major road. Subsequently Vehicle SLN1836H collided against the rear of my vehicle.

Declaration

I/We declare the foregoing particulars are true in every respect.

TANG HONG MENG
23/08/2019 22:13

Policyholder's Signature / Date & Time

TANG HONG MENG
23/08/2019 22:13

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Tang Hong Meng ADDRESS : Blk 351A Canberra Road #11-317 Singapore 751351 TEL : 97415545		WIP : 61551 EXCESS : DATE : 27-Aug-19 <i>not about</i> <i>6 days</i> <i>take the body part</i> <i>3/8/19</i>	
VEH NO :	SKX189H	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6CW1071G0122894	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	24-Nov-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MC513-50-221EBB	DD	\$ 961.20
2	1	MC235-56-B9XC	su	\$ 155.40
3	2	MGD7A-50-EA1	rel	\$ - 6.40
4	2	M9991-00-501	rel	\$ - 6.00
5	2	MC235-50-ES1	rel	\$ - 9.40
6	4	MBHN1-50-021A	rel	\$ - 10.80
7	4	MBN8F-50-355	rel	\$ - 22.80
8	2	MB45A-56-146A	rel	\$ - 6.00
9	2	MG043-62-864A	rel	\$ - 7.00
10	1	MCGY3-62-02XF	Body	\$ 1,637.00
11	1	MC513-68-960B	17	\$ 432.00
12	2	MGHP9-58-867	17	\$ 24.00
13	5	MGJ21-68-885B02	rel	\$ - 15.00
14	1	MC513-62-310A	su	\$ 256.20
15	1	MD652-62-361	17	\$ 57.90
16	1	MC513-50-810F53	17	\$ 447.90
17	3	MEG21-51-SJ3	rel	\$ - 17.10
18	1	MCGY0-51-711	rel	\$ - 45.30
19	1	MCGY0-51-721	rel	\$ - 36.30
20	1	MTD11-51-731	rel	\$ - 44.10
21	1	MC597-51-771	rel	\$ - 80.00
22	1	MC513-51-3J8	rel	\$ - 95.40
23	1	MC513-51-3H8	rel	\$ - 95.40
24	1	MC513-50-611	rel	\$ - 60.50
25	6	MD204-50-896A	rel	\$ - 16.80
26	1	MDJ01-50-897	rel	\$ - 7.20
27	2	MC273-50-896	rel	\$ - 16.40
28	4	MGJ6A-50-897	rel	\$ - 51.20
29	1	MG21E-63-938B	rel	\$ - 11.10
30	2	MC514-51-979B	17	\$ 11.00

31	PROTECTOR, SPOILER	2	MC514-51-982B	17	\$ 24.00	X
32	PROTECTOR, SPOILER	2	MC514-51-972B	17	\$ 28.20	X
33	CLIP, SPOILER	2	MC514-51-958A	del	\$- 15.40	X
34	CLIP, SPOILER	1	MC525-51-958A	del	\$- 8.70	X
35	REAR END PANEL	1	MCG15-70-750B	17	\$ 515.70	X
36	TRIM, END PANEL	1	MC513-68-89XD	17	\$ 80.40	X
37	BEZEL, LOCK	1	MC513-68-894A	17	\$ 13.70	X
38	FASTENER, TRIM	8	MGJ21-68-885B02	17	\$ 24.00	X
39	SUB TRUNK, FLOOR PANEL	1	MC235-68-8MXD00	17	\$ 359.70	X
40	SPARE WHEEL BOARD	1	MC235-68-83XC02	17	\$ 496.30	X
TOTAL PARTS					\$ 6,208.90	
LESS 10%					\$ 620.89	
TOTAL PARTS COST					\$ 5,588.01	

Labour Description

1		TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	1650	\$ 4,290.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND TAILGATE.	1890	\$ 3,150.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	net	\$ 120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	NETT	\$ 330.00
6		TO REMOVE AND INSTALL SPOILER TAILGATE.	17	NETT X 180.00
7	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	200	NETT \$ 660.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	200	NETT \$ 330.00
9	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	sent	NETT \$ 70.00
10	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	150	\$ 990.00
11	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	11 X	\$ 350.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	120	\$ 250.00
13	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00

14	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$	350.00
15		TO SUPPLY BODY COATING.	11X	NETT	TBA
16	MZ-BR-SUNDRI	SUNDRIES.	100	NETT	\$ 100.00
				TOTAL LABOUR	\$ - \$ 11,980.00
				TOTAL PARTS	\$ - \$ 5,588.01
				TOTAL	\$ - \$ 17,568.01
				LESS EXCESS	\$ - \$ -
				TOTAL AFTER EXCESS	\$ -
				GST 7%	\$ - \$ -
				GRAND TOTAL	\$ - \$ -

TRANS EUROKARS PTE LTD

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

 Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No other modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Tang Hong Meng ADDRESS : Blk 351A Canberra Road #11-317 Singapore 751351 TEL : 97415545	WIP : 61551 EXCESS : DATE: 27-Aug-19
VEH NO :	SKX189H	DATE IN :	CONTACT PERSON : Ronald 63957875
CHASSIS NO :	JM6CW1071G0122894	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.: 24-Nov-15	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MC513-50-221EBB	\$ 961.20	\$ 961.20
2	1	MC235-56-89XC		\$ 155.40
3	2	MGD7A-50-EA1	\$ 6.40	\$ 6.40
4	2	M9991-00-501	\$ 6.00	\$ 6.00
5	2	MC235-50-ES1	\$ 9.40	\$ 9.40
6	4	MBHN1-50-021A	\$ 10.80	\$ 10.80
7	4	MBN8F-50-355	\$ 22.80	\$ 22.80
8	2	MB45A-56-146A	\$ 6.00	\$ 6.00
9	2	MG043-62-864A	\$ 7.00	\$ 7.00
10	1	MCGY3-62-02XF	\$ 1,637.00	\$ 1,637.00
11	1	MC513-68-960B		\$ 432.00
12	2	MGHP9-58-867		\$ 24.00
13	5	MGJ21-68-885B02	\$ 15.00	\$ 15.00
14	1	MC513-62-310A		\$ 256.20
15	1	MD652-62-361		\$ 57.90
16	1	MC513-50-810F53		\$ 447.90
17	3	MEG21-51-SJ3	\$ 17.10	\$ 17.10
18	1	MCGY0-51-711	\$ 45.30	\$ 45.30
19	1	MCGY0-51-721	\$ 36.30	\$ 36.30
20	1	MTD11-51-731	\$ 44.10	\$ 44.10
21	1	MC597-51-771	\$ 80.00	\$ 80.00
22	1	MC513-51-3J8	\$ 95.40	\$ 95.40
23	1	MC513-51-3H8	\$ 95.40	\$ 95.40
24	1	MC513-50-611	\$ 60.50	\$ 60.50
25	6	MD204-50-896A	\$ 16.80	\$ 16.80
26	1	MDJ01-50-897	\$ 7.20	\$ 7.20
27	2	MC273-50-896	\$ 16.40	\$ 16.40
28	4	MGJ6A-50-897	\$ 51.20	\$ 51.20
29	1	MG21E-63-938B	\$ 11.10	\$ 11.10
30	2	MC514-51-979B		\$ 11.00
31	2	MC514-51-982B		\$ 24.00

32	PROTECTOR, SPOILER	2	MC514-51-972B		\$ 28.20
33	CLIP, SPOILER	2	MC514-51-958A	\$ 15.40	\$ 15.40
34	CLIP, SPOILER	1	MC525-51-958A	\$ 8.70	\$ 8.70
35	REAR END PANEL	1	MCG15-70-750B		\$ 515.70
36	TRIM, END PANEL	1	MC513-68-89XD		\$ 80.40
37	BEZEL, LOCK	1	MC513-68-894A		\$ 13.70
38	FASTENER, TRIM	8	MGJ21-68-885B02		\$ 24.00
39	SUB TRUNK, FLOOR PANEL	1	MC235-68-8MXD00		\$ 359.70
40	SPARE WHEEL BOARD	1	MC235-68-83XC02		\$ 496.30
				TOTAL PARTS	\$ 3,282.50
				LESS 10%	\$ 328.25
				TOTAL PARTS COST	\$ 2,954.25

Labour Description

1		TO REPLACE REAR BUMPER AND TAILGATE. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,650.00	\$ 4,290.00
2		TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.	\$ 1,890.00	\$ 3,150.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$ 560.00	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$ 120.00	\$ 120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	\$ 330.00	\$ 330.00
6		TO REMOVE AND INSTALL SPOILER TAILGATE.		\$ 180.00
7	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	\$ 200.00	\$ 660.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ 200.00	\$ 330.00
9	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	\$ 70.00	\$ 70.00
10	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 150.00	\$ 990.00
11	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 350.00
12	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 120.00	\$ 250.00
13	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
14	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
15		TO SUPPLY BODY COATING.		TBA
16	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 5,610.00
			TOTAL PARTS	\$ 2,954.25
			TOTAL	\$ 8,564.25
			LESS EXCESS	\$ -
			TOTAL AFTER EXCESS	\$ 8,564.25
			GST 7%	\$ 599.50
			GRAND TOTAL	\$ 9,163.75

REMARKS:

6 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Third Party Insurer Enquiry

Our Ref No: GR-19-139194
Date of Request: 27/08/2019

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
12 Sungei Kadut Ave
Singapore 729648

Dear Sir/Madam,

Enquiry Date 27/08/2019
Enquiry By Ronald Yap
TP Vehicle No. SLN1836H
Accident Date 23/08/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLN1836H	China Taiping Insurance (Singapore) Pte. Ltd.	25/04/2019-24/04/2020	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

TAX INVOICE

Our Ref No: GR-19-139194
Date of Request: 27/08/2019

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
12 Sungei Kadut Ave
Singapore 729648

Dear Sir/Madam,

Enquiry Date 27/08/2019
Enquiry By Ronald Yap
TP Vehicle No. SLN1836H
Accident Date 23/08/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119015606/UVD3N2

Date: 24/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30227419000
Claimant Vehicle No :	SKX189H	Insured Vehicle No :	SLN1836H
Date of Loss:	23/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D203983C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX189H	Engine No:	PE10282523
Make & Model:	MAZDA 5, 2.0 (A)	Chassis No:	JM6CW1071G0122894
Reg. Date:	24/11/2015 (Man. Year: 2015)	Odometer:	89576 km
Colour:	Brown		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,758.01	3,044.25	2,713.76	47.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,810.00	5,520.00	6,290.00	53.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,568.01	8,564.25	9,003.76	51.25
+ GST 7.00/7.00% (S\$)	1,229.76	599.50	630.26	51.25
Nett Amount (S\$)	18,797.77	9,163.75	9,634.02	51.25

INSPECTION

Date of Assignment:	12/09/2019	Inspected At:	Trans Eurokars Pte Ltd (Ubi)
Date Inspected:	03/09/2019		5 Ubi Close
			Singapore 408605

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2019)
Parts: M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKX189H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	961.20 FL	*961.20 FL
2	1		*REAR REINFORCEMENT	Serviceable	155.40 FL	*- FL
3	2		*FASTENER,REAR BUMPER	Necessary	6.40 FL	*6.40 FL
4	2		*GROMMET,REAR BUMPER	Necessary	6.00 FL	*6.00 FL
5	2		*GROMMET,REAR BUMPER	Necessary	9.40 FL	*9.40 FL
6	4		*GROMMET,REAR BUMPER	Necessary	10.80 FL	*10.80 FL
7	4		*RIVET,REAR BUMPER	Necessary	22.80 FL	*22.80 FL
8	2		*FASTENER,REAR BUMPER	Necessary	6.00 FL	*6.00 FL
9	2		*TAPE PROTECTOR,REAR BUMPER	Necessary	7.00 FL	*7.00 FL
10	1		*TAILGATE	Badly Dented	1,637.00 FL	*1,637.00 FL
11	1		*TRIM LOWER,TAILGATE	Not Necessary	432.00 FL	*- FL
12	2		*VALVE,ONEWAY	Not Necessary	24.00 FL	*- FL
13	5		*FASTENER,TRIM	Necessary	15.00 FL	*15.00 FL
14	1		*LOCK,TAILGATE	Serviceable	256.20 FL	*- FL
15	1		*STRIKER,LOCK	Not Necessary	57.90 FL	*- FL
16	1		*FINISHER,TAILGATE	Not Necessary	447.90 FL	*- FL
17	3		*CLIP,FINISHER	Necessary	17.10 FL	*17.10 FL
18	1		*ORNAMENT,MAZDA	Necessary	45.30 FL	*45.30 FL
19	1		*ORNAMENT,5	Necessary	36.30 FL	*36.30 FL
20	1		*MASCOT,REAR	Necessary	44.10 FL	*44.10 FL
21	1		*ORNAMENT,SKYACTIVE	Necessary	80.00 FL	*80.00 FL
22	1		*GASKET LHS,TAILGATE	Necessary	95.40 FL	*95.40 FL
23	1		*GASKET RHS,TAILGATE	Necessary	95.40 FL	*95.40 FL
24	1		*REAR WINDSCREEN MOULDING	Necessary	60.50 FL	*60.50 FL
25	6		*FASTENER,REAR WINDSCREEN	Necessary	16.80 FL	*16.80 FL
26	1		*SPACER,REAR WINDSCREEN	Necessary	7.20 FL	*7.20 FL
27	2		*FASTENER,REAR WINDSCREEN	Necessary	16.40 FL	*16.40 FL
28	4		*SPACER,REAR WINDSCREEN	Necessary	51.20 FL	*51.20 FL
29	1		*PIN STUD,REAR WINDSCREEN	Necessary	11.10 FL	*11.10 FL
30	2		*PROTECTOR,SPOILER	Not Necessary	11.00 FL	*- FL
31	2		*PROTECTOR,SPOILER	Not Necessary	24.00 FL	*- FL
32	2		*PROTECTOR,SPOILER	Not Necessary	28.20 FL	*- FL
33	2		*CLIP,SPOILER	Necessary	15.40 FL	*15.40 FL
34	1		*CLIP,SPOILER	Necessary	8.70 FL	*8.70 FL
35	1		*REAR END PANEL	Repair	515.70 FL	*- FL
36	1		*TRIM,END PANEL	Not Necessary	80.40 FL	*- FL
37	1		*BEZEL,LOCK	Not Necessary	13.70 FL	*- FL
38	8		*FASTENER,TRIM	Not Necessary	24.00 FL	*- FL
39	1		*SUB TRUNK,FLOOR PANEL	Not Necessary	359.70 FL	*- FL
40	1		*SPARE WHEEL BOARD	Not Necessary	496.30 FL	*- FL
41	1		*NUMBER PLATE	Bent	70.00 FS	*70.00 FS
42	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 6,378.90 3,372.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			- List Item Discount on L Items 10.00/10.00% (S\$)		620.89	328.25
			Total Parts (S\$)		5,758.01	3,044.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,REAR REINFORCEMENT,REAR END PANEL AND TAILGATE.TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT	New	4,290.00	1,650.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT,REAR END PANEL,REAR FLOOR PANEL AND TAILGATE	New	3,150.00	1,890.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	120.00	120.00
5	TO TRANSFER TAILGATE MECHANISM	New	330.00	330.00
6	TO REMOVE AND INSTALL SPOILER TAILGATE	New	180.00	0.00
7	TO TRANSFER REVERSE SENSORS (WITH REVERSE SENSOR)	New	660.00	200.00
8	TO TRANSFER REVERSE CAMERA	New	330.00	200.00
9	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	990.00	150.00
10	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	0.00
11	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	120.00
12	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
13	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
14	TO SUPPLY BODY COATING (NPA)	New	0.00	0.00
Gross Labour Cost (S\$)			11,810.00	5,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >