

ASS. REC. BY:

REF: CS/FCI 19015614/K9f3 n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Joanne of FCI Date/Time: 3.9.19 5.45p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5566R Insured: SHA 7737L

at Workshop m/s Trans cab Tel: 62876666

of NO2 AMK strut 63

Policy No: Claim No: D19005684mFCH

Sum Insured: Excess:

Make of Veh: D.O.A. 30.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.9.19 9.00a.m Person Contacted: Amanda

Vehicle: IN/OUT

| Date/Time                                          | Action/Instruction (✓) Estimate                           |
|----------------------------------------------------|-----------------------------------------------------------|
|                                                    | SHC 5566R - (C4 / AXA 16011862 / Aug 392 ROA - 24/04/2016 |
|                                                    | SHA 7737L - (CS3 / FCI 17018612 / Gbs2 DOA - 27/09/2017   |
| 05/9/19 @ 5.01pm revised to Joanne Young by email. |                                                           |
|                                                    |                                                           |
|                                                    |                                                           |
|                                                    |                                                           |

A.S. REC. BY:

REF:

FCI

## ASSIGNMENT

From:

Date:

4/9/2019

Veh No:

SITC 5566R Yr Regt: 09, 14

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SHC 5566R

Make:

Renault Latitude C.C. 1995

at Workshop m/s

Transcab

Colour

m White / Red

A/C:

Insured / Std / NI / NA

of

No. 2 Amk st - 63

Sp. Reading

398488

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

VI-1ABC15AUC-279249

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or


Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

9 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

9 mm

L/Bal.

6 mm

Est. Repairs:

03

days

Res.:

Yes or No

D.O.A.

30/8/19

D.O.I.

4/9/19

Lum Sum:

20

%

3 Val.:

Yes or No

Survey held at

✓

CA / REV / REP. / 24 HRS

(wp)

Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

0/1 Frt

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L1 Imp @ 3350L (Red @ 37153.38, 92%)

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

3

1) 09/9 trans



Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

3 + FS, 91

Photos

Others

Report Format:

TP

Lump Sum / F.R. (\$)

3350

TOTAL

350



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005684MFSH

Date: 05 September 2019

Our Ref: CS/FCI19015614/Kqf3

The Motor Claims Department  
MS First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5566R .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/09/2019 at the premises of M/s TRANS-CAB and have the following to report:-

|                          |                   |
|--------------------------|-------------------|
| Workshop Estimate Amount | : S\$ 40,503.38 . |
| Revised Estimate Amount  | : S\$ 4,211.34 .  |
| "Check" Items Amount     | : S\$ - .         |
| Market Value             | : S\$ - .         |
| LTA Reimbursement Value  | : S\$ - .         |
| Nett Value               | : S\$ - .         |

**Description of Damage:**

The vehicle sustained damages at the o/s front portion.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                           |                              |                                      |
|---------------------------|------------------------------|--------------------------------------|
| <b>Date</b>               | 03-09-2019                   | <b>Our Ref No.</b> D19005684MFSH     |
| <b>Accident Date</b>      | 30-08-2019                   | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHA7737L                     | <b>Third Party Vehicle.</b> SHC5566R |
| <b>Survey Location</b>    | NO. 2 ANG MO KIO STREET 63   |                                      |
| <b>Contact Person.</b>    | AMANDA TAY                   |                                      |
| <b>Contact No.</b>        | 62876666/ 0                  | <b>Fax No.</b> 62571330              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE:           |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD |                                      |
| <b>Contact Person</b>     | NA                           | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                           |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                                 |                                |
|--------------------------|---------------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | TRANS-CAB AUTO SERVICES PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                              | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | JOANNEY                         |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 6 September 2019 12:00 PM  
**To:** Shiau Chan (LKKAUTO)  
**Subject:** RE: TP VEHICLE SHC 5566R (DOA: 30/08/2019) -- AAD1908-234  
**Attachments:** image001.wmz

Hi Shiau Chan

Amount confirmed \$ 3,350.00 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shiau Chan (LKKAUTO) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Thursday, 5 September, 2019 5:51 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHC 5566R (DOA: 30/08/2019)

Dear Wai Yin,

Based on our surveyor's estimate marking, the calculation of repair cost will be at Lump Sum \$3,350.00 before GST and 3 repair days.

Kindly check.

Best Regards,  
**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 5 September 2019 5:01 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Joanne Yong'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19005684MFSH/1  
**Attachments:** CSFCI19015614Kqf3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHC 5566R.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 3 September 2019 5:45 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Joanne Yong <[JoanneYong@msfirstcapital.com.sg](mailto:JoanneYong@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19005684MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 878K    |

**Vehicle Details**

|                               |                                 |
|-------------------------------|---------------------------------|
| Vehicle No.:                  | SHC5566R                        |
| Vehicle to be Exported:       | Yes                             |
| Intended Deregistration Date: | 30 Aug 2019                     |
| Vehicle Make:                 | RENAULT                         |
| Vehicle Model:                | LATITUDE 2.0L DCI AUTO D/AB 4DR |
| Primary Colour:               | Red                             |
| Manufacturing Year:           | 2014                            |
| Engine No.:                   | M9R8839C001966                  |
| Chassis No.:                  | VF1ABL15AUC279249               |
| Maximum Power Output:         | 127.0 kW (170 bhp)              |
| Open Market Value:            | \$19,998.00                     |
| Original Registration Date:   | 15 Sep 2014                     |
| First Registration Date:      | 15 Sep 2014                     |
| Transfer Count:               | 0                               |
| Actual ARF Paid:              | \$12,498.00                     |

**Intended PARF Rebate Details**

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 14 Sep 2022 |
| PARF Rebate Amount:           | \$9,373.00  |

**Intended COE Rebate Details**

|                             |                                      |
|-----------------------------|--------------------------------------|
| COE Expiry Date:            | 14 Sep 2022                          |
| COE Category:               | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):          | 8                                    |
| PQP Paid:                   | \$50,704.00                          |
| COE Rebate Amount:          | \$19,277.00                          |
| <b>Total Rebate Amount:</b> | <b>\$28,650.00</b>                   |

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Aug 2019

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5566R****AAD1908-234***Not Authored  
11 Sep 8 3350h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

04 SEP 2019

**SHC 5566R**

VF1ABL15AUC279249

RENAULT

LATITUDE

30.8.19

**FIRST CAPITAL**

15/9/2014

| PART |                                 | LIST |            |
|------|---------------------------------|------|------------|
| 1    | BUMPER COVER FRT                | \$   | SL 747.20  |
| 1    | BUMPER SPOILER FRT              | \$   | SL 344.70  |
| 1    | BUMPER ABSORBER FRT             | \$   | SL 394.68  |
| 1    | BUMPER RETAINER FRT RH          | \$   | SL 101.40  |
| 1    | BUMPER SUPPORT FRT              | \$   | SL 10.70   |
| 1    | BUMPER UNDERTRAY FRT            | \$   | SL 292.50  |
| 1    | BUMPER GRILLE LOWER FRT         | \$   | SL 147.00  |
| 1    | BUMPER FOG LAMP GRILLE RH       | \$   | SL 207.21  |
| 1    | BUMPER BEAM FRT                 | \$   | N 663.70   |
| 1    | HEADLAMP RH                     | \$   | SL 743.60  |
| 1    | HEADLAMP PANEL FRT RH           | \$   | N 128.30   |
| 1    | FENDER PANEL FRT RH             | \$   | R 437.10   |
| 1    | WHEELARCH FRT RH                | \$   | DIY 191.40 |
| 1    | FENDER BRACKET LOWER RH         | \$   | SL 11.80   |
| 1    | FENDER INSULATOR RH             | \$   | SL 66.30   |
| 1    | TOW COVER FRT                   | \$   | SL 60.90   |
| 1    | FRONT BRACE PANEL               | \$   | N 177.22   |
| 1    | RADIATOR GRILLE                 | \$   | SL 969.90  |
| 1    | RADIATOR GRILLE BADGE 'RENAULT' | \$   | SL 225.36  |
| 1    | RADIATOR GRILLE FRAME           | \$   | SL 686.00  |
| 1    | FRAME FULL SUPPORT PANEL        | \$   | SL 592.70  |
| 1    | FRAME FULL SUPPORT BRACKET      | \$   | SL 41.60   |
| 1    | BONNET                          | \$   | N 1,312.70 |
| 1    | BONNET INSULATOR                | \$   | SL 294.30  |
| 1    | BONNET STRUT LH                 | \$   | SL 53.30   |
| 1    | BONNET STRUT RH                 | \$   | SL 53.30   |
| 1    | BONNET HINGE LH                 | \$   | N 236.50   |
| 1    | BONNET HINGE RH                 | \$   | N 237.40   |



**Trans-cab Auto Services Pte Ltd****AAD1908-234**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5566R**

|              |                               |           |                  |   |
|--------------|-------------------------------|-----------|------------------|---|
| 1            | BONNET LOCK                   | \$        | 152.80           | X |
| 1            | BONNET CABLE                  | \$        | 55.20            | X |
| 1            | BONNET CABLE COVER            | \$        | 80.60            | X |
| 1            | BONNET SEAL OUTER             | \$        | 83.20            | X |
| 1            | BONNET SEAL INNER             | \$        | 70.10            | X |
| 1            | DOOR PANEL FRT RH             | \$        | 2,844.66         | ✓ |
| 1            | DOOR HINGE UPPER RH           | \$        | 261.28           | } |
| 1            | DOOR HINGE LOWER RH           | \$        | 300.55           |   |
| 1            | DOOR CHECK FRT RH             | \$        | 194.77           |   |
| 1            | DOOR CATCH FRT RH             | \$        | 131.23           |   |
| 1            | DOOR GUIDE FRONT RH           | \$        | 136.40           |   |
| 1            | DOOR WHEATHESTRIIP FRONT RH   | \$        | 410.27           |   |
| 1            | DOOR SEAL FRONT RH            | \$        | 72.82            |   |
| 1            | DOOR BLIND FRONT RH           | \$        | 506.90           |   |
| 1            | DOOR MOULDING FRONT RH        | \$        | 100.50           |   |
| 1            | DOOR MIRROR ASSY RH           | \$        | 1,483.40         |   |
| 1            | LOWER ARM RH L70Y             | \$        | 192.70           |   |
| 1            | KNUCKLE ARM RH L70Y           | \$        | 481.50           |   |
| 1            | ABSORBER FRT RH L70Y          | \$        | 203.50           |   |
| 1            | DRIVESHAFT RH                 | \$        | 1,355.70         |   |
| 1            | STABILIZER BAR FRT            | \$        | 427.90           |   |
| 1            | WIPER RESERVOIR MOTOR         | \$        | 82.60            | } |
| 1            | WIPER RESERVOIR               | \$        | 179.60           |   |
| 1            | WIPER RESERVOIR NECK          | \$        | 29.30            |   |
| 1            | DOOR HARNESS WIRE RH          | \$        | 2,670.00         | } |
| 1            | ROCKER PANEL INNER GARNISH RH | \$        | 466.51           |   |
| 1            | ROCKER PANEL INNER RH         | \$        | 1,024.79         |   |
| 1            | ROCKER PANEL OUTER RH         | \$        | 1,184.99         |   |
| 1            | ROCKER PANEL CENTER RH        | \$        | 990.25           | X |
| <b>TOTAL</b> |                               | <b>\$</b> | <b>25,602.79</b> |   |
| <b>10%</b>   |                               | <b>\$</b> | <b>2,560.28</b>  |   |
|              |                               | <b>\$</b> | <b>23,042.51</b> |   |

**Special Nett**

|   |                                |    |       |      |
|---|--------------------------------|----|-------|------|
| 1 | FRONT DOOR STICKER 'Trans-cab' | \$ | 80.00 | 60sm |
| 1 | FRONT DOOR STICKER 'Classic'   | \$ | 80.00 | 15sm |
| 1 | BUMPER CLIP FRT                | \$ | 66.00 | X    |

**Trans-cab Auto Services Pte Ltd**

AAD1908-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5566R

|              |                                    |           |    |                 |     |
|--------------|------------------------------------|-----------|----|-----------------|-----|
| 1            | BUMPER BRACKET CLIP FRT RH         | \$        | na | 12.00           | X   |
| 1            | BUMPER SUPPORT CLIP FRT RH         | \$        | na | 10.50           | X   |
| 1            | BUMPER GRILLE LOWER CLIP           | \$        | na | 69.00           | X   |
| 1SET         | FRAME FULL SUPPORT PANEL CLIP      | \$        | na | 70.00           | X   |
| 2            | FRAME FULL SUPPORT PANEL NUT       | \$        | na | 20.00           | X   |
| 2            | FRAME FULL SUPPORT PANEL STUD      | \$        | na | 30.00           | X   |
| 1            | WHEELARCH CLIP FRT RH              | \$        | na | 30.50           | ✓   |
| 1            | FRONT RIGHT TYRE                   | \$        | sh | 300.00          | } X |
| 1            | FRONT RIGHT TYRE RIM               | \$        | sh | 380.00          |     |
| 1SET         | Front licence plate with holder    | \$        | sh | 80.00           |     |
| 1SET         | RADIATOR GRILLE SCREW              | \$        | sh | 16.00           |     |
| 1SET         | RADIATOR GRILLE FRAME CLIP         | \$        | na | 52.00           |     |
| 1            | WINDSCREEN SEALANT                 | \$        | na | 253.80          |     |
| 1            | FRONT WINDSCREEN MOULDING          | \$        | na | 120.00          |     |
| 1            | FRONT WINDSCREEN INNER SPONGE SEAL | \$        | na | 100.00          |     |
| 6            | BONNET INSULATOR CLIP L70Y         | \$        | na | 7.30            | }   |
| 2            | BONNET STRUT L70Y                  | \$        | sh | 106.60          |     |
| 2            | BONNET CABLE CLIP L70Y             | \$        | na | 6.31            |     |
| 2            | BONNET CABLE COVER SCREW L70Y      | \$        | na | 10.85           |     |
| <b>TOTAL</b> |                                    | <b>\$</b> |    | <b>1,900.87</b> |     |

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>24,943.38</b> |
|--------------------|-----------|------------------|

**LABOUR**

|                                                                                                                           |    |          |          |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|----------|
| Putty and spray painting of the affected portion.                                                                         | \$ | 6,000.00 | 4800     |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 6,000.00 | 4000     |
| To check steering geometry and computer wheel alignment                                                                   | \$ | na       | 220.00 X |
| To transfer of front windscreen glass to facilitate bodywork repair.                                                      | \$ | na       | 170.00 X |
| To rust-proofing of the affected areas.                                                                                   | \$ | 170.00   | 600      |

**Trans-cab Auto Services Pte Ltd**

AAD1908-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5566R

|                                                                                                 |           |                  |
|-------------------------------------------------------------------------------------------------|-----------|------------------|
| To transfer of front fender fittings, attachment and perform water seepage test.                | \$        | ~ 380.00 X       |
| To transfer of tire, rim and on wheel balancing.                                                | \$        | ~ 170.00 X       |
| To dismantle and refit front end suspension, undercarriage parts, final checking and testing.   | \$        | ~ 380.00 X       |
| To Check Electrical Lighting Concerned.                                                         | \$        | 170.00 2cl       |
| To transfer of front bumper fittings, attachment and perform water seepage test.                | \$        | ~ 380.00 X       |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$        | ~ 380.00 X       |
| To transfer of front door fittings, attachment and perform water seepage test.                  | \$        | 380.00 6cl       |
| To transfer of bonnet fittings, attachment and perform water seepage test.                      | \$        | ~ 380.00 X       |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                 | \$        | ~ 380.00 X       |
| <b>TOTAL</b>                                                                                    | <b>\$</b> | <b>15,560.00</b> |
| <b>Over All Total</b>                                                                           | <b>\$</b> | <b>40,503.38</b> |

**LUMP SUM (REPAIR DAY)**~~20 DAYS~~

3 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |                                                                                                                                                                                    |                                                                              |                             |                                                                                     |
|-------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|
| MS FIRST CAPITAL INSURANCE LTD                                    |                                                                                                                                                                                    |                                                                              | Ref : CS/FCI19015614/Kqf3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877             |                                                                                                                                                                                    |                                                                              | Date : 11-09-2019           |  |
|                                                                   |                                                                                                                                                                                    |                                                                              | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                 |                                                                                                                                                                                    |                                                                              |                             |                                                                                     |
|                                                                   | Insured Veh.                                                                                                                                                                       | SHA 7737L                                                                    | Veh. Inspected              | SHC 5566R                                                                           |
|                                                                   | Policy No.                                                                                                                                                                         |                                                                              | Coverage (\$)               | 0.00                                                                                |
|                                                                   | Claim No.                                                                                                                                                                          | D19005684MFSH                                                                | Excess (\$)                 | 0.00                                                                                |
|                                                                   | Assign From                                                                                                                                                                        | JOANNEY                                                                      | Assign Date                 | 03/09/2019                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                     |                                                                                                                                                                                    |                                                                              |                             |                                                                                     |
|                                                                   | Make & Model                                                                                                                                                                       | RENAULT LATITUDE (A)                                                         | c.c                         | 1995                                                                                |
|                                                                   | Engine No.                                                                                                                                                                         | HIDDEN                                                                       | Year of Reg.                | 2014                                                                                |
|                                                                   | Chassis No.                                                                                                                                                                        | VF1ABL15AUC279249                                                            | Colour                      | METALLIC WHITE / RED                                                                |
|                                                                   | Odometer                                                                                                                                                                           | 398488                                                                       | Steering                    | IN ORDER                                                                            |
|                                                                   | Brakes                                                                                                                                                                             | IN ORDER                                                                     | Modification                | NIL                                                                                 |
|                                                                   | General                                                                                                                                                                            | GOOD                                                                         |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                     |                                                                                                                                                                                    |                                                                              |                             |                                                                                     |
|                                                                   |                                                                                                                                                                                    | Size                                                                         | Make                        | Balance                                                                             |
|                                                                   | R/H Front Tyre                                                                                                                                                                     | 215/60 R16                                                                   | SAILUN                      | 9 mm                                                                                |
|                                                                   | L/H Front Tyre                                                                                                                                                                     | 215/60 R16                                                                   | SAILUN                      | 9 mm                                                                                |
|                                                                   | R/H Rear Tyre                                                                                                                                                                      | 215/60 R16                                                                   | GITI                        | 6 mm                                                                                |
|                                                                   | L/H Rear Tyre                                                                                                                                                                      | 215/60 R16                                                                   | GITI                        | 6 mm                                                                                |
| <b>4. Description of Damages</b>                                  |                                                                                                                                                                                    |                                                                              |                             |                                                                                     |
|                                                                   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                                                                    |                                                                              |                             |                                                                                     |
| <b>5. General Information</b>                                     |                                                                                                                                                                                    |                                                                              |                             |                                                                                     |
|                                                                   | Accident Date                                                                                                                                                                      | 30/08/2019                                                                   | Inspection Date             | 04/09/2019                                                                          |
|                                                                   | Survey held at                                                                                                                                                                     | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                |                                                                                                                                                                                    |                                                                              |                             |                                                                                     |
|                                                                   | A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                |                                                                                                                                                                                    |                                                                              |                             |                                                                                     |
|                                                                   | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                |                                                                              | <b>3 Working Days</b>       |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5566R

| Qty | Description of Parts            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>     |                      |                           |                   |
| 1   | BUMPER COVER FRT                | SERVICEABLE          | 747.20                    | -                 |
| 1   | BUMPER SPOILER FRT              | SERVICEABLE          | 344.70                    | -                 |
| 1   | BUMPER ABSORBER FRT             | SERVICEABLE          | 394.68                    | -                 |
| 1   | BUMPER RETAINER FRT RH          | SERVICEABLE          | 101.40                    | -                 |
| 1   | BUMPER SUPPORT FRT              | SERVICEABLE          | 10.70                     | -                 |
| 1   | BUMPER UNDERTRAY FRT            | SERVICEABLE          | 292.50                    | -                 |
| 1   | BUMPER GRILLE LOWER FRT         | SERVICEABLE          | 147.00                    | -                 |
| 1   | BUMPER FOG LAMP GRILLE RH       | SERVICEABLE          | 207.21                    | -                 |
| 1   | BUMPER BEAM FRT                 | TO REPAIR SEE LABOUR | 663.70                    | -                 |
| 1   | HEADLAMP RH                     | SERVICEABLE          | 743.60                    | -                 |
| 1   | HEADLAMP PANEL FRT RH           | TO REPAIR SEE LABOUR | 128.30                    | -                 |
| 1   | FENDER PANEL FRT RH             | BENT                 | 437.10                    | 437.10            |
| 1   | WHEELARCH FRT RH                | DISTORTED            | 191.40                    | 191.40            |
| 1   | FENDER BRACKET LOWER RH         | SERVICEABLE          | 11.80                     | -                 |
| 1   | FENDER INSULATOR RH             | SERVICEABLE          | 66.30                     | -                 |
| 1   | TOW COVER FRT                   | SERVICEABLE          | 60.90                     | -                 |
| 1   | FRONT BRACE PANEL               | TO REPAIR SEE LABOUR | 177.22                    | -                 |
| 1   | RADIATOR GRILLE                 | SERVICEABLE          | 969.90                    | -                 |
| 1   | RADIATOR GRILLE BADGE "RENAULT" | SERVICEABLE          | 225.36                    | -                 |
| 1   | RADIATOR GRILLE FRAME           | SERVICEABLE          | 686.00                    | -                 |
| 1   | FRAME FULL SUPPORT PANEL        | SERVICEABLE          | 592.70                    | -                 |
| 1   | FRAME FULL SUPPORT BRACKET      | SERVICEABLE          | 41.60                     | -                 |
| 1   | BONNET                          | TO REPAIR SEE LABOUR | 1,312.70                  | -                 |
| 1   | BONNET INSULATOR                | SERVICEABLE          | 294.30                    | -                 |
| 1   | BONNET STRUT LH                 | SERVICEABLE          | 53.30                     | -                 |
| 1   | BONNET STRUT RH                 | SERVICEABLE          | 53.30                     | -                 |
| 1   | BONNET HINGE LH                 | TO REPAIR SEE LABOUR | 236.50                    | -                 |

Report Ref No. CS/FCI19015614/Kqf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

| Qty | Description of Parts          | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------|----------------------|---------------------------|-------------------|
| 1   | BONNET HINGE RH               | TO REPAIR SEE LABOUR | 237.40                    | -                 |
| 1   | BONNET LOCK                   | TO REPAIR SEE LABOUR | 152.80                    | -                 |
| 1   | BONNET CABLE                  | SERVICEABLE          | 55.20                     | -                 |
| 1   | BONNET CABLE COVER            | SERVICEABLE          | 80.60                     | -                 |
| 1   | BONNET SEAL OUTER             | SERVICEABLE          | 83.20                     | -                 |
| 1   | BONNET SEAL INNER             | SERVICEABLE          | 70.10                     | -                 |
| 1   | DOOR PANEL FRT RH             | BENT                 | 2,844.66                  | 2,844.66          |
| 1   | DOOR HINGE UPPER RH           | TO REPAIR SEE LABOUR | 261.28                    | -                 |
| 1   | DOOR HINGE LOWER RH           | TO REPAIR SEE LABOUR | 300.55                    | -                 |
| 1   | DOOR CHECK FRT RH             | SERVICEABLE          | 194.77                    | -                 |
| 1   | DOOR CATCH FRT RH             | TO REPAIR SEE LABOUR | 131.23                    | -                 |
| 1   | DOOR GUIDE FRONT RH           | SERVICEABLE          | 136.40                    | -                 |
| 1   | DOOR WEATHERSTRIP FRONT RH    | SERVICEABLE          | 410.27                    | -                 |
| 1   | DOOR SEAL FRONT RH            | SERVICEABLE          | 72.82                     | -                 |
| 1   | DOOR BLIND FRONT RH           | SERVICEABLE          | 506.90                    | -                 |
| 1   | DOOR MOULDING FRONT RH        | SERVICEABLE          | 100.50                    | -                 |
| 1   | DOOR MIRROR ASSY RH           | SERVICEABLE          | 1,483.40                  | -                 |
| 1   | LOWER ARM RH L70Y             | SERVICEABLE          | 192.70                    | -                 |
| 1   | KNUCKLE ARM RH L70Y           | SERVICEABLE          | 481.50                    | -                 |
| 1   | ABSORBER FRT RH L70Y          | SERVICEABLE          | 203.50                    | -                 |
| 1   | DRIVESHAFT RH                 | TO REPAIR SEE LABOUR | 1,355.70                  | -                 |
| 1   | STABILIZER BAR FRT            | SERVICEABLE          | 427.90                    | -                 |
| 1   | WIPER RESERVOIR MOTOR         | SERVICEABLE          | 82.60                     | -                 |
| 1   | WIPER RESERVOIR               | SERVICEABLE          | 179.60                    | -                 |
| 1   | WIPER RESERVOIR NECK          | SERVICEABLE          | 29.30                     | -                 |
| 1   | DOOR HARNESS WIRE RH          | SERVICEABLE          | 2,670.00                  | -                 |
| 1   | ROCKER PANEL INNER GARNISH RH | SERVICEABLE          | 466.51                    | -                 |
| 1   | ROCKER PANEL INNER RH         | TO REPAIR SEE LABOUR | 1,024.79                  | -                 |

Report Ref No. CS/FCI19015614/Kqf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

| Qty | Description of Parts                              | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | ROCKER PANEL OUTER RH                             | TO REPAIR SEE LABOUR | 1,184.99                  | -                 |
| 1   | ROCKER PANEL CENTER RH                            | TO REPAIR SEE LABOUR | 990.25                    | -                 |
|     | LESS 10% DISCOUNT                                 |                      | -2,560.28                 | -347.32           |
|     |                                                   |                      | 23,042.51                 | 3,125.84          |
|     | <b>SPECIAL NETT ITEMS</b>                         |                      |                           |                   |
| 1   | FRONT DOOR STICKER "TRANS-CAB" (SN)               | NECESSARY            | 80.00                     | 60.00             |
| 1   | FRONT DOOR STICKER "CLASSIC" (SN)                 | NECESSARY            | 80.00                     | 15.00             |
| 1   | BUMPER CLIP FRT (SN)                              | NOT NECESSARY        | 66.00                     | -                 |
| 1   | BUMPER BRACKET CLIP FRT RH (SN)                   | NOT NECESSARY        | 12.00                     | -                 |
| 1   | BUMPER SUPPORT CLIP FRT RH (SN)                   | NOT NECESSARY        | 10.50                     | -                 |
| 1   | BUMPER GRILLE LOWER CLIP (SN)                     | NOT NECESSARY        | 69.00                     | -                 |
| 1   | SET FRAME FULL SUPPORT PANEL CLIP (SN)            | NOT NECESSARY        | 70.00                     | -                 |
| 2   | FRAME FULL SUPPORT PANEL NUT (SN)                 | NOT NECESSARY        | 20.00                     | -                 |
| 2   | FRAME FULL SUPPORT PANEL STUD (SN)                | NOT NECESSARY        | 30.00                     | -                 |
| 1   | WHEELARCH CLIP FRT RH (SN)                        | NECESSARY            | 30.50                     | 30.50             |
| 1   | FRONT RIGHT TYRE (SN)                             | SERVICEABLE          | 300.00                    | -                 |
| 1   | FRONT RIGHT TYRE RIM (SN)                         | SERVICEABLE          | 380.00                    | -                 |
| 1   | SET FRONT LICENCE PLATE WITH HOLDER (SN)          | SERVICEABLE          | 80.00                     | -                 |
| 1   | SET RADIATOR GRILLE SCREW (SN)                    | SERVICEABLE          | 16.00                     | -                 |
| 1   | SET RADIATOR GRILLE FRAME CLIP (SN)               | NOT NECESSARY        | 52.00                     | -                 |
| 1   | WINDSCREEN SEALANT (SN)                           | NOT NECESSARY        | 253.80                    | -                 |
| 1   | FRONT WINDSCREEN MOULDING (SN)                    | NOT NECESSARY        | 120.00                    | -                 |
| 1   | FRONT WINDSCREEN INNER SPONGE SEAL (SN)           | NOT NECESSARY        | 100.00                    | -                 |
| 6   | BONNET INSULATOR CLIP L70Y (SN)                   | NOT NECESSARY        | 7.30                      | -                 |
| 2   | BONNET STRUT L70Y (SN)                            | SERVICEABLE          | 106.60                    | -                 |
| 2   | BONNET CABLE CLIP L70Y (SN)                       | NOT NECESSARY        | 6.31                      | -                 |
| 2   | BONNET CABLE COVER SCREW L70Y (SN)                | NOT NECESSARY        | 10.85                     | -                 |
|     |                                                   |                      | 1,900.86                  | 105.50            |
|     | <b>LABOUR</b>                                     |                      |                           |                   |
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. |                      | 6,000.00                  | 440.00            |

Report Ref No. CS/FCI19015614/Kqf3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

| Qty                | Description of Parts                                                                                                                                                                                                                                                                                                                                                                                         | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                    | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT RH,FRONT BRACE PANEL,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR CATCH FRT RH,DRIVESHAFT RH,ROCKER PANEL INNER RH,ROCKER PANEL OUTER RH AND ROCKER PANEL CENTER RH. |               | 6,000.00                  | 400.00            |
|                    | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                                                                                                                                                                                                                                                                                                     | NOT NECESSARY | 220.00                    | -                 |
|                    | TO TRANSFER OF FRONT WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.                                                                                                                                                                                                                                                                                                                                         | NOT NECESSARY | 170.00                    | -                 |
|                    | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                                                                                                                                                                                                                                                                                                      |               | 170.00                    | 60.00             |
|                    | TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                                                                                                              | NOT NECESSARY | 380.00                    | -                 |
|                    | TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.                                                                                                                                                                                                                                                                                                                                                              | NOT NECESSARY | 170.00                    | -                 |
|                    | TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.                                                                                                                                                                                                                                                                                                                  | NOT NECESSARY | 380.00                    | -                 |
|                    | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                                                                                                                                                                                                                                                                                                      |               | 170.00                    | 20.00             |
|                    | TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                                                                                                              | NOT NECESSARY | 380.00                    | -                 |
|                    | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.                                                                                                                                                                                                                                                                                                                 | NOT NECESSARY | 380.00                    | -                 |
|                    | TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                                                                                                                |               | 380.00                    | 60.00             |
|                    | TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                                                                                                                                    | NOT NECESSARY | 380.00                    | -                 |
|                    | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.                                                                                                                                                                                                                                                                                                                               | NOT NECESSARY | 380.00                    | -                 |
|                    |                                                                                                                                                                                                                                                                                                                                                                                                              |               | 15,560.00                 | 980.00            |
| <b>GRAND TOTAL</b> |                                                                                                                                                                                                                                                                                                                                                                                                              |               | <b>40,503.37</b>          | <b>4,211.34</b>   |





|                                                                         |  |  |          |
|-------------------------------------------------------------------------|--|--|----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |  |  | 3,350.00 |
|-------------------------------------------------------------------------|--|--|----------|

Report Ref No. CS/FC119015614/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.