

Director *Taufik*
Merimen

REF: AIG CC3/AIG19015618/T1y#322

ALC

ASSIGNMENT

From: *Merimen* Date: *3.9.2019*

Estimated Cost:

☒ OD/TP / ☒ VS / TP RES / ☒ OD RES / ☒ EVA / ☒ INV / ☒ MV

To Inspect Vehicle No: *SDW 854J*

at Workshop m/s *Premium*

of *24 Bono Sector*

Insured:

Policy No:

Claims No:

Sum Insured: *\$1600-00* Excess: *5/9/19*

(Client's Record)

Make of Veh: *Merimen*

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: *\$138K* Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *days* Res.: Yes or No

Lump Sum: *%* 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: *5/9/19* Person Contacted:

Vehicle: IN / OUT

Veh No: *SDW 854J* Yr Regn: *2018 Sep.*

Type: ☒ M.Cat / ☒ M.Cycle / ☒ Bus / ☒ Van / ☒ Lorry / ☒ Taxi / ☒ Prime Mover /

Truck / Trailer or

Make: *Indo 194* CC *1984*

Colour: *Blue* A/C: *Insured / Std / NI / NA*

Sp. Reading: *23487* T/Radio: *Insured / Std / NI / NA*

Eng/No:

C/No: *W447E2F48JA233024*

Gen. Cond: *Good / Fair / Poor / Burnt*

Steering: *Inorder / Jammed / Leaked / Burnt or*

Brake: *Inorder / Jammed / Leaked / Burnt or*

Modl: *Nil / S/Rim / STD A/Rim or*

Tyre Size: *F: 205/60R16*

R: *4*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Confused*

Front

R/Bal: *C* mm R/Bal: *6* mm

L/Bal: *C* mm L/Bal: *C* mm

D.O.A. *3/9/19 2450*

Survey held at *Premium Blue*

Des. of Damages: *Frt / Rear / O/S / N/S / U/C / Rooftop or*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/9 *Revert via Merimen*
Request Mandate

5/9 *Remark and approval by Victor see attach*

5/9 *Sent E-Mail to premium to Authorise. and Excess \$1600/=*

26/9 *Ezywan call said Part need to wait 4 week repair 1 weeks 1 ask him to call Victor*

6/2/20 *Confirm Final Aig \$21,714-00 Sent by email (Red \$30,867-00, 58%*

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) *5/3/20* *Typist*

Days Of Repair: *15*

Resurvey No. of Trip: *2*

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + R/S, \$

Photo:

Others:

TOTAL

200

11

211

RECEIVED 5 MAR 2020

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 04 Sep 2019

Preliminary Advice

Vehicle No	: SDW854J	Accident Date	: 30/08/2019
Make	: AUDI A4	Policy No.	: 1800114327
Assignment Date	: 04/09/2019	Excess	: S\$0.00
Date of Inspection	: 03/09/2019	Est. Duration of Repair	: 15.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages O/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	52,243.00
Revised Amount	:S\$	19,479.00
Check Items (Estimated)	:S\$	15,128.00
Total	:S\$	34,607.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	138,000.00
COE / PARF Rebate	:S\$	54,703.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,297.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Received Message

This mail is associated with :

***SDW854J (5606193234SG)**
OD
Aug 30 2019 5:10PM
[TAN ENG CHONG]
Premium Automobiles Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 05/03/2020 12:50 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$21714.00) - SDW854J - Claim Handler: Chan, Yoke Shi

Approved:21714.00.

DOCUMENTS SUMMARY
There are no documents.

View Received Message

This mail is associated with :

***SDW854J (5606193234SG)**

OD

Aug 30 2019 5:10PM

[TAN ENG CHONG]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 05/09/2019 14:14 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$19479.00) - SDW854J - Claim Handler: Chan, Yoke Shi

Approved:19479.00:A pillar and b pillar damage photos require, no photos labour and spray paint need to be re-adjusted. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, September 05, 2019 5:27 PM
To: Premiumauto Claims; SUR
Cc: 'Lim, Sheng Yang'
Subject: OD claim # SDW854J

Dear Sir/Mdm,

As instructed by our client, please proceed to repair the insured vehicle SDW854J (**excess \$1600/-**).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Remarks: A pillar and b pillar damage photos require, no photos labour and spray paint need to be re-adjusted

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Premiumauto Claims [mailto:claims@premiumauto.com.sg]

Sent: Thursday, September 05, 2019 10:11 AM

To: 'Chan, Yoke Shi' <yokeshi.chan@aig.com>; SUR <sur@lkkauto.com>

Cc: 'Lim, Sheng Yang' <ShengYang.Lim@aig.com>; 'Parthiban, Theerthan' <Theerthan.Parthiban@aig.com>; Claims <claims@premiumauto.com.sg>

Subject: RE: - OD claim # SDW854J # request DL, UT letter and IV form

Dear Ezuwan,

AIG Chasing driving licence.

For your next action.

Best Regards,
Kee Siang

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/09/2019 10:51
Date Of Accident	30/08/2019 17:10
Exact Location Of Accident	JUNCTION OF COLEMAN LANE & NORTH BRIDGE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW854J
Insured/Policyholder	
Name Of Registered Owner	TAN ENG CHONG
NRIC No	S7027769G
Email Address	TANEC168@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96722454
Alternative Phone No	OFFICE-96722454

Vehicle Particulars

Manufacturer	AUDI
Model	A4-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800114327
Cover Note Number	

Driver

Name of Driver	TAN ENG CHONG
NRIC No	S7027769G
Date Of Birth	16/08/1970
Occupation	INDOOR
Date Of Driving Pass	09/11/2001
Driving Experience	17 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96722454
Fax Number	
Contact Number	OFFICE-96722454
EMail Address	TANEC168@YAHOO.COM

Address 38 CHOA CHU KANG ST 64 #16-07
 Postcode 689102
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 1
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.


(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature
Name: Tracy
SAR/C/Fity No: _____

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was leaving Capital Piazza around 5pm. While I was doing a right turn down Coleman Road near North Bridge Road, a car was approaching at a high speed and I accidentally swerve the car to the right and hit the concrete divider separating the road and the roadside construction site. The right side of my vehicle was damaged and I realised that my ~~left~~ right rear tyre was punctured.

I continue to drive towards Victoria Street and turn into a side alley to call for tow truck service.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 31/5/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Egan
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



UNDERTAKING

I, TAN ENG CHONG, (NRIC No. S7027769G), hereby confirm that the Singapore Accident Statement lodged by me on 31/8/2019 at 1000 hours pertaining to the accident involving motor car Reg. No: SDW 854 J, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature

:



Name of Insured / Driver

:

TAN ENG CHONG

Nric No.

:

S7027769G

Date

:

31/8/2019

Signature

:



Name of Policyholder

:

TAN ENG CHONG

Nric No.

:

S7027769G

Date

:

31/8/2019



AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : TAN ENG CHONG
VEHICLE NUMBER : SDW 854 J
DATE/ TIME OF ACCIDENT : 30/08/2019, 1710 hrs
PLACE OF ACCIDENT : Junction of German Lane & North Bridge Rd.
THIRD PARTY VEHICLE (IF ANY) : N.A.

.....
WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

Started journey from Capitol Piazza, heading to Pei Hwa Presbyterian Primary School at Pei Wah Ave to meet my son.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?

No.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

My vehicle hit the road divider (concrete) and scratch the right side of my vehicle and right rear tyre was punctured.
No other vehicle was involved.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

Not applicable, I am not injured.


NAME: TAN ENG CHONG

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	769G
Vehicle Details	
Vehicle No.:	SDW854J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CVK069094
Chassis No.:	WAUZZZF49JA233024
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$33,432.00
Original Registration Date:	25 Sep 2018
First Registration Date:	25 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$38,805.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2028
PARF Rebate Amount:	\$29,103.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,001.00
COE Rebate Amount:	\$25,600.00
Total Rebate Amount:	\$54,703.00

The information contained herein is correct as at 04 Sep 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10658

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1054/2019/NS
Date	:	3-Sep-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Tan Eng Chong
Address	:	38 Choa Chu Kang Street 64 #16-07 Singapore 689102
Telephone	:	HP +65 96722454
Type of Claim	:	Own Damage Claims
Policy No.	:	1800114327
Vehicle No	:	SDW 854 J
Model Code	:	A4 Sedan 2.0 TFSI
Model / Year	:	Sep-18
Engine No	:	CVK 069094
Chassis No	:	WAUZZZF49JA233024
Mileage	:	-
Date In	:	30-Aug-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-Aug-19
Place of Accident	:	Junction Of Coleman Lane & North Bridge Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 8541

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	\$480.00
2	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 X	
3	To carry out first measurement test on car o-liner	S/N \$ 800.00 ? photo.	
4	To remove and transfer rhs front door and rhs rear door multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 560.00 ✓	\$560.00
5	To dislodge and reinstall rhs A-pillar, door harness, rear wire harness, battery manager duse and electrical trays, audio and electrical equipment.	S/N \$ 1,800.00 ? photo	\$1800.00
SUB TOTAL LABOUR CHARGES		\$ 4,000.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 8541

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
6	To remove and reinstall front and rear seat assy, back rest, ABCD pillar trims, curtain airbags, safety belts, carpets, roof liner, carpets, sill trims, etc.	S/N S	1,800.00	? photo \$1800.00
7	To remove centre console and dashboard assy for A-pillar renewal. Inspect for damages.	S/N S	3,200.00	? photo
8	To remove and renew rhs rear 1/4 glass and rear windscree.	S/N S	600.00	X
9	To install rear windscreen solar film.	S/N S	400.00	X
10	To place vehicle on car o-liner.	S/N S	1,800.00	? photo
SUB TOTAL LABOUR CHARGES		:	<u>\$7,800.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 854]

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
11	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door, rear bumper and rear lid. To cut out and weld rhs A-pillar, rhs B-pillar, rhs sill panel and rhs rear fender. To renew rhs front fender, rhs wing mirror assy, rhs front door and rhs rear door. re-organise crash management components. reinstall all parts removed.	\$ 11,900.00	7000 \$4000-00
12	To respray rhs front fender, rhs front door, rhs wing mirror cover. Rhs rear door, door handle, rhs A-pillar, rhs sill panel, rhs B-pillar, hinges rhs rear fender, door entrances, roof channel, drain panel, and end panelling. To carry out joint sealer work and stone chip treatment.	\$ 8,650.00	3300 \$3300-00
13	To renew rhs rear rim and tyre. To carry out wheel alignment.	S/N \$ 280.00 ✓	\$280-00
14	To carry out diagnostic checks.	S/N \$ 384.00 ✓	\$384-00
TOTAL LABOUR CHARGES		: <u>533,014.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 8541

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	A-PILLAR FRAME - RH	\$ 2,856.00	hl - plnt \$2284-80
2	FRONT FENDER - RH	\$ 700.00	hl - \$559-60
3	FRONT FENDER ATTACHMENT PARTS	\$ 183.00	?
4	FRONT FENDER CLOSING ELEMENT - RH	\$ 45.00	?
5	FRONT FENDER BRACKET - RH	\$ 32.00	?
6	FRONT FENDER DEFORMATION ELEMENT BRACKET	\$ 45.00	?
7	FRONT FENDER REAR BRACKET	\$ 29.00	?
8	FRONT FENDER UPPER BRACKET	\$ 31.00	?
9	FRONT FENDER BRACE - RH	\$ 107.00	X
10	FRONT FENDER CLOSING ELEMENT - RH	\$ 30.00	?
11	FRONT FENDER END COVER - RH	\$ 11.00	?
12	FRONT WHEEL HOUSING LINER - RH	\$ 220.00	?
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 82.00	?
14	STONE CHIP GUARD - RH	\$ 46.00	hl ✓ \$36-64
15	FENDER TOP LEDGE COVER - INNER	\$ 28.00	? photo
16	FENDER TOP LEDGE COVER - OUTER	\$ 21.00	?
17	FRONT DOOR - RH	\$ 2,152.00	hl ✓ \$1721-60
18	OUTER DOOR SEAL	NEC \$ 185.00	hl ✓ \$147-60
19	BONDING AGENT	NEC \$ 45.00	hl ✓
20	CLEANING SOLUTION	NEC \$ 65.00	hl ✓
SUB TOTAL SPARE PARTS CHARGES		\$ 6,913.00	

VIE GER

6/9

PRE SK

9/9

WIE GER

SK ME

SK ME

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 8541

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT DOOR ATTACHMENT PARTS	\$ 488.00	?
22	FRONT DOOR CATCH	\$ 96.00	?
23	DOOR HINGE HALF-UPPER PART - RH UPPER	\$ 41.00	? \$32.08
24	HINGE HALVES - RH UPPER	\$ 42.00	? \$33.04
25	DOOR HINGE HALF-UPPER PARTT - RH LOWER	\$ 39.00	? \$35.04
26	HINGE HALVES - RH LOWER	\$ 42.00	? \$33.36
27	INNER DOOR SEAL	\$ 185.00	?
28	EXTERIOR MIRROR MOUNTING - RH	\$ 824.00	?
29	MIRROR CAP - RH	\$ 220.00	?
30	FRONT WINDOW REGULATOR - RH	\$ 250.00	?
31	FRONT WINDOW REGULATOR MOTOR - RH	\$ 278.00	?
32	DOOR CONTROL UNIR - RH	\$ 685.00	X
33	FRONT WINDOW SLOT SEAL - RH	\$ 280.00	? photo.
34	FRONT WINDOW GUIDE TRIM STRIP - RH	\$ 235.00	?
35	FRONT SILL TRIM STRIP - RH	\$ 109.00	? photo \$57.20
36	REAR DOOR - RH	\$ 2,152.00	bt ✓ \$1721.60
37	OUTER DOOR SEAL	NEC \$ 185.00	NI ✓ \$147.60
38	BONDING AGENT	NEC \$ 45.00	NI ✓ \$35.92
39	CLEANING SOLUTION	NEC \$ 65.00	NI ✓ \$31.68
40	SEALING STRIP	\$ 15.00	?
	SUB TOTAL SPARE PARTS CHARGES	: \$ 6,276.00	

ALSK-
MASK-

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 8541

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	REAR DOOR CATCH	\$ 109.00	?
42	DOOR HINGE HALF-UPPER PART - RH UPPER	\$ 41.00	?
43	HINGE HALVES - RH UPPER	\$ 42.00	?
44	HINGE HALVES - RH LOWER	\$ 42.00	?
45	HINGE HALVES - RH LOWER	\$ 42.00	?
46	REAR WINDOW SLOT SEAL - RH	\$ 335.00	?
47	REAR WINDOW GUIDE TRIM STRIP - RH	\$ 216.00	?
48	REAR WINDOW	\$ 1,049.00	X
49	PRIMER	\$ 19.00	X
50	QUARTER GLASS	\$ 561.00	X
51	REAR WHEEL HOUSING LINER - RH	\$ 223.00	X
52	REAR WHEEL HOUSING LINER ATTACHMENT PAR	\$ 82.00	X
53	REAR ALUMINIUM RIM - RH	\$ 651.00	cut ✓
54	ALUMINIUM RIM RUBBER VALVE	\$ 13.00	nei ✓
55	TYRE PRESSURE DATA PLATE	\$ 35.00	nei ✓
56	ACRYLIC SEALANT	S/N \$ 360.00	nei ✓
57	CAVITY WAX	S/N \$ 280.00	nei ✓
58	STONE CHIP	S/N \$ 360.00	nei ✓
59	METAL FILLER POWDER	S/N \$ 280.00	nei ✓
60	REAR WINDSCREEN SEALANT	S/N \$ 200.00	X
61	1/4 GLASS SEALANT	S/N \$ 100.00	X
62	RHS REAR TYRE	TBC	✓ 80% \$269.00
63	SUNDRIES	\$ 1,000.00	? \$1240 ✓
TOTAL SPARE PARTS CHARGES		\$ 19,229.00	
TOTAL LABOUR CHARGES		\$ 33,014.00	
GRAND TOTAL		\$ 52,243.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 9749574
Not Authorise
3/9/1990
Exp to be advise.
Resing before point
15 days
Sylvia Khuan

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10658

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1054/2019/NS
Date : 3-Sep-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Eng Chong
Address : 38 Choa Chu Kang Street 64
#16-07
Singapore 689102
Telephone : HP +65 96722454
Type of Claim : Own Damage Claims
Policy No. : 1800114327
Vehicle No : **SDW 854 J**
Model Code : A4 Sedan 2.0 TFSI
Model / Year : Sep-18
Engine No : CVK 069094
Chassis No : WAUZZZF49JA233024
Mileage : -
Date In : 30-Aug-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Aug-19
Place of Accident : Junction Of Coleman Lane & North Bridge Road

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is **allowed**
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 854]

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00 ✓	\$480.00
2	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00 X	nn. \$360.00
3	To carry out first measurement test on car o-liner	S/N \$	800.00	nn. photo. \$800.00
4	To remove and transfer rhs front door and rhs rear door multi-lock system and power window devices. Check function and renew if necessary.	S/N \$	560.00 ✓	\$560.00
5	To dislodge and reinstall rhs A-pillar, door harness, rear wire harness, battery manager duse and electrical trays, audio and electrical equipment.	S/N \$	1,800.00	photo. \$1800.00
SUB TOTAL LABOUR CHARGES		:	<u>\$4,000.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 854 1

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
6	To remove and reinstall front and rear seat assy, back rest, ABCD pillar trims, curtain airbags, safety belts, carpets, roof liner, carpets, sill trims, etc.	S/N \$	1,800.00	? photo. \$1800.00
7	To remove centre console amd dashboard assy for A-pillar renewal. Inspect for damages.	S/N \$	3,200.00	nm 2 photo.
8	To remove and renew rhs rear 1/4 glass and rear windscree.	S/N \$	600.00	X ny
9	To install rear windscreen solar film.	S/N \$	400.00	X ny
10	To place vehicle on car o-liner.	S/N \$	1,800.00	2 photo
SUB TOTAL LABOUR CHARGES		:	<u>\$7,800.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 854 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
11	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door, rear bumper and rear lid. To cut out and weld rhs A-pillar, rhs B-pillar, rhs sill panel and rhs rear fender. To renew rhs front fender, rhs wing mirror assy, rhs front door and rhs rear door. re-organise crash management components. reinstall all parts removed.	S 11,900.00	4000 \$4000-00
12	To respray rhs front fender, rhs front door, rhs wing mirror cover. Rhs rear door, door handle, rhs A-pillar, rhs sill panel, rhs B-pillar, hinges rhs rear fender, door entrances, roof channel, drain panel, and end panelling. To carry out joint sealer work and stone chip treatment.	S 8,650.00	3300 \$3300-00
13	To renew rhs rear rim and tyre. To carry out wheel alignment.	S/N S 280.00 ✓	\$280-00
14	To carry out diagnostic checks.	S/N S 384.00 ✓	\$384-00
TOTAL LABOUR CHARGES		: <u>\$33,014.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 854 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	A-PILLAR FRAME - RH	\$ 2,856.00	ht - plus 2284.80
2	FRONT FENDER - RH	\$ 700.00	ht - 559.60
3	FRONT FENDER ATTACHMENT PARTS	\$ 183.00	} X un
4	FRONT FENDER CLOSING ELEMENT - RH	\$ 45.00	
5	FRONT FENDER BRACKET - RH	\$ 32.00	
6	FRONT FENDER DEFORMATION ELEMENT BRACKET	\$ 45.00	
7	FRONT FENDER REAR BRACKET	\$ 29.00	
8	FRONT FENDER UPPER BRACKET	\$ 31.00	
9	FRONT FENDER BRACE - RH	\$ 107.00	
10	FRONT FENDER CLOSING ELEMENT - RH	\$ 30.00	
11	FRONT FENDER END COVER - RH	\$ 11.00	
12	FRONT WHEEL HOUSING LINER - RH	\$ 220.00	
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 82.00	
14	STONE CHIP GUARD - RH	\$ 46.00	ht - 36.64
15	FENDER TOP LEDGE COVER - INNER	\$ 28.00	X un
16	FENDER TOP LEDGE COVER - OUTER	\$ 21.00	X un
17	FRONT DOOR - RH	\$ 2,152.00	ht - 1721.60
18	OUTER DOOR SEAL	NEC \$ 185.00	ht - 147.60
19	BONDING AGENT	NEC \$ 45.00	ht X un
20	CLEANING SOLUTION	NEC \$ 65.00	ht X un
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,913.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 854 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT DOOR ATTACHMENT PARTS	\$ 488.00	X by
22	FRONT DOOR CATCH	\$ 96.00	X un
23	DOOR HINGE HALF-UPPER PART - RH UPPER	\$ 41.00	? 32.08 bt
24	HINGE HALVES - RH UPPER	\$ 42.00	? 33.04 bt
25	DOOR HINGE HALF-UPPER PARTT - RH LOWER	\$ 39.00	? 35.04 bt
26	HINGE HALVES - RH LOWER	\$ 42.00	? 33.36 bt
27	INNER DOOR SEAL	\$ 185.00	X
28	EXTERIOR MIRROR MOUNTING - RH	\$ 824.00	X
29	MIRROR CAP - RH	\$ 220.00	X
30	FRONT WINDOW REGULATOR - RH	\$ 250.00	X
31	FRONT WINDOW REGULATOR MOTOR - RH	\$ 278.00	X
32	DOOR CONTROL UNIR - RH	\$ 685.00	X
33	FRONT WINDOW SLOT SEAL - RH	\$ 280.00	? photo X un
34	FRONT WINDOW GUIDE TRIM STRIP - RH	\$ 235.00	? un
35	FRONT SILL TRIM STRIP - RH	\$ 109.00	? photo 87.20 de
36	REAR DOOR - RH	\$ 2,152.00	bt 1721.60
37	OUTER DOOR SEAL	NEC \$ 185.00	net 147.60
38	BONDING AGENT	NEC \$ 45.00	net 35.92
39	CLEANING SOLUTION	NEC \$ 65.00	net 51.68
40	SEALING STRIP	\$ 15.00	X un
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,276.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 854 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	REAR DOOR CATCH	\$ 109.00	X 87.20 W-
42	DOOR HINGE HALF-UPPER PART - RH UPPER	\$ 41.00	X
43	HINGE HALVES - RH UPPER	\$ 42.00	X
44	HINGE HALVES - RH LOWER	\$ 42.00	X
45	HINGE HALVES - RH LOWER	\$ 42.00	X
46	REAR WINDOW SLOT SEAL - RH	\$ 335.00	X nh
47	REAR WINDOW GUIDE TRIM STRIP - RH	\$ 216.00	X
48	REAR WINDOW	\$ 1,049.00	X
49	PRIMER	\$ 19.00	X
50	QUARTER GLASS	\$ 561.00	X
51	REAR WHEEL HOUSING LINER - RH	\$ 223.00	X
52	REAR WHEEL HOUSING LINER ATTACHMENT PAR	\$ 82.00	X
53	REAR ALUMINIUM RIM - RH	\$ 651.00	cut ✓ 520.80
54	ALUMINIUM RIM RUBBER VALVE	\$ 13.00	nei ✓ 2.48
55	TYRE PRESSURE DATA PLATE	\$ 35.00	nei ✓ 27.36
56	ACRYLIC SEALANT	S/N \$ 360.00	nei ✓ 180
57	CAVITY WAX	S/N \$ 280.00	nei ✓ 140
58	STONE CHIP	S/N \$ 360.00	nei ✓ 180
59	METAL FILLER POWDER	S/N \$ 280.00	nei ✓ 280
60	REAR WINDSCREEN SEALANT	S/N \$ 200.00	X nh
61	1/4 GLASS SEALANT	S/N \$ 100.00	X nh
62	RHS REAR TYRE	330 TBC	perfect ✓ 80% 264
63	SUNDRIES	\$ 1,000.00	? 162.40. nei ✓
TOTAL SPARE PARTS CHARGES		:	\$ 19,229.00
TOTAL LABOUR CHARGES		:	\$ 33,014.00
GRAND TOTAL		:	\$ 52,243.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

6/7/05

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 97495744
Not Authorise
3/9/190440
Exp to be advise.
Resumy before part
15 days
syrethhauto.com

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

GST Reg No. 19-9902271-W

For Premium Automobiles Pte Ltd

Authorised Signature



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

~~X~~ local purpose.

Tel : (65) 6366 2323 Fax : (65) 6841 1183

GST Reg No. 19-9902271-W

Estimate No.	PA/OD/1054/2019/NS
Date	12-Sep-19
Service Advisor	Glory Tan
Pages	1 of 1
Regn No	SDW 854 J
Model No	A4 Sedan 2.0 TFSI

Rare
12/09/19


 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10658

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1054/2019/NS
Date : 3-Sep-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Taufikh

We took 30 days and 5 Sundays

jb - 4 Dec 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Eng Chong
Address : 38 Choa Chu Kang Street 64
#16-07
Singapore 689102
Telephone : HP +65 96722454
Type of Claim : Own Damage Claims
Policy No. : 1800114327
Vehicle No : **SDW 854 J**
Model Code : A4 Sedan 2.0 TFSI
Model / Year : Sep-18
Engine No : CVK 069094
Chassis No : WAUZZZF49JA233024
Mileage : -
Date In : 30-Aug-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Aug-19
Place of Accident : Junction Of Coleman Lane & North Bridge Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 854 J

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	na
3	To carry out first measurement test on car o-liner	S/N \$	800.00	na
4	To remove and transfer rhs front door and rhs rear door multi-lock system and power window devices. Check function and renew if necessary.	S/N \$	560.00	\$ 560.00
5	To dislodge and reinstall rhs A-pillar, door harness, rear wire harness, battery manager duse and electrical trays, audio and electrical equipment.	S/N \$	1,800.00	\$ 1,800.00
SUB TOTAL LABOUR CHARGES		:	<u>\$4,000.00</u>	<u>\$ 2,840.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 854 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
			\$ 2,840.00
6	To remove and reinstall front and rear seat assy, back rest, ABCD pillar trims, curtain airbags, safety belts, carpets, roof liner, carpets, sill trims, etc.	S/N \$ 1,800.00	\$ 1,800.00
7	To remove centre console and dashboard assy for A-pillar renewal. Inspect for damages.	S/N \$ 3,200.00	
8	To remove and renew rhs rear 1/4 glass and rear windscree.	S/N \$ 600.00	
9	To install rear windscreen solar film.	S/N \$ 400.00	
10	To place vehicle on car o-liner.	S/N \$ 1,800.00	
SUB TOTAL LABOUR CHARGES		: <u>\$7,800.00</u>	<u>\$ 4,640.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 854 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
			\$ 4,640.00
11	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door, rear bumper and rear lid. To cut out and weld rhs A-pillar, rhs B-pillar, rhs sill panel and rhs rear fender. To renew rhs front fender, rhs wing mirror assy, rhs front door and rhs rear door. re-organise crash management components. reinstall all parts removed.	\$ 11,900.00	\$ 4,000.00
12	To respray rhs front fender, rhs front door, rhs wing mirror cover. Rhs rear door, door handle, rhs A-pillar, rhs sill panel, rhs B-pillar, hinges rhs rear fender, door entrances, roof channel, drain panel, and end panelling. To carry out joint sealer work and stone chip treatment.	\$ 8,650.00	\$ 3,300.00
13	To renew rhs rear rim and tyre. To carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
14	To carry out diagnostic checks.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: <u>\$33,014.00</u>	<u>\$ 12,604.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 854 J

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	A-PILLAR FRAME - RH	\$ 2,856.00	\$ 2,284.80
2	FRONT FENDER - RH	\$ 700.00	\$ 559.60
3	FRONT FENDER ATTACHMENT PARTS	\$ 183.00	
4	FRONT FENDER CLOSING ELEMENT - RH	\$ 45.00	
5	FRONT FENDER BRACKET - RH	\$ 32.00	
6	FRONT FENDER DEFORMATION ELEMENT BRACKET	\$ 45.00	
7	FRONT FENDER REAR BRACKET	\$ 29.00	
8	FRONT FENDER UPPER BRACKET	\$ 31.00	
9	FRONT FENDER BRACE - RH	\$ 107.00	
10	FRONT FENDER CLOSING ELEMENT - RH	\$ 30.00	
11	FRONT FENDER END COVER - RH	\$ 11.00	
12	FRONT WHEEL HOUSING LINER - RH	\$ 220.00	
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 82.00	
14	STONE CHIP GUARD - RH	\$ 46.00	\$ 36.64
15	FENDER TOP LEDGE COVER - INNER	\$ 28.00	
16	FENDER TOP LEDGE COVER - OUTER	\$ 21.00	
17	FRONT DOOR - RH	\$ 2,152.00	\$ 1,721.60
18	OUTER DOOR SEAL	NEC \$ 185.00	\$ 147.60
19	BONDING AGENT	NEC \$ 45.00	
20	CLEANING SOLUTION	NEC \$ 65.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 6,913.00	\$ 4,750.24

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6641 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 854 J

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remark	
			\$	4,750.24
21	FRONT DOOR ATTACHMENT PARTS	\$ 488.00		
22	FRONT DOOR CATCH	\$ 96.00		
23	DOOR HINGE HALF-UPPER PART - RH UPPER	\$ 41.00	\$	32.08
24	HINGE HALVES - RH UPPER	\$ 42.00	\$	33.04
25	DOOR HINGE HALF-UPPER PARTT - RH LOWER	\$ 39.00	\$	35.04
26	HINGE HALVES - RH LOWER	\$ 42.00	\$	33.36
27	INNER DOOR SEAL	\$ 185.00		
28	EXTERIOR MIRROR MOUNTING - RH	\$ 824.00		
29	MIRROR CAP - RH	\$ 220.00		
30	FRONT WINDOW REGULATOR - RH	\$ 250.00		
31	FRONT WINDOW REGULATOR MOTOR - RH	\$ 278.00		
32	DOOR CONTROL UNIR - RH	\$ 685.00		
33	FRONT WINDOW SLOT SEAL - RH	\$ 280.00		
34	FRONT WINDOW GUIDE TRIM STRIP - RH	\$ 235.00		
35	FRONT SILL TRIM STRIP - RH	\$ 109.00	\$	87.20
36	REAR DOOR - RH	\$ 2,152.00	\$	1,721.60
37	OUTER DOOR SEAL	NEC \$ 185.00	\$	147.60
38	BONDING AGENT	NEC \$ 45.00	\$	35.92
39	CLEANING SOLUTION	NEC \$ 65.00	\$	51.68
40	SEALING STRIP	\$ 15.00		
	SUB TOTAL SPARE PARTS CHARGES	\$ 6,276.00	\$	6,927.76

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 854 J

S/N	Parts Description	C/F	Damaged Parts & Prices	
			S/Nett	Remark
			\$	6,927.76
41	REAR DOOR CATCH		\$ 109.00	\$ 87.20
42	DOOR HINGE HALF-UPPER PART - RH UPPER		\$ 41.00	
43	HINGE HALVES - RH UPPER		\$ 42.00	
44	HINGE HALVES - RH LOWER		\$ 42.00	
45	HINGE HALVES - RH LOWER		\$ 42.00	
46	REAR WINDOW SLOT SEAL - RH		\$ 335.00	
47	REAR WINDOW GUIDE TRIM STRIP - RH		\$ 216.00	
48	REAR WINDOW		\$ 1,049.00	
49	PRIMER		\$ 19.00	
50	QUARTER GLASS		\$ 561.00	
51	REAR WHEEL HOUSING LINER - RH		\$ 223.00	
52	REAR WHEEL HOUSING LINER ATTACHMENT P.		\$ 82.00	
53	REAR ALUMINIUM RIM - RH		\$ 651.00	\$ 520.80
54	ALUMINIUM RIM RUBBER VALVE	4	\$ 13.00	\$ 2.48
55	TYRE PRESSURE DATA PLATE		\$ 35.00	\$ 27.36
56	ACRYLIC SEALANT	S/N	\$ 360.00	\$ 180.00
57	CAVITY WAX	S/N	\$ 280.00	\$ 140.00
58	STONE CHIP	S/N	\$ 360.00	\$ 180.00
59	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
60	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
61	1/4 GLASS SEALANT	S/N	\$ 100.00	
62	RHS REAR TYRE 80%		\$ 330.00	\$ 264.00
63	Added parts - see attached		\$ 816.50	\$ 653.20 338
64	SUNDRIES		\$ 1,000.00	\$ 162.40
TOTAL SPARE PARTS CHARGES		:	\$ 20,375.50	\$ 9,426.20 9110
TOTAL LABOUR CHARGES		:	\$ 33,014.00	\$ 12,604.00
GRAND TOTAL		:	\$ 53,389.50	\$ 22,029.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

21714-00

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SDW 854 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1054/2019/NH

22nd February 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SDW 854 J, Audi A4 SEDAN 2.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SDW 854 J**, claimant, **Mr. Tan Eng Chong**, please find the related document per attached.

1. A copy of the Original invoice no. 85014868 – S\$ 21,521.98.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SDW 854 J

Premium Automobiles Pte Ltd



Audi Centre Singapore
261 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
261 Alexandra Road
Singapore 159938
Main Telephone 6368 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408999
Main Telephone 6368 2223
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:47

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014868 Date : 20/02/2020 Order : SDW0854J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SDW0854J (V 39557) Regn Date: 25/09/2018 Mileage: 32463 WIP No.: 10658

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF49JA233024 Engine: CVK 069094 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1600.00	1.00	-1,600.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. CHECK FUNCTION AND RENEW IF NECESSARY	560.00	1.00	560.00
S	BODYWORK	M: TO DISLodge AND REINSTALL RHS A PILLAR, DOOR ENTRANCE, REAR WIRE HARNESS, BATTERY MANAGER, ELECTRICAL TRAY AND AUDIO EQUIPMENT.	1800.00	1.00	1,800.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT AND REAR SEAT ASSY, BACK REST, ABCD PILLAR TRIM, CURTAIN AIRBAG, SAFETY BELTS, CARPETS, ROOF LINER AND SILL TRIMS	1800.00	1.00	1,800.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, RHS FRONT AND REAR DOOR, REAR BUMPER AND REAR LID. TO CUT OUT AND WELD RHS A B PILLAR, RHS SILL PANEL AND RHS REAR FENDER. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	4000.00	1.00	4,000.00
S	BODYWORK	M: TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, RHS A PILLAR, RHS SILL PANEL AND RHS B PILLAR. TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT	3300.00	1.00	3,300.00
S	BODYWORK	M:	280.00	1.00	280.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 16:47

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014868 Date : 20/02/2020 Order : SDW0854J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SDW0854J (V 39557) Regn Date: 25/09/2018 Mileage: 32463 WIP No.: 10658

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF49JA233024 Engine: CVK 069094 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO RENEW RHS REAR TYRE.TO CARRY OUT WHEEL ALIGNMENT M:	384.00	1.00	384.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	780.00	1.00	780.00
X	ABW5810076	TO SUPPLY ACRYLIC SEALANT,CAVITY WAX,STONE CHIP AND METAL FILLER POWDER.			
X	ABW0821106A	(V) (GER) FRAME 6/9/19	Less 020%	1.00	2856.00
X	ABW0853824B 9B9	(SK) FENDER	Less 020%	1.00	699.50
X	ABW0831052D	STONEGUARD	Less 020%	1.00	45.80
X	ABW0837912A	(A) (SK) DOOR 6/9/19	Less 020%	1.00	2152.00
X	AD 355205A2	SEAL(LAST)	Less 020%	1.00	184.50
X	AD 00940104	(GER) BONDAGENT	Less 020%	1.00	44.90
X	ABX4833408A	CLEANER	Less 020%	1.00	64.60
X	ABW5831404A	HINGE(LAST) AP	Less 020%	1.00	40.10
X	ABX4833406A	HINGE(LAST) AP	Less 020%	1.00	41.30
X	ABW5833052C	HINGE(LAST) AP	Less 020%	1.00	43.80
X	ABW5839912A	(A) (SK) DOOR 6/9/19	Less 020%	1.00	2152.00
X	ABW0839249	(A) (SK) SEAL 6/9/19	Less 020%	1.00	184.50
X	ABW0831404A	(SK) CHECK ROD AP	Less 020%	1.00	109.00
X	ABW0601025EF	HINGE AP	Less 020%	1.00	41.70
X	A311601361	(A) (SK) WHEEL 6/9/19	Less 020%	1.00	651.00
X	AWHT007978	RUBBER VAL	Less 020%	1.00	3.10
X	AWHT004869	BOLT AP	Less 020%	2.00	5.00
X	AWHT001234B	NUT AP	Less 020%	2.00	1.50
X	AWHT003497	BOLT AP	Less 020%	2.00	1.70
X	AWHT003237	BOLT AP	Less 020%	2.00	2.10
X	AWHT006772A	BOLT AP	Less 020%	4.00	1.00
X	ABK0837199	NUT	Less 020%	2.00	5.00
X	AN 0385053	CLIP AP	Less 020%	12.00	0.70
X	A4L0000279	RIVET AP	Less 020%	6.00	0.50
X	ABW0010502D	007435/IDENTPLATE	Less 020%	1.00	422.50
X	A000979940	LABEL	Less 020%	1.00	34.20
		CONNECTOR	Less 020%	5.00	9.60

Premium Automobiles Pte Ltd



Audi Centre Singapore
291 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
291 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408698
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 16:47

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014868 Date : 20/02/2020 Order : SDW0854J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SDW0854J (V 39557) Regn Date: 25/09/2018 Mileage: 32463 WIP No.: 10658

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF49JA233024 Engine: CVK 069094 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	A8W0853373F 9B9	SCUFF PLAT - A/P	Less 020%	1.00	109.00	87.20
X	A8W0853374F 9B9	SCUFF PLAT AP	Less 020%	1.00	109.00	87.20
X	EC205/60R16W	CONTI CONTACT 5	Less 020%	1.00	330.00	264.00

Parts 8,330.00
Labour 0.00
Sublet 13,384.00
Menus 0.00
Lubricant 0.00



Sub-Total 20,114.00
7% GST 1,407.98
Grand Total 21,521.98

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SDW 854 J

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1054/2019/TG
09 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 2.0 TFSI
Vehicle Chassis No. : WAUZZZF49JA233024
Vehicle Regn No. : SDW 854 J
Vehicle Mileage : 16428 KM
Vehicle Owner : Mr. Tan Eng Chong
Certificate No : 1800114327
Own Damage Excess : S\$ 1,712.00 (Inclusive 7% GST)
Accident Date : 30/08/2019
Place : Junction of Coleman Lane & North Bridge Rd
Repair Cost : \$ 21,521.98
WIP No. : 10658
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1730
Date : 10/10/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019 13:20		04 Sep 2019 10:47 Edit Adj Rpt	S\$21,714.00 Edit Estimates	S\$21,714.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN ENG CHONG , ID: S7027769G, Tel: +6596722454, Email: TANEC168@YAHOO.COM									
Vehicle Reg. No.: SDW854J		Date of Loss: 30/08/2019 17:00 - :59 [11 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 5606193234SG		Policy/Cover Note No.: 1800114327 (Comprehensive)							
		Excess: S\$1,600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/09/2019]									
Driver/Custodian: TAN ENG CHONG (49 / Male) , NRIC: S7027769G, Tel: +6596722454 Email: TANEC168@YAHOO.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (05/03/2020): Alert - Adj Mandate Approved (S\$21714.00) - SDW854J - Claim Handler: Chan, Yoke ... - AIG_SG (31/01/2020): Alert - Adj Mandate Maintained - SDW854J - Claim Handler: Chan, Yoke Shi - AIG_SG (05/09/2019): Alert - Adj Mandate Approved (S\$19479.00) - SDW854J - Claim Handler: Chan, Yoke ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDW854J (5606193234SG)
 OD
 Aug 30 2019 5:10PM
 [TAN ENG CHONG]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	04/09/19 14:52	Adjuster Immediate Advice														Load HTM				
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	04/09/19 13:27	General View														Load JPG	☒			
2	04/09/19 13:27	General View														Load JPG	☒			
3	04/09/19 13:27	General View														Load JPG	☒			
4	04/09/19 13:27	General View														Load JPG	☒			
5	04/09/19 13:27	General View														Load JPG	☒			
6	04/09/19 13:27	General View														Load JPG	☒			
7	04/09/19 13:27	General View														Load JPG	☒			
8	04/09/19 13:27	General View														Load JPG	☒			
9	04/09/19 13:27	General View														Load JPG	☒			
10	04/09/19 13:27	General View														Load JPG	☒			
11	04/09/19 13:27	General View														Load JPG	☒			
12	04/09/19 13:27	General View														Load JPG	☒			
13	04/09/19 13:27	General View														Load JPG	☒			
14	04/09/19 13:27	General View														Load JPG	☒			
15	04/09/19 13:27	General View														Load JPG	☒			
16	04/09/19 13:27	General View														Load JPG	☒			
17	04/09/19 13:27	General View														Load JPG	☒			
18	04/09/19 13:27	General View														Load JPG	☒			
19	04/09/19 13:27	General View														Load JPG	☒			
20	04/09/19 13:27	General View														Load JPG	☒			
21	04/09/19 13:27	General View														Load JPG	☒			
22	04/09/19 13:27	General View														Load JPG	☒			
23	04/09/19 13:27	General View														Load JPG	☒			
24	04/09/19 13:27	General View														Load JPG	☒			
25	04/09/19 13:27	General View														Load JPG	☒			
26	04/09/19 13:27	General View														Load JPG	☒			
27	04/09/19 13:27	General View														Load JPG	☒			
28	04/09/19 13:27	General View														Load JPG	☒			
29	04/09/19 13:27	General View														Load JPG	☒			
30	04/09/19 13:27	General View														Load JPG	☒			
31	04/09/19 13:27	General View														Load JPG	☒			
32	04/09/19 13:27	General View														Load JPG	☒			
33	04/09/19 13:27	General View														Load JPG	☒			
34	04/09/19 13:27	General View														Load JPG	☒			
35	04/09/19 13:27	General View														Load JPG	☒			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	04/09/19 13:27	General View		☒
37	04/09/19 13:27	General View		☒
38	04/09/19 13:27	General View		☒
39	04/09/19 13:27	General View		☒
40	04/09/19 13:27	General View		☒
41	04/09/19 13:27	General View		☒
42	04/09/19 13:27	General View		☒
43	04/09/19 13:27	General View		☒
44	04/09/19 13:27	General View		☒
45	04/09/19 13:27	General View		☒
46	04/09/19 13:27	General View		☒
47	04/09/19 13:27	General View		☒
48	04/09/19 13:27	General View		☒
49	16/01/20 12:26	Reinspection Photo		☒
50	16/01/20 12:26	Reinspection Photo		☒
51	16/01/20 12:26	Reinspection Photo		☒
52	16/01/20 12:26	Reinspection Photo		☒
53	16/01/20 12:26	Reinspection Photo		☒
54	16/01/20 12:26	Reinspection Photo		☒
55	16/01/20 12:26	Reinspection Photo		☒
56	16/01/20 12:26	Reinspection Photo		☒
57	16/01/20 12:26	Reinspection Photo		☒
58	16/01/20 12:26	Reinspection Photo		☒
59	16/01/20 12:26	Reinspection Photo		☒
60	16/01/20 12:26	Reinspection Photo		☒
61	16/01/20 12:26	Reinspection Photo		☒
62	16/01/20 12:26	Reinspection Photo		☒
63	16/01/20 12:26	Reinspection Photo		☒
64	16/01/20 12:26	Reinspection Photo		☒
65	16/01/20 12:28	Reinspection Photo		☒
66	16/01/20 12:28	Reinspection Photo		☒
67	16/01/20 12:28	Reinspection Photo		☒
68	16/01/20 12:28	Reinspection Photo		☒
69	16/01/20 12:28	Reinspection Photo		☒
70	16/01/20 12:28	Reinspection Photo		☒
71	16/01/20 12:28	Reinspection Photo		☒
72	16/01/20 12:28	Reinspection Photo		☒
73	16/01/20 12:31	Replacement Part Photo		☒
74	16/01/20 12:31	Replacement Part Photo		☒
75	16/01/20 12:31	Replacement Part Photo		☒
76	16/01/20 12:31	Replacement Part Photo		☒
77	16/01/20 12:31	Replacement Part Photo		☒
78	16/01/20 12:31	Replacement Part Photo		☒
79	16/01/20 12:31	Replacement Part Photo		☒
80	16/01/20 12:31	Replacement Part Photo		☒
81	16/01/20 12:31	Replacement Part Photo		☒
82	16/01/20 12:31	Replacement Part Photo		☒
83	16/01/20 12:31	Replacement Part Photo		☒
84	16/01/20 12:31	Replacement Part Photo		☒
85	16/01/20 12:31	Replacement Part Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
87	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
88	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
89	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
90	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
91	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
92	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
93	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
94	16/01/20 12:31	Replacement Part Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/19 13:45	estimate	 Load PDF	
2	04/09/19 13:45	Singapore Accident Statement	 Load PDF	
3	04/09/19 14:32	UNDERTAKING LETTER	 Load PDF	
4	05/09/19 11:59	Driver's Driving License	 Load PDF	
5	29/01/20 14:54	MARKING ESTIMATE	 Load PDF	
6	31/01/20 10:38	ESTIMATE	 Load PDF	
7	02/03/20 09:17	Supplementary	 Load PDF	
8	06/03/20 08:47	Workshop Invoice	 Load PDF	
9	06/03/20 08:47	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/09/19 11:02	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/09/19 11:00	Accident Photo	 Load JPG	☒
2	02/09/19 11:00	Accident Photo	 Load JPG	☒
3	02/09/19 11:00	Accident Photo	 Load JPG	☒
4	02/09/19 11:00	Accident Photo	 Load JPG	☒
5	02/09/19 11:00	Accident Photo	 Load JPG	☒
6	02/09/19 11:00	Accident Photo	 Load JPG	☒
7	02/09/19 11:00	Accident Photo	 Load JPG	☒
8	02/09/19 11:00	Accident Photo	 Load JPG	☒
9	02/09/19 11:00	Accident Photo	 Load JPG	☒
10	02/09/19 11:00	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/09/19 11:02	Sketch Plan	 Load JPG	☒
2	02/09/19 11:02	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19015618/T1YF3E2

Date: 06/03/2020

REFERENCE

Insured/Claimant: TAN ENG CHONG Policy No: 1800114327
Date of Loss: 30/08/2019 Nature of Claim: OD Claim No: 5606193234SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDW854J
Make & Model: AUDI A4, 2.0 (A) Engine No: CVK069094
Reg. Date: 25/09/2018 (Man. Year: 2018) Chassis No: WAUZZZF49JA233024
Colour: Blue Odometer: 23487 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$138,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,291.00	9,110.00	11,181.00	55.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	33,014.00	12,604.00	20,410.00	61.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,305.00	21,714.00	31,591.00	59.26
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	51,705.00	20,114.00	31,591.00	61.10
+ GST 7.00/7.00% (S\$)	3,619.35	1,407.98	2,211.37	61.10
Nett Amount (S\$)	55,324.35	21,521.98	33,802.37	61.10

INSPECTION

Date of Assignment: 04/09/2019
Date Inspected: 03/09/2019 Inspected At: 24 Benoi Sector
Estimated Period of Repair: 15.0 days
Repairer : Premium Automobiles Pte Ltd

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*A-PILLAR FRAME - RH	Bent	2,856.00 FS	*2,284.80 FS
2	1		*FRONT FENDER - RH	Bent	700.00 FS	*559.60 FS
3	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
4	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	45.00 FS	*- FS
5	1		*FRONT FENDER BRACKET - RH	Not Necessary	32.00 FS	*- FS
6	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET	Not Necessary	45.00 FS	*- FS
7	1		*FRONT FENDER REAR BRACKET	Not Necessary	29.00 FS	*- FS
8	1		*FRONT FENDER UPPER BRACKET	Not Necessary	31.00 FS	*- FS
9	1		*FRONT FENDER BRACE - RH	Not Necessary	107.00 FS	*- FS
10	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	30.00 FS	*- FS
11	1		*FRONT FENDER END COVER - RH	Not Necessary	11.00 FS	*- FS
12	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	220.00 FS	*- FS
13	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
14	1		*STONE CHIP GUARD - RH	Necessary	46.00 FS	*36.64 FS
15	1		*FENDER TOP LEDGE COVER - INNER	Not Necessary	28.00 FS	*- FS
16	1		*FENDER TOP LEDGE COVER - OUTER	Not Necessary	21.00 FS	*- FS
17	1		*FRONT DOOR - RH	Bent	2,152.00 FS	*1,721.60 FS
18	1		*OUTER DOOR SEAL	Necessary	185.00 FS	*147.60 FS
19	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
20	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
21	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	488.00 FS	*- FS
22	1		*FRONT DOOR CATCH	Not Necessary	96.00 FS	*- FS
23	1		*DOOR HINGE HALF - UPPER PART - RH UPPER	Bent	41.00 FS	*32.08 FS
24	1		*HINGE HALVES - RH UPPER	Bent	42.00 FS	*33.04 FS
25	1		*DOOR HINGE HALF - UPPER PARTT - RH LOWER	Bent	39.00 FS	*35.04 FS
26	1		*HINGE HALVES - RH LOWER	Bent	42.00 FS	*33.36 FS
27	1		*INNER DOOR SEAL	Not Necessary	185.00 FS	*- FS
28	1		*EXTERIOR MIRROR MOUNTING - RH	Not Necessary	824.00 FS	*- FS
29	1		*MIRROR CAP - RH	Not Necessary	220.00 FS	*- FS
30	1		*FRONT WINDOW REGULATOR - RH	Not Necessary	250.00 FS	*- FS
31	1		*FRONT WINDOW REGULATOR MOTOR - RH	Not Necessary	278.00 FS	*- FS
32	1		*DOOR CONTROL UNIT - RH	Not Necessary	685.00 FS	*- FS
33	1		*FRONT WINDOW SLOT SEAL - RH	Not Necessary	280.00 FS	*- FS
34	1		*FRONT WINDOW GUIDE TRIM STRIP - RH	Not Necessary	235.00 FS	*- FS
35	1		*FRONT SILL TRIM STRIP - RH	Deformed	109.00 FS	*87.20 FS
36	1		*REAR DOOR - RH	Bent	2,152.00 FS	*1,721.60 FS
37	1		*OUTER DOOR SEAL	Necessary	185.00 FS	*147.60 FS
38	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
39	1		*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
40	1		*SEALING STRIP	Not Necessary	15.00 FS	*- FS
41	1		*REAR DOOR CATCH	Bent	109.00 FS	*87.20 FS
42	1		*DOOR HINGE HALF - UPPER PART - RH UPPER	Not Necessary	41.00 FS	*- FS
43	1		*HINGE HALVES - RH UPPER	Not Necessary	42.00 FS	*- FS
44	1		*HINGE HALVES - RH LOWER	Not Necessary	42.00 FS	*- FS
45	1		*HINGE HALVES - RH LOWER	Not Necessary	42.00 FS	*- FS
46	1		*REAR WINDOW SLOT SEAL - RH	Not Necessary	335.00 FS	*- FS
47	1		*REAR WINDOW GUIDE TRIM STRIP - RH	Not Necessary	216.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*REAR WINDOW	Not Necessary	1,049.00 FS	*- FS
49	1		*PRIMER	Not Necessary	19.00 FS	*- FS
50	1		*QUARTER GLASS	Not Necessary	561.00 FS	*- FS
51	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	223.00 FS	*- FS
52	1		*REAR WHEEL HOUSING LINER ATTACHMENT PAR	Not Necessary	82.00 FS	*- FS
53	1		*REAR ALUMINIUM RIM - RH	Cut	651.00 FS	*520.80 FS
54	1		*ALUMINIUM RIM RUBBER VALVE (4PCS)	Necessary (1Pc Only)	13.00 FS	*2.48 FS
55	1		*ACRYLIC SEALANT	Necessary	360.00 FS	*180.00 FS
56	1		*CAVITY WAX	Necessary	280.00 FS	*140.00 FS
57	1		*STONE CHIP	Necessary	360.00 FS	*180.00 FS
58	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
59	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
60	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
61	1		*RHS REAR TYRE (80%)	Punctured	330.00 FS	*264.00 FS
62	1		*SUNDRIES	Necessary	1,000.00 FS	*162.40 FS
63	1		*ROUND CONNECTOR HSG WITH CABLE	Not Necessary	241.00 FS	*- FS
64	1		*DEFROSTER NOZZLE FOR WINDSCREEN	Not Necessary	153.00 FS	*- FS
65	1		*CHASSIS NO PLATE	Necessary	338.00 FS	*338.00 FS
66	1		*TYRE PRESSURE DATA PLATE	Necessary	35.00 FS	*27.36 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 20,291.00 9,110.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
3	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	0.00
4	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. CHECK FUNCTION AND RENEW IF NECESSARY	New	560.00	560.00
5	TO DISLODGE AND REINSTALL RHS A-PILLAR, DOOR HARNESS, REAR WIRE HARNESS, BATTERY MANAGER FUSE AND ELECTRICAL TRAYS, AUDIO AND ELECTRICAL EQUIPMENT	New	1,800.00	1,800.00
6	TO REMOVE AND REINSTALL FRONT AND REAR SEAT ASSY, BACK REST, ABCD PILLAR TRIMS, CURTAIN AIRBAGS, SAFETY BELTS, CARPETS, ROOF LINER, CARPETS, SILL TRIMS, ETC	New	1,800.00	1,800.00
7	TO REMOVE CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES	New	3,200.00	0.00
8	TO REMOVE AND RENEW RHS REAR 1/4 GLASS AND REAR WINDSCREEN	New	600.00	0.00
9	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	0.00
10	TO PLACE VEHICLE ON CAR O-LINER	New	1,800.00	0.00
11	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, REAR BUMPER AND REAR LID. TO CUT OUT AND WELD RHS A-PILLAR, RHS B-PILLAR, RHS SILL PANEL AND RHS REAR FENDER. TO RENEW RHS FRONT FENDER, RHS WING MIRROR ASSY, RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	11,900.00	4,000.00
12	TO RENEW RHS REAR RIM AND TYRE. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
13	TO CARRY OUT DIAGNOSTIC CHECKS	New	384.00	384.00
14	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER. RHS REAR DOOR, DOOR HANDLE, RHS A-PILLAR, RHS SILL PANEL, RHS B-PILLAR, HINGES RHS REAR FENDER, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, AND END PANELLING. TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT	New	8,650.00	3,300.00
Gross Labour Cost (\$\$)			33,014.00	12,604.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >