

ASS. REC. BY:

REF: CS/FCI 19015636/Kv f3

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Serene

of FCI

Date/Time: 3.9.19 5.46pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SBT 10891

Insured: SHC 8889P

at Workshop m/s Lai Huat

Tel: 64538110

of 160 Sh Ming Drive #04-01

Policy No:

Claim No: D19005627MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.9.19 11.03a.m

Person Contacted:

Jenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SBT 10891 - X

SHC 8889P - CS/FCI 19015636/f3

ROA - 23/08/2019

9/9/19

Email preli revised to FCI

1119 8824.18 Confirmed (Red 686.78, 4570) (No LS)

ASS. REC. BY:

REF: FOLKenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Ulink

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1-Bu % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBT 1088J Yr Regn: 01, 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy HIAS C.C. 1598Colour: 2 Silver A/C: Insured / Std / NI / NASp. Reading: 39981 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053RE14104542307Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 29/8/19

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 6/9/19

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 11 SEP 2019

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 11/9- typistDays Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

CWS

Lump Sum / I.B.I. (\$)

824.18

215



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005627MFSH

Our ref: CS/FCI19015636/Kvf3

Date : 9/9/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SBT 1089J


We thank for your instruction on 3/9/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 6/9/2019 at the premises of M/s LAI HUAT (MENG KEE) MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$1,510.96
Revised Estimate Amount	: S\$996.95
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	30-08-2019	Our Ref No. D19005627MFSH
Accident Date	29-08-2019	Claim Type. Third Party
Insured Vehicle	SHC8889P	Third Party Vehicle. SBT1089J
Survey Location	160 SIN MING DRIVE #04-01/#04-02/#07-03SIN MING AUTOCITY	
Contact Person.	JENNY LIM	
Contact No.	64538110/ 0	Fax No. 64596267
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LAI HUAT (MENG KEE) MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 9 September 2019 2:31 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19005627MFSH/1-SBT 1089J
Attachments: SBT 1089J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SBT 1089J

Date of survey: 6/9/2019

Number of days (estimated) : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 4 September 2019 11:05 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005627MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Tuesday, 3 September, 2019 5:46 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19005627MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S0182725A**
 Name: **QUEK HWAI KWANG**
 Birth Date: **30 Aug 1952**
 Issue Date: **11 Feb 2004**

001116672C

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S0182725A**



Name
QUEK HWAI KWANG

Race
CHINESE
Date of birth
30-08-1952
Country of birth
SINGAPORE

Sex
M

S0182725A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 2B Motorcycles <= 200 CC	11 Mar 1972
Class 2A Motorcycles between 201 CC and 400 CC	11 Mar 1972
Class 2 Motorcycles > 400 CC	11 Mar 1972
Class 3 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg	13 Apr 1972

S0182725A S / No. 9000290309

NP 428A

Licence No. S0182725A



5048481



NRIC No. **S0182725A**

Date of issue
13-06-2012

Address

**APT BLK 974 HOUGANG STREET 91
#08-228
SINGAPORE 530974**

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0023110
Quek Hwai Kwang

Page 1 of 1
Your ref. TP-SHC 8889P MS FC
Job No. 70824
Our ref. 19.08.38
Payment
Date 31/8/2019

Attn

Vehicle No SBT 1089J
Vehicle Model : Toyota Altis
Accident on ... 29/8/2019

Not Notified
Running B4 pain
2 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	482.00	25.00	361.50 ✓
1.00	Pc	Rear bumper reflector LH	56.90	25.00	42.68 ✓
1.00	Pc	Rear boot lid chrome moulding	230.37	25.00	172.78 X
1.00	Pc	Rear logo emblem	52.15	25.00	39.11 X
1.00	Pc	Rear Corolla emblem	42.35	25.00	31.76 X
1.00	Pc	Rear Altis emblem	44.17	25.00	33.13 X
Labour & Misc:					
1.00		To transfer rear camera	50.00		50.00 X
1.00		To knock dents on rear boot lid and renew of parts	300.00		300.00
1.00		To spray paint	480.00		480.00

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

1,510.96
105.77
S\$ 1,616.73

Acknowledged by Repairer
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19015636/Kvf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8889P	Veh. Inspected	SBT 1089J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005627MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	03/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104542307	Colour	METALLIC SILVER	
Odometer	39981	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	6 mm	
L/H Front Tyre	205/55 R16	DUNLOP	6 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2019	Inspection Date	06/09/2019	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBT 1089J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED	482.00	482.00
1	REAR BUMPER REFLECTOR LH	CRACKED	56.90	56.90
1	REAR BOOT LID CHROME MOULDING	SERVICEABLE	230.37	-
1	REAR LOGO EMBLEM	NOT NECESSARY	52.15	-
1	REAR COROLLA EMBLEM	NOT NECESSARY	42.35	-
1	REAR ALTIS EMBLEM	NOT NECESSARY	44.17	-
	LESS 25% DISCOUNT		-226.98	-134.72
			680.96	404.18
	LABOUR			
	TO TRANSFER REAR CAMERA.	NOT NECESSARY	50.00	-
	TO KNOCK DENTS ON REAR BOOT LID AND RENEW OF PARTS.		300.00	200.00
	TO SPRAY PAINT.		480.00	220.00
			830.00	420.00
	GRAND TOTAL		1,510.96	824.18
	RECOMMENDED COST OF REPAIRS			824.18

Report Ref No. CS/FC119015636/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.