



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE5505X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No **36672**
Reg No/Reg Date **SKE5505X / 13/02/2019**
Date In/Mileage **0**
Chassis No **WDD2050402R4570561**
Engine No **27491031605743**
Make/Model **MB/MB C 180 AVANTGARDE/AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 041 138 ARTICO Magm**

Account No	Terms	Date/Time Printed	CSE	Operator			
WI000576	Credit	02/09/2019/ 23:04	AQ	305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : PNPV2019-00003385 // 28-08-2019
DRIVE IN: 29-08-2019 // TP CAR NO: SHD3661G (INDIA INTERNATIONAL INS)

DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT

A BPILAB

REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL

A BPILAB

REMOVE & REPLACE EXHAUST SYSTEM / MUFFLER.

A BPILAB

RENEW REAR WINDSHIELD

S BPNSUB

SUPPLY 1PC REAR WINDSHIELD SOLAR FILM
PURCHASE ORDER NO:

A BPILAB

REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR

A BPILAB

TO SEAL PANEL JOINTS WITH SEALANT

S BPNSUB

SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT
PURCHASE ORDER NO:

A BPILAB

REMOVE & REPLACE DRIVER AND PASSENGER AIRBAG AND SAFETY BELT , RESET
WITH REPROGRAMMING.

A BPILAB

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document. No signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE5505X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No **36672**
Reg No/Reg Date **SKE5505X / 13/02/2019**
Date In/Mileage **1 / 0**
Chassis No **WDD2050402R4570561**
Engine No **27491031605743**
Make/Model **MB/MB C 180 AVANTGARDE/AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 041 138 ARTICO Magm**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WI000576	Credit	02/09/2019/ 23:04	AQ	305 / Alan Quek Ai Lun					
					REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE				
					A BPILAB			0.07	1000.00
					PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMEN				
					A BPILAB				540.00
					INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				
					A BPILAB				13440 15360.00
					REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER, REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER, REAR RIGHT FENDER, REAR END PANEL & REAR FRONT AND REAR SUPPORT ASSY COMPONENTS & REFINISH.				5400.
					A BPIRES			0.00	6500.00
					RESPRAYFRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER, FRONT RIGHT FENDER, FRONT LEFT DOOR, REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER, REAR RIGHT FENDER & REAR END PANEL				
					M LH/F HEADLAMP	1.00	3231.97	00.00	3231.97
					M LH/F HEADLAMP CONTROL UNIT	1.00	646.66	00.00	646.66
					M RADIATOR GRILLE SUPPORT	1.00	134.39	00.00	134.39
					M RADIATOR GRILLE GARNISH SUPPORT	1.00	174.16	00.00	174.16
					M RADIATOR GRILLE TOP LEFT GARNISH	1.00	65.91	00.00	65.91
					M RADIATOR GRILLE TOP RIGHT GARNISH	1.00	65.91	00.00	65.91
					M RADIATOR GRILLE BOTTOM LEFT GARNISH	1.00	81.43	00.00	81.43
					M RADIATOR GRILLE BOTTOM RIGHT GARNISH	1.00	81.43	00.00	81.43
					M BONNET	1.00	2083.09	00.00	2083.09
					M BONNET INSULATION	1.00	238.78	00.00	238.78
					M BONNET LEFT HINGE	1.00	189.58	00.00	189.58
					M BONNET RIGHT HINGE	1.00	189.58	00.00	189.58
					M BONNET ACTUATOR	2.00	189.21	00.00	378.42
					M BONNET SPRING ELEMENT	2.00	33.02	00.00	66.04
					M BONNET UPPER CATCH	1.00	34.18	00.00	34.18
					M BONNET LOWER CATCH	1.00	68.26	00.00	68.26
					M LH/F FENDER	1.00	909.44	00.00	909.44
					M RH/F FENDER	1.00	909.44	00.00	909.44

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE5505X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No **36672**
Reg No/Reg Date **SKE5505X / 13/02/2019**
Date In/Mileage **1 / 0**
Chassis No **WDD2050402R4570561**
Engine No **27491031605743**
Make/Model **MB/MB C 180 AVANTGARDE/AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 041 138 ARTICO Magm**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WI000576	Credit	02/09/2019/ 23:04	AQ	305 / Alan Quek Ai Lun					
					M LH/F WHEEL ARCH	1.00	124.78	00.00	124.78
					M FRT BUMPER	1.00	1557.32	00.00	1557.32
					M LH/F BUMPER BRACKET	1.00	12.19	00.00	12.19
					M LH/F BOTTOM GRILLE	1.00	64.78	00.00	64.78
					M FRT BUMPER TOP SEAL	1.00	27.55	00.00	27.55
					M CT/F BOTTOM GARNISH	1.00	172.46	00.00	172.46
					M LH/F PARKING SENSOR	2.00	176.11	00.00	352.22
					M LH/F PARKING SENSOR SEAL	2.00	6.35	00.00	12.70
					M LH/F BASIC CARRIER FOR BUMPER	1.00	97.04	00.00	97.04
					M FRT BOTTOM BASIC CARRIER FOR BUMPER	1.00	190.78	00.00	190.78
					M FRT TOP BASIC MOUNTING FOR BUMPER	1.00	86.01	00.00	86.01
					M FRT IMPACT ABSORBER	1.00	159.17	00.00	159.17
					M FRT PARKING SENSOR WIRING HARNESS	1.00	151.64	00.00	151.64
					M FRT PRESSURE SENSOR	1.00	117.30	00.00	117.30
					M LH/F BASIC CARRIER FOR BUMPER	1.00	97.04	00.00	97.04
					M LH/F SEAT BELT	1.00	689.16	00.00	689.16
					M RH/F SEAT BELT	1.00	689.16	00.00	689.16
					M LH/F SEAT BELT LOCK	1.00	137.81	00.00	137.81
					M RH/F SEAT BELT LOCK	1.00	137.81	00.00	137.81
					M LH/F SEAT BELT HEIGHT ADJUSTMENT	1.00	107.15	00.00	107.15
					M RH/F SEAT BELT HEIGHT ADJUSTMENT	1.00	107.15	00.00	107.15
					M LH/R SEAT BELT	1.00	413.57	00.00	413.57
					M RH/R SEAT BELT	1.00	413.57	00.00	413.57
					M REAR WINDSHIELD	1.00	1094.09	00.00	1094.09
					M REAR WINDSHIELD PAD	4.00	2.51	00.00	10.04
					M GLAZING REPAIR KIT	5.00	156.83	00.00	784.15
					M ADHESIVE SEALANT	3.00	776.81	00.00	2330.43
					M SRS CONTROL UNIT	1.00	933.06	00.00	933.06
					M SRS ACCELERATION SENSOR	2.00	136.78	00.00	273.56
					M LH/R EXHAUST MUFFLER	1.00	1379.92	00.00	1379.92
					M RH/R EXHAUST MUFFLER	1.00	1180.45	00.00	1180.45
					M LH/R EXHAUST MUFFLER BRACKET	1.00	119.37	00.00	119.37
					M LH/R EXHAUST MUFFLER INNER SHIELDING	1.00	167.85	00.00	167.85

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE5505X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No **36672**
Reg No/Reg Date **SKE5505X / 13/02/2019**
Date In/Mileage **/ 0**
Chassis No **WDD2050402R4570561**
Engine No **27491031605743**
Make/Model **MB/MB C 180 AVANTGARDE/AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 041 138 ARTICO Magm**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WI000576	Credit	02/09/2019/ 23:04	AQ	305 / Alan Quek Ai Lun					
					M LH/R EXHAUST MUFFLER OUTER SHIELDING	1.00	77.97	00.00	77.97
					M LH/R TAIL LAMP	1.00	702.52	00.00	702.52
					M RH/R TAIL LAMP	1.00	702.52	00.00	702.52
					M REAR LICENSE PLATE LAMP	2.00	28.84	00.00	57.68
					M REAR BUMPER	1.00	1635.44	00.00	1635.44
					M REAR BOTTOM PANEL	1.00	258.66	00.00	258.66
					M REAR BOTTOM PANEL GARNISH	1.00	291.84	00.00	291.84
					M LH/R BOTTOM BRACKET	1.00	33.30	00.00	33.30
					M RH/R BOTTOM BRACKET	1.00	33.96	00.00	33.96
					M REAR PARKING SENSOR	4.00	176.11	00.00	704.44
					M REAR PARKING SENSOR SEAL	4.00	6.35	00.00	25.40
					M REAR BOTTOM HANDFREE ASSIST BRACKET	1.00	39.80	00.00	39.80
					M REAR BOTTOM HANDFREE ASSIST COVER	1.00	104.89	00.00	104.89
					M REAR BOTTOM HANDFREE ASSIST SENSOR	1.00	133.40	00.00	133.40
					M REAR HANDFREE ASSIST CODE A WIRE	1.00	122.99	00.00	122.99
					M REAR HANDFREE ASSIST CODE B WIRE	1.00	122.99	00.00	122.99
					M REAR PARKING SENSOR WIRING HARNESS	1.00	130.18	00.00	130.18
					M CT/R BASIC MOUNTING FOR BUMPER	1.00	91.92	00.00	91.92
					M LH/R BASIC MOUNTING FOR BUMPER	1.00	56.64	00.00	56.64
					M RH/R BASIC MOUNTING FOR BUMPER	1.00	56.64	00.00	56.64
					M LH/R TOP BASIC MOUNTING FOR BUMPER	1.00	32.64	00.00	32.64
					M RH/R TOP BASIC MOUNTING FOR BUMPER	1.00	32.14	00.00	32.14
					M LH/R BUMPER SIDE BRACKET	1.00	55.82	00.00	55.82
					M RH/R BUMPER SIDE STABILITY	1.00	56.01	00.00	56.01
					M REAR BOOT LID	1.00	2127.67	00.00	2127.67
					M REAR BOOT LID SEAL	1.00	195.71	00.00	195.71
					M REAR BOOT LID INNER TRIM	1.00	231.33	00.00	231.33
					M REAR BOOT LID CLOSING ASSIST DRIVE UNIT	1.00	940.97	00.00	940.97
					M LH/R BOOT LID HINGE LEVER	1.00	249.05	00.00	249.05
					M RH/R BOOT LID HINGE LEVER	1.00	249.05	00.00	249.05
					M LH/R BOOT LID DRIVE UNIT BRACKET	1.00	81.77	00.00	81.77
					M REAR BOOT LID GARNISH	1.00	132.35	00.00	132.35
					M C180 EMBLEM	1.00	89.09	00.00	89.09

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKE5505X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No **36672**
Reg No/Reg Date **SKE5505X / 13/02/2019**
Date In/Mileage **0**
Chassis No **WDD2050402R4570561**
Engine No **27491031605743**
Make/Model **MB/MB C 180 AVANTGARDE/AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 041 138 ARTICO Magm**

Account No	Terms	Date/Time Printed	CSE	Operator				
WI000576	Credit	02/09/2019/ 23:04	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REAR STAR EMBLEM				1.00	47.69	00.00	47.69
M	GROMMET				3.00	2.20	00.00	6.60
M	REAR BOOT LID HANDLE MOLDING				1.00	208.53	00.00	208.53
M	REAR BOOT LID LOCK				1.00	287.44	00.00	287.44
M	REAR BOOT LID U-SHAPED STRIKER	photo			1.00	465.12	00.00	465.12
M	REAR BOOT LID U-SHAPED STRIKER DRIVE				1.00	173.56	00.00	173.56
M	REAR CROSS MEMBER				1.00	651.93	00.00	651.93
M	REAR SPARE WHEEL WELL	photo			1.00	538.00	00.00	538.00
M	REAR SPARE WHEEL WELL BOTTOM COVER				1.00	41.34	00.00	41.34
M	LOADING EDGE PANEL				1.00	131.12	00.00	131.12
M	LH/R BOOT LID COMPARTMENT SIDE TRIM				1.00	48.94	00.00	48.94
M	RH/R BOOT LID COMPARTMENT SIDE TRIM				1.00	48.94	00.00	48.94
M	REAR BOOT LID COMPARTMENT FLOOR BOARD				1.00	366.82	00.00	366.82
M	REAR END PANEL				1.00	1414.23	00.00	1414.23
M	LH/R FENDER				1.00	2196.72	00.00	2196.72
M	RH/R FENDER				1.00	2196.72	00.00	2196.72
M	REAR FENDER INSULATION				2.00	59.34	00.00	118.68
M	REAR FENDER AIR FLAP				2.00	25.79	00.00	51.58
M	LH/R WHEEL ARCH				1.00	184.18	00.00	184.18
M	RH/R WHEEL ARCH				1.00	184.18	00.00	184.18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cvcyclecarriage.com.sg

Confirmed & accepted by Repairer

Signature:
Date:

Nett **74,859.05**
7% GST on **74859.05** **5240.13**

Authorized signatory and company stamp

Total Payable 80,099.18

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany