

Our ref: SKE 5505X
Your ref: _____

Date: 23 OCT 2019 **Direct Settlement**

To: India International Insurance

Singapore 04 9711

Attn: Motor Claims Department

Re: **Accident Involving Motor Vehicle Nos.** SKE 5505X & SHD 3661G
At/Along Alexandra Rd Outside Delta Sport Complex **On** 28/08/19 @ 19:40

I am the owner of vehicle no. SKE 5505X that was involved in an accident with your insured vehicle no. SHD 3661G of the above accident.

As the accident was caused by your insured negligent/inconsiderate driving, thus I am claiming from you for the following: -

| | |
|---|----------------------------|
| 1. Cost of Repairs | \$ <u>68,466.69</u> |
| 2. Loss of Use / Rental (<u>36</u> days @ \$ <u>100</u> per day) | \$ <u>3,852</u> |
| 3. LTA/GIA Search Fee | \$ _____ |
| 4. GIA Report Fee | \$ _____ |
| 5. Others | \$ _____ |
| Total: | \$ <u>72,318.69</u> |

I hereby give you fourteen (14) days to comply with the above, failing which, I shall instruct my solicitor to commence legal action against you. If you have any queries, please contact the representative of **CYCLE & CARRIAGE INDUSTRIES PTE LTD** at Telephone No: **67714377 (Mr Alan Quek) / 67714304 (Ms Amanda Ang)**.

I hereby give full authority to CYCLE & CARRIAGE INDUSTRIES PTE LTD and their representative to negotiate/comprise settlement of the above claim on my behalf.

Your co-operation and immediate attention to the above is greatly appreciated. I hereby look forward to hearing from you soon.

Yours faithfully


Name & Signature

NOTE: This claim is Without Prejudice to our client's rights to claim for compensation for personal injury.


Address: C/o. 188 Pandan Loop Singapore 128378
Cc: Mr Alan Quek/ Ms Amanda Ang
E-mail: alan.quek@cyclecarriage.com.sg / amanda.ang@cyclecarriage.com.sg
Fax No. 67795383



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

| Invoice Name & Address | | | | Owner Name & Vehicle Info | | | |
|---|--------|-------------------|-----|---------------------------|--|------------------------|------------|
| INDIA INTERNATIONAL INSURANCE P/L | | | | Cust No/Name | WCV38852/Chin Jiayang, Kenneth (Chen Jia | | |
| ATTN: MOTOR CLAIM DEPARTMENT | | | | Reg No/Reg Date | SKE5505X / 13/02/2019 | | |
| 64 CECIL STREET | | | | Date In/Mileage | 05/09/2019/ 6644 | | |
| #04/#05 IOB BUILDING | | | | Chassis No | WDD2050402R4570561 | | |
| SINGAPORE 049711 | | | | Engine No | 27491031605743 | | |
| Contact No 63476100 | | | | Make/Model | MB/MB C 180 AVANTGARDE/AVANTGARDE | | |
|  | | | | Colour/Trim | 029 992 Selenite Gr/ 041 138 ARTICO Magm | | |
| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | Invoice/Credit Note No | |
| WI000576 | Credit | 22/10/2019/ 16:39 | AQ | 305 / Alan Quek Ai Lun | 36672 | 28159185 | |
| Description of Goods / Services | | | | | Qty | Unit Price S\$ | Amount S\$ |
| M BPNSUN | | | | | | | F.O.C. |
| POLICY NO/ACC DATE :PNPV2019-00003385 // 28-08-2019 | | | | | | | |
| DRIVE IN:29-08-2019 // TP CAR NO:SHD3661G (INDIA INTERNATIONAL INS) | | | | | | | |
| DATE IN/DATE SURVEY:03-09-2019 // LKK TAUFIKH | | | | | | | |
| BY/AUTHORIZED ON :VIVIAN LAU // 10-09-2019 | | | | | | | |
| A BPILAB | | | | | 0.10 | | 380.00 |
| USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO | | | | | | | |
| STANDARD SETTINGS.NETT | | | | | | | 120.00 |
| A BPILAB | | | | | | | 120.00 |
| CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT | | | | | | | |
| A BPILAB | | | | | | | 120.00 |
| CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT | | | | | | | |
| A BPILAB | | | | | | | 240.00 |
| REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL | | | | | | | |
| A BPILAB | | | | | | | 240.00 |
| REMOVE & REPLACE EXHAUST SYSTEM / MUFFLER. | | | | | | | |
| A BPILAB | | | | | 0.07 | | 560.00 |
| RENEW REAR WINDSHIELD | | | | | | | |
| S BPNSUB | | | | | | | 300.00 |
| SUPPLY AND INSTALL 1 PC HUPER OPTIK WINDOW | | | | | | | |
| FILM ON: REAR WINDSCREEN | | | | | | | |
| A BPILAB | | | | | | | 960.00 |
| REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR | | | | | | | |
| A BPILAB | | | | | | | 120.00 |
| TO SEAL PANEL JOINTS WITH SEALENT | | | | | | | |
| S BPNSUB | | | | | | | 60.00 |
| SUPPLY 1 PC NO PLATE | | | | | | | |
| A BPILAB | | | | | | | 1920.00 |
| REMOVE & REPLACE DRIVER AND PASSENGER AIRBAG AND SAFETY BELT , RESET | | | | | | | |
| WITH REPROGRAMMING. | | | | | | | |
| A BPILAB | | | | | | | 1920.00 |
| REMOVE & INSTALL REAR SUSPENSION & WHEEL BASE | | | | | | | |

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------------|---|
| INDIA INTERNATIONAL INSURANCE P/L | Cust No/Name WCV38852/Chin Jiayang, Kenneth (Chen Jia |
| ATTN: MOTOR CLAIM DEPARTMENT | Reg No/Reg Date SKE5505X / 13/02/2019 |
| 64 CECIL STREET | Date In/Mileage 05/09/2019/ 6644 |
| #04/#05 IOB BUILDING | Chassis No WDD2050402R4570561 |
| SINGAPORE 049711 | Engine No 27491031605743 |
| Contact No 63476100 | Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE |
| | Colour/Trim 029 992 Selenite Gr/ 041 138 ARTICO Magm |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | Invoice/Credit Note No |
|--|--------|-------------------|-----|------------------------|----------------|------------------------|
| WI000576 | Credit | 22/10/2019/ 16:39 | AQ | 305 / Alan Quek Ai Lun | 36672 | 28159185 |
| Description of Goods / Services | | | | Qty | Unit Price S\$ | Amount S\$ |
| A BPILAB | | | | | 0.07 | 1000.00 |
| PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMEN | | | | | | |
| A BPILAB | | | | | | 540.00 |
| INSPECT & CONDUCT WHEEL ALIGNMENT.NETT | | | | | | |
| A BPILAB | | | | | | 13440.00 |
| REMOVE & REPLACE FRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER, REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER, REAR RIGHT FENDER, REAR END PANEL & REAR FRONT AND REAR SUPPORT ASSY COMPONENTS & REFINISH. | | | | | | |
| A BPIRES | | | | | 0.02 | 5400.00 |
| RESPRAYFRONT BUMPER, FRONT BONNET, FRONT LEFT FENDER, FRONT RIGHT FENDER, FRONT LEFT DOOR, REAR BUMPER, REAR BOOT LID, REAR LEFT FENDER, REAR RIGHT FENDER & REAR END PANEL | | | | | | |
| X LH/F HEADLAMP | | | | 1.00 | 3231.97 | 3231.97 |
| X LH/F HEADLAMP CONTROL UNIT | | | | 1.00 | 646.66 | 646.66 |
| X RADIATOR GRILLE SUPPORT | | | | 1.00 | 134.39 | 134.39 |
| X BONNET | | | | 1.00 | 2083.09 | 2083.09 |
| X BONNET INSULATION | | | | 1.00 | 238.78 | 238.78 |
| X BONNET SPRING ELEMENT | | | | 2.00 | 33.02 | 66.04 |
| X BONNET UPPER CATCH | | | | 1.00 | 34.18 | 34.18 |
| X BONNET LOWER CATCH | | | | 1.00 | 68.26 | 68.26 |
| X LH/F FENDER | | | | 1.00 | 909.44 | 909.44 |
| X LH/F WHEEL ARCH | | | | 1.00 | 124.78 | 124.78 |
| X FRT BUMPER | | | | 1.00 | 1557.32 | 1557.32 |
| X LH/F BUMPER BRACKET | | | | 1.00 | 12.19 | 12.19 |
| X LH/F BOTTOM GRILLE | | | | 1.00 | 64.78 | 64.78 |
| X FRT BUMPER TOP SEAL | | | | 1.00 | 27.55 | 27.55 |
| X LH/F BASIC CARRIER FOR BUMPER | | | | 1.00 | 97.04 | 97.04 |
| X FRT IMPACT ABSORBER | | | | 1.00 | 159.17 | 159.17 |
| X RH/F SEAT BELT | | | | 1.00 | 689.16 | 689.16 |
| X LH/R SEAT BELT | | | | 1.00 | 413.57 | 413.57 |
| X RH/R SEAT BELT | | | | 1.00 | 413.57 | 413.57 |

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------------|---|
| INDIA INTERNATIONAL INSURANCE P/L | Cust No/Name WCV38852/Chin Jiayang, Kenneth (Chen Jia |
| ATTN: MOTOR CLAIM DEPARTMENT | Reg No/Reg Date SKE5505X / 13/02/2019 |
| 64 CECIL STREET | Date In/Mileage 05/09/2019/ 6644 |
| #04/#05 IOB BUILDING | Chassis No WDD2050402R4570561 |
| SINGAPORE 049711 | Engine No 27491031605743 |
| Contact No 63476100 | Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE |
| | Colour/Trim 029 992 Selenite Gr/ 041 138 ARTICO Magm |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | Invoice/Credit Note No |
|------------|--------|-------------------|-----|------------------------|--------|------------------------|
| WI000576 | Credit | 22/10/2019/ 16:39 | AQ | 305 / Alan Quek Ai Lun | 36672 | 28159185 |

| Description of Goods / Services | Qty | Unit Price S\$ | Amount S\$ |
|---------------------------------------|------|----------------|------------|
| X SRS CONTROL UNIT | 1.00 | 933.06 | 933.06 |
| X SRS ACCELERATION SENSOR | 2.00 | 136.78 | 273.56 |
| X LH/R TAIL LAMP | 1.00 | 702.52 | 702.52 |
| X RH/R TAIL LAMP | 1.00 | 702.52 | 702.52 |
| X REAR BUMPER | 1.00 | 1635.44 | 1635.44 |
| X REAR BOTTOM PANEL | 1.00 | 258.66 | 258.66 |
| X REAR BOTTOM PANEL GARNISH | 1.00 | 291.84 | 291.84 |
| X LH/R BOTTOM BRACKET | 1.00 | 33.30 | 33.30 |
| X RH/R BOTTOM BRACKET | 1.00 | 33.96 | 33.96 |
| X REAR PARKING SENSOR | 4.00 | 176.11 | 704.44 |
| X REAR PARKING SENSOR SEAL | 4.00 | 6.35 | 25.40 |
| X REAR BOTTOM HANDFREE ASSIST BRACKET | 1.00 | 39.80 | 39.80 |
| X REAR BOTTOM HANDFREE ASSIST COVER | 1.00 | 104.89 | 104.89 |
| X REAR SWITCH MODULE | 1.00 | 133.40 | 133.40 |
| X REAR HANDFREE ASSIST CODE A WIRE | 1.00 | 122.99 | 122.99 |
| X REAR HANDFREE ASSIST CODE B WIRE | 1.00 | 122.99 | 122.99 |
| X CT/R BASIC MOUNTING FOR BUMPER | 1.00 | 91.92 | 91.92 |
| X LH/R BASIC MOUNTING FOR BUMPER | 1.00 | 56.64 | 56.64 |
| X RH/R BASIC MOUNTING FOR BUMPER | 1.00 | 56.64 | 56.64 |
| X LH/R TOP BASIC MOUNTING FOR BUMPER | 1.00 | 32.64 | 32.64 |
| X RH/R TOP BASIC MOUNTING FOR BUMPER | 1.00 | 32.14 | 32.14 |
| X LH/R BUMPER SIDE BRACKET | 1.00 | 55.82 | 55.82 |
| X RH/R BUMPER SIDE STABILITY | 1.00 | 56.01 | 56.01 |
| X REAR BOOT LID | 1.00 | 2127.67 | 2127.67 |
| X REAR BOOT LID SEAL | 1.00 | 195.71 | 195.71 |
| X REAR BOOT LID INNER TRIM | 1.00 | 231.33 | 231.33 |
| X REAR BOOT LID GARNISH | 1.00 | 132.35 | 132.35 |
| X C180 EMBLEM | 1.00 | 89.09 | 89.09 |
| X REAR STAR EMBLEM | 1.00 | 47.69 | 47.69 |
| X GROMMET | 3.00 | 2.20 | 6.60 |
| X REAR BOOT LID HANDLE MOLDING | 1.00 | 208.53 | 208.53 |
| X REAR BOOT LID LOCK | 1.00 | 287.44 | 287.44 |
| X REAR BOOT LID U-SHAPED STRIKER | 1.00 | 465.12 | 465.12 |

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------------|---|
| INDIA INTERNATIONAL INSURANCE P/L | Cust No/Name WCV38852/Chin Jiayang, Kenneth (Chen Jia |
| ATTN: MOTOR CLAIM DEPARTMENT | Reg No/Reg Date SKE5505X / 13/02/2019 |
| 64 CECIL STREET | Date In/Mileage 05/09/2019/ 6644 |
| #04/#05 IOB BUILDING | Chassis No WDD2050402R4570561 |
| SINGAPORE 049711 | Engine No 27491031605743 |
| Contact No 63476100 | Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE |
| | Colour/Trim 029 992 Selenite Gr/ 041 138 ARTICO Magm |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | Invoice/Credit Note No |
|------------|--------|-------------------|-----|------------------------|--------|------------------------|
| WI000576 | Credit | 22/10/2019/ 16:39 | AQ | 305 / Alan Quek Ai Lun | 36672 | 28159185 |

| Description of Goods / Services | Qty | Unit Price S\$ | Amount S\$ |
|--|------|----------------|------------|
| X REAR CROSS MEMBER | 1.00 | 651.93 | 651.93 |
| X REAR SPARE WHEEL WELL | 1.00 | 538.00 | 538.00 |
| X REAR SPARE WHEEL WELL BOTTOM COVER | 1.00 | 41.34 | 41.34 |
| X LOADING EDGE PANEL | 1.00 | 131.12 | 131.12 |
| X LH/R BOOT LID COMPARTMENT SIDE TRIM | 1.00 | 48.94 | 48.94 |
| X RH/R BOOT LID COMPARTMENT SIDE TRIM | 1.00 | 48.94 | 48.94 |
| X REAR END PANEL | 1.00 | 1414.23 | 1414.23 |
| X LH/R FENDER | 1.00 | 2196.72 | 2196.72 |
| X REAR FENDER INSULATION | 2.00 | 59.34 | 118.68 |
| X REAR FENDER AIR FLAP | 2.00 | 25.79 | 51.58 |
| X FRT CROSS MEMBER | 1.00 | 423.49 | 423.49 |
| X LH/F CROSS MEMBER BRACKET | 1.00 | 73.35 | 73.35 |
| X FRT END SUPPORT MEMBER | 1.00 | 718.12 | 718.12 |
| X LH/F CROSS MEMBER ABSORBER | 1.00 | 202.53 | 202.53 |
| X FRT CONSOLE | 1.00 | 209.91 | 209.91 |
| X FRT CROSS MEMBER STRUT | 1.00 | 46.46 | 46.46 |
| X BONNET LATCH SWITCH | 1.00 | 42.00 | 42.00 |
| X RADIATOR GRILLE TOP LEFT GARNISH | 1.00 | 65.91 | 65.91 |
| X NUT | 4.00 | 5.37 | 21.48 |
| X RH/R FENDER | 1.00 | 2196.72 | 2196.72 |
| X FRT AIR DUCT | 1.00 | 127.48 | 127.48 |
| X LEFT ROOF MOULDING | 1.00 | 177.11 | 177.11 |
| X LH/R EXHAUST TAIL PIPE BRACKET | 1.00 | 97.89 | 97.89 |
| X PLUG | 2.00 | 5.06 | 10.12 |
| X REAR BOOT COMPARTMENT END FLOOR HOLDER | 1.00 | 104.77 | 104.77 |
| X REAR VOOT LID COMPARTMENT FLOOR BOARD | 1.00 | 151.64 | 151.64 |
| X LH/R BOOT LID HINGE LEVER | 1.00 | 249.05 | 249.05 |
| X RH/R BOOT LID HINGE LEVER | 1.00 | 249.05 | 249.05 |
| X RH/R WHEEL HOUSE STRUT | 1.00 | 113.03 | 113.03 |
| X REAR END FLOOR SUPPORT PANEL | 1.00 | 696.83 | 696.83 |
| X RH/R WHEEL HOUSE STRIKER PLATE | 1.00 | 275.00 | 275.00 |
| X ADHESIVE SEALANT | 2.00 | 776.81 | 1553.62 |
| X TWO-COMPONENT ADHESIVE | 2.00 | 102.00 | 204.00 |

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------------|---|
| INDIA INTERNATIONAL INSURANCE P/L | Cust No/Name WCV38852/Chin Jiayang, Kenneth (Chen Jia |
| ATTN: MOTOR CLAIM DEPARTMENT | Reg No/Reg Date SKE5505X / 13/02/2019 |
| 64 CECIL STREET | Date In/Mileage 05/09/2019/ 6644 |
| #04/#05 IOB BUILDING | Chassis No WDD2050402R4570561 |
| SINGAPORE 049711 | Engine No 27491031605743 |
| Contact No 63476100 | Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE |
| | Colour/Trim 029 992 Selenite Gr/ 041 138 ARTICO Magm |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | Invoice/Credit Note No |
|------------|--------|-------------------|-----|------------------------|--------|------------------------|
| WI000576 | Credit | 22/10/2019/ 16:39 | AQ | 305 / Alan Quek Ai Lun | 36672 | 28159185 |

| Description of Goods / Services | Qty | Unit Price S\$ | Amount S\$ |
|--|-------|----------------|------------|
| X SEAM SEAL | 2.00 | 104.99 | 209.98 |
| X BLIND RIVET | 12.00 | 1.29 | 15.48 |
| X BLIND RIVET W CSK. HEAD | 4.00 | 1.88 | 7.52 |
| X RIVET | 15.00 | 5.69 | 85.35 |
| X RIVET | 7.00 | 4.43 | 31.01 |
| X LH/R BOOT LID COMPARTMENT SIDE TRIM | 1.00 | 48.94 | 48.94 |
| X LH/R EXHAUST MUFFLER INNER SHIELDING | 1.00 | 167.85 | 167.85 |
| X REAR FENDER AIR FLAP | 1.00 | 25.79 | 25.79 |
| X HEXAGON NUT W COLLAR | 5.00 | 2.51 | 12.55 |
| X PIN | 2.00 | 1.23 | 2.46 |
| X RUBBER PLUG | 2.00 | 11.53 | 23.06 |
| X RETAINER WEDGE | 2.00 | 10.59 | 21.18 |
| X SCREW | 1.00 | 2.51 | 2.51 |
| X FRT TOP BASIC MOUNTING FOR BUMPER | 1.00 | 86.01 | 86.01 |
| X REAR WINDSHIELD | 1.00 | 1094.09 | 1094.09 |
| X SEAL RING | 3.00 | 2.51 | 7.53 |
| X GLAZING REPAIR KIT | 1.00 | 156.83 | 156.83 |
| X REAR BOOT COMPARTMENT FLOOR INSULATION | 1.00 | 108.00 | 108.00 |
| X RELAY FUSE | 1.00 | 36.85 | 36.85 |
| X CLIP | 2.00 | 4.74 | 9.48 |

*Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!*

| | | | |
|-----------------|-----------|---------------|-----------|
| Parts | 36,667.56 | Nett | 63,987.56 |
| Labour | 26,960.00 | 7% GST on | 4479.13 |
| Standard Menu | 0.00 | | |
| Specialist Job | 360.00 | Total Payable | 68,466.69 |
| Diagnostics Job | 0.00 | Paid | 0.00 |
| Sundry/Others | 0.00 | Total Due | 68,466.69 |
| Total(w/o GST) | 63,987.56 | | |

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

FLEXI-DRIVE ENTERPRISE

SKE5505X

Blk 8 Kaki Bukit Avenue 4 Premier@kaki bukit gate 2 #06-33 lobby C Singapore 415875




Tel: (65) 6292 5455 Fax: (65) 6292 2866 e-mail: sales@wellscope.com.sg

H/Phone : 9667 5455 (24 Hrs)

INVOICE

RA : 08946

ALAN.

| | | | |
|--|---------------------------------------|---|---|
| V. A. No. | Vehicle Regn. No. SMK 7128H | Model Type Mazda 3 | Renting Location 188 Pandan Loop C&C |
| Reference | Agreed Return Date | | 5 Hours = 1 Day Rental (1 Day Rental ÷ 5 = 1 Hour Extension) |
| \$ 107p/day x 26 Day | per Day \$ | per | Time / Date In 04 Oct 19 14:00hrs |
| \$ | per Week \$ | per | Time / Date Out 29/08/19 15:40 |
| \$ | per Month Cts | per Kilometre | Total / Time Chargeable |
| Hirer's Name Mr Chin Jiayang Kenneth | Rental Charges | | Dollars Cents |
| Address 42 Pasir Panjang Hill #02-04 Spore 118894 | Total 36 Days Rental | | \$107p/day x 26 Day |
| I/C No. | Tel. No. 94577411 | | |
| Reference Contact | Driver's Name AS ABOVE. | | Passport / IC No. / Country |
| Address | Driving Licence No. | | Expiry |
| | Issued by | | |
| | Additional Driver | | Tel. No. (Home) |
| Address | Passport / IC No. / Country | | |
| Driving Licence No. | Expiry | | Issued by |
| Method of Payment | | By: (Name in Block Letters) | |
| By TO: CIRCLE K CARRIAGE. IND P&F LTD 188 PANDAN LOOP. | | CASH | |
| - RATES QUOTED ARE FOR USE IN SINGAPORE ONLY. - THE HIRER IS SOLELY RESPONSIBLE FOR BREACH OF TRAFFIC LAWS AND ANY PARKING FINES OR SURCHARGES DURING PERIOD OF HIRE. | | Amount Due / Refundable | |
| Hirer's signature signifies acceptance of agreement | | Refund Received \$ | |
| X  | | by receiver X | |
| Hirer's Signature / Company Stamp | | Out by  | |
| Remarks | | In by  | |
| | | FRONT | |
| | | LH RH | |
| | | REAR | |
| | | CAR | |
| | | FRONT | |
| | | LH RH | |
| | | REAR | |
| | | MPV | |

NB: Please notify our office should there be any accident involving this hired vehicle as soon as possible.