

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

07/04/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 111

Xiao Tony

Accident date: 30/08/2019

Estimated repair cost for vehicle no: XD3817K HINO FS1ETKA

8312

CHASSIS: JHDFS1ETKXXX12004

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper Distorted		\$1,908.00 ✓
2	1	Front Bumper Lower Garnish Del'd		\$588.00 ✓
3	1	Front R/H Bumper Apron Panel Dist'd		\$358.00 ✓
4	1	Front Bumper Inner Frame New		\$835.00 X
5	1	Front R/H Bumper Side Garnish (BLACK) Missing		\$205.00 ✓
6	1	Front Grille Lower New		\$485.00 X
7	1	Front R/H Headlamp Cracked		\$1,980.00 ✓
8	1	Front R/H Headlamp Bracket Cracked		\$388.00 ✓
9	1	Front R/H Signal Lamp Cracked		\$335.00 ✓
10	1	Front R/H Corner Panel Cracked		\$650.00 ✓
11	1	Front R/H Corner Panel Inner Rubber New		\$85.00 X
12	1	Front R/H Door Distorted		\$3,850.00 ✓
13	1	Front R/H Door Lower Cover Cracked		\$535.00 ✓
14	1	Front R/H Door Euro4 Logo New		\$60.00 ✓
15	1	Front R/H Door Signal Lamp New		\$158.00 X
16	1	Front R/H Door Hinge Lower New		\$125.00 X
17	1	Front R/H Door Weather Strip New		\$385.00 X
18	1	Front R/H Upper Step Board New		\$395.00 X
19	1	Front R/H Upper Step Garnish Cracked		\$645.00 ✓
20	1	Front R/H Lower Step Board New		\$395.00 X
21	1	Front R/H Lower Step Garnish Del'd		\$670.00 ✓
22	1	Front R/H Lower Step Garnish Reflector New		\$35.00 X
23	1	Front R/H Lower Step Garnish Lamp New		\$230.00 X

12142

1082780

Subtotal :- \$15,300.00

Labour charges

To remove & refit front R/H door & components	\$280.00 120
To check wiring	\$100.00 50
Tuff kote	\$200.00 80
Panel beating	2250 \$1,200.00 800
Spray painting	\$1,800.00 1200

Subtotal :- \$3,580.00

Total:- \$18,880.00

Total 13177.80

2/s: 10.5K

06 Days

10.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: