

ADVANCE AUTO GARAGE

23 Kaki Bukit Avenue 4
VICOM KAKI BUKIT INSPECTION CENTRE
#04-01 SINGAPORE 415933
Tel: +65 9007 9247
Email: advanceag@hotmail.com
Reg No: 53395571L

TO	: INDIA INSURANCE	DATE	: 2/9/2019
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SGA2823R		
VEHICLE MODEL	: TOYOTA WISH		
CHASSIS NO	:		
ACCIDENT DETAILS	DATE	: 1/9/2019	
	TIME	: 1615HRS	
THIRD PARTY REQUESTOR / CONTACT	:	XAIVER	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR QUARTER GLASS MOULDING <i>new</i>	1	\$ 150.00	\$ 150.00
2	REAR BUMPER <i>torn</i>	1	\$ 665.00	\$ 665.00
3	REAR BUMPER SIDE RETAINER <i>new 2H</i>	2	\$ 90.00	\$ 180.00
4	REAR BUMPER AIR VENTS <i>new</i>	1	\$ 160.00	\$ 160.00
5	REAR TAIL LIGHT L/H <i>new</i>	1	\$ 520.00	\$ 520.00
6	REAR FENDER L/H <i>Repair</i>	1	\$ 1,000.00	\$ 1,000.00
7	REAR FENDER INNER COWLING L/H <i>torn</i>	1	\$ 238.00	\$ 238.00
8	REAR KNUCKLE BEARING L/H <i>new</i>	1	\$ 638.00	\$ 638.00
9	REAR SHOCK ABSORBER L/H <i>new</i>	1	\$ 310.00	\$ 310.00
10	REAR PASSENGER DOOR L/H <i>Dented</i>	1	\$ 1,400.00	\$ 1,400.00
11	REAR PASSENGER DOOR HINGE L/H <i>2 new</i>	2	\$ 90.00	\$ 180.00
12	REAR PASSENGER DOOR CHECKER L/H <i>new</i>	1	\$ 185.00	\$ 185.00
13	REAR PASSENGER DOOR WINDOW MOTOR L/H <i>new</i>	1	\$ 755.00	\$ 755.00
14	REAR PASSENGER DOOR WINDOW REGULATOR L/H <i>new</i>	1	\$ 260.00	\$ 260.00
15	REAR PASSENGER DOOR INNER LOCK L/H <i>new</i>	1	\$ 530.00	\$ 530.00
16	REAR PASSENGER DOOR INNER BOARD L/H <i>torn</i>	1	\$ 945.00	\$ 945.00
17	REAR PASSENGER DOOR INNER WEATHER STRIPE <i>new</i>	1	\$ 180.00	\$ 180.00
18	FRONT PASSENGER DOOR L/H <i>Distorted</i>	1	\$ 1,480.00	\$ 1,480.00
19	FRONT PASSENGER DOOR HINGE L/H <i>2 new</i>	2	\$ 90.00	\$ 180.00
20	FRONT PASSENGER DOOR CHECKER L/H <i>new</i>	1	\$ 185.00	\$ 185.00
21	FRONT PASSENGER DOOR WINDOW MOTOR L/H <i>new</i>	1	\$ 755.00	\$ 755.00
22	FRONT PASSENGER DOOR WINDOW REGULATOR L/H <i>new</i>	1	\$ 260.00	\$ 260.00

+
 ✓
 65
 x
 409.
 x
 145
 x
 1245
 x
 x
 x
 481
 ✓
 1075
 x
 x
 x
 2

23	FRONT PASSENGER DOOR INNER LOCK L/H <i>Not Nec</i>	1	\$	530.00	\$ 530.00	<i>x</i>
24	FRONT PASSENGER DOOR INNER BOARD L/H <i>Emblnd</i>	1	\$	945.00	\$ 945.00	<i>481</i>
25	FRONT PASSENGER DOOR INNER WEATHER STRIPE <i>Nec</i>	1	\$	180.00	\$ 180.00	<i>-</i>
26	ROCKER PANEL <i>Dented.</i>	1	\$	595.00	\$ 595.00	<i>-</i>

TOTAL PRICE: \$ 13,406.00
 LESS 25% \$ 3,351.50
 SUB TOTAL PRICE: \$ 10,054.50

6679
 5009.25

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR BUMPER CLIP (SET) <i>Nec</i>	3	\$ 20.00	\$ 60.00	<i>30</i>
2	REAR WHEEL TYRE L/H <i>Not Nec</i>	1	\$ 350.00	\$ 350.00	<i>x</i>
3	REAR WHEEL SPORT RIM L/H <i>Cut</i>	1	\$ 600.00	\$ 600.00	<i>450.</i>
4	REAR FENDER SEALANT <i>Not Nec</i>	1	\$ 100.00	\$ 100.00	<i>x</i>
5	REAR FENDER INNER COWLING L/H CLIP (SET) <i>Nec</i>	1	\$ 20.00	\$ 20.00	<i>-</i>
6	REVERSE SENSOR <i>Not Nec</i>	2	\$ 200.00	\$ 400.00	<i>x.</i>

500

TOTAL : \$ 1,530.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,800.00	<i>1200.</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>1000</i>	
3	WIRING CHECK FOR CENTRAL LOCKING	\$ 200.00	<i>30</i>	
4	TUFF COAT	\$ 200.00	<i>60.</i>	
5	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>	
6	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 300.00	<i>100</i>	
7	REMOVE AND REFIX FRONT DOOR WINDOW MECHANISM L/H	\$ 180.00	<i>80</i>	
8	REMOVE AND REFIX REAR DOOR WINDOW MECHANISM L/H	\$ 180.00	<i>80</i>	
9	REMOVE AND REFIX REAR L/H QUARTER GLASS	\$ 100.00	<i>x</i>	
10	WATER LEAKAGE TEST	\$ 150.00	<i>x</i>	
11	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATIONS	\$ 300.00	<i>x</i>	

2630

TOTAL: \$ 5,330.00

ESTIMATE REPORT

TOTAL PARTS COST:	\$	11,584.50
TOTAL LABOUR COST:	\$	5,330.00
TOTAL REPAIR COST:	\$	16,914.50

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

Adrian King,
H/s 03/09/15.

07 Days

total: 8139.25

1/5: 4.51c (Nett Value)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: