

ASS. REC. BY:

REF: CS/FCI/10015654/Utd3n2 Special Instruction:

Crew: Marcus
WS

ASSIGNMENT (Office)

From (Person): Karen Tan

of

Fei

Date/Time: 5:18pm @ 3/9/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJV 9780M

Insured:

SHC 2906M

at Workshop in/s

Zoom Autoworks

Tel:

of

130 Bedok Reservoir Road # 08-1339

Policy No:

Claim No:

D19005698MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31/8/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

105)

H.O.D. Endorsement:

Date/Time: 10:59am @ 4/9/19

Person Contacted:

Glin

Vehicle IN/OUT

Date/Time

Action/Instruction

Voluntary

Insp: 15/Kaki Bukit Rd 4 # 01-53

SJV 9780M - NA/INC/1905508/24

DOA: 31/8/2019

SHC 2906M - NA/INC/1905508/24

DOA: 31/08/2019

6/9@1:43pm Reused via email pending estimate

(08/1/13) wef
ASS. REC. BY: *MORIS*

REF:

201/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SVJ 9780M*
at Workshop m/s: *200N*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *22*
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *8* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: *MT 10532* Vehicle: IN / OUT

Veh No: *SVJ 9780M* Yr Regn: *3, 09*
Type: M/Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
Make: *Hyundai Avante* c.c. *1591*
Colour: *Grey* A/C: Insured / Std / NI / NA
Sp. Reading: *24371* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *KMH1DU41BR94 699678*
Gen. Cond: *8* Good / Fair / Poor / Burnt
Steering: *8* In order / Jammed / Leaked / Burnt or
Brake: *8* In order / Jammed / Leaked / Burnt or
Modi: *8* Nil / S/Rim / STD A/Rim or
Tyre Size: F: *215/45 R17*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *KumHo*
Front: *6* mm Rear: *6* mm
R/Bal. *6* mm L/Bal. *6* mm
D.O.A. *3.18/19* D.O.I. *4/9/19*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & Lp.
The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction

100 8-3-2024 LT A11468

RECEIVED 16 SEP 2019

1/9/19 *2/5 8200 confirmed with Elor.* (Red: 16282.04; 66%)
market value 22,000/-
CTA 114681-
Net value: 10532

Date/Time, File Pass to?

1) *16/9 Typist*

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: *8*

Resurvey No. of Trip: *1*

Survey Fees

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS (\$ _____)
☐ : Interview (\$ _____) ☐ : Photos *580*
☐ : Tech. Invs (\$ _____) ☐ : Others *580*
☐ : Weekend (\$ _____)

TOTAL *16/9/19*

Report Format: *TP*

Lump Sum / I.B.I. (\$) *8200*

170 + 210
50
50
129
609

MOTOR SURVEY ASSIGNMENT

Date	03-09-2019	Our Ref No. D19005698MFSH
Accident Date	31-08-2019	Claim Type. Third Party
Insured Vehicle	SHC2906M	Third Party Vehicle. SJV9780M
Survey Location	130 BEDOK RESERVOIR ROAD#08-1339	
Contact Person.	ELIN CAI	
Contact No.	0/ 94507920	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZOOM AUTOWERKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 6 September 2019 1:43 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005698MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJV 9780M on 4/9/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 4 September 2019 11:33 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005698MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 3 September 2019 5:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005698MFSH/1

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Post an Advertisement
Sell it yourself! Advertise It at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Honda Civic 1.6A



Low Mileage, Immaculate
Condition, View To Believe!
Direct Owner, No Reg.



Browse by Category ▾

« Back (1 2 3 4 5 6) Next »

Sort by Date Posted

106 vehicles

Avante

Refining Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Avante		Any	Any	2009	Any	Any	



Hyundai Avante 1.6M (COE till 05/2024)

\$23,998

\$5,080 /yr

20-Jun-2009

1,591 cc

-

Drive With Assurance! Genuine And Transparent Deal! Attractive Trade In/Flexible Bank/In House 100% Full Loan Monthly \$549, All Our Quality Consignment Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA Inspection Welcome! Fully Refurbished..

CarQuotz Singapore

Posted: 10-Sep-2019

Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai



Hyundai Avante 1.6A S (COE till 01/2024)

\$22,998

\$5,230 /yr

29-Jul-2009

1,591 cc

-

Drive With Assurance! Genuine And Transparent Deal! Attractive Trade In/Flexible Bank/In House 100% Full Loan Monthly \$545, All Our Quality Consignment Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA Inspection Welcome! Fully Refurbished..

CarQuotz Singapore

Posted: 10-Sep-2019

Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai



Hyundai Avante 1.6A S (New 5-yr COE)

\$25,800

\$5,150 /yr

12-Aug-2009

1,591 cc

-

100% Quality Buy, Full Loan Available At Monthly \$500 Plus, Interest Rate From 3.88%, Price Include New Paint/New Leather Seats, Rims, Showroom Condition Guarantee, Comes With 6 Months Engine And Gearbox Warranty, All Our Quality Pre-owned Car Are Selling..

Car World Automobile

Posted: 09-Sep-2019

Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai



Hyundai Avante 1.6A S (New 5-yr COE)

\$26,888

\$5,370 /yr

03-Oct-2009

1,591 cc

137,991 km

(Showroom Condition Assured!) Buy With Confidence From CaseTrust Accredited Dealer. Vehicle Fully Done Up With Premium Grooming And Brand New Paint Coat. Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance Coverage

Sincere Motoring Pte Ltd

Posted: 09-Sep-2019

Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai

**GET YOUR
COE
RENEWAL
LOA**

Compare

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town approval in 2 days without effort! Enquire today.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	407I

Vehicle Details

Vehicle No.:	SJV9780M
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Sep 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A S/R
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	G4FC9U607424
Chassis No.:	KMH DU41BR9U699678
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$12,345.00
Original Registration Date:	09 Mar 2009
First Registration Date:	09 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$11,062.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	08 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$11,468.00
Total Rebate Amount:	\$11,468.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Sep 2019

OK



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SJV9780M

Date: 04/09/2019

Model: Hyundai Advante

Damaged Area: (Front and Rear Portion Damaged)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

not Authorized
1/508200
4/9/19

Parts / Material :

		Quantity			
1	Front Bumper	480.60	1	\$76.80 X 2pcs	\$ 963.30 ✓
2	Front Bumper Side Retainer		1		153.60 X
3	Front bumper Reinforcement	431.50	1		514.20 ✓
4	Front Bumper Centre Air-Grille		1		315.20 X
5	Front Bumper Fog Lamp Garnish		1	\$105.00 X 2pcs	210.00 X
6	Front Bumper Fog Lamp		1	\$178.40 X 2pcs	356.80 X
7	Front Bumper Clips		1	\$4.00 X 10pcs	40.00 ✓
8	Front Grille	385.00	1		526.20 ✓
9	Front Grille Logo	39.00	1		61.00 ✓
10	Front Grille Clips		1	\$4.00 X 10pcs	40.00 X
11	Front Support Panel		1		1,365.20 X
12	Horn		1		71.00 X
13	Front Headlamp Assy	581.60 X 2 = 1163.20	1	\$852.00 X 2pcs	1,704.00 ✓
14	Front Headlamp Bracket		1	\$67.20 X 2pcs	134.40 X
15	Front Fender		1	\$523.20 X 2pcs	1,046.40 X
16	Front Fender Inner Shield		1	\$226.40 X 2pcs	452.80 X
17	Front Fender Inner Shield Clips		1	\$4.00 X 20pcs	80.00 X
18	Bonnet		1		1,125.50 ✓
19	Bonnet Lock		1		230.20 X
20	Bonnet Insulator		1		285.60 X
21	Front Bonnet Insulator Clips		1	\$4.00 X 10pcs	40.00 X
22	Bonnet Hinge		1	\$83.40 X 2pcs	166.80 X
23	AC Condenser Assy		1		1,198.50 X
24	Radiator Assy		1		1,236.20 X
25	Radiator Expansion Tank		1		68.60 X
26	Radiator Top Bracket		1	\$50.40 X 2pcs	100.80 X
27	AC Condenser Pipe (Big)		1		225.00 X
28	AC Compressor pipe (Small)		1		195.00 X
29	Rear Bumper	486.90	1		996.30 ✓
30	Rear Bumper Bracket	145.30	1	\$28.10 X 4	112.40 ✓
31	Rear Bumper Sponge		1		251.20 ✓
32	Rear Bumper Reinforcement Bracket	135.20 X 2 = 270.40	1	\$182.00 X 2pcs	364.00 ✓
33	Rear Bumper Reinforcement	35.4	1		541.20 ✓
34	Rear Bumper Clips		1	\$4.00 X 10pcs	40.00 ✓
35	Rear Bumper Reflector		1	\$31.00 X 2pcs	62.00 X
36	BootLid	907.60	1		1,425.60 ✓
37	Bootlid Badge	30.80	1		52.00 ✓
38	Bootlid outer Garnish		1		102.90 X
39	Bootlid Outer Garnish Clips		1	\$4.00 X 10pcs	40.00 X
40	Bootlid Number Plate Lamp		1	\$65.00 X 2pcs	130.00 X
41	Bootlid Lamp	285.00 X 2 = 570.00	1	\$392.50 X 2pcs	785.00 ✓
42	Bootlid Inner lock	183.60	1		285.90 ✓

17730.8

4897

43	Bootlid Catch		11	\$	75.20	X	
44	Bootlid weather Strip	165.30	1w1	\$	199.60	/	
45	Rear Taillamp	266.50 X 2 = 533	CNE	\$458.50 X 2pcs	\$	917.00	/
46	Rear Taillamp Panel		R	\$377.00 X 2pcs	\$	754.00	X
47	Rear End Panel	637.90	505500	\$	815.20	/	
48	Rear End Panel Top Garnish	188.60	CNE	\$	195.60	/	
49	Rear Fender Inner Shield		11	\$135.00 X 2pcs	\$	270.00	X
50	Rear Fender Inner Shield Clips		11	\$4.00 X 20pcs	\$	80.00	X
51	Spare Tyre Panel		R	\$	1,165.20	X	
52	Spare Tyre Top Board		11	\$	425.20	X	
				Parts :	\$	22,783.80	
				Less Parts 20% :	\$	4,556.76	
				Total Parts :	\$	18,227.04	

Special Net Items :

Reverse Sensor	1 set	shock	\$	250.00	200
Front Number Plate With Garnish		one	\$	55.00	40
Rear Number Plate With Garnish		11	\$	55.00	X
Rear Bootlid Panel Sealant		ME	\$	80.00	50
Radiator Coolant		11	\$	65.00	X
Total S/N Parts :			\$	505.00	

Labour :

To Remove & Renew Front Affected Accident Areas	\$	1,200.00	520
To Putty, Spray Paint on Front Affected Accident Areas	\$	1,200.00	400
To Check & Re-Connect all electrical wiring	\$	50.00	15
To Remove & Renew Rear Affected Accident Areas	\$	1,400.00	1100
To Putty, Spray Paint on Rear Affected Accident Areas	\$	1,200.00	1180
To Conduct AC Leakage Test & Top Up AC Gas	\$	11 150.00	X
To Re-position & Install Reverse Sensor	\$	150.00	50
To Re-Programme & Reset Diagnostic	\$	11 250.00	X
To Rust Proof Affected Areas	\$	150.00	80
Total Labour :		\$	5,750.00

TOTAL PARTS :	\$	18,227.04
TOTAL SPECIAL NET ITEM :	\$	505.00
TOTAL LABOUR :	\$	5,750.00
TOTAL REPAIR COST :	\$	24,482.04

24642.04.

8290.20
202
6632.16
10267.16
8213

DATE OF SURVEY / INSPECTED:
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

LMV Auto Consultants hence notify the Repairer of the following:

- To remove rust after spray painting
- To remove damaged control drums reservoir
- All work is subject to confirmation
- All work is subject to a "without prejudice" basis
- No other modification(s) is allowed
- Any warranty item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19015654/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2906M	Veh. Inspected	SVJ 9780M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005698MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	03/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U699678	Colour	GREY	
Odometer	243171	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	KUMHO	6 mm	
L/H Front Tyre	215/45 ZR17	KUMHO	6 mm	
R/H Rear Tyre	215/45 ZR17	KUMHO	6 mm	
L/H Rear Tyre	215/45 ZR17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2019	Inspection Date	04/09/2019	
Survey held at	15 KAKI BUKIT ROAD 4# 01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 9780M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DENTED / DEFORMED	963.30	480.60
2	FRONT BUMPER SIDE RETAINER @\$76.80	NOT NECESSARY	153.60	-
1	FRONT BUMPER REINFORCEMENT	DENTED	514.20	431.50
1	FRONT BUMPER CENTRE AIR-GRILLE	NOT NECESSARY	315.20	-
2	FRONT BUMPER FOG LAMP GARNISH @\$105.00	NOT NECESSARY	210.00	-
2	FRONT BUMPER FOG LAMP @\$178.40	NOT NECESSARY	356.80	-
10	FRONT BUMPER CLIPS @\$4.00	NECESSARY	40.00	40.00
1	FRONT GRILLE	CRACKED	526.20	385.00
1	FRONT GRILLE LOGO	NECESSARY	61.00	39.00
10	FRONT GRILLE CLIPS @\$4.00	NOT NECESSARY	40.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	1,365.20	-
1	HORN	NOT NECESSARY	71.00	-
2	FRONT HEADLAMP ASSY @\$852.00	CRACKED	1,704.00	1,163.20
2	FRONT HEADLAMP BRACKET @\$67.20	NOT NECESSARY	134.40	-
2	FRONT FENDER @\$523.20	NOT NECESSARY	1,046.40	-
2	FRONT FENDER INNER SHIELD @\$226.40	NOT NECESSARY	452.80	-
20	FRONT FENDER INNER SHIELD CLIPS @\$4.00	NOT NECESSARY	80.00	-
1	BONNET	BENT / BUCKLED	1,125.50	1,125.50
1	BONNET LOCK	NOT NECESSARY	230.20	-
1	BONNET INSULATOR	NOT NECESSARY	285.60	-
10	FRONT BONNET INSULATOR CLIPS @\$4.00	NOT NECESSARY	40.00	-
2	BONNET HINGE @\$83.40	NOT NECESSARY	166.80	-
1	AIR CONDENSER ASSY	NOT NECESSARY	1,198.50	-
1	RADIATOR ASSY	NOT NECESSARY	1,236.20	-
1	RADIATOR EXPANSION TANK	NOT NECESSARY	68.60	-
2	RADIATOR TOP BRACKET @\$50.40	NOT NECESSARY	100.80	-
1	AC CONDENSER PIPE (BIG)	NOT NECESSARY	225.00	-
1	AC COMPRESSOR PIPE (SMALL)	NOT NECESSARY	195.00	-
1	REAR BUMPER	DISTORTED	996.30	486.90
4	REAR BUMPER BRACKET LOWER @\$28.10	BENT	112.40	112.40

Report Ref No. CS/FCI19015654/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SPONGE	TORN	251.20	145.30
2	REAR BUMPER REINFORCEMENT BRACKET	BENT	356.00	270.00
1	REAR BUMPER REINFORCEMENT	CRACKED	541.20	354.00
10	REAR BUMPER CLIPS @\$4.00	NECESSARY	40.00	40.00
2	REAR BUMPER REFLECTOR @\$31.00	NOT FITTED	62.00	-
1	BOOTLID	BENT / BUCKLED	1,425.60	907.60
1	BOOTLID BADGE	NECESSARY	52.00	30.80
1	BOOTLID OUTER GARNISH	NOT NECESSARY	102.90	-
10	BOOTLID OUTER GARNISH CLIPS @\$4.00	NOT NECESSARY	40.00	-
2	BOOTLID NUMBER PLATE LAMP @\$65.00	NOT NECESSARY	130.00	-
2	BOOTLID LAMP @\$392.50	CRACKED	785.00	570.00
1	BOOTLID INNER LOCK	TWISTED	285.90	183.60
1	BOOTLID CATCH	NOT NECESSARY	75.20	-
1	BOOTLID WEATHERSTRIP	TWISTED	199.60	165.30
2	REAR TAILLAMP @\$458.50	CRACKED	917.00	533.00
2	REAR TAILLAMP PANEL @\$377.00	TO REPAIR SEE LABOUR	754.00	-
1	REAR END PANEL	BADLY DENTED	815.20	637.90
1	REAR END PANEL TOP GARNISH	CRACKED	195.60	188.60
2	REAR FENDER INNER SHIELD @\$135.00	NOT NECESSARY	270.00	-
20	REAR FENDER INNER SHIELD CLIPS @\$4.00	NOT NECESSARY	80.00	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,165.20	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	425.20	-
	LESS 20% DISCOUNT		-4,596.76	-1,658.04
			18,387.04	6,632.16
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	FRONT NUMBER PLATE WITH GARNISH (SN)	CRACKED	55.00	40.00
1	REAR NUMBER PLATE WITH GARNISH (SN)	NOT NECESSARY	55.00	-
1	REAR PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	65.00	-
			505.00	290.00

Report Ref No. CS/FCI19015654/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & RENEW FRONT AFFECTED ACCIDENT AREAS.		1,200.00	520.00
	TO PUTTY, SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS.		1,200.00	400.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.		50.00	15.00
	TO REMOVE & RENEW REAR AFFECTED ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR TAILLAMP PANEL AND SPARE TYRE PANEL.		1,400.00	1,100.00
	TO PUTTY, SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS.		1,200.00	1,180.00
	TO CONDUCT AC LEAKAGE TEST & TOP UP AC GAS.	NOT NECESSARY	150.00	-
	TO RE-POSITION & INSTALL REVERSE SENSOR.		150.00	50.00
	TO RE-PROGRAMME & RESET DIAGNOSTIC.	NOT NECESSARY	250.00	-
	TO RUST PROOF AFFECTED AREAS.		150.00	80.00
			5,750.00	3,345.00
	GRAND TOTAL		24,642.04	10,267.16

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,200.00
---	--	--	-----------------

Report Ref No. CS/FCI19015654/Utd3n2

MARKET VALUE: \$22,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$11,468.00=NETT VALUE: \$10,532.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.