

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5267Z**AAD1909-011***Not Withheld**Runway B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 SEP 2019

SHD 5267Z

JTDKB3FU803079365

TOYOTA

PRIUS

30.8.19

AIG

17/1/2019

		PART	LIST
1	1	REAR BUMPER	\$ CM 458.60 ✓
2	1	REAR BUMPER RE-INFORCEMENT	\$ B 318.80 ✓
3	1	REAR BUMPER TOWING COVER	\$ mis 14.70 X ✓
4	1	REAR BUMPER UNDER COVER (BLACK)	\$ CM 552.60 ✓
5	1	REAR BUMPER SIDE RETAINER LH	\$ pri 112.70 ✓
6	1	REAR BUMPER SIDE RETAINER RH	\$ su 112.70 X
7	1	REAR TAILGATE	\$ B 1,547.27 ✓
8	1	REAR TAILGATE OUTER GARNISH	\$ not com 905.10 ✓
9	1	ANTENNA, ELECTRICAL KEY	\$ su 61.40 X
10	1	COVER, REAR COMBINATION LAMP, RH	\$ su 54.70 X
11	1	COVER, REAR COMBINATION LAMP, RH	\$ su 54.70 X
12	1	GARNISH, BACK DOOR SIDE, LH	\$ su 93.60 X
13	1	GARNISH, BACK DOOR SIDE, RH	\$ su 93.60 X
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$ su 55.40 X
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$ su 55.40 X
16	1	BOARD ASSY, BACK DOOR TRIM	\$ 254.40 ?
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$ su 51.20 X
18	1	REAR TAILGATE WEATHERSTRIP	\$ su 365.20 X
19	1	PANEL SUB-ASSY, BODY LOWER BACK	\$ B 641.50 ✓
20	1	TAILLAMP LOWER RH	\$ su 548.40 X
21	1	TAILLAMP UPPER RH	\$ su 557.90 X
22	1	REAR BUMPER SIDE RH	\$ su 232.00 X
23	1	REAR BUMPER SIDE LH	\$ my cm 232.00 ✓
24	1	TAILLAMP LOWER LH	\$ 548.40 ?
25	1	TAILLAMP UPPER LH	\$ CM 557.90 ✓
26	1	REAR FENDER RH	\$ R 836.70 X
27	1	REAR FENDER LH	\$ R 836.70 X

Trans-cab Auto Services Pte Ltd

AAD1909-011

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5267Z

28	1	LINER, REAR WHEEL HOUSE, LH	\$	11	138.10	}
29	1	LINER, REAR WHEEL HOUSE, RH	\$	11	138.10	
30	1	BOARD, BACK DOOR TRIM	\$	12	220.70	
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	12	351.10	
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	12	351.10	
33	1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	11	292.20	
34	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	11	292.20	
35	1	COVER, FLOOR UNDER, NO.1	\$	12	172.60	
36	1	COVER, FLOOR UNDER, NO.2	\$	12	238.70	
37	1	COVER, REAR FLOOR	\$	12	226.80	
38	1	PAN, REAR FLOOR	\$	11	572.10	
39	1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	11	77.00	
40	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	11	192.90	
41	1	EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	11	77.00	
42	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	11	192.90	
43	1	PIPE ASSY, EXHAUST, TAIL	\$	11	1,409.20	
44	1	SUPPORT, EXHAUST PIPE, NO.4	\$	12	41.90	
45	1	SUPPORT, EXHAUST PIPE, NO.5	\$	12	41.90	
46	1	GASKET, EXHAUST PIPE	\$	12	45.60	
47	1	TROUGH, BACK DOOR OPENING, LH	\$	12	101.80	
TOTAL			\$		15,327.47	
25%			\$		3,831.87	
			\$		11,495.60	

Special Nett

1	1SET	PARKING AID	\$	Phat	700.00	2500
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	2	REAR WINDSCREEN SEALANT	\$	na	80.00	4000
4	1	WINDSCREEN MOULDING	\$	na	100.00	—
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	3000
6	1	REAR TAILGATE TOYOTA LOGO	\$	na	47.00	—
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90	—
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50	—
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00	3000
10	1	REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	3000
11	1	REAR BUMPER PROTECTOR	\$	na	100.00	X

Trans-cab Auto Services Pte Ltd

AAD1909-011

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5267Z

12	1	REAR WHEEL RIM	\$	1,570.55	} X
13	1	REAR WHEEL RIM COVER	\$	175.80	
14	1	SPARE WHEEL RIM	\$	1,570.55	
15	1	SPARE WHEEL RIM COVER	\$	175.80	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	
17	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	
18	1	REAR TYRE 195/65/15	\$	350.00	
TOTAL			\$	5,372.10	
TOTAL PARTS			\$	16,867.70	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	11001
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	7001
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	220.00	X

Trans-cab Auto Services Pte Ltd

AAD1909-011

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5267Z

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2 of
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Towing Fees	\$	nn 150.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
TOTAL	\$	19,140.00	
Over All Total	\$	36,007.70	

**LKK Auto Consultants hence notify
(PART-BY-PART) Repair Days**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25 Days**5 days**