

REC. REC. BY:

REP:

AIG (C3/AIG1905658/R191302

7043

ASSIGNMENT

From:

Date:

4/9/19

Estimated Cost:

OD TP WS TP RES OD RES EVA INV MV

To inspect Vehicle No: SGS 2156 M

at Workshop m/s Premium

of 24 Beroi sector

Insured:

Policy No. 2100394198-04

Claims No. 640458841456

Sum Insured:

Excess:

TBA 800

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

69K

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGS 2156M

Yr Regn: 2014 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

AWD N418TPS1 MU

C.C 1798

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

107946

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU228K8FA048868

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R16

R:

2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

02/09/19

D.O.I:

04/09/19

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SGS 2156M - X

04/9/19 @ 5.40pm revert to Victor via Messenger.

RECEIVED 04 FEB 2020

05/9/19 @ 5.18pm 2nd revert to Victor via Messenger. (repairer asking @ 18K & they said the owner had express his intention to repair his vehicle).

11/9/19 @ 4.47pm Victor informed of A at repair limit \$14400. If owner insist to repair his vehicle at Premium, Insured has to top up \$1800 of balance \$3600 & excess before GST. (ATE will pay \$1800 up ^{another} balance \$3600.) via messenger.

02/12/19 @ 3.11pm Email Carrier, repair limit \$14400, repairer agreed to repair @ 18K. Balance of \$3600 will bear by Insured & Insurance 50% each at \$1800.

Date/Time, File Pass (s):

☐

Preli. Report

Days Of Repair:

10

(Red \$1695, 48%)

04/2 transfer

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

200

Date/Time, File Return (s):

Transportation:

5 + RS - \$1

Phone

Others

11

TOTAL

211

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wheel align (\$

Report Format:

NER-01

Lump Sum / LBJ: \$

16200

(repair limit \$14400 + insurance top-up \$1800)

MCA 00 vehicle: SES 2156M DOA: 07/9/19

11/9/19 @ 5.33p informed TRAY CIA on US boats. & Ex: \$800.
And informed that insurance only approve at repair limit
\$14400. If owner insist to repair US vehicle at premium,
we need to top-up \$1800 of balance \$3600 & excess
before GST.

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 3 September 2019 4:38 PM
To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'
Cc: 'Claims'
Subject: RE: OD CLAIM FOR SGS 2156 M ON 2/9/2019

Dear all,

Please do take note that which the mentioned vehicle has tow to our 24 Benoi Sector.

For the arrangement survey location will be change to 24 Benoi. 04/09/2019@VEH IN.

Thanks

Best Regards,
T Roy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 3 September 2019 10:45 AM
To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIM FOR SGS 2156 M ON 2/9/2019

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 4/9/2019. Vehicle is in

Best Regards,

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 2 December 2019 3:11 PM
To: Carrine Leong
Cc: 'Boo seng yak'; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'; SUR
Subject: RE: FINAL CLOSURE - SGS2156M - OD AIG - SURVEYED 4 SEP 19 - RASUL

Dear Carrine,

WITHOUT PREJUDICE

Repair limit \$14,400.00.

Repairer agreed to repair at \$18,000.00.

Balance of \$3,600.00 will be bear by Insured and Insurance 50% each at \$1,800.00.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Friday, 29 November 2019 1:52 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL CLOSURE - SGS2156M - OD AIG - SURVEYED 4 SEP 19 - RASUL

Hi Shiau Chan,

Revised estimate is attached.

Please confirm repair cost of \$18,000.00 @ 10 days of repairs exclude 2 Sundays.

(For this case insurance approve repair limit \$14,400.00, balance of \$3600.00 owner and insurance need to top up \$1800.00)

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Friday, 25 October 2019 1:36 PM
To: Adrian Ling (LKKAUTO); Shiau Chan (LKKAUTO); SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL CLOSURE - SGS2156M - OD AIG - SURVEYED 4 SEP 19 - RASUL
Attachments: WhatsApp Image 2019-09-18 at 3.42.34 PM.jpeg; WhatsApp Image 2019-09-18 at 3.42.32 PM.jpeg; WhatsApp Image 2019-09-18 at 3.42.33 PM.jpeg; WhatsApp Image 2019-09-18 at 3.42.34 PM (1).jpeg

Hi Adrian, Rasul and all,

We have completed repairing the above vehicle on Lump Sump \$14,400.00 @ 10 days of repairs exclude 2 Sundays.

Attached, B4 paint photographs.

We appreciated your approval for us to proceed billing with a view to close file earlier.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 11 September 2019 5:33 PM
To: Claims
Cc: SUR
Subject: RE: OD CLAIM FOR SGS 2156 M ON 2/9/2019

Dear TRoy,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SGS 2156M at repair cost on Lump Sum basis (Excess \$800/-)**.

Please be informed that insurance only approve at repair limit \$14,400.00. If owner insist to repair his vehicle at your workshop, he need to top up half of the balance \$3,600.00 which is \$1,800.00 before excess and GST.

Kindly contact our surveyor to conduct resurvey and take damages photo of NOISE INSULATION, RADIATOR, LOCK CARRIER.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

***Our client reserve their right not to pay if there is no valid approval obtained before repair.**

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Sent: Tuesday, 10 September 2019 9:55 AM

To: Claims <claims@premiumauto.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OD CLAIM FOR SGS 2156 M ON 2/9/2019

Dear TRoy,

Please be informed that we are still pending for Insurance's approval. Once approve, we will send you an email.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 9 September 2019 7:26 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SGS 2156 M ON 2/9/2019

Dear Shiau Chan,

Any update for the mentioned case?

Thanks

Best Regards,
TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Premiumauto Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Thursday, 5 September 2019 4:52 PM
To: 'Shiau Chan (LKKAUTO)'
Cc: 'SUR'; Claims
Subject: RE: OD CLAIM FOR SGS 2156 M ON 2/9/2019

Dear Shiau Chan,

Our client has express his intention to have his vehicle repair back. We seek your kind understanding on this.

Therefore, we counter propose lump sum repair for this vehicle at \$18,000.00

Thank you in advance.

Best Regards,
TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	03 Sep 2019 10:36	Cim Veh Model Changed			[] Merimen Administrator
2	03 Sep 2019 10:36	Cim Created	Reg No: SGS2156M, Policy No: 2100394198-04, Acct Date: 2019/09/02, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119116432		[I] Merimen Administrator
3	04 Sep 2019 15:53	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD,		[] LEE SU THING
4	04 Sep 2019 15:53	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[] LEE SU THING
5	04 Sep 2019 15:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] LEE SU THING
6	04 Sep 2019 15:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/13		[A] LEE SU THING
7	04 Sep 2019 15:53	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.		[A] LEE SU THING
8	04 Sep 2019 15:53	Cim Registration Modified	Rep:1137->200611.		[A] LEE SU THING
9	04 Sep 2019 15:53	Cim Veh Model Changed	(201405) AUDI A4 1.8 TFSI MU Ambition (A).		[A] LEE SU THING
10	04 Sep 2019 15:53	Adj Adjuster Assigned	[None] -> MOHD RASUL		[A] LEE SU THING
11	04 Sep 2019 17:05	Adj Rpt Initiated			[A] SHIAU CHAN
12	04 Sep 2019 17:05	Cim Dtl Modified	JPJ Reg. Date: -> 2014/11/28.		[A] SHIAU CHAN
13	04 Sep 2019 17:05	Cim Details Notified			[A] SHIAU CHAN
14	04 Sep 2019 17:39	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/13		[A] SHIAU CHAN
15	04 Sep 2019 17:40	Adj Mandate Request	Cur.Req:27920.50:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
16	05 Sep 2019 17:14	Adj Mandate Request Cancelled			[A] SHIAU CHAN
17	05 Sep 2019 17:17	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/13		[A] SHIAU CHAN
18	05 Sep 2019 17:18	Adj Mandate Request	Cur.Req:27920.50:DAMAGES CONSISTENT. ACCORDING TO THE REPAIRER THAT THE OWNER HAD EXPRESS HIS INTENTION TO REPAIR HIS VEHICLE AND REPAIRER ASKING REPAIR COST AT \$18,000.00. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
19	10 Sep 2019 14:56	Cim Registration Modified	Init.Est.->5,000 - 6,000.		[I] Gan, Hunchung
20	11 Sep 2019 09:32	Cim Registration Modified	Excess: -> 800.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.		[I] Gan, Hunchung
21	11 Sep 2019 09:32	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
22	11 Sep 2019 11:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/13, Mandate Remarks: Upload damage photos of Noise insulation, Radiator, Lock carrier, Re-inspection to be done for damage check and supplementary items / labour;		[I] Koh, Victor-CK
23	11 Sep 2019 11:15	Adj Mandate Set	Approved:22213.50:Upload damage photos of Noise insulation, Radiator, Lock carrier, Re-inspection to be done for damage check and supplementary items / labour, Reinsp:Yes.		[I] Koh, Victor-CK
24	11 Sep 2019 16:47	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/09/13, Mandate Remarks: Repair limit at \$14,400.00. If owner insist to repair at Premium, Insured has to top up half of the balance \$3600 which is \$1800 b/f excess and GST. Upload damage photos of Noise insulation, Ra		[I] Koh, Victor-CK
25	11 Sep 2019 16:47	Adj Mandate Set	Approved:14400.00:Repair limit at \$14,400.00. If owner insist to repair at Premium, Insured has to top up half of the balance \$3600 which is \$1800 b/f excess and GST. Upload damage photos of Noise insulation, Radiator, Lock carrier, Re-inspection		[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2269722	04 Sep 2019 17:05:00	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGS2156M		11.77

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khoo, Kay-Eng

Date: 05 Sep 2019

Preliminary Advice

Vehicle No	: SGS2156M	Accident Date	: 02/09/2019
Make	: AUDI A4	Policy No.	: 2100394198-04
Assignment Date	: 04/09/2019	Excess	: S\$0.00
Date of Inspection	: 04/09/2019	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,925.00
Revised Amount	:S\$	22,213.50
Check Items (Estimated)	:S\$	5,707.00
Total	:S\$	27,920.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	69,000.00
COE / PARF Rebate	:S\$	54,554.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,446.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : ACCORDING TO THE REPAIRER THAT THE OWNER HAD EXPRESS HIS INTENTION TO REPAIR HIS VEHICLE AND REPAIRER ASKING REPAIR COST AT \$18,000.00.

Shiau Chan (LKKAuto)

From: Premiumauto Claims <claims@premiumauto.com.sg>
Sent: Thursday, 5 September 2019 4:52 PM
To: Shiau Chan (LKKAuto)
Cc: SUR; Claims
Subject: RE: OD CLAIM FOR SGS 2156 M ON 2/9/2019

Dear Shiau Chan,

Our client has express his intention to have his vehicle repair back. We seek your kind understanding on this.

Therefore, we counter propose lump sum repair for this vehicle at \$18,000.00

Thank you in advance.

Best Regards,
TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 5 September, 2019 8:54 AM
To: Claims <claims@premiumauto.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SGS 2156 M ON 2/9/2019

Dear TRoy,

Kindly advise whether your workshop able to repair the vehicle within repair limit \$14,000.00.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 04 Sep 2019

Preliminary Advice

Vehicle No	: SGS2156M	Accident Date	: 02/09/2019
Make	: AUDI A4	Policy No.	: 2100394198-04
Assignment Date	: 04/09/2019	Excess	: S\$0.00
Date of Inspection	: 04/09/2019	Est. Duration of Repair	: 10.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,925.00
Revised Amount	:S\$	22,213.50
Check Items (Estimated)	:S\$	5,707.00
Total	:S\$	27,920.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	69,000.00
COE / PARF Rebate	:S\$	54,554.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,446.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	704J
Vehicle Details	
Vehicle No.:	SGS2156M
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU (EU6)
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	CJE090532
Chassis No.:	WAUZZZ8K8FA048868
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$28,946.00
Original Registration Date:	28 Nov 2014
First Registration Date:	28 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$22,525.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2024
PARF Rebate Amount:	\$16,893.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,201.00
COE Rebate Amount:	\$37,661.00
Total Rebate Amount:	\$54,554.00

The information contained herein is correct as at 04 Sep 2019

OK



Deliver
Superior
Safety in W...



2.7" LCD
FULL HD
1080P HEL...



Quality Air
Filter For
Nissan Cars



8.5" Model
Unit With
GPS. Free...


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Sporty White Mercedes-Benz CLA180 Urban On Offer.



5 Units CLA180. C&C Warranty.
Low Mileage, High Trade In. In
House Finance Avail.
Speedo Motoring (Star42)



Browse by Category

Sort by Date Posted

20 results/page

5 vehicles

AUDI A4

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	AUDI A4		Any	Any	2014	Any	Any	Any	Available
	Audi A4 1.8A TFSI MU		\$67,800	\$11,330 /yr	30-Aug-2014	1,798 cc	59,339 km	Luxury	Available
Graded B by STP Promo 1.98% Interest Rate! Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident-Free Quality Pre-Owned With Low Mileage Done And Agent Service History For Peace Of Mind. 100% Loan Approval With Our F... Cosmo Automobiles Posted: 04-Sep-2019 Tags: 2014 Audi A4, 2014 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi									
	Audi A4 1.8A TFSI MU		\$64,800	\$11,230 /yr	27-Mar-2014	1,798 cc	71,339 km	Luxury	Available
Graded B by STP Promo 1.98% Interest Rate! Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident-Free Quality Pre-Owned With Low Mileage Done And Agent Service History For Peace Of Mind. 100% Loan Approval With Our F... Cosmo Automobiles Posted: 02-Sep-2019 Tags: 2014 Audi A4, 2014 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi									
	Audi A4 1.8A TFSI MU		\$70,800	\$11,220 /yr	24-Dec-2014	1,798 cc	63,000 km	Luxury	Available
Low Mileage, 1 Owner, Full Agent Maintained. Comes With Warranty And 1 Year Servicing Package. Call Now For Viewing. Posted: 30-Aug-2019 Tags: 2014 Audi A4, 2014 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi									
	Audi A4 1.8A TFSI MU		\$65,800	\$10,930 /yr	29-Aug-2014	1,798 cc	86,692 km	Luxury	Available
Comfortable Interior With A Classy Exterior! Don't Miss This Deal! Only 2 Owners. This Car Is Very Well Maintained And Taken Care Of, With Regular Servicing And Low Mileage. 6 Months Warranty! Buy With A Peace Of Mind. We Provide High Loan Schemes With Attractiv... Tradet.Com Pte Ltd Posted: 24-Aug-2019 Tags: 2014 Audi A4, 2014 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi									
	Peek a sportier-looking CLA-Class The Mercedes-Benz CLA200 AMG Line adds a touch of sporty equipment without taking away from the car's innate comfort, stylishness and daily capability. Find out more!								
	Audi A4 1.8A TFSI MU		\$69,998	\$12,010 /yr	15-May-2014	1,798 cc	58,000 km	Luxury	Available
Probably The Best Condition Audi A4 In The Market! Good Buy! Best Deal! \$0 Downpayment! Balloon Scheme Available! Original Owner's Condition! Nearly New Condition! No Repair Needed! Accident-Free! Up To 3 Years Unlimited Mileage Warranty! High Trade In! Flexible... 007 Posted: 09-Jul-2019 Tags: 2014 Audi A4, 2014 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

20 results/page

Compare

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2019 10:11
Date Of Accident	02/09/2019 19:45
Exact Location Of Accident	MINDEF TAXI STAND
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGS2156M
Insured/Policyholder	
Name Of Registered Owner	JOSEPH PEH CHIN LEONG
NRIC No	S8200704J
Email Address	PEH.JOSEPH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93638470
Alternative Phone No	OFFICE-93638470

Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.8T FSI MU 8K203
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100394198-04
Cover Note Number	

Driver

Name of Driver	JOSEPH PEH CHIN LEONG
NRIC No	S8200704J
Date Of Birth	01/01/1982
Occupation	INDOOR
Date Of Driving Pass	12/02/2007
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93638470
Fax Number	
Contact Number	OFFICE-93638470
Email Address	PEH.JOSEPH@GMAIL.COM

Address	7 SKY HABITAT #05-06
Postcode	573908
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I LEFT MINDEF AT ABOUT 7.40PM, TO HEAD TO SERANGOON. AS I TOOK THE RIGHT TURN AS SHOWN, I STARTED TO COUGH. SPEED WAS ABOUT 15KM/H OR LESS. I COULDN'T STOP COUGHING SO I WANTED TO VEER RIGHT TO THE WAITING BAY TO GET MY LOZENGES AND DRINK WATER. BUT I DID NOT VEER RIGHT SUFFICIENTLY (PARTIALLY BECAUSE I WAS STILL COUGHING) AND HIT 2 METAL BARRIERS. THIS WAS AT 7.45PM, I STOPPED TO INSPECT THE DAMAGES. AS THERE WAS NO ONE AROUND, I LEFT THE AREA AND DROVE HOME, AS THE VEHICLE LOOKED SERVICEABLE. I HAVE CONTACTED MINDEF - GOMBAK BASE TO REPORT THE DAMAGES OF THE METAL BARRIERS. AFTER I GOT HOME, THE "COOLANT" LAMP LIT, AND I SAW THAT IT WAS LEAKING. THAT'S WHEN I CALLED FOR TOW. NO VIDEO OR PHOTOS OF INCIDENT AREA AS I'M AN EMPLOYEE OF THE SAF. CAR NOT FITTED WITH RECORDER, AND I WAS USING A NON-CAM PHONE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:
3/9/19 0630hrs.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Colt S. M. Wong
NRIC/VIN No: G657726

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ① I left MINDEF at about 7.40pm, to head to Damansara.
- ② As I took the right turn as shown, I started to cough. Speed was about 15 km/h, or less.
- ③ I couldn't stop coughing so I wanted to veer right to the waiting bay to get my bottles and drink water.
- ④ But I did not veer right sufficiently (partially because I was still coughing) and hit 2 metal barriers. This was at around 7.45pm.
- ⑤ I stopped to inspect the damages as there was no one around. I left the area and drove home, as the vehicle looked serviceable.
 - I have contacted MINDEF - Gombak base to report the damages of the metal barriers.
 - After I got home, the "cockpit" lamp lit, and I saw that it was leaking/leaking. That's when I called for tow.
- ⑥ No video or photos of incident area as I'm an employee of the SAF. Car not fitted with recorder, and I was using a non-cam phone.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

3/4/19 0930hrs.

SAF & SAF Insurance, Ltd.

Driver's Signature

(if driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Evelyn Siew Han, Wang

NRIC/FIN No: 6152 7702

Accident Photo



Accident Photo



Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10889

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1058/2019/TG
Date : 3-Sep-19

Vehicle IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 62564315

Owner's Name : Mr. Joseph Peh Chin Leong
Address : 7 Bishan Street 15
#05-06
Singapore 573908
Telephone : (HP)+65 93638470
Type of Claim : Own Damage Claim
Policy No. : 2100394198-04
Vehicle No : **SGS 2156 M**
Model Code : Audi 1.4 1.8 TFSI MU (A)
Model / Year : 11/11/2014
Engine No : CJE 090532
Chassis No : WAUZZZ8K8FA048868
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Feb-19
Place of Accident : Mindef Taxi Stand

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 2156 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and recover vehicle from scene of accident.	S/N \$ 280.00	
2	To remove, check and reinstall front wire harness for headlight, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	
3	To remove and renew aircon condenser, charge air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	
4	To dismantle and renew front bumper, bonnet, lhs front fender, lhs headlight. Renew front lock	\$ 5,220.00 3000	
SUB TOTAL LABOUR CHARGES		: \$ 7,060.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 2156 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
5	To respray front bumper, lhs front fender and bonnet.	S 3,300.00 1650	
6	To carry out wheel alignment. To inspect lhs front suspension for further damages.	S/N S 240.00 ? X 11	
7	To carry out diagnostic checks.	S/N S 192.00	
TOTAL LABOUR CHARGES		: <u>S 10,792.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2156 M

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	FRONT BUMPER <i>70Rn /</i>	S	2,100.00	1680.00
2	FRONT BUMPER FIXING PARTS <i>ne /</i>	S	234.00	187.20
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>cm /</i>	S	207.00	165.60
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>cm /</i>	S	123.00	98.40
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>? X SUC</i>	S	177.00	X
6	RADIATOR GRILLE <i>Brn /</i>	S	1,005.00	804.00
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>MCS /</i>	S	123.00	98.40
8	FRONT BUMPER VENT GRILLE - RH <i>MCS /</i>	S	123.00	98.40
9	FRONT BUMPER WHEEL SPOILER - LH / RH <i>sun /</i>	2 S	90.00	72.00
10	FRONT BUMPER REINFORCEMENT <i>bt /</i>	S	802.00	641.60
11	FRONT BUMPER FOAM FILLER PIECE <i>cm /</i>	S	113.00	90.40
12	FRONT BUMPER COVER <i>? X SUC</i>	S	116.00	X
13	FRONT BUMPER BRACKET - LH <i>X SUC</i>	S	207.00	X
14	FRONT BUMPER SUPPORT <i>X SUC</i>	2 S	23.00	X
15	FRONT BUMPER GUIDE SECTION - LH <i>cm /</i>	S	33.00	26.40
16	FRONT FENDER - LH <i>bt /</i>	S	904.00	723.20
17	FRONT FENDER ATTACHEMENT PARTS <i>ne /</i>	S	52.00	41.60
18	FRONT FENDER BRACKET - LH <i>ne /</i>	S	48.00	37.92
19	DEFORMATION ELEMENT BRACKET - REAR LH <i>X SUC</i>	S	45.00	X
20	FRONT FENDER BRACE - LOWER LH <i>bt /</i>	S	107.00	85.60

SUB TOTAL SPARE PARTS

: \$ 6,632.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2156 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	STONE CHIP GUARD <i>acc /</i>	\$ 67.00	<i>52.96 ✓</i>
22	FRONT FENDER ADHESIVE TAPE <i>X nn</i>	\$ 50.00	<i>X</i>
23	FRONT WHEEL HOUSING LINER <i>ca ✓</i>	\$ 223.00	<i>178.40 ✓</i>
24	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS <i>acc /</i>	\$ 41.00	<i>32.80 ✓</i>
25	BONNET <i>bt ✓</i>	\$ 2,549.00	<i>2039.20 ✓</i>
26	BONNET ATTACHEMENT PARTS <i>? X nn</i>	\$ 152.00	<i>X</i>
27	BONNET CATCH HOOK <i>X svc</i>	\$ 127.00	<i>X</i>
28	BONNET GAS FILLED STRUT - LH <i>X svc</i>	\$ 109.00	<i>X</i>
29	BONNET EDGE PROTECTION - FRONT <i>X svc</i>	\$ 25.00	<i>X</i>
30	BONNET LID LOCK <i>X svc</i>	\$ 196.00	<i>X</i>
31	BONNET LID LOCK CABLE - FRONT / REAR <i>X svc</i>	\$ 111.00	<i>X</i>
32	SIGNAL HORN - HIGH TONE LH <i>X svc</i>	\$ 184.00	<i>X</i>
33	SIGNAL HORN SPRING SHACKLE - HIGH TONE LH <i>X svc</i>	\$ 23.00	<i>X</i>
34	HEADLIGHT MOUNTING - LH <i>ca ✓</i>	\$ 107.00	<i>85.60 ✓</i>
35	HEADLIGHT BRACKET - LH <i>ca ✓</i>	\$ 96.00	<i>76.56 ✓</i>
36	HEADLIGHT - LH <i>sc ✓</i>	\$ 2,152.00	<i>1721.60 ✓</i>
37	DRIVING LIGHT POWER MODULE <i>? X svc</i>	\$ 520.00	<i>X</i>
38	GAS DISCHARGE LAMP CONTROL UNIT <i>? X svc</i>	\$ 1,051.00	<i>X</i>
39	GAS DISCHARGE LAMP <i>? X svc</i>	\$ 398.00	<i>X</i>
40	HEADLIGHT HOSE - LH <i>X svc</i>	\$ 32.00	

SUB TOTAL SPARE PARTS

: \$ 8,213.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2156 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	HEADLIGHT RETAINING PLATE - LH <i>ca</i> ✓	\$ 22.00	<i>17.12</i> ✓
42	HALOGEN FOG LAMP - LH <i>MIS</i> ✓	\$ 242.00	<i>193.60</i> ✓
43	HEADLIGHT LIFT CYLINDER - LH <i>ca</i> ✓	\$ 192.00	<i>153.70</i> ✓
44	HEADLIGHT HOSE <i>X</i> <i>suc</i>	\$ 170.00	<i>✓</i>
45	HEADLIGHT T-PIECE <i>X</i> <i>suc</i>	\$ 14.00	<i>X</i>
46	HEADLIGHT CONNECTING PIECE - STRAIGHT <i>X</i> <i>suc</i> 2	\$ 26.00	<i>✓</i>
47	HEADLIGHT WASHER SYSTEM PUMP <i>X</i> <i>suc</i>	\$ 96.00	<i>✓</i>
48	HEADLIGHT WASHER PUMP INSULATOR <i>X</i> <i>suc</i>	\$ 19.00	<i>✓</i>
49	WASHER RESERVOIR <i>X</i> <i>suc</i>	\$ 200.00	<i>✓</i>
50	HEADLIGHT FUEL FILLER NECK <i>X</i> <i>suc</i>	\$ 87.00	<i>✓</i>
51	WINDSCREEN WASHER SYSTEM PUMP <i>X</i> <i>suc</i>	\$ 118.00	<i>X</i>
52	COOLANT RADIATOR LOCK CARRIER <i>ca</i> ✓	\$ 928.00	<i>742</i> ✓
53	COOLANT REGULATOR SUPPORT <i>ca</i> ✓ <i>1pc</i> <i>X</i>	\$ 69.00	<i>27.76</i> ✓
54	A/C CONDENSER <i>? X</i> <i>suc</i>	\$ 677.00	<i>X</i>
55	REFRIGERANT HOSE <i>X</i> <i>suc</i>	\$ 508.00	<i>✓</i>
56	REFRIGERANT PIPE <i>ca</i> ✓	\$ 289.00	<i>236.70</i> ✓
57	PRESSURE RELIEF VALVE <i>X</i> <i>suc</i>	\$ 48.00	<i>✓</i>
58	PRESSURE SENSOR <i>X</i> <i>suc</i>	\$ 175.00	<i>✓</i>
59	EXTERNAL TEMPERATURE SENSOR <i>? X</i> <i>suc</i>	\$ 54.00	<i>✓</i>
60	TEMPERATURE SENSOR BRACKET <i>ca</i> ✓	\$ 17.00	<i>13.04</i> ✓

SUB TOTAL SPARE PARTS

: \$ 3,951.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2156 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	CHARGE AIR COOLER <i>bt ✓</i>	\$ 513.00	<i>490.40 ✓</i>
62	COOLER PRESSURE PIPE <i>X suc</i>	\$ 494.00	<i>X</i>
63	COOLANT RADIATOR <i>bt ✓</i>	\$ 1,246.00	<i>996.88 ✓</i>
64	COOLANT RADIATOR RUBBER BUSH - UPPER <i>? X suc 2</i>	\$ 12.00	<i>18.37 ✓</i>
65	READY MIX COOLANT <i>ne ✓</i>	\$ 84.00	<i>67.20 ✓</i>
66	COOLANT TWIN FAN RING <i>? X suc</i>	\$ 237.00	<i>X</i>
67	RADIATOR FAN <i>? X suc</i>	\$ 779.00	<i>X</i>
68	RADIATOR FAN <i>? X suc</i>	\$ 673.00	<i>X</i>
69	COOLANT AIR GUIDE - LH <i>ca ✓</i>	\$ 24.00	<i>18.64 ✓</i>
70	COOLANT SECURING STRIP - LOWER <i>? X suc</i>	\$ 21.00	<i>X</i>
71	NOISE INSULATION <i>ca ✓</i>	\$ 579.00	<i>463.20 ✓</i>
72	CAUTION SIGN <i>X 11</i>	\$ 13.00	<i>X</i>
73	A/C STICKER <i>ne ✓</i>	NEC \$ 22.00	<i>16.96 ✓</i>
74	FRONT NO PLATE <i>bt ✓</i>	NEC \$ 40.00	<i>40 ✓</i>
75	SUNDRIES <i>? X suc</i>	<i>all</i> S/N \$ 600.00	<i>60.24 ✓</i>

TOTAL SPARE PARTS

: \$ 24,133.00

TOTAL LABOUR CHARGES

\$ 10,792.00

GRAND TOTAL

\$ 34,925.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

:

:

:

:

:

:

Rasul - Hp 90010068

10 days

04/09/11 @ 1200

EXCESS: TBA

Revert

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10889

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1058/2019/TG
Date	:	3-Sep-19

Vehicle IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,

10 days to repair this vehicle

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 62564315

Owner's Name	:	Mr. Joseph Peh Chin Leong
Address	:	7 Bishan Street 15 #05-06 Singapore 573908
Telephone	:	(HP) +65 93638470
Type of Claim	:	Own Damage Claim
Policy No.	:	2100394198-04
Vehicle No	:	SGS 2156 M
Model Code	:	Audi 1.4 1.8 TFSI MU (A)
Model / Year	:	11/11/2014
Engine No	:	CJE 090532
Chassis No	:	WAUZZZ8K8FA048868
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	9-Feb-19
Place of Accident	:	Mindef Taxi Stand

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 2156 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and recover vehicle from scene of accident.	S/N \$ 280.00	\$ 280.00
2	To remove, check and reinstall front wire harness for headlight, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
3	To remove and renew aircon condenser, charge air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	\$ 1,200.00
4	To dismantle and renew front bumper, bonnet, lhs front fender, lhs headlight. Renew front lock	\$ 5,220.00	\$ 3,000.00
SUB TOTAL LABOUR CHARGES		: \$ 7,060.00	\$ 4,840.00

Premium Automobiles

55 Ibbi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 2156 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
			\$ 4,840.00
5	To respray front bumper, lhs front fender and bonnet.	\$ 3,300.00	\$ 1,650.00
6	To carry out wheel alignment. To inspect lhs front suspension for further damages.	S/N \$ 240.00	
7	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 10,792.00	\$ 6,882.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6356 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2156 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,100.00	\$ 1,680.00 /
2	FRONT BUMPER FIXING PARTS	\$ 234.00	\$ 187.20 /
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	\$ 165.60 /
4	FRONT BUMPER GRILLE - LOWER CENTRE	\$ 123.00	\$ 98.00 /
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	\$ 177.00	
6	RADIATOR GRILLE	\$ 1,005.00	\$ 804.00 /
7	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 123.00	\$ 98.00 /
8	FRONT BUMPER VENT GRILLE - RH	\$ 123.00	\$ 98.00 /
9	FRONT BUMPER WHEEL SPOILER - LH / RH	2 \$ 90.00	\$ 72.00 /
10	FRONT BUMPER REINFORCEMENT	\$ 802.00	\$ 641.60 /
11	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	\$ 90.40 /
12	FRONT BUMPER COVER	\$ 116.00	
13	FRONT BUMPER BRACKET - LH	\$ 207.00	
14	FRONT BUMPER SUPPORT	2 \$ 23.00	
15	FRONT BUMPER GUIDE SECTION - LH	\$ 33.00	\$ 26.08 /
16	FRONT FENDER - LH	\$ 904.00	\$ 722.80 /
17	FRONT FENDER ATTACHMENT PARTS	\$ 52.00	\$ 41.60 /
18	FRONT FENDER BRACKET - LH	\$ 48.00	\$ 37.92 /
19	DEFORMATION ELEMENT BRACKET - REAR LH	\$ 45.00	
20	FRONT FENDER BRACE - LOWER LH	\$ 107.00	\$ 85.60 /
SUB TOTAL SPARE PARTS		\$ 6,632.00	\$ 4,848.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 0366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2156 M

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 4,848.80
21	STONE CHIP GUARD	\$	67.00	\$ 52.96 ✓
22	FRONT FENDER ADHESIVE TAPE	\$	50.00	
23	FRONT WHEEL HOUSING LINER	\$	223.00	\$ 178.40 ✓
24	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS	\$	41.00	\$ 32.80 ✓
25	BONNET	\$	2,549.00	\$ 2,039.20 ✓
26	BONNET ATTACHEMENT PARTS	\$	152.00	
27	BONNET CATCH HOOK	\$	127.00	
28	BONNET GAS FILLED STRUT - LH	\$	109.00	
29	BONNET EDGE PROTECTION - FRONT	\$	25.00	
30	BONNET LID LOCK	\$	196.00	
31	BONNET LID LOCK CABLE - FRONT / REAR	\$	111.00	
32	SIGNAL HORN - HIGH TONE LH	\$	184.00	
33	SIGNAL HORN SPRING SHACKLE - HIGH TONE LH	\$	23.00	
34	HEADLIGHT MOUNTING - LH	\$	107.00	\$ 85.60 ✓
35	HEADLIGHT BRACKET - LH	\$	96.00	\$ 76.56 ✓
36	HEADLIGHT - LH	\$	2,152.00	\$ 1,721.60 ✓
37	DRIVING LIGHT POWER MODULE	\$	520.00	
38	GAS DISCHARGE LAMP CONTROL UNIT	\$	1,051.00	
39	GAS DISCHARGE LAMP	\$	398.00	
40	HEADLIGHT HOSE - LH	\$	32.00	
SUB TOTAL SPARE PARTS			\$ 8,213.00	\$ 9,035.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2156 M

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	9,035.92
41	HEADLIGHT RETAINING PLATE - LH		\$ 22.00	\$ 17.12 ✓
42	HALOGEN FOG LAMP - LH		\$ 242.00	\$ 193.60 ✓
43	HEADLIGHT LIFT CYLINDER - LH		\$ 192.00	\$ 153.20 ✓
44	HEADLIGHT HOSE		\$ 170.00	
45	HEADLIGHT T-PIECE		\$ 14.00	
46	HEADLIGHT CONNECTING PIECE - STRAIGHT	2	\$ 26.00	
47	HEADLIGHT WASHER SYSTEM PUMP		\$ 96.00	
48	HEADLIGHT WASHER PUMP INSULATOR		\$ 19.00	
49	WASHER RESERVOIR		\$ 200.00	
50	HEADLIGHT FUEL FILLER NECK		\$ 87.00	
51	WINDSCREEN WASHER SYSTEM PUMP		\$ 118.00	
52	COOLANT RADIATOR LOCK CARRIER		\$ 928.00	\$ 742.00 ✓
53	COOLANT REGULATOR SUPPORT	2	\$ 69.00	\$ 27.36 ✓
54	A/C CONDENSER		\$ 677.00	
55	REFRIGERANT HOSE		\$ 508.00	
56	REFRIGERANT PIPE		\$ 289.00	\$ 231.20 ✓
57	PRESSURE RELIEF VALVE		\$ 48.00	
58	PRESSURE SENSOR		\$ 175.00	
59	EXTERNAL TEMPERATURE SENSOR		\$ 54.00	
60	TEMPERATURE SENSOR BRACKET		\$ 17.00	\$ 13.04 ✓

SUB TOTAL SPARE PARTS

: \$ 3,951.00 \$ 10,413.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2156 M

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 10,413.44
61	CHARGE AIR COOLER		\$ 513.00	\$ 410.40 ✓
62	COOLER PRESSURE PIPE		\$ 494.00	
63	COOLANT RADIATOR		\$ 1,246.00	\$ 996.80 ✓
64	COOLANT RADIATOR RUBBER BUSH - UPPER	2	\$ 12.00	\$ 18.72 ✓
65	READY MIX COOLANT		\$ 84.00	\$ 67.20 ✓
66	COOLANT TWIN FAN RING		\$ 237.00	
67	RADIATOR FAN		\$ 779.00	
68	RADIATOR FAN		\$ 673.00	
69	COOLANT AIR GUIDE - LH		\$ 24.00	\$ 18.64 ✓
70	COOLANT SECURING STRIP - LOWER		\$ 21.00	
71	NOISE INSULATION		\$ 579.00	\$ 463.20 ✓
72	CAUTION SIGN		\$ 13.00	
73	A/C STICKER	NEC	\$ 22.00	\$ 16.96 ✓
74	FRONT NO PLATE	NEC	\$ 40.00	\$ 40.00
75	SUNDRIES	S/N	\$ 600.00	\$ 60.24 ✓
TOTAL SPARE PARTS			\$ 24,133.00	\$ 12,505.60
TOTAL LABOUR CHARGES			\$ 10,792.00	\$ 6,682.00
GRAND TOTAL			\$ 34,925.00	\$ 19,187.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Repair limit
14,400

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGS 2156 M

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1058/2019/NH

24TH JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SGS 2156 M, Audi A4 1.8T FSI MU.

With reference to the above-mentioned vehicle, no. **SGS 2156 M**, claimant, **Mr. Joseph Peh Chin Leong**, please find the related document per attached.

1. A copy of the Original invoice no. 85014769 – S\$ 16,478.00.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept


Encl
AIG – SGS 2156 M

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service

Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:11

Company Reg.No.199902271W

GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014769 Date : 23/01/2020 Order : SGS2156M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SGS2156M (V 24948)

Regn Date: 28/11/2014

Mileage: 109920

WIP No : 10889

Model: A4 1.8T FSI MU 8K203H

Chassis: WAUZZZ8K8FA048868

Engine: CJE 090532

DEPT: U

You have been assisted by: UB-Tony Poong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LIMIT repair basis as agreed	18,000.00	1.00	18,000.00
Q	EXC	Insurance Excess/Liability	-800.00	1.00	-800.00
Q	EXC	50% Contribution of repair cost	-1,800.00	1.00	-1,800.00

Parts 0.00
Labour 0.00
Sublet 18,000.00
Menus 0.00
Lubricant 0.00

Sub- Total 15,400.00

7% GST 1,078.00

Grand Total 16,478.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SGS 2156 M

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1058/2019/TG
26 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 1.8 TFSI MU (A)
Vehicle Chassis No. : WAUZZZ8K8FA048868
Vehicle Regn No. : **SGS 2156 M**
Vehicle Mileage : 107947 KM
Vehicle Owner : Mr. Joseph Peh Chin Leong
Certificate No : 2100394198-04
Own Damage Excess : \$856.00 (Inclusive 7% GST)
Accident Date : 02/09/2019
Place : Mindef Taxi Stand
Repair Cost : \$ 16,478.00
WIP No. : 10889
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


18.06pm
26/9/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Sep 2019 17:05		04 Sep 2019 15:53 Edit Adj Rpt	\$16,200.00 Edit Estimates	\$16,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

JOSEPH PEH CHIN LEONG, ID: S82007043, Tel: +6593638470, Email: PEH.JOSEPH@GMAIL.COM

Vehicle Reg. No.:

SGS2156M

Claim Type:

OD / 6404588414SG

Repairer:

Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/09/2019]

Driver/Custodian:

JOSEPH PEH CHIN LEONG (37 / Male), NRIC: S82007043, Tel: +6593638470 Email: PEH.JOSEPH@GMAIL.COM

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (22/11/2019): Alert - Adj Mandate Approved (\$16200.00) - SGS2156M - Claim Handler: Gan, Hunch...
- AIG_SG (11/09/2019): Alert - Adj Mandate Approved (\$14400.00) - SGS2156M - Claim Handler: Gan, Hunch...
- AIG_SG (11/09/2019): Alert - Adj Mandate Approved (\$22213.50) - SGS2156M - Claim Handler: Gan, Hunch...
- AIG_SG (11/09/2019): SGS2156M / OD / 02/09/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGS2156M (6404588414SG)
OD
Sep 2 2019 7:45PM
[JOSEPH PEH CHIN LEONG]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	04/09/19 17:39	Adjuster Immediate Advice														Load HTM				
2	05/09/19 17:17	Adjuster Immediate Advice														Load HTM				
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	05/09/19 11:11	Odometer Reading														Load JPG	☒			
2	05/09/19 11:11	Chassis Number														Load JPG	☒			
3	05/09/19 11:11	General View														Load JPG	☒			
4	05/09/19 11:11	General View														Load JPG	☒			
5	05/09/19 11:11	General View														Load JPG	☒			
6	05/09/19 11:11	General View														Load JPG	☒			
7	05/09/19 11:11	General View														Load JPG	☒			
8	05/09/19 11:11	General View														Load JPG	☒			
9	05/09/19 11:11	General View														Load JPG	☒			
10	05/09/19 11:11	General View														Load JPG	☒			
11	05/09/19 11:11	General View														Load JPG	☒			
12	05/09/19 11:11	General View														Load JPG	☒			
13	05/09/19 11:11	General View														Load JPG	☒			
14	05/09/19 11:11	General View														Load JPG	☒			
15	05/09/19 11:11	General View														Load JPG	☒			
16	05/09/19 11:11	General View														Load JPG	☒			
17	05/09/19 11:11	General View														Load JPG	☒			
18	05/09/19 11:11	General View														Load JPG	☒			
19	05/09/19 11:11	General View														Load JPG	☒			
20	05/09/19 11:11	General View														Load JPG	☒			
21	05/09/19 11:11	General View														Load JPG	☒			
22	05/09/19 11:11	General View														Load JPG	☒			
23	05/09/19 11:11	General View														Load JPG	☒			
24	05/09/19 11:11	General View														Load JPG	☒			
25	05/09/19 11:11	General View														Load JPG	☒			
26	05/09/19 11:11	General View														Load JPG	☒			
27	05/09/19 11:11	General View														Load JPG	☒			
28	05/09/19 11:11	General View														Load JPG	☒			
29	05/09/19 11:11	General View														Load JPG	☒			
30	05/09/19 11:11	General View														Load JPG	☒			
31	05/09/19 11:11	General View														Load JPG	☒			
32	05/09/19 11:11	General View														Load JPG	☒			
33	05/09/19 11:11	General View														Load JPG	☒			
34	05/09/19 11:11	General View														Load JPG	☒			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	05/09/19 11:11	General View	 Load JPG	☒
36	05/09/19 11:11	General View	 Load JPG	☒
37	05/09/19 11:11	General View	 Load JPG	☒
38	05/09/19 11:11	General View	 Load JPG	☒
39	05/09/19 11:11	General View	 Load JPG	☒
40	05/09/19 11:11	General View	 Load JPG	☒
41	05/09/19 11:11	General View	 Load JPG	☒
42	05/09/19 11:11	General View	 Load JPG	☒
43	05/09/19 11:11	General View	 Load JPG	☒
44	05/09/19 11:11	General View	 Load JPG	☒
45	05/09/19 11:11	General View	 Load JPG	☒
46	05/09/19 11:11	General View	 Load JPG	☒
47	05/09/19 11:11	General View	 Load JPG	☒
48	05/09/19 11:11	General View	 Load JPG	☒
49	05/09/19 11:11	General View	 Load JPG	☒
50	05/09/19 11:11	General View	 Load JPG	☒
51	05/09/19 11:11	General View	 Load JPG	☒
52	05/09/19 11:11	General View	 Load JPG	☒
53	05/09/19 11:11	General View	 Load JPG	☒
54	05/09/19 11:11	General View	 Load JPG	☒
55	05/09/19 11:11	General View	 Load JPG	☒
56	05/09/19 11:11	General View	 Load JPG	☒
57	05/09/19 11:11	General View	 Load JPG	☒
58	05/09/19 11:11	General View	 Load JPG	☒
59	05/09/19 11:11	General View	 Load JPG	☒
60	05/09/19 11:11	General View	 Load JPG	☒
61	05/09/19 11:11	General View	 Load JPG	☒
62	05/09/19 11:11	General View	 Load JPG	☒
63	05/09/19 11:11	General View	 Load JPG	☒
64	05/09/19 11:11	General View	 Load JPG	☒
65	05/09/19 11:11	General View	 Load JPG	☒
66	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
67	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
68	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
69	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
70	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
71	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
72	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
73	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
74	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
75	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
76	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
77	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
78	04/11/19 11:32	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/19 17:41	Log card (if available)	 Load PDF	
2	04/09/19 17:45	Singapore Accident Statement	 Load PDF	
3	04/09/19 17:45	Certificate of Insurance	 Load PDF	
4	04/09/19 17:45	UNDERTAKING FORM	 Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
5	04/09/19 17:45	INTERVIEW FORM	 Load PDF	
6	05/09/19 11:10	ESTIMATE	 Load PDF	
7	06/09/19 15:42	Police Report	 Load PDF	
8	11/09/19 09:18	Driver's Driving License	 Load PDF	
9	04/11/19 15:10	REVISED ESTIMATE	 Load PDF	
10	05/02/20 14:34	Workshop Invoice	 Load PDF	
11	05/02/20 14:34	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/09/19 10:36	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/09/19 10:30	Accident Photo	 Load JPG	☒
2	03/09/19 10:30	Accident Photo	 Load JPG	☒
3	03/09/19 10:30	Accident Photo	 Load JPG	☒
4	03/09/19 10:30	Accident Photo	 Load JPG	☒
5	03/09/19 10:30	Accident Photo	 Load JPG	☒
6	03/09/19 10:30	Accident Photo	 Load JPG	☒
7	03/09/19 10:30	Accident Photo	 Load JPG	☒
8	03/09/19 10:30	Accident Photo	 Load JPG	☒
9	03/09/19 10:30	Accident Photo	 Load JPG	☒
10	03/09/19 10:30	Accident Photo	 Load JPG	☒
11	03/09/19 10:30	Accident Photo	 Load JPG	☒
12	03/09/19 10:30	Accident Photo	 Load JPG	☒
13	03/09/19 10:30	Accident Photo	 Load JPG	☒
14	03/09/19 10:30	Accident Photo	 Load JPG	☒
15	03/09/19 10:30	Accident Photo	 Load JPG	☒
16	03/09/19 10:30	Accident Photo	 Load JPG	☒
17	03/09/19 10:30	Accident Photo	 Load JPG	☒
18	03/09/19 10:30	Accident Photo	 Load JPG	☒
19	03/09/19 10:30	Accident Photo	 Load JPG	☒
20	03/09/19 10:30	Accident Photo	 Load JPG	☒
21	03/09/19 10:30	Accident Photo	 Load JPG	☒
22	03/09/19 10:30	Accident Photo	 Load JPG	☒
23	03/09/19 10:30	Accident Photo	 Load JPG	☒
24	03/09/19 10:30	Accident Photo	 Load JPG	☒
25	03/09/19 10:30	Accident Photo	 Load JPG	☒
26	03/09/19 10:30	Accident Photo	 Load JPG	☒
27	03/09/19 10:30	Accident Photo	 Load JPG	☒
28	03/09/19 10:30	Accident Photo	 Load JPG	☒
29	03/09/19 10:30	Accident Photo	 Load JPG	☒
30	03/09/19 10:30	Accident Photo	 Load JPG	☒
31	03/09/19 10:30	Accident Photo	 Load JPG	☒
32	03/09/19 10:30	Accident Photo	 Load JPG	☒
33	03/09/19 10:30	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/09/19 10:35	Sketch Plan	 Load JPG	☒
2	03/09/19 10:35	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19015658/R1QF3E2

Date: 05/02/2020

REFERENCE

Insured/Claimant: JOSEPH PEH CHIN LEONG Policy No: 2100394198-04
Date of Loss: 02/09/2019 Nature of Claim: OD Claim No: 6404588414SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGS2156M**
Make & Model: AUDI A4, 1.8 TFSI MU Ambition (A) Engine No: CJE090532
Reg. Date: 28/11/2014 (Man. Year: 2014) Chassis No: WAUZZZ8K8FA048868
Colour: White Odometer: 107946 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$69,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R16 Rear Tyre Size: 225/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,133.00	14,305.60	9,827.40	40.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,792.00	6,682.00	4,110.00	38.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,925.00	20,987.60	13,937.40	39.91
Approved Total (Overridden) (S\$)		16,200.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	34,125.00	15,400.00	18,725.00	54.87
+ GST 7.00/7.00% (S\$)	2,388.75	1,078.00	1,310.75	54.87
Nett Amount (S\$)	36,513.75	16,478.00	20,035.75	54.87

INSPECTION

Date of Assignment: 04/09/2019
Date Inspected: 04/09/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Repair limit \$14,400.00.

Repairer agreed to repair at \$18,000.00.

Balance of \$3,600.00 will be bear by Insured and Insurance 50% each at \$1,800.00.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,100.00 FS	*1,680.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	234.00 FS	*187.20 FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	207.00 FS	*165.60 FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Cracked	123.00 FS	*98.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Serviceable	177.00 FS	*- FS
6	1		*RADIATOR GRILLE	Broken	1,005.00 FS	*804.00 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	123.00 FS	*98.00 FS
8	1		*FRONT BUMPER VENT GRILLE - RH	Missing	123.00 FS	*98.00 FS
9	2		*FRONT BUMPER WHEEL SPOILER - LH/RH	Scratched	90.00 FS	*72.00 FS
10	1		*FRONT BUMPER REINFORCEMENT	Bent	802.00 FS	*641.60 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	113.00 FS	*90.40 FS
12	1		*FRONT BUMPER COVER	Serviceable	116.00 FS	*- FS
13	1		*FRONT BUMPER BRACKET - LH	Serviceable	207.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT	Serviceable	23.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	33.00 FS	*26.08 FS
16	1		*FRONT FENDER - LH	Bent	904.00 FS	*722.80 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Necessary	52.00 FS	*41.60 FS
18	1		*FRONT FENDER BRACKET - LH	Necessary	48.00 FS	*37.92 FS
19	1		*DEFORMATION ELEMENT BRACKET - REAR LH	Serviceable	45.00 FS	*- FS
20	1		*FRONT FENDER BRACE - LOWER LH	Bent	107.00 FS	*85.60 FS
21	1		*STONE CHIP GUARD	Necessary	67.00 FS	*52.96 FS
22	1		*FRONT FENDER ADHESIVE TAPE	Not Necessary	50.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER	Cracked	223.00 FS	*178.40 FS
24	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	41.00 FS	*32.80 FS
25	1		*BONNET	Bent	2,549.00 FS	*2,039.20 FS
26	1		*BONNET ATTACHMENT PARTS	Not Necessary	152.00 FS	*- FS
27	1		*BONNET CATCH HOOK	Serviceable	127.00 FS	*- FS
28	1		*BONNET GAS FILLED STRUT - LH	Serviceable	109.00 FS	*- FS
29	1		*BONNET EDGE PROTECTION - FRONT	Serviceable	25.00 FS	*- FS
30	1		*BONNET LID LOCK	Serviceable	196.00 FS	*- FS
31	1		*BONNET LID LOCK CABLE - FRONT / REAR	Serviceable	111.00 FS	*- FS
32	1		*SIGNAL HORN - HIGH TONE LH	Serviceable	184.00 FS	*- FS
33	1		*SIGNAL HORN SPRING SHACKLE - HIGH TONE LH	Serviceable	23.00 FS	*- FS
34	1		*HEADLIGHT MOUNTING - LH	Cracked	107.00 FS	*85.60 FS
35	1		*HEADLIGHT BRACKET - LH	Cracked	96.00 FS	*76.56 FS
36	1		*HEADLIGHT - LH	Scratched	2,152.00 FS	*1,721.60 FS
37	1		*DRIVING LIGHT POWER MODULE	Serviceable	520.00 FS	*- FS
38	1		*GAS DISCHARGE LAMP CONTROL UNIT	Serviceable	1,051.00 FS	*- FS
39	1		*GAS DISCHARGE LAMP	Serviceable	398.00 FS	*- FS
40	1		*HEADLIGHT HOSE - LH	Serviceable	32.00 FS	*- FS
41	1		*HEADLIGHT RETAINING PLATE - LH	Cracked	22.00 FS	*17.12 FS
42	1		*HALOGEN FOG LAMP - LH	Missing	242.00 FS	*193.60 FS
43	1		*HEADLIGHT LIFT CYLINDER - LH	Cracked	192.00 FS	*153.20 FS
44	1		*HEADLIGHT HOSE	Serviceable	170.00 FS	*- FS
45	1		*HEADLIGHT T-PIECE	Serviceable	14.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*HEADLIGHT CONNECTING PIECE - STRAIGHT	Serviceable	26.00 FS	*- FS
47	1		*HEADLIGHT WASHER SYSTEM PUMP	Serviceable	96.00 FS	*- FS
48	1		*HEADLIGHT WASHER PUMP INSULATOR	Serviceable	19.00 FS	*- FS
49	1		*WASHER RESERVIOR	Serviceable	200.00 FS	*- FS
50	1		*HEADLIGHT FUEL FILLER NECK	Serviceable	87.00 FS	*- FS
51	1		*WINDSCREEN WASHER SYSTEM PUMP	Serviceable	118.00 FS	*- FS
52	1		*COOLANT RADIATOR LOCK CARRIER	Cracked	928.00 FS	*742.00 FS
53	1		*COOLANT REGULATOR SUPPORT	Cracked (1pc only)	69.00 FS	*27.36 FS
54	1		*A/C CONDENSER	Serviceable	677.00 FS	*- FS
55	1		*REFRIGERANT HOSE	Serviceable	508.00 FS	*- FS
56	1		*REFRIGERANT PIPE	Bent	289.00 FS	*231.20 FS
57	1		*PRESSURE RELIEF VALVE	Serviceable	48.00 FS	*- FS
58	1		*PRESSURE SENSOR	Serviceable	175.00 FS	*- FS
59	1		*EXTERNAL TEMPERATURE SENSOR	Serviceable	54.00 FS	*- FS
60	1		*TEMPERATURE SENSOR BRACKET	Cracked	17.00 FS	*13.04 FS
61	1		*CHARGE AIR COOLER	Bent	513.00 FS	*410.40 FS
62	1		*COOLER PRESSURE PIPE	Serviceable	494.00 FS	*- FS
63	1		*COOLER RADIATOR	Bent	1,246.00 FS	*996.80 FS
64	2		*COOLER RADIATOR RUBBER BUSH - UPPER	Necessary	12.00 FS	*18.72 FS
65	1		*READY MIX COOLANT	Necessary	84.00 FS	*67.20 FS
66	1		*COOLANT TWIN FAN RING	Serviceable	237.00 FS	*- FS
67	1		*RADIATOR FAN	Serviceable	779.00 FS	*- FS
68	1		*RADIATOR FAN	Serviceable	673.00 FS	*- FS
69	1		*COOLANT AIR GUIDE - LH	Cracked	24.00 FS	*18.64 FS
70	1		*COOLANT SECURING STRIP - LOWER	Serviceable	21.00 FS	*- FS
71	1		*NOISE INSULATION	Cracked	579.00 FS	*463.20 FS
72	1		*CAUTION SIGN	Not Necessary	13.00 FS	*- FS
73	1		*A/C STICKER	Necessary	22.00 FS	*16.96 FS
74	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
75	1		*SUNDRIES	Necessary	600.00 FS	*60.24 FS
76	1		*TOP UP FROM INSURANCE		-	*1,800.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	24,133.00	14,305.60
--------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	New	280.00	280.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,200.00	1,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS HEADLIGHT. RENEW FRONT LOCK.	New	5,220.00	3,000.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	New	3,300.00	1,650.00
6	TO CARRY OUT WHEEL ALIGNMENT. TO INSPECT LHS FRONT SUSPENSION FOR FURTHER DAMAGES.	New	240.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour Cost (S\$)			10,792.00	6,682.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >